

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64eefb53eb1f822256dc8fd5"
    },
    "firstName": "Shashank",
    "type": "CREDITOFFICER",
    "_id": "66aa25866ade5c6fb59be3d9",
    "email": "bom1302@mahabank.co.in",
    "lastName": "Sharma",
    "mobileNo": "",
    "workMobileNo": "9799873713"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64eefb53eb1f822256dc8fd5",
  "name": "Ghodbunder Road Branch",
  "branchCode": "",
  "mobileNo": "022 25895856",
  "alternateMobileNo": "",
  "email": "bom1302@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No. 8 & 9, Pride Park, Near R-Mall, Ghodbunder Road, Thane -400
607 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90ffff3dd69653a591ae9",
  "zoneName": "THANE ZONE"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.234171001817856",
  "longitude": "72.99236021141031"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-18",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-18",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Balkum",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "30",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lodha Amara",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kolshet Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Clariant Compound",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "W30",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Lodha Amara - Tower 26, 27. 28. 30, 34 & 35 Project",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "64/3, 64/7, 65/2, 65/3, 65/4, 65/5, 68/3, 68/4, 68/5, 69/2, 69/6, 70/1, 70/2,
70/3, 70/4, 72/2, 72/3 & 73/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3004",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 607",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Celling",
  "label": "Cement Plastering with POP false Celling"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - W38",
    "west": "Wing - W29",
    "south": "Internal Road",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Passage",
      "east": "Flat No. 3003",
      "south": "Walls",
      "west": "Lift"
    },
    "asPerDocument": {
```

```
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "7.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "19275",
  "depreciatedBuildingRate": "2775"
```

```
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "103600",
  "landRate": "33200",
  "igrImage": "cases/6710f0149f905c0b8b765fa9/igr_1729255215616_Image.png",
  "squareMeterGuideLineRate": "119140.00",
  "squareFeetGuideLineRate": "11068.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "95",
  "rate": "10669.00",
  "squareFeetGuideLineRate": "10669.00",
  "squareMeterGuideLineRate": "114843.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per TMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with one car parking space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2019",
    "fullDate": "1/1/2019"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
```



```
    "label": "Information not available"
  },
  "provisionOfFirefighting": {
    "value": "Information_not_available",
    "label": "Information not available"
  },
  "groundStilt": {
    "value": "ground",
    "label": "Ground"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_occupancy_certificate",
    "label": "As per occupancy certificate"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "55",
  "ageOfBuilding": "5",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "30",
  "flatFloorNo": "30",
  "noOfLifts": "2",
  "noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "740.30",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6710f0149f905c0b8b765fa9/
routeMap_1729316073433_Image.png",
    "routeLat": "19.234307",
    "routeLng": "72.992214",
    "stationName": "Thane",
    "routeDistance": "6.8 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
```

```
"coordinates": [
  0,
  0
],
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "5tv4o",
    "name": "5tv4o",
    "image": "cases/6710f0149f905c0b8b765fa9/
routeMap_1729316003327_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```

```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "12972075.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "12972075.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Oct 19 2024 15:51:28 GMT+0530 (India Standard Time)",
  "number": "2308710",
  "dayCount": "7",
  "monthCount": "250",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "7898261.00",
  "selectedBuildUpValue": "740.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "671251db2c873c347146ae2c",
      "name": "externallmg_r_1729253702870_1729253604595_image_1.jpg",
      "path": "cases/6710f0149f905c0b8b765fa9/externallmg_r_1729253702870_1729253604595_image_1.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "671251db2c873c347146ae32",
      "name": "externallmg_r_1729253752613_1729253604595_image_7.jpg",
      "path": "cases/6710f0149f905c0b8b765fa9/externallmg_r_1729253752613_1729253604595_image_7.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "671251db2c873c347146ae31",
      "name": "externallmg_r_1729253748144_1729253604595_image_6.jpg",
      "path": "cases/6710f0149f905c0b8b765fa9/externallmg_r_1729253748144_1729253604595_image_6.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "671251db2c873c347146ae34",
      "name": "externallmg_r_1729253764508_1729253604595_image_8.jpg",
```

```
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253764508_1729253604595_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671251db2c873c347146ae36",
    "name": "externallmg_r_1729253793515_1729253604595_image_10.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253793515_1729253604595_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671251db2c873c347146ae33",
    "name": "externallmg_r_1729253783744_1729253604595_image_9.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253783744_1729253604595_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671251db2c873c347146ae35",
    "name": "externallmg_r_1729253798714_1729253604595_image_11.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253798714_1729253604595_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671251db2c873c347146ae37",
    "name": "externallmg_r_1729253803995_1729253604595_image_12.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253803995_1729253604595_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671251db2c873c347146ae2e",
    "name": "externallmg_r_1729253665700_1729253604595_image_0.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253665700_1729253604595_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "671251db2c873c347146ae2c",
    "name": "externallmg_r_1729253702870_1729253604595_image_1.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253702870_1729253604595_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671251db2c873c347146ae2d",
    "name": "externallmg_r_1729253718106_1729253604595_image_2.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253718106_1729253604595_image_2.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "671251db2c873c347146ae38",
    "name": "externallmg_r_1729253823063_1729253604595_image_13.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253823063_1729253604595_image_13.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17428.00",
    "max": "21399.00"
  },
  "builtUpRateRange": {
    "min": "15843.00",
    "max": "19454.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "673.00",
"empanelmentNo": [
  "AX33 /CREMON/Valuer/Empanelment/Sr No.55/2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6710f0149f905c0b8b765fa9",
"ownerName": "Sushilkumar Jagdish Gade & Nikita Sushilkumar Gade",
"ownerPhoneNo": "8793559539",
"fullAddress": "Residential Flat No. 3004, 30th Floor, Wing - W30, Lodha Amara,
Lodha Amara - Tower 26, 27. 28. 30, 34 & 35 Project, Clariant Compound, Kolshet
Road, Village - Balkum, Taluka - Thane, District - Thane, Thane (West), PIN Code - 400
607, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e1",
      "label": "Agreement To Sale"
    },
  },
  "inputs": {
    "documentDate": "26/03/2020",
    "from": {
      "value": "Company",
      "label": "Company"
    },
  },
  "Company": "Macrotech Developers Limited",
```

```
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "Sushilkumar Jagdish Gade & Nikita Sushilkumar Gade",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "5904 / 2020"
},
"isHardCopy": false,
"displayStatus": true,
"id": "488239",
"path": "cases/6710f0149f905c0b8b765fa9/
document_1729237395700_BOM_R_Mall_GB_RoadMr_gade.pdf",
"fileName": "document_1729237395700_BOM_R_Mall_GB_RoadMr_gade.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700001031"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1729314972605_RERA.pdf",
"path": "cases/6710f0149f905c0b8b765fa9/document_1729314972605_RERA.pdf",
"id": "658532",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Sat Oct 19 2024 10:46:12 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
```

```
"label": "Amended Commencement Certificate"
},
"inputs": {
  "documentDate": "20/01/2018",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "remark": " (As Download from RERA Site)",
  "number": {
    "value": "V.P._No._",
    "label": "V.P. No. "
  },
  "V.P._No._": "S05 / 0083 / 14 / TMC / TDD / 2486 / 18"
},
"isHardCopy": false,
"displayStatus": true,
"id": "618150",
"path": "cases/6710f0149f905c0b8b765fa9/document_1729315034387_CC.pdf",
"fileName": "document_1729315034387_CC.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "29/11/2019",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "V.P._No._",
      "label": "V.P. No. "
    },
    "V.P._No._": "S05 / 0083 / 14 / TMC / TDD / OCC / 0773 / 19"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1729315107410_OC.pdf",
  "path": "cases/6710f0149f905c0b8b765fa9/document_1729315107410_OC.pdf",
  "id": "330891",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Sat Oct 19 2024 10:48:27 GMT+0530 (India Standard Time)"
}
```

```
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "011866",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "876077",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Oct 17 2024 16:38:04 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sushilkumar Jagdish Gade & Nikita Sushilkumar Gade",
    "phone": "8793559539",
    "ownershipShare": "",
    "email": "",
    "id": "705504"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Living Room",
    "length": "",
    "length1": "14",
    "length2": "0",
    "width": "",
    "width1": "10",
    "width2": "0",
    "totalArea": "140.00",
    "images": [],
    "finalArea": "140.00",
    "extraAreas": []
  },
  {

```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"name": "Dining",
"length": "4.00",
"length1": "4",
"length2": "00",
"width": "7.00",
"width1": "7",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "",
  "length1": "14",
  "length2": "0",
  "width": "",
  "width1": "7",
  "width2": "0",
  "totalArea": "98.00",
  "images": [],
  "finalArea": "98.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "14.00",
  "length1": "14",
  "length2": "00",
  "width": "8.00",
```

```
"width1": "8",
"width2": "00",
"totalArea": "112.00",
"images": [],
"extraAreas": [],
"finalArea": "112.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "70.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "70.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "60.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
```



```
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "19.00",
  "length1": "19",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "38.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "38.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
```

```
"totalArea": "16.00",
"images": [],
"extraAreas": [],
"finalArea": "16.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Cupboard",
  "length": "2.00",
  "length1": "2",
  "length2": "0",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "8.00",
  "images": [],
  "finalArea": "8.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Cupboard",
  "length": "",
  "length1": "2",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "6.00",
  "images": [],
  "finalArea": "6.00",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
```

```
    "value": "Carpet"
  },
  "name": {
    "label": "Entrance",
    "value": "Entrance"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27",
  "percentageBeforeTotal": "27.00",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "62.52",
    "totalAreaDocument": "673",
    "docBuiltpUpPercentage": "10",
    "docFinalBuiltpUp": "740.30",
    "docFinalBuiltpUpSquareMeter": "68.78",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "601784"
  }
]
```

```
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "958.00",
      "squareMeterArea": "89.00",
      "expectedRate": "21398.75",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1053.80",
      "squareMeterArea": "97.90",
      "expectedRate": "19453.41",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "6712577e2c873c347146b8a6",
    "property": "Residential Flat",
    "area": "958",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "magic_bricks",
    "expectedPrice": "20500000",
    "expectedRate": "21398.75",
    "builtUpExpectedRate": "19453.41",
    "image": "cases/6710f0149f905c0b8b765fa9/
indicator_1729254897676_Image.png",
    "squareMeter": "89.00",
    "id": "658301"
  },
  {
    "carpetArea": {
      "area": "955.00",
      "squareMeterArea": "88.72",
      "expectedRate": "20732.98",
```

```
"percentage": ""
},
"builtUpArea": {
  "area": "1050.50",
  "squareMeterArea": "97.59",
  "expectedRate": "18848.17",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "6712577e2c873c347146b8a7",
"property": " Residential Flat",
"area": "955",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "19800000",
"expectedRate": "20732.98",
"builtUpExpectedRate": "18848.17",
"image": "cases/6710f0149f905c0b8b765fa9/
indicator_1729254927934_Image.png",
"squareMeter": "88.72",
"id": "922167"
},
{
  "carpetArea": {
    "area": "453.00",
    "squareMeterArea": "42.09",
    "expectedRate": "17427.15",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "498.30",
    "squareMeterArea": "46.29",
    "expectedRate": "15842.87",
    "percentage": "10"
  },
  "saleableArea": {
```

```
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6712577e2c873c347146b8a8",
"property": "Residential Flat",
"area": "453",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "7894500",
"expectedRate": "17427.15",
"builtUpExpectedRate": "15842.87",
"image": "cases/6710f0149f905c0b8b765fa9/
indicator_1729254972720_Image.png",
"squareMeter": "42.09",
"id": "623193"
},
{
"carpetArea": {
"area": "453.00",
"squareMeterArea": "42.09",
"expectedRate": "17427.15",
"percentage": ""
},
"builtUpArea": {
"area": "498.30",
"squareMeterArea": "46.29",
"expectedRate": "15842.87",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6712577e2c873c347146b8a9",
"property": "Residential Flat",
"area": "453",
```

```
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "7894500",
"expectedRate": "17427.15",
"builtUpExpectedRate": "15842.87",
"image": "cases/6710f0149f905c0b8b765fa9/
indicator_1729255025537_Image.png",
"squareMeter": "42.09",
"id": "876718"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "671251db2c873c347146ae2b",
"name": "externallmg_r_1729253730527_1729253604595_image_3.jpg",
"path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253730527_1729253604595_image_3.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "671251db2c873c347146ae2c",
"name": "externallmg_r_1729253702870_1729253604595_image_1.jpg",
"path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253702870_1729253604595_image_1.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "671251db2c873c347146ae2d",
"name": "externallmg_r_1729253718106_1729253604595_image_2.jpg",
"path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253718106_1729253604595_image_2.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```

```
    "_id": "671251db2c873c347146ae2e",
    "name": "externallmg_r_1729253665700_1729253604595_image_0.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253665700_1729253604595_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae2f",
    "name": "externallmg_r_1729253738059_1729253604595_image_4.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253738059_1729253604595_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae30",
    "name": "externallmg_r_1729253744228_1729253604595_image_5.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253744228_1729253604595_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae31",
    "name": "externallmg_r_1729253748144_1729253604595_image_6.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253748144_1729253604595_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae32",
    "name": "externallmg_r_1729253752613_1729253604595_image_7.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253752613_1729253604595_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae33",
```



```
    "name": "externallmg_r_1729253783744_1729253604595_image_9.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253783744_1729253604595_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae34",
    "name": "externallmg_r_1729253764508_1729253604595_image_8.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253764508_1729253604595_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae35",
    "name": "externallmg_r_1729253798714_1729253604595_image_11.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253798714_1729253604595_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae36",
    "name": "externallmg_r_1729253793515_1729253604595_image_10.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253793515_1729253604595_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae37",
    "name": "externallmg_r_1729253803995_1729253604595_image_12.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253803995_1729253604595_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671251db2c873c347146ae38",
    "name": "externallmg_r_1729253823063_1729253604595_image_13.jpg",
```

```
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253823063_1729253604595_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671250f0fd439c34722c691a",
    "name": "externallmg_1729253571085_1729253569469_image_0.png",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_1729253571085_1729253569469_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671250f0fd439c34722c691b",
    "name": "externallmg_r_1729253587918_1729253569469_image_1.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253587918_1729253569469_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671250f0fd439c34722c691c",
    "name": "externallmg_r_1729253600101_1729253569469_image_2.jpg",
    "path": "cases/6710f0149f905c0b8b765fa9/
externallmg_r_1729253600101_1729253569469_image_2.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "BOM R Mall GB Road..Mr. gade.pdf",
    "filename": "1729255276551_BOM_R_Mall_GB_RoadMr_gade.pdf",
    "path": "cases/6710f0149f905c0b8b765fa9/
processingDocuments/1729255276551_BOM_R_Mall_GB_RoadMr_gade.pdf",
    "size": "12142137",
    "createdAt": "Fri Oct 18 2024 18:11:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1729255276788_Calculation_Sheet_NEW.xlsx",
```

```
    "path": "cases/6710f0149f905c0b8b765fa9/
processingDocuments/1729255276788_Calculation_Sheet_NEW.xlsx",
    "size": "3412912",
    "createdAt": "Fri Oct 18 2024 18:11:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Final Report - BOB - M_s.Yogeshwar Realty - Nashik.pdf",
    "filename":
"1729255276841_Final_Report__BOB__M_sYogeshwar_Realty__Nashik.pdf",
    "path": "cases/6710f0149f905c0b8b765fa9/processingDocuments/1729255276841_
Final_Report__BOB__M_sYogeshwar_Realty__Nashik.pdf",
    "size": "12139700",
    "createdAt": "Fri Oct 18 2024 18:11:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1729318304256_CC.pdf",
    "path": "cases/6710f0149f905c0b8b765fa9/
processingDocuments/1729318304256_CC.pdf",
    "size": "342682",
    "createdAt": "Sat Oct 19 2024 11:41:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "627222afafd7d55eddeddd82"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1729318304319_OC.pdf",
    "path": "cases/6710f0149f905c0b8b765fa9/
processingDocuments/1729318304319_OC.pdf",
    "size": "524211",
    "createdAt": "Sat Oct 19 2024 11:41:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "627222afafd7d55eddeddd82"
  },
  {
    "originalname": "RERA.pdf",
    "filename": "1729318304363_RERA.pdf",
    "path": "cases/6710f0149f905c0b8b765fa9/
processingDocuments/1729318304363_RERA.pdf",
    "size": "153208",
    "createdAt": "Sat Oct 19 2024 11:41:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "627222afafd7d55eddeddd82"
  },
  {
    "originalname": "Approved Building Plan 1.pdf",
    "filename": "1729318355837_Approved_Building_Plan_1.pdf",
```

```
    "path": "cases/6710f0149f905c0b8b765fa9/
processingDocuments/1729318355837_Approved_Building_Plan_1.pdf",
    "size": "883266",
    "createdAt": "Sat Oct 19 2024 11:42:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "627222afafd7d55eddeddd82"
  },
  {
    "originalName": "Approved Building Plan.pdf",
    "filename": "1729318356102_Approved_Building_Plan.pdf",
    "path": "cases/6710f0149f905c0b8b765fa9/
processingDocuments/1729318356102_Approved_Building_Plan.pdf",
    "size": "836292",
    "createdAt": "Sat Oct 19 2024 11:42:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "627222afafd7d55eddeddd82"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67121a042c873c34714657b4",
    "note": "Value given for confirmation",
    "taskId": "6710f01d97568e0b99df12a5",
    "createdAt": "2024-10-18T08:19:16.240Z"
  }
],
"createdAt": "2024-10-17T11:08:04.031Z",
"updatedAt": "2024-10-19T10:27:19.757Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mrs. Nikita Sushilkumar Gade",
"email": "",
"isExternal": "false",
```

```
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8793559539",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 673.00",
"flatRate": "19500",
"landOtherRate": "16500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet + 2
Passage + 2 Cupboard",
"carpetTotal": "594",
"otherCarpetTotal": "27.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "27.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "683.10",
"finalCarpetArea": "621.00",
"finalSalableArea": "751.41",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 621.00\nEBVT Area in Sq. Ft. =
52.00\n\nAll the above areas are within 9% of the Agreement for Sale Area. The above
calculations and detailed measurements taken by us prove that the Agreement for Sale
area is not exorbitantly inflated. Hence, valuation is prepared based on the Agreement
for Sale area.",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 609.00\nCupboard Area in Sq.
Ft. = 12.00\n\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
```

```

"label": "Free Hold",
"value": "Free_Hold"
},
"leaseDetails": {
"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Sat Oct 19 2024 09:44:26 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-10-18"
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'0"	10'0"	140.00
Dining	4'00"	7'00"	28.00
Bedroom	14'0"	7'0"	98.00
Bedroom	14'00"	8'00"	112.00
Kitchen	7'00"	10'00"	70.00
Toilet	6'00"	10'00"	60.00
Toilet	19'00"	2'00"	38.00
Passage	3'00"	6'00"	18.00
Passage	4'00"	4'00"	16.00
Cupboard	2'0"	4'0"	8.00
Cupboard	2'0"	3'0"	6.00
Other Composition :			
Entrance	3'00"	9'00"	27.00