

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63afbb0c191f7b344b005e34"
    },
    "firstName": "Rohit ",
    "type": "CREDITOFFICER",
    "_id": "66de81ed3389c50dfa6b064b",
    "email": "1brmgr415@mahabank.co.in",
    "lastName": "Patil",
    "mobileNo": "9212400402",
    "workMobileNo": "9212400402"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Rakesh Roshan Singh",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63afbb0c191f7b344b005e34",
  "name": "Sewree Branch",
  "branchCode": "",
  "mobileNo": "2224115814",
  "alternateMobileNo": "",
  "email": "brmgr415@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bussa Udyog Bhavan, T.J Road Sewree West Mumbai 400015"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "665ac13f42f4717ae30de3d5",
```

```
"role": "PICKUPPERSON",
"firstName": "NIDHI",
"email": "nidhi.kajwe97@gmail.com",
"lastName": "KAJWE",
"mobileNo": "8850520881",
"shortName": "NIDHI",
"workWithDocumentMaker": ""
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62ea09ea4e679b264caf07d7",
"role": "SITEENGINEER",
"firstName": "Suraj",
"email": "suraj@vastukala.org",
"lastName": "Zore",
"mobileNo": "8652448654",
"designation": "",
"shortName": "SZ",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
"profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
```

```
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.236492447044753",
  "longitude": "72.98869746178443"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.98869746178443,
    19.236492447044753
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-10-19",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-10-17",
    "remark": "MANUAL_IN_TASK"
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kolshet",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "23",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "T3",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lodha Crown Kolshet - Tower 3",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sandoz Baug",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "54/1, 55/14 & 55/15",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2312",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```

    "key": "postalCode",
    "value": "PIN - 400 067",
    "label": false
  },
  "suburb": {
    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Thane (West)",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RC.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_CP_fittings._Proposed_Electrical_wi
ring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring
with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {

```

```
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Thane_Municipal_Corporation",
"label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Forest Ville",
"west": "Lodha Business District ",
"south": "Open Plot ",
"east": "Kolshet Road "
},
"asPerDocumentAgreement": {
"north": "Details not available ",
"west": "Details not available ",
"south": "Details not available ",
"east": "Details not available "
},
"unitBoundaries": {
"asPerActual": {
"north": "Flat No. 2314",
"east": "Passage ",
"south": "Flat No. 2311",
"west": "Marginal Space "
},
"asPerDocument": {
"north": "Building is under construction ",
"east": "Building is under construction ",
"south": "Building is under construction ",
"west": "Building is under construction "
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
"buses": {
"title": "Buses"
}
```

```
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "As per Approved Building Plan, the composition of Flat will be 2 Bedrooms + Living Room + Kitchen + Passage + 2 Toilets. (i.e. 2BHK)",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan No. S05 / 0083 / 14 / TMC / TD - DP / TPS / 0157 / P / C / 2024 / Auto DCR dated 27.09.2024.",
  "approvePlanVerified": "Yes",
  "empanelledOfApprovePlan": "Building is under construction ",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": " Residential Flat",
  "rate": "92300",
  "landRate": "20000",
  "igrImage": "cases/6711dfe52c873c347145f873/igr_1729331511824_Image.png",
  "squareMeterGuideLineRate": "106145.00",
  "squareFeetGuideLineRate": "9861.00"
},
"igrFinalRate": {
```

```
"floorRatePercentage": "15",
"depreciationPercentage": "95",
"rate": "9461.00",
"squareFeetGuideLineRate": "9461.00",
"squareMeterGuideLineRate": "101838.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per TMC norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RC.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
}
```

```
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Along with One Car Parking Space",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_RC.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_RC.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building Under Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Standard",
```

```
"label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "Building Under Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building Under Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building Under Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
},
```



```
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "24",
"flatFloorNo": "23",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "14"
},
"finalPlinthArea": {
  "area": "583.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6711dfe52c873c347145f873/
routeMap_1729666615334_Image.png",
    "routeLat": "19.236139",
    "routeLng": "72.988750",
    "stationName": "Thane",
    "routeDistance": "7.7 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
}
```

```
"locationMapImg": [
  {
    "id": "7yvt5m",
    "name": "7yvt5m",
    "image": "cases/6711dfe52c873c347145f873/
routeMap_1729666515462_Image.png"
  }
],
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "9540000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
```

```
"bookValue": "0",
"finalValue": "9540000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Oct 23 2024 07:30:29 GMT+0000 (Coordinated Universal Time)",
  "number": "2308769",
  "dayCount": "9",
  "monthCount": "309",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5748963.00",
```

```
"selectedBuildUpValue": "583.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "671324b9fd439c34722c8733",
      "name": "externallmg_r_1729307828284_1729307826889_image_0.jpg",
      "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307828284_1729307826889_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "671324b9fd439c34722c8732",
      "name": "externallmg_r_1729307829741_1729307826889_image_2.jpg",
      "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307829741_1729307826889_image_2.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "671324b9fd439c34722c8736",
      "name": "externallmg_r_1729307829770_1729307826889_image_3.jpg",
      "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307829770_1729307826889_image_3.jpg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "671324b9fd439c34722c8737",
      "name": "externallmg_r_1729307832285_1729307826889_image_6.jpg",
      "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307832285_1729307826889_image_6.jpg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "16452.00",
  "max": "19616.00"
},
"builtUpRateRange": {
  "min": "14956.00",
  "max": "17833.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "530.00",
"empanelmentNo": [
  "AX33/CREMON/Valuer/Empanelment/ Sr No.55/ 2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6711dfe52c873c347145f873",
"ownerName": "Umesh Ashok Satkar, Amol Ashok Satkar & Sunit Ashok Satkar",
"ownerPhoneNo": "9867634606",
```

```
"appAddress": "T3 2312 Lodha Crown Kolshet Sandoz Baug, Kolshet Road Thane
West - 400607",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "15/10/2024",
      "from": {
        "value": "Company",
        "label": "Company"
      },
      "Company": "M/s. Macrotech Developers Ltd.",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Umesh Ashok Satkar, Amol Ashok Satkar & Sunit Ashok Satkar",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "27408 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "646226",
    "path": "cases/6711dfe52c873c347145f873/
document_1729224615455_1729224587502_ScanningFile.pdf",
    "fileName": "document_1729224615455_1729224587502_ScanningFile.pdf"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "27/09/2024",
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      },
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "S05 / 0083 / 14 / TMC / TD - DP / TPS / 0157 / P / C / 2024 / Auto DCR"
},
"documentType": {
  "value": "60ae1247aa6d152c1801b2ea",
  "label": "Commencement Certificate"
},
"inputs": {
  "documentDate": "15/07/2022",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  }
},
  "No": "S05 / 0083 / 14 / TMC / TDD / 4135 / 22"
},
"documentType": {
  "value": "60ae129faa6d152c1801b47d",
  "label": "RERA Certificate"
},
"inputs": {
  "documentDate": "25/08/2022",
```

```
"nameOfApprovingAuthority": {
  "value": "Maharashtra_Real_Estate_Regulatory_Authority",
  "label": "Maharashtra Real Estate Regulatory Authority"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "P51700046319"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1729664301075_RERA.pdf",
"path": "cases/6711dfe52c873c347145f873/document_1729664301075_RERA.pdf",
"id": "703522",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Wed Oct 23 2024 06:18:21 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "011872",
"createdBy": "665ac13f42f4717ae30de3d5",
"caseHistory": [
  {
    "id": "541075",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 18 2024 09:41:17 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Umesh Ashok Satkar, Amol Ashok Satkar & Sunit Ashok Satkar",
    "phone": "9867634606",
    "ownershipShare": "",
    "email": "",
    "id": "292343"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "286745",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "530",
  "squareMeterArea": "49.24",
  "docFinalBuiltUp": "583",
  "docFinalBuiltUpSquareMeter": "54.164",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "520.00",
      "squareMeterArea": "48.31",
      "expectedRate": "19615.38",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "572.00",
      "squareMeterArea": "53.14",
      "expectedRate": "17832.17",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "6713816f726e053a21bfe7cd",
  "property": "Residential Flat",
  "area": "520",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "10200000",
"expectedRate": "19615.38",
"builtUpExpectedRate": "17832.17",
"image": "cases/6711dfe52c873c347145f873/
indicator_1729331107498_Image.png",
"squareMeter": "48.31",
"id": "176863"
},
{
"carpetArea": {
"area": "530.00",
"squareMeterArea": "49.24",
"expectedRate": "18867.92",
"percentage": ""
},
"builtUpArea": {
"area": "583.00",
"squareMeterArea": "54.16",
"expectedRate": "17152.66",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "6713816f726e053a21bfe7ce",
"property": " Residential Flat",
"area": "530",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "10000000",
"expectedRate": "18867.92",
"builtUpExpectedRate": "17152.66",
"image": "cases/6711dfe52c873c347145f873/
indicator_1729331152844_Image.png",
```

```
"squareMeter": "49.24",
"id": "338882"
},
{
  "carpetArea": {
    "area": "530.00",
    "squareMeterArea": "49.24",
    "expectedRate": "16451.35",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "583.00",
    "squareMeterArea": "54.16",
    "expectedRate": "14955.78",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6713816f726e053a21bfe7cf",
  "property": "Residential Flat",
  "area": "530",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "8719218",
  "expectedRate": "16451.35",
  "builtUpExpectedRate": "14955.78",
  "image": "cases/6711dfe52c873c347145f873/
indicator_1729331219244_Image.png",
  "squareMeter": "49.24",
  "id": "606553"
},
{
  "carpetArea": {
    "area": "322.00",
    "squareMeterArea": "29.91",
    "expectedRate": "16726.05",
    "percentage": ""
  },
```

```
    },
    "builtUpArea": {
      "area": "354.20",
      "squareMeterArea": "32.91",
      "expectedRate": "15205.50",
      "percentage": "10"
    },
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    },
    "printlnReport": true,
    "_id": "6713816f726e053a21bfe7d0",
    "property": " Residential Flat",
    "area": "322",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "5385788",
    "expectedRate": "16726.05",
    "builtUpExpectedRate": "15205.50",
    "image": "cases/6711dfe52c873c347145f873/
indicator_1729331291973_Image.png",
    "squareMeter": "29.91",
    "id": "427183"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671324b9fd439c34722c8731",
    "name": "externalImg_1729307828693_1729307826889_image_1.png",
    "path": "cases/6711dfe52c873c347145f873/
externalImg_1729307828693_1729307826889_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671324b9fd439c34722c8732",
```



```
    "name": "externallmg_r_1729307829741_1729307826889_image_2.jpg",
    "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307829741_1729307826889_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671324b9fd439c34722c8733",
    "name": "externallmg_r_1729307828284_1729307826889_image_0.jpg",
    "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307828284_1729307826889_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671324b9fd439c34722c8734",
    "name": "externallmg_r_1729307830998_1729307826889_image_4.jpg",
    "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307830998_1729307826889_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671324b9fd439c34722c8735",
    "name": "externallmg_r_1729307831639_1729307826889_image_5.jpg",
    "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307831639_1729307826889_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671324b9fd439c34722c8736",
    "name": "externallmg_r_1729307829770_1729307826889_image_3.jpg",
    "path": "cases/6711dfe52c873c347145f873/
externallmg_r_1729307829770_1729307826889_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671324b9fd439c34722c8737",
    "name": "externallmg_r_1729307832285_1729307826889_image_6.jpg",
```

```
    "path": "cases/6711dfe52c873c347145f873/
externalImg_r_1729307832285_1729307826889_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6713248c477b35348d3fcce6",
    "name": "externalImg_1729307786214_1729307785491_image_0.png",
    "path": "cases/6711dfe52c873c347145f873/
externalImg_1729307786214_1729307785491_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6713248c477b35348d3fcce7",
    "name": "externalImg_r_1729307787821_1729307785491_image_1.jpg",
    "path": "cases/6711dfe52c873c347145f873/
externalImg_r_1729307787821_1729307785491_image_1.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1729331548992_Calculation_Sheet_NEW.xlsx",
    "path": "cases/6711dfe52c873c347145f873/
processingDocuments/1729331548992_Calculation_Sheet_NEW.xlsx",
    "size": "1383224",
    "createdAt": "Sat Oct 19 2024 15:22:29 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Adobe Scan 22 Oct 2024 (3).pdf",
    "filename": "1729666681807_Adobe_Scan_22_Oct_2024_3.pdf",
    "path": "cases/6711dfe52c873c347145f873/
processingDocuments/1729666681807_Adobe_Scan_22_Oct_2024_3.pdf",
    "size": "688717",
    "createdAt": "Wed Oct 23 2024 06:58:02 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Adobe Scan 22 Oct 2024 (4).pdf",
    "filename": "1729666681918_Adobe_Scan_22_Oct_2024_4.pdf",
```

```
    "path": "cases/6711dfe52c873c347145f873/
processingDocuments/1729666681918_Adobe_Scan_22_Oct_2024_4.pdf",
    "size": "225402",
    "createdAt": "Wed Oct 23 2024 06:58:02 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Arc Certificate - Floor Numbering - Crown Kolshet (3).pdf",
    "filename":
"1729666681941_Arc_Certificate__Floor_Numbering__Crown_Kolshet_3.pdf",
    "path": "cases/6711dfe52c873c347145f873/processingDocuments/1729666681941_
Arc_Certificate__Floor_Numbering__Crown_Kolshet_3.pdf",
    "size": "62470",
    "createdAt": "Wed Oct 23 2024 06:58:02 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1729666681945_CC.pdf",
    "path": "cases/6711dfe52c873c347145f873/
processingDocuments/1729666681945_CC.pdf",
    "size": "547307",
    "createdAt": "Wed Oct 23 2024 06:58:02 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "RERA.pdf",
    "filename": "1729666682016_RERA.pdf",
    "path": "cases/6711dfe52c873c347145f873/
processingDocuments/1729666682016_RERA.pdf",
    "size": "152709",
    "createdAt": "Wed Oct 23 2024 06:58:02 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
```

```
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "671374a2c6eb1c39d992a9cb",
    "note": "Value given for confirmation ",
    "taskId": "6711e957fd439c34722bc470",
    "createdAt": "2024-10-19T08:58:10.150Z"
  }
],
"createdAt": "2024-10-18T04:11:17.159Z",
"updatedAt": "2024-10-23T07:30:39.118Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2312, 23rd Floor, Building No T3, Lodha Crown
Kolshet - Tower 3, Sandoz Baug, Village - Kolshet, Thane (West), Taluka - Thane,
District - Thane, PIN - 400 067, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "665ac13f42f4717ae30de3d5",
"contactPersonName": "Mr. Anupam ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Customer Relationship Manager",
"siteVisitContactNo": "8433704946",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 530.00",
"flatRate": "18000",
"landOtherRate": "15000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
```

```

    "roadFacing": false,
    "mall": false
  },
  "builtupPercentage": "10",
  "carpetTotal": "0",
  "extendOfSiteRemark": "Carpet Area in Sq. Ft. = 510.00\nEBVT Area in Sq. Ft. =
20.00",
  "finalBuiltupArea": "0.00",
  "finalCarpetArea": "0.00",
  "finalSalableArea": "0.00",
  "otherCarpetTotal": "0",
  "salablePercentage": "10",
  "siteMeasurementRemark": "",
  "toBeAdded": "",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    },
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Oct 23 2024 05:39:25 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-10-17"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			