

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8da"
    },
    "firstName": "Sonali",
    "type": "CREDITOFFICER",
    "_id": "64e31653ae896715ef7f8b9b",
    "lastName": "Keni",
    "mobileNo": "",
    "workMobileNo": "9870198131",
    "email": "sonalikenic@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1200000",
    "discussWithPerson": "Sonali",
    "expectedFees": 600,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8da",
  "branchCode": "000003",
  "type": "BRANCH",
  "name": "Kandivali (West) Branch",
  "email": "kandivali@cosmosbank.in",
  "mobileNo": "022-28073762 ",
  "alternateMobileNo": "28051426",
  "address": "Shop No. 6 - 7, Sangita Apartment, Opp. Balbharti School, S. V. Road,
Kandivali (West), Mumbai - 400 067, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "COSMOS BANK- KANDIVALI(WEST)",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.30432622276063",
  "longitude": "72.84964432369138"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84964432369138,
    19.30432622276063
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "21/10/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bhayandar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhayander (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Parmanand Nagar Bldg. 'D' Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Devchand Nagar Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Bavan Jinalay",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "24",
  "label": true
},
"newSurveyNumber": {
  "status": true,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "2, Hissa No. 5",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B/405",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"value": "R.C.C._slab",
"label": "R.C.C. slab"
},
"flooring": {
"value": "Vitrified_tiles_flooring",
"label": "Vitrified tiles flooring"
},
"doors": {
"value": "Teak_wood_door_frame_with_flush_shutters",
"label": "Teak wood door frame with flush shutters"
},
"windows": {
"value": "Powder_coated_Aluminum_sliding_windows",
"label": "Powder coated Aluminum sliding windows"
},
"fixtures": {
"value":
"Concealed_plumbing_with_C.P._fixtures._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fixtures. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mira_Bhayander_Municipal_Corporation",
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
}
},
```

```
"asPerActualAgreement": {
  "north": "Open Land",
  "west": "New Parmanand Building",
  "south": "Road",
  "east": "Road"
},
"asPerDocumentAgreement": {
  "north": "Open Plot",
  "west": "New Parmanand Building",
  "south": "Shambhu Sadan",
  "east": "Jain Apartment"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "",
    "west": "Information not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
}
```

```
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved Building Plan were not provided and not
verified.",
"approvePlanVerified": "No",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"apfDetails": {
"buildings": [],
"compositions": []
},
"igrFinalRate": {
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per MBMC norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
"marketabilityList": {
```

```
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "335.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67128958477b35348d3fcb62/
routeMap_1729495745972_Image.png",
    "routeLat": "19.304474",
    "routeLng": "72.851725",
    "stationName": "Bhayandar",
    "routeDistance": "1.1 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "8t1uqh",
    "name": "8t1uqh",
    "image": "cases/67128958477b35348d3fcb62/
routeMap_1729496228463_Image.png"
  }
]
```

```
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "335.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6715fff59f41bc3db4e44d15",
      "name": "externallmg_1729495029236_externallmg_1729488753070_WhatsApp_I
mage_20241021_at_105857.jpeg",
      "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029236_externa
llmg_1729488753070_WhatsApp_Image_20241021_at_105857.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "671600169f41bc3db4e44d8c",
      "name": "externallmg_1729495061692_externallmg_1729488769753_WhatsApp_I
mage_20241021_at_105850_2.jpeg",
      "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061692_externa
llmg_1729488769753_WhatsApp_Image_20241021_at_105850_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6715fff59f41bc3db4e44d14",
      "name": "externallmg_1729495029232_externallmg_1729488753068_WhatsApp_I
mage_20241021_at_105857_1.jpeg",
      "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029232_externa
llmg_1729488753068_WhatsApp_Image_20241021_at_105857_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6715fff59f41bc3db4e44d13",
      "name": "externallmg_1729495029231_externallmg_1729488753035_WhatsApp_I
mage_20241021_at_105856.jpeg",
      "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029231_externa
llmg_1729488753035_WhatsApp_Image_20241021_at_105856.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6715fff59f41bc3db4e44d17",
    "name": "Living Room",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029294_externa
llmg_1729488753138_WhatsApp_Image_20241021_at_105836.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67160000e73f0c3db52c0720",
    "name": "Living Room",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495040085_externa
llmg_1729488769684_WhatsApp_Image_20241021_at_105847.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671600169f41bc3db4e44d8a",
    "name": "Living Room",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061691_externa
llmg_1729488769735_WhatsApp_Image_20241021_at_105848.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "671600169f41bc3db4e44d8b",
    "name": "Living Room",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061692_externa
llmg_1729488769741_WhatsApp_Image_20241021_at_105850_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```

```
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "335.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67128958477b35348d3fcb62",
"ownerName": "Mr. Paresh Kantilal Madhani",
"ownerPhoneNo": "9821899420",
"appAddress": "Flat no B/405 fourth floor Parmanad Nagar Bldg D Co-op HSG Soc
Ltd Devchand Nagar Road Bhayander West Thane 401101",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  }
]
```

```
},
"inputs": {
  "documentDate": "12/10/2023",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mr. Rakeshkumar Surajmal Ladhani",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mr. Paresh Kantilal Madhani & Mrs. Jimi Paresh Madhani",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "18220/2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "455209",
"path": "cases/67128958477b35348d3fcb62/
document_1729267453679_1729267452021_agreement.pdf",
"fileName": "document_1729267453679_1729267452021_agreement.pdf"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67128958477b35348d3fcb62/
document_1729267566134_1729267564345_Document.pdf",
  "fileName": "document_1729267566134_1729267564345_Document.pdf",
  "id": "411044",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Fri Oct 18 2024 21:44:16 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Society NOC Certificate",
    "value": "60ae127aaa6d152c1801b3db"
  },
  "isHardCopy": false,

```

```

      "displayStatus": false,
      "path": "cases/67128958477b35348d3fcb62/
document_1729267844963_1729267843216_noc.pdf",
      "fileName": "document_1729267844963_1729267843216_noc.pdf",
      "id": "121275",
      "uploadedBy": "60af6ae22ffdf65bcd65861d",
      "createdAt": "Fri Oct 18 2024 21:44:16 GMT+0530 (India Standard Time)"
    },
    {
      "documentType": {
        "label": "Commencement Certificate",
        "value": "60ae1247aa6d152c1801b2ea"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "path": "cases/67128958477b35348d3fcb62/
document_1729267865844_1729267864464_C_C_paper_Parmanand.pdf",
      "fileName":
"document_1729267865844_1729267864464_C_C_paper_Parmanand.pdf",
      "id": "339840",
      "uploadedBy": "60af6ae22ffdf65bcd65861d",
      "createdAt": "Fri Oct 18 2024 21:44:16 GMT+0530 (India Standard Time)"
    },
    {
      "documentType": {
        "label": "Share Certificate ",
        "value": "60ae1264aa6d152c1801b371"
      },
      "inputs": {
        "remark": "bearing Nos. 276 to 280 having 5 Shares of Rs. 50/- each transferred
dated 23.10.2023 in the name of Paresh Kantilal & Jimi Paresh Madhani issued by
Parmanand Nagar Bldg. 'D' Co-op. Hsg. Soc. Ltd.",
        "number": {
          "value": "No",
          "label": "No"
        },
        "No": "056"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "id": "699758",
      "path": "cases/67128958477b35348d3fcb62/
document_1729268026015_1729268024518_sher_certificate.pdf",
      "fileName": "document_1729268026015_1729268024518_sher_certificate.pdf"
    }
  ],

```



```
"caseNumber": "011903",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "601555",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 18 2024 21:44:16 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Paresh Kantilal Madhani",
    "phone": "9821899420",
    "ownershipShare": "",
    "email": "",
    "id": "459887"
  },
  {
    "name": "Mrs. Jimi Paresh Madhani",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "873733"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Living Room",
    "length": "13.25",
    "length1": "13",
    "length2": "3",
    "width": "8.58",
    "width1": "8",
    "width2": "7",
    "totalArea": "113.73",
    "images": [],
    "finalArea": "113.73",
    "extraAreas": []
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "40.49",
  "images": [],
  "extraAreas": [],
  "finalArea": "40.49"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "12.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.85"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "8.17",
  "length1": "8",
```

```
"length2": "2",
"width": "6.42",
"width1": "6",
"width2": "5",
"totalArea": "52.40",
"images": [],
"extraAreas": [],
"finalArea": "52.40"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "7.50",
  "length1": "7",
  "length2": "6",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "21.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "WC",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "13.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.46"
}
],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "915221",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "335",
    "squareMeterArea": "31.12",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6715e771056a390f7e6886c3",
    "name":
"externallmg_1729488753092_WhatsApp_Image_20241021_at_105742_1.jpeg",
    "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488753092_WhatsApp_Image_20241021_at_105742_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6715e771056a390f7e6886c4",
    "name":
"externallmg_1729488753093_WhatsApp_Image_20241021_at_105742_2.jpeg",
    "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488753093_WhatsApp_Image_20241021_at_105742_2.jpeg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715e771056a390f7e6886c5",
  "name":
"externallmg_1729488753106_WhatsApp_Image_20241021_at_105742.jpeg",
  "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488753106_WhatsApp_Image_20241021_at_105742.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715e781056a390f7e688730",
  "name":
"externallmg_1729488769756_WhatsApp_Image_20241021_at_105851_1.jpeg",
  "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769756_WhatsApp_Image_20241021_at_105851_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715e781056a390f7e688731",
  "name":
"externallmg_1729488769781_WhatsApp_Image_20241021_at_105851_2.jpeg",
  "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769781_WhatsApp_Image_20241021_at_105851_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715e781056a390f7e688732",
  "name":
"externallmg_1729488769781_WhatsApp_Image_20241021_at_105851.jpeg",
  "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769781_WhatsApp_Image_20241021_at_105851.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715e781056a390f7e688733",
  "name":
"externallmg_1729488769801_WhatsApp_Image_20241021_at_105852_1.jpeg",
```

```
    "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769801_WhatsApp_Image_20241021_at_105852_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6715e781056a390f7e688734",
    "name":
"externallmg_1729488769801_WhatsApp_Image_20241021_at_105852.jpeg",
    "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769801_WhatsApp_Image_20241021_at_105852.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6715e781056a390f7e688735",
    "name":
"externallmg_1729488769806_WhatsApp_Image_20241021_at_105853.jpeg",
    "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769806_WhatsApp_Image_20241021_at_105853.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6715e781056a390f7e688736",
    "name":
"externallmg_1729488769807_WhatsApp_Image_20241021_at_105854_1.jpeg",
    "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769807_WhatsApp_Image_20241021_at_105854_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6715e781056a390f7e688737",
    "name":
"externallmg_1729488769807_WhatsApp_Image_20241021_at_105854_2.jpeg",
    "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769807_WhatsApp_Image_20241021_at_105854_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6715e781056a390f7e688738",
  "name":
"externallmg_1729488769808_WhatsApp_Image_20241021_at_105854.jpeg",
  "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769808_WhatsApp_Image_20241021_at_105854.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715e781056a390f7e68873b",
  "name":
"externallmg_1729488769809_WhatsApp_Image_20241021_at_105855.jpeg",
  "path": "cases/67128958477b35348d3fcb62/
externallmg_1729488769809_WhatsApp_Image_20241021_at_105855.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715fff59f41bc3db4e44d11",
  "name": "externallmg_1729495029228_externallmg_1729488753031_WhatsApp_I
mage_20241021_at_105856_1.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029228_externall
mg_1729488753031_WhatsApp_Image_20241021_at_105856_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715fff59f41bc3db4e44d12",
  "name": "externallmg_1729495029229_externallmg_1729488753033_WhatsApp_I
mage_20241021_at_105856_2.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029229_externall
mg_1729488753033_WhatsApp_Image_20241021_at_105856_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715fff59f41bc3db4e44d13",
  "name": "externallmg_1729495029231_externallmg_1729488753035_WhatsApp_I
mage_20241021_at_105856.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029231_externall
mg_1729488753035_WhatsApp_Image_20241021_at_105856.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715fff59f41bc3db4e44d14",
  "name": "externallmg_1729495029232_externallmg_1729488753068_WhatsApp_I
mage_20241021_at_105857_1.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029232_externall
mg_1729488753068_WhatsApp_Image_20241021_at_105857_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715fff59f41bc3db4e44d15",
  "name": "externallmg_1729495029236_externallmg_1729488753070_WhatsApp_I
mage_20241021_at_105857.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029236_externall
mg_1729488753070_WhatsApp_Image_20241021_at_105857.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715fff59f41bc3db4e44d16",
  "name": "externallmg_1729495029291_externallmg_1729488753070_WhatsApp_I
mage_20241021_at_105857_2.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029291_externall
mg_1729488753070_WhatsApp_Image_20241021_at_105857_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6715fff59f41bc3db4e44d17",
  "name": "externallmg_1729495029294_externallmg_1729488753138_WhatsApp_I
mage_20241021_at_105836.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495029294_externall
mg_1729488753138_WhatsApp_Image_20241021_at_105836.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67160000e73f0c3db52c071b",
```



```
    "name": "externalimg_1729495040080_externalimg_1729488753139_WhatsApp_I
mage_20241021_at_105840.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externalimg_1729495040080_external
mg_1729488753139_WhatsApp_Image_20241021_at_105840.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67160000e73f0c3db52c071c",
    "name": "externalimg_1729495040081_externalimg_1729488753140_WhatsApp_I
mage_20241021_at_105841.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externalimg_1729495040081_external
mg_1729488753140_WhatsApp_Image_20241021_at_105841.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67160000e73f0c3db52c071d",
    "name": "externalimg_1729495040082_externalimg_1729488753167_WhatsApp_I
mage_20241021_at_105843_1.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externalimg_1729495040082_external
mg_1729488753167_WhatsApp_Image_20241021_at_105843_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67160000e73f0c3db52c071e",
    "name": "externalimg_1729495040083_externalimg_1729488753168_WhatsApp_I
mage_20241021_at_105843.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externalimg_1729495040083_external
mg_1729488753168_WhatsApp_Image_20241021_at_105843.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67160000e73f0c3db52c071f",
    "name": "externalimg_1729495040084_externalimg_1729488753175_WhatsApp_I
mage_20241021_at_105847_1.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externalimg_1729495040084_external
mg_1729488753175_WhatsApp_Image_20241021_at_105847_1.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67160000e73f0c3db52c0720",
  "name": "externallmg_1729495040085_externallmg_1729488769684_WhatsApp_I
mage_20241021_at_105847.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495040085_externall
mg_1729488769684_WhatsApp_Image_20241021_at_105847.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67160000e73f0c3db52c0721",
  "name": "externallmg_1729495040087_externallmg_1729488769705_WhatsApp_I
mage_20241021_at_105848_1.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495040087_externall
mg_1729488769705_WhatsApp_Image_20241021_at_105848_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671600169f41bc3db4e44d89",
  "name": "externallmg_1729495061691_externallmg_1729488769716_WhatsApp_I
mage_20241021_at_105848_2.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061691_externall
mg_1729488769716_WhatsApp_Image_20241021_at_105848_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671600169f41bc3db4e44d8a",
  "name": "externallmg_1729495061691_externallmg_1729488769735_WhatsApp_I
mage_20241021_at_105848.jpeg",
  "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061691_externall
mg_1729488769735_WhatsApp_Image_20241021_at_105848.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671600169f41bc3db4e44d8b",
  "name": "externallmg_1729495061692_externallmg_1729488769741_WhatsApp_I
mage_20241021_at_105850_1.jpeg",
```

```
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061692_externallmg_1729488769741_WhatsApp_Image_20241021_at_105850_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671600169f41bc3db4e44d8c",
    "name": "externallmg_1729495061692_externallmg_1729488769753_WhatsApp_Image_20241021_at_105850_2.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061692_externallmg_1729488769753_WhatsApp_Image_20241021_at_105850_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671600169f41bc3db4e44d8d",
    "name": "externallmg_1729495061694_externallmg_1729488769755_WhatsApp_Image_20241021_at_105850.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061694_externallmg_1729488769755_WhatsApp_Image_20241021_at_105850.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671600169f41bc3db4e44d8e",
    "name": "externallmg_1729495061695_externallmg_1729488769808_WhatsApp_Image_20241021_at_105855_1.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061695_externallmg_1729488769808_WhatsApp_Image_20241021_at_105855_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671600169f41bc3db4e44d8f",
    "name": "externallmg_1729495061696_externallmg_1729488769808_WhatsApp_Image_20241021_at_105855_2.jpeg",
    "path": "cases/67128958477b35348d3fcb62/externallmg_1729495061696_externallmg_1729488769808_WhatsApp_Image_20241021_at_105855_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-18T16:14:16.763Z",
"updatedAt": "2024-10-21T08:16:17.387Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B/405, 4th Floor, Wing - B, Parmanand Nagar Bldg.
'D' Co-op. Hsg. Soc. Ltd., Devchand Nagar Road, Near Bavan Jinalay, Village -
Bhayandar, Taluka - Thane, District - Thane, Bhayander (West), PIN - 401 101, State -
Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mrs. Jimi Paresh Madhani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"rerald": "",
"siteVisitContactNo": "9821899420",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
WC",
"carpetTotal": "254.18",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "305.02",
"finalCarpetArea": "254.18",
"finalSalableArea": "305.02",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
```

"finalValuationAreaString": "Built Up Area in Sq. Ft. = 335.00"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	13'3"	8'7"	113.73
Kitchen	8'10"	4'7"	40.49
Passage	4'2"	3'1"	12.85
Bedroom	8'2"	6'5"	52.40
Bathroom	7'6"	2'10"	21.25
WC	4'3"	3'2"	13.46
Other Composition :			