

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9d6"
    },
    "firstName": "Mahesh",
    "type": "CREDITOFFICER",
    "_id": "65fd18fe5ca1625e505b7a95",
    "lastName": "Raut",
    "mobileNo": "",
    "workMobileNo": "9869141488",
    "email": "1kandivali_west@jansewabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9000000",
    "discussWithPerson": "Mahesh",
    "expectedFees": 4500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank (Borivali) LTD",
  "displayName": "Janaseva Sahakari Bank (Borivali) LTD",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9d6",
  "branchCode": "000007",
  "type": "BRANCH",
  "name": "Kandivali (West) Branch",
  "email": "kandivali_west@jansevabank.in",
  "mobileNo": " 022 2861 1344",
  "alternateMobileNo": "",
  "address": "Laxmi Villa, Opposite Kala Hanuman Mandir, Mahatma Gandhi Road,
Kamala Nagar, Kandivali (West), Mumbai - 400067, State - Maharashtra, Country -
India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
```

```
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "ACCOUNTANT",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
}_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.20443953990578",
  "longitude": "72.83760936935296"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.83760936935296,
19.20443953990578
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-19",
      "remark": "OC NOT AVAILABLE"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Kandivali",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kanidvali (West), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Rajaram Residency Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mathuradas Extn. Cross Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Atul Tower",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1342",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "501",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 067",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
```

```
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Dattani Apartments",
  "west": "Abhiram Apartment",
  "south": "Internal Road and Open Land",
  "east": "Road"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Lift",
    "east": "Lobby / Flat No. 502",
    "south": "Lobby / Staircasse",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
}
```

```
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan were not provided and
not verified.",
"approvePlanVerified": "No",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "27",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "21325",
  "depreciatedBuildingRate": "1825"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "143500",
  "landRate": "67730",
  "igrImage": "cases/67134360c6eb1c39d9926480/igr_1729332879933_Image.png",
  "squareMeterGuideLineRate": "150675.00",
  "squareFeetGuideLineRate": "13998.00"
```

```
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "83",
  "rate": "12688.00",
  "squareFeetGuideLineRate": "12688.00",
  "squareMeterGuideLineRate": "136574.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
```

```
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Parking Space",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2006",
"fullDate": "1/1/2006"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
```

```
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
```



```
"label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_agreement",
  "label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "42",
"ageOfBuilding": "18",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "505.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67134360c6eb1c39d9926480/
routeMap_1729335071729_Image.png",
    "routeLat": "19.204270",
    "routeLng": "72.837605",
    "stationName": "Kandivali",
    "routeDistance": "1.9 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
```

```
"finallatlng": false
},
"locationMapImg": [
  {
    "id": "r970q",
    "name": "r970q",
    "image": "cases/67134360c6eb1c39d9926480/
routeMap_1729334960521_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8977825.00",
```

```
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8977825.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6371077.00",
  "selectedBuildUpValue": "505.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67138d00c6eb1c39d992d057",
      "name": "externallmg_1729334527839_externallmg_1729323252273_1729323197632_image_3.jpeg",
      "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527839_externallmg_1729323252273_1729323197632_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "67138d00c6eb1c39d992d05b",
      "name": "externallmg_1729334527845_externallmg_1729323275983_1729323197632_image_7.jpeg",
      "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527845_externallmg_1729323275983_1729323197632_image_7.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67138d00c6eb1c39d992d056",
      "name": "externallmg_1729334527837_externallmg_1729323241004_1729323197632_image_2.jpeg",
      "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527837_externallmg_1729323241004_1729323197632_image_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "67139d8b853e2039d8469a47",
      "name": "externallmg_1729338763289_1.jpg",
      "path": "cases/67134360c6eb1c39d9926480/externallmg_1729338763289_1.jpg",
      "orientation": "portrait"
    }
  ],
  "compositionImages": [
    {
```

```
    "status": false,
    "_id": "67138d00c6eb1c39d992d054",
    "name": "Living Room",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527836_extern
allmg_1729323215124_1729323207613_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67138d00c6eb1c39d992d05a",
    "name": "Living Room",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527844_extern
allmg_1729323272088_1729323197632_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67138d15c6eb1c39d992d089",
    "name": "Living Room",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548863_extern
allmg_1729323283799_1729323197632_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67138d15c6eb1c39d992d08b",
    "name": "Living Room",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548863_extern
allmg_1729323292148_1729323197632_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67138d15c6eb1c39d992d088",
    "name": "Living Room",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548862_extern
allmg_1729323276283_1729323197632_image_8.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "19011.00",
    "max": "22858.00"
  }
},
```

```
"builtUpRateRange": {
  "min": "15842.00",
  "max": "19048.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```

```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "421.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67134360c6eb1c39d9926480",
"ownerName": "Mrs. Nisha Chirag Sanghavi",
"ownerPhoneNo": "9930410002",
"appAddress": "FLAT NO 501 5TH FLOOR A WING RAJARAM RESIDENCY CHS
LTD MATHURADAS EXTENSION CROSS ROAD NEAR ATUL TOWER KANDIVALI
WEST MUMBAI 400067",
"remark": "OC NOT AVAILABLE",
```

```

"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "17/10/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Nilesh B. Thanki & Mrs. Meena N. Thanki",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mrs. Nisha Chirag Sanghavi & Mr. Chirag Dalsukh Sanghavi",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": " 22412/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "379088",
    "path": "cases/67134360c6eb1c39d9926480/
document_1729336969367_Sale_Deed.pdf",
    "fileName": "document_1729336969367_Sale_Deed.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "13/05/2005",
      "nameOfApprovingAuthority": {
        "value": "Municipal_Corporation_of_Greater_Mumbai",
        "label": "Municipal Corporation of Greater Mumbai"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
]

```

```
"No": " CHE/A-0483/BP(WS)/AP/AR"
},
"isHardCopy": false,
"displayStatus": false,
"id": "278330",
"path": "cases/67134360c6eb1c39d9926480/document_1729337175771_CC.pdf",
"fileName": "document_1729337175771_CC.pdf"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "remark": " bearing Nos. 76 to 80 having 5 Shares of Rs. 50/- each dated
29/08/2010 in the name of Shri. Nilesh B. Thanki & Mrs. Meena N. Thanki issued by
Rajaram Residency Co-op. Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "16"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "215985",
  "path": "cases/67134360c6eb1c39d9926480/
document_1729337336735_Share_Certificate.pdf",
  "fileName": "document_1729337336735_Share_Certificate.pdf"
}
],
"caseNumber": "011906",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "175939",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 19 2024 10:58:00 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Nisha Chirag Sanghavi",
    "phone": "9930410002",
    "ownershipShare": ""
  }
]
```

```
"email": "",
"id": "808367"
},
{
  "name": "Mr. Chirag Dalsukh Sanghavi",
  "phone": "",
  "email": "",
  "ownershipShare": "",
  "id": "557056"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Living Room",
    "length": "9.75",
    "length1": "9",
    "length2": "9",
    "width": "16.33",
    "width1": "16",
    "width2": "4",
    "totalArea": "159.25",
    "images": [],
    "finalArea": "159.25",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Toilet",
    "length": "4.33",
    "length1": "4",
    "length2": "4",
    "width": "3.17",
    "width1": "3",
    "width2": "2",
    "totalArea": "13.72",
```

```
"images": [],
"extraAreas": [],
"finalArea": "13.72"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "5.08",
  "length1": "5",
  "length2": "1",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "13.75",
  "width1": "13",
  "width2": "9",
  "totalArea": "136.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "136.35"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
```

```
"name": "Kitchen",
"length": "5.83",
"length1": "5",
"length2": "10",
"width": "10.33",
"width1": "10",
"width2": "4",
"totalArea": "60.28",
"images": [],
"extraAreas": [],
"finalArea": "60.28"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "30.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.75"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "261471",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "421",
```

```
"squareMeterArea": "39.11",
"docFinalBuiltUp": "505.2",
"docFinalBuiltUpSquareMeter": "46.932",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "689.17",
    "squareMeterArea": "64.03",
    "expectedRate": "19588.78",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "827.00",
    "squareMeterArea": "76.83",
    "expectedRate": "16324.06",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67138694c6eb1c39d992c3a3",
  "property": "Residential Flat",
  "area": "827",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "13500000",
  "expectedRate": "19588.78",
  "builtUpExpectedRate": "13500000",
  "image": "cases/67134360c6eb1c39d9926480/
indicator_1729332736783_Image.png",
  "squareMeter": "76.83",
```



```
"id": "743928"
},
{
  "carpetArea": {
    "area": "420.83",
    "squareMeterArea": "39.10",
    "expectedRate": "19010.05",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "505.00",
    "squareMeterArea": "46.92",
    "expectedRate": "15841.58",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "67138694c6eb1c39d992c3a4",
  "property": "Residential Flat",
  "area": "505",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "8000000",
  "expectedRate": "19010.05",
  "builtUpExpectedRate": "8000000",
  "image": "cases/67134360c6eb1c39d9926480/
indicator_1729332749666_Image.png",
  "squareMeter": "46.92",
  "id": "425496"
},
{
  "carpetArea": {
    "area": "487.50",
    "squareMeterArea": "45.29",
    "expectedRate": "22564.10",
    "percentage": ""
  },
  }
```

```
"builtUpArea": {
  "area": "585.00",
  "squareMeterArea": "54.35",
  "expectedRate": "18803.42",
  "percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "67138694c6eb1c39d992c3a5",
"property": "Residential Flat",
"area": "585",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "11000000",
"expectedRate": "22564.10",
"builtUpExpectedRate": "11000000",
"image": "cases/67134360c6eb1c39d9926480/
indicator_1729332763755_Image.png",
"squareMeter": "54.35",
"id": "252695"
},
{
  "carpetArea": {
    "area": "350.00",
    "squareMeterArea": "32.52",
    "expectedRate": "22857.14",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "420.00",
    "squareMeterArea": "39.02",
    "expectedRate": "19047.62",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
```

```
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67138694c6eb1c39d992c3a6",
  "property": "Residential Flat",
  "area": "350",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "8000000",
  "expectedRate": "22857.14",
  "builtUpExpectedRate": "19047.62",
  "image": "cases/67134360c6eb1c39d9926480/
indicator_1729332805842_Image.png",
  "squareMeter": "32.52",
  "id": "800541"
}
],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6713612cc6eb1c39d992992b",
    "name": "externalImg_1729323209164_1729323197632_image_0.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/
externalImg_1729323209164_1729323197632_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6713612cc6eb1c39d992992c",
    "name": "externalImg_1729323227308_1729323197632_image_1.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/
externalImg_1729323227308_1729323197632_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67138d00c6eb1c39d992d054",
    "name": "externalImg_1729334527836_externalImg_1729323215124_17293232076
```

```
13_image_0.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527836_externallmg_1729323215124_1729323207613_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d00c6eb1c39d992d055",
  "name": "externallmg_1729334527837_externallmg_1729323238428_1729323207613_image_1.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527837_externallmg_1729323238428_1729323207613_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d00c6eb1c39d992d056",
  "name": "externallmg_1729334527837_externallmg_1729323241004_1729323197632_image_2.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527837_externallmg_1729323241004_1729323197632_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d00c6eb1c39d992d057",
  "name": "externallmg_1729334527839_externallmg_1729323252273_1729323197632_image_3.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527839_externallmg_1729323252273_1729323197632_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d00c6eb1c39d992d058",
  "name": "externallmg_1729334527841_externallmg_1729323263478_1729323197632_image_4.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527841_externallmg_1729323263478_1729323197632_image_4.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67138d00c6eb1c39d992d059",
    "name": "externallmg_1729334527842_externallmg_1729323268368_17293231976
32_image_5.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527842_externall
mg_1729323268368_1729323197632_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67138d00c6eb1c39d992d05a",
    "name": "externallmg_1729334527844_externallmg_1729323272088_17293231976
32_image_6.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527844_externall
mg_1729323272088_1729323197632_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67138d00c6eb1c39d992d05b",
    "name": "externallmg_1729334527845_externallmg_1729323275983_17293231976
32_image_7.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334527845_externall
mg_1729323275983_1729323197632_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67138d15c6eb1c39d992d088",
    "name": "externallmg_1729334548862_externallmg_1729323276283_17293231976
32_image_8.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548862_externall
mg_1729323276283_1729323197632_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67138d15c6eb1c39d992d089",
    "name": "externallmg_1729334548863_externallmg_1729323283799_17293231976
32_image_9.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548863_externall
```

```
mg_1729323283799_1729323197632_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d15c6eb1c39d992d08a",
  "name": "externallmg_1729334548864_externallmg_1729323288424_17293231976
32_image_10.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548864_externall
mg_1729323288424_1729323197632_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d15c6eb1c39d992d08b",
  "name": "externallmg_1729334548910_externallmg_1729323292148_17293231976
32_image_11.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548910_externall
mg_1729323292148_1729323197632_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d15c6eb1c39d992d08c",
  "name": "externallmg_1729334548914_externallmg_1729323295438_17293231976
32_image_12.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548914_externall
mg_1729323295438_1729323197632_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67138d15c6eb1c39d992d08d",
  "name": "externallmg_1729334548917_externallmg_1729323297613_17293231976
32_image_13.jpeg",
  "path": "cases/67134360c6eb1c39d9926480/externallmg_1729334548917_externall
mg_1729323297613_1729323197632_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67138d15c6eb1c39d992d08e",
    "name": "externalimg_1729334548919_externalimg_1729323303398_17293231976
32_image_14.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/externalimg_1729334548919_external
mg_1729323303398_1729323197632_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67139d8b853e2039d8469a47",
    "name": "externalimg_1729338763289_1.jpg",
    "path": "cases/67134360c6eb1c39d9926480/externalimg_1729338763289_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1729332906905_AGR.pdf",
    "path": "cases/67134360c6eb1c39d9926480/
processingDocuments/1729332906905_AGR.pdf",
    "size": "8628468",
    "createdAt": "Sat Oct 19 2024 15:45:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externalimg_1729323209164_1729323197632_image_0.jpeg",
    "filename":
"1729332907003_externalimg_1729323209164_1729323197632_image_0.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/processingDocuments/1729332907003
_externalimg_1729323209164_1729323197632_image_0.jpeg",
    "size": "1424345",
    "createdAt": "Sat Oct 19 2024 15:45:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externalimg_1729323227308_1729323197632_image_1.jpeg",
    "filename":
"1729332907022_externalimg_1729323227308_1729323197632_image_1.jpeg",
    "path": "cases/67134360c6eb1c39d9926480/processingDocuments/1729332907022
_externalimg_1729323227308_1729323197632_image_1.jpeg",
    "size": "2831725",
    "createdAt": "Sat Oct 19 2024 15:45:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
]
```

```
    },
    {
      "originalname": "IGR-01.pdf",
      "filename": "1729332907054_IGR01.pdf",
      "path": "cases/67134360c6eb1c39d9926480/
processingDocuments/1729332907054_IGR01.pdf",
      "size": "154761",
      "createdAt": "Sat Oct 19 2024 15:45:07 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-02.pdf",
      "filename": "1729332907056_IGR02.pdf",
      "path": "cases/67134360c6eb1c39d9926480/
processingDocuments/1729332907056_IGR02.pdf",
      "size": "154758",
      "createdAt": "Sat Oct 19 2024 15:45:07 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "Summary New=NISHA.xlsx",
      "filename": "1729332907061_Summary_NewNISHA.xlsx",
      "path": "cases/67134360c6eb1c39d9926480/
processingDocuments/1729332907061_Summary_NewNISHA.xlsx",
      "size": "1529074",
      "createdAt": "Sat Oct 19 2024 15:45:07 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-10-19T05:28:00.862Z",
  "updatedAt": "2024-10-19T12:02:31.248Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 501, 5th Floor, Wing - A, Rajaram Residency Co-
op. Hsg. Soc. Ltd., Mathuradas Extn. Cross Road, Near Atul Tower, Village - Kandivali,
Taluka - Borivali, District - Mumbai Suburban, Kanidvali (West), Mumbai, PIN - 400 067,
State - Maharashtra, India",
  "updatedBy": "60eeaeddf3dd69653a581316",
  "addressForMap": "",
  "caseReferredBy": "659ccce98f39506e83489828",
```



```
"contactPersonName": "Mrs. Nisha Chirag Sanghavi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"rerald": "",
"siteVisitContactNo": "9930410002",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 421.00",
"flatRate": "22000",
"landOtherRate": "19500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"carpetTotal": "420.67999999999995",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "504.82",
"finalCarpetArea": "420.68",
"finalSalableArea": "504.82",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
```

```

    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	9'9"	16'4"	159.25
Toilet	4'4"	3'2"	13.72
Toilet	5'1"	4'00"	20.33
Bedroom	9'11"	13'9"	136.35
Kitchen	5'10"	10'4"	60.28
Passage	6'10"	4'6"	30.75
Other Composition :			