

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "645f05abee6a9735bf768588"
    },
    "firstName": "Inderjeet",
    "type": "CREDITOFFICER",
    "_id": "66d1bc81da840b1214d0c0ce",
    "email": "Ubin0901067@unionbankofindia.bank",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "6397619247"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Inderjeet",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "645f05abee6a9735bf768588",
  "name": "Wadala Branch",
  "branchCode": "",
  "mobileNo": "02224103887",
  "alternateMobileNo": "",
  "email": "ubin0901067@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "India Priting House, 42 G D Ambedkar Marg, Wadala, Mumbai -400031\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "665ac13f42f4717ae30de3d5",
```

```
"role": "PICKUPPERSON",
"firstName": "NIDHI",
"email": "nidhi.kajwe97@gmail.com",
"lastName": "KAJWE",
"mobileNo": "8850520881",
"shortName": "NIDHI",
"workWithDocumentMaker": ""
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62550ed0aba01e0af98f2f75",
"role": "SITEENGINEER",
"firstName": "Chandan",
"email": "ck06806@gmail.com",
"lastName": "Singh",
"mobileNo": "8454863607",
"designation": "",
"shortName": "CH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
}
],
}
```

```
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.749545551136386",
  "longitude": "73.41818566869614"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  73.41818566869614,
  18.749545551136386
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "19/10/2024 12:00 am"
    },
    {
      "dateTime": "19/10/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nangargaon",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Lawns Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "4",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```



```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67139d7fc6eb1c39d992ebf0",
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"ownerName": "Dipendra Gajanan Bhivade & Shruti Dipendra Bhivade ",
"ownerPhoneNo": "8806072224",
"appAddress": "Flat No 4 First floor Wing-D Shree Lawns Apartments Village
Nangargaon Taluka Maval District Pune ",
"remark": "It is an urgent case...banker wants the soft copy of the report by Monday
evening or Tuesday morning ",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67139d7fc6eb1c39d992ebf0/document_1729338420468_172933841
6365_Dipendra_Gajanan_Bhivade__Shruti_Dipendra_Bhivade.pdf",
    "fileName": "document_1729338420468_1729338416365_Dipendra_Gajanan_Bhiv
```

```
ade__Shruti_Dipendra_Bhivade.pdf",
  "id": "437173",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Sat Oct 19 2024 17:22:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67139d7fc6eb1c39d992ebf0/document_1729338600714_66372.pdf",
  "fileName": "document_1729338600714_66372.pdf",
  "id": "463783",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Sat Oct 19 2024 17:22:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67139d7fc6eb1c39d992ebf0/document_1729338616081_84507.pdf",
  "fileName": "document_1729338616081_84507.pdf",
  "id": "413349",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Sat Oct 19 2024 17:22:31 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011927",
"createdBy": "665ac13f42f4717ae30de3d5",
"caseHistory": [
  {
    "id": "658647",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 19 2024 17:22:31 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Dipendra Gajanan Bhivade & Shruti Dipendra Bhivade ",
    "phone": "8806072224",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "473976"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec143f",
    "name":
"externalImg_1729572239970_WhatsApp_Image_20241022_at_093530_1.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externalImg_1729572239970_WhatsApp_Image_20241022_at_093530_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1440",
    "name":
"externalImg_1729572240093_WhatsApp_Image_20241022_at_093530_2.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externalImg_1729572240093_WhatsApp_Image_20241022_at_093530_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1441",
    "name":
"externalImg_1729572240150_WhatsApp_Image_20241022_at_093531_1.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externalImg_1729572240150_WhatsApp_Image_20241022_at_093531_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67172d919415217725ec1442",
    "name":
"externallmg_1729572240213_WhatsApp_Image_20241022_at_093531_2.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240213_WhatsApp_Image_20241022_at_093531_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1443",
    "name":
"externallmg_1729572240243_WhatsApp_Image_20241022_at_093531.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240243_WhatsApp_Image_20241022_at_093531.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1444",
    "name":
"externallmg_1729572240316_WhatsApp_Image_20241022_at_093532_1.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240316_WhatsApp_Image_20241022_at_093532_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1445",
    "name":
"externallmg_1729572240355_WhatsApp_Image_20241022_at_093532_2.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240355_WhatsApp_Image_20241022_at_093532_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1446",
    "name":
"externallmg_1729572240426_WhatsApp_Image_20241022_at_093532.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240426_WhatsApp_Image_20241022_at_093532.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1447",
    "name":
"externallmg_1729572240460_WhatsApp_Image_20241022_at_093533_1.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240460_WhatsApp_Image_20241022_at_093533_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1448",
    "name":
"externallmg_1729572240490_WhatsApp_Image_20241022_at_093533.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240490_WhatsApp_Image_20241022_at_093533.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec1449",
    "name":
"externallmg_1729572240542_WhatsApp_Image_20241022_at_093534.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240542_WhatsApp_Image_20241022_at_093534.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec144a",
    "name":
"externallmg_1729572240573_WhatsApp_Image_20241022_at_093535_1.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240573_WhatsApp_Image_20241022_at_093535_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172d919415217725ec144b",
```

```
    "name":
"externallmg_1729572240629_WhatsApp_Image_20241022_at_093535_2.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240629_WhatsApp_Image_20241022_at_093535_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172d919415217725ec144c",
  "name":
"externallmg_1729572240663_WhatsApp_Image_20241022_at_093535.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240663_WhatsApp_Image_20241022_at_093535.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172d919415217725ec144d",
  "name":
"externallmg_1729572240701_WhatsApp_Image_20241022_at_093536_1.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240701_WhatsApp_Image_20241022_at_093536_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172d919415217725ec144e",
  "name":
"externallmg_1729572240733_WhatsApp_Image_20241022_at_093536_2.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240733_WhatsApp_Image_20241022_at_093536_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172d919415217725ec144f",
  "name":
"externallmg_1729572240797_WhatsApp_Image_20241022_at_093536.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240797_WhatsApp_Image_20241022_at_093536.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172d919415217725ec1450",
  "name":
"externallmg_1729572240829_WhatsApp_Image_20241022_at_093537.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240829_WhatsApp_Image_20241022_at_093537.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172d919415217725ec1451",
  "name":
"externallmg_1729572240867_WhatsApp_Image_20241022_at_094757.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240867_WhatsApp_Image_20241022_at_094757.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172d919415217725ec1452",
  "name":
"externallmg_1729572240910_WhatsApp_Image_20241022_at_094758.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572240910_WhatsApp_Image_20241022_at_094758.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a103",
  "name":
"externallmg_1729572312609_WhatsApp_Image_20241022_at_094758.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312609_WhatsApp_Image_20241022_at_094758.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a104",
  "name":
"externallmg_1729572312658_WhatsApp_Image_20241022_at_093510.jpeg",
```

```
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312658_WhatsApp_Image_20241022_at_093510.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a105",
    "name":
"externallmg_1729572312703_WhatsApp_Image_20241022_at_093512.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312703_WhatsApp_Image_20241022_at_093512.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a106",
    "name":
"externallmg_1729572312747_WhatsApp_Image_20241022_at_093513.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312747_WhatsApp_Image_20241022_at_093513.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a107",
    "name":
"externallmg_1729572312784_WhatsApp_Image_20241022_at_093517.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312784_WhatsApp_Image_20241022_at_093517.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a108",
    "name":
"externallmg_1729572312820_WhatsApp_Image_20241022_at_093518_1.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312820_WhatsApp_Image_20241022_at_093518_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "67172dd9fd024a772487a109",
  "name":
"externallmg_1729572312854_WhatsApp_Image_20241022_at_093518.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312854_WhatsApp_Image_20241022_at_093518.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a10a",
  "name":
"externallmg_1729572312877_WhatsApp_Image_20241022_at_093519_1.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312877_WhatsApp_Image_20241022_at_093519_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a10b",
  "name":
"externallmg_1729572312915_WhatsApp_Image_20241022_at_093519.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312915_WhatsApp_Image_20241022_at_093519.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a10c",
  "name":
"externallmg_1729572312942_WhatsApp_Image_20241022_at_093520.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312942_WhatsApp_Image_20241022_at_093520.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a10d",
  "name":
"externallmg_1729572312968_WhatsApp_Image_20241022_at_093521_1.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572312968_WhatsApp_Image_20241022_at_093521_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a10e",
    "name":
"externallmg_1729572313001_WhatsApp_Image_20241022_at_093521.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313001_WhatsApp_Image_20241022_at_093521.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a10f",
    "name":
"externallmg_1729572313054_WhatsApp_Image_20241022_at_093522.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313054_WhatsApp_Image_20241022_at_093522.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a110",
    "name":
"externallmg_1729572313085_WhatsApp_Image_20241022_at_093524_1.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313085_WhatsApp_Image_20241022_at_093524_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a111",
    "name":
"externallmg_1729572313143_WhatsApp_Image_20241022_at_093524_2.jpeg",
    "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313143_WhatsApp_Image_20241022_at_093524_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67172dd9fd024a772487a112",
```

```
    "name":
"externallmg_1729572313185_WhatsApp_Image_20241022_at_093524.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313185_WhatsApp_Image_20241022_at_093524.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a113",
  "name":
"externallmg_1729572313212_WhatsApp_Image_20241022_at_093525.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313212_WhatsApp_Image_20241022_at_093525.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a114",
  "name":
"externallmg_1729572313242_WhatsApp_Image_20241022_at_093526_1.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313242_WhatsApp_Image_20241022_at_093526_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a115",
  "name":
"externallmg_1729572313271_WhatsApp_Image_20241022_at_093526.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313271_WhatsApp_Image_20241022_at_093526.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67172dd9fd024a772487a116",
  "name":
"externallmg_1729572313299_WhatsApp_Image_20241022_at_093530.jpeg",
  "path": "cases/67139d7fc6eb1c39d992ebf0/
externallmg_1729572313299_WhatsApp_Image_20241022_at_093530.jpeg",
  "orientation": "portrait"
}
}
```

```

],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-19T11:52:31.196Z",
"updatedAt": "2024-10-22T04:45:13.861Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 4, Ground Floor, Wing - D, Shree Lawns
Apartment, Village - Nangargaon, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "665ac13f42f4717ae30de3d5",
"contactPersonName": "Dipendra Gajanan Bhivade & Shruti Dipendra Bhivade ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "8806072224"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			