

```
{
  "typeOfReport": {
    "value": "Plant Machinery",
    "label": "Plant & Machinery"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair Market Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646869f246e69b7878e9c07a"
    },
    "firstName": "Mr. Satish",
    "type": "CREDITOFFICER",
    "_id": "646869f246e69b7878e9c07c",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "9769699931",
    "email": "satish.sambare@siemens.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "646867a446e69b7878e9b892",
  "type": "INSTITUTION",
  "name": "Siemens Financial Services Private Limited",
  "displayName": "",
  "initial": "SFS"
},
"branch": {
  "_id": "646869f246e69b7878e9c07a",
  "name": "SFS COF E RU-IN RM AM",
  "branchCode": "",
  "mobileNo": "9769699930",
  "alternateMobileNo": "",
  "email": "satish.sambare@siemens.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Thane Belapur Road\n400708 Thane, India"
},
"assetsClass": {
  "value": "Land Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "6468691f46e69b7878e9be2e",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
    "role": "FRONTDESK",
```

```
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720e52afd7d55eddedc887",
  "role": "PICKUPPERSON",
  "firstName": "Harshad",
  "email": "harshad@vastukala.org",
  "lastName": "Panchal",
  "mobileNo": "9029575553",
  "designation": "",
  "shortName": "HP",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
```

```
"role": "MAKER+CHECKER",
"firstName": "Avinash",
"email": "avinash.pandey@vastukala.org",
"lastName": "Pandey",
"mobileNo": "9021605621",
"designation": "",
"shortName": "AV",
"workWithDocumentMaker": ""
},
"valuers": []
},
"clientType": {
"value": "INSTITUTION",
"label": "INSTITUTION"
},
"location": {
"latitude": "14.448108527056831",
"longitude": "78.8690317564075"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true

```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kadapa",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "58 & 59",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shirdi Sai Electricals Limited",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Industrial Development Park",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```



```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 516 004",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6718951203856193623095f9",
"ownerName": "Shirdi Sai Electricals Limited",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Plant & Machinery No. Ground Floor, Shirdi Sai Electricals
Limited, Industrial Development Park, Plot No. 58 & 59, Village - Kadapa, PIN Code -
```



```
516 004, State - Andhra Pradesh",
  "remark": "",
  "documents": [],
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "caseNumber": "012002",
  "createdBy": "656aa949cebbe1714411d21b",
  "caseHistory": [
    {
      "id": "986391",
      "title": "Create Lead",
      "description": "Create Lead",
      "datetime": "Wed Oct 23 2024 06:17:54 GMT+0000 (Coordinated Universal Time)"
    }
  ],
  "owners": [
    {
      "name": "Shirdi Sai Electricals Limited",
      "phone": "0000000000",
      "ownershipShare": "",
      "email": "",
      "id": "884015"
    }
  ],
  "proposePurchasers": [],
  "siteInspection": [],
  "composition": [],
  "otherComposition": [],
  "externalReport": [],
  "documentPerArea": [],
  "images": [],
  "indicatorArr": [],
  "externalImages": [
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6718c29dfd14bf9350aa4b66",
      "name":
"externalImg_1729675932181_WhatsApp_Image_20241020_at_95433_AM.jpeg",
      "path": "cases/6718951203856193623095f9/
externalImg_1729675932181_WhatsApp_Image_20241020_at_95433_AM.jpeg",
      "orientation": "portrait"
    }
  ],
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c29dfd14bf9350aa4b67",
    "name":
"externallmg_1729675932221_WhatsApp_Image_20241020_at_95434_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675932221_WhatsApp_Image_20241020_at_95434_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c29dfd14bf9350aa4b68",
    "name":
"externallmg_1729675932593_WhatsApp_Image_20241020_at_95435_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675932593_WhatsApp_Image_20241020_at_95435_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c29dfd14bf9350aa4b69",
    "name":
"externallmg_1729675932891_WhatsApp_Image_20241020_at_95436_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675932891_WhatsApp_Image_20241020_at_95436_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c29dfd14bf9350aa4b6a",
    "name":
"externallmg_1729675933246_WhatsApp_Image_20241020_at_95437_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675933246_WhatsApp_Image_20241020_at_95437_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c29dfd14bf9350aa4b6b",
    "name":
"externallmg_1729675933489_WhatsApp_Image_20241020_at_95439_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675933489_WhatsApp_Image_20241020_at_95439_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c29dfd14bf9350aa4b6c",
    "name":
"externallmg_1729675933584_WhatsApp_Image_20241020_at_95441_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675933584_WhatsApp_Image_20241020_at_95441_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c29dfd14bf9350aa4b6d",
    "name":
"externallmg_1729675933657_WhatsApp_Image_20241020_at_95442_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675933657_WhatsApp_Image_20241020_at_95442_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2b5772666934f236c26",
    "name":
"externallmg_1729675955986_WhatsApp_Image_20241020_at_95445_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675955986_WhatsApp_Image_20241020_at_95445_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2b5772666934f236c27",
    "name":
"externallmg_1729675956112_WhatsApp_Image_20241020_at_95448_AM_1.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675956112_WhatsApp_Image_20241020_at_95448_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2b5772666934f236c28",
```

```
    "name":  
    "externallmg_1729675956137_WhatsApp_Image_20241020_at_95449_AM.jpeg",  
    "path": "cases/6718951203856193623095f9/  
externallmg_1729675956137_WhatsApp_Image_20241020_at_95449_AM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6718c2b5772666934f236c29",  
    "name":  
    "externallmg_1729675956260_WhatsApp_Image_20241020_at_95451_AM_1.jpeg",  
    "path": "cases/6718951203856193623095f9/  
externallmg_1729675956260_WhatsApp_Image_20241020_at_95451_AM_1.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6718c2b5772666934f236c2a",  
    "name":  
    "externallmg_1729675956444_WhatsApp_Image_20241020_at_95452_AM.jpeg",  
    "path": "cases/6718951203856193623095f9/  
externallmg_1729675956444_WhatsApp_Image_20241020_at_95452_AM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6718c2b5772666934f236c2b",  
    "name":  
    "externallmg_1729675956553_WhatsApp_Image_20241020_at_95525_AM_1.jpeg",  
    "path": "cases/6718951203856193623095f9/  
externallmg_1729675956553_WhatsApp_Image_20241020_at_95525_AM_1.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6718c2b5772666934f236c2c",  
    "name":  
    "externallmg_1729675956644_WhatsApp_Image_20241020_at_102102_AM.jpeg",  
    "path": "cases/6718951203856193623095f9/  
externallmg_1729675956644_WhatsApp_Image_20241020_at_102102_AM.jpeg",  
    "orientation": "portrait"  
  },  
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2b5772666934f236c2d",
  "name":
"externallmg_1729675956799_WhatsApp_Image_20241020_at_102105_AM_1.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675956799_WhatsApp_Image_20241020_at_102105_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2b5772666934f236c2e",
  "name":
"externallmg_1729675957050_WhatsApp_Image_20241020_at_102105_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675957050_WhatsApp_Image_20241020_at_102105_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2b5772666934f236c2f",
  "name":
"externallmg_1729675957199_WhatsApp_Image_20241020_at_102106_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675957199_WhatsApp_Image_20241020_at_102106_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2b5772666934f236c30",
  "name":
"externallmg_1729675957300_WhatsApp_Image_20241020_at_102108_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675957300_WhatsApp_Image_20241020_at_102108_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2b5772666934f236c31",
  "name":
"externallmg_1729675957407_WhatsApp_Image_20241020_at_102109_AM.jpeg",
```

```
    "path": "cases/6718951203856193623095f9/
externallmg_1729675957407_WhatsApp_Image_20241020_at_102109_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2d9fd14bf9350aa4be4",
    "name":
"externallmg_1729675992311_WhatsApp_Image_20241020_at_100037_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675992311_WhatsApp_Image_20241020_at_100037_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2d9fd14bf9350aa4be5",
    "name":
"externallmg_1729675992401_WhatsApp_Image_20241020_at_100038_AM_1.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675992401_WhatsApp_Image_20241020_at_100038_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2d9fd14bf9350aa4be6",
    "name":
"externallmg_1729675992521_WhatsApp_Image_20241020_at_100038_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675992521_WhatsApp_Image_20241020_at_100038_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2d9fd14bf9350aa4be7",
    "name":
"externallmg_1729675992763_WhatsApp_Image_20241020_at_100044_AM_1.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675992763_WhatsApp_Image_20241020_at_100044_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6718c2d9fd14bf9350aa4be8",
  "name":
"externallmg_1729675992844_WhatsApp_Image_20241020_at_100046_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675992844_WhatsApp_Image_20241020_at_100046_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2d9fd14bf9350aa4be9",
  "name":
"externallmg_1729675992925_WhatsApp_Image_20241020_at_100050_AM_1.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675992925_WhatsApp_Image_20241020_at_100050_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2d9fd14bf9350aa4bea",
  "name":
"externallmg_1729675992999_WhatsApp_Image_20241020_at_102409_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675992999_WhatsApp_Image_20241020_at_102409_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2d9fd14bf9350aa4beb",
  "name":
"externallmg_1729675993125_WhatsApp_Image_20241020_at_102411_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675993125_WhatsApp_Image_20241020_at_102411_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c2d9fd14bf9350aa4bec",
  "name":
"externallmg_1729675993197_WhatsApp_Image_20241020_at_102412_AM_1.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729675993197_WhatsApp_Image_20241020_at_102412_AM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2d9fd14bf9350aa4bed",
    "name":
    "externallmg_1729675993302_WhatsApp_Image_20241020_at_102413_AM_1.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729675993302_WhatsApp_Image_20241020_at_102413_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2ef038561936230ef69",
    "name":
    "externallmg_1729676014888_WhatsApp_Image_20241020_at_100431_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729676014888_WhatsApp_Image_20241020_at_100431_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2ef038561936230ef6a",
    "name":
    "externallmg_1729676015043_WhatsApp_Image_20241020_at_100434_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729676015043_WhatsApp_Image_20241020_at_100434_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2ef038561936230ef6b",
    "name":
    "externallmg_1729676015244_WhatsApp_Image_20241020_at_100437_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729676015244_WhatsApp_Image_20241020_at_100437_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c2ef038561936230ef6c",
```



```
    "name":
"externallmg_1729676015313_WhatsApp_Image_20241020_at_102713_AM_1.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676015313_WhatsApp_Image_20241020_at_102713_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c303fd14bf9350aa4c1f",
  "name":
"externallmg_1729676035551_WhatsApp_Image_20241020_at_105731_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676035551_WhatsApp_Image_20241020_at_105731_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c90",
  "name":
"externallmg_1729676061901_WhatsApp_Image_20241020_at_100853_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676061901_WhatsApp_Image_20241020_at_100853_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c91",
  "name":
"externallmg_1729676062013_WhatsApp_Image_20241020_at_100855_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676062013_WhatsApp_Image_20241020_at_100855_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c92",
  "name":
"externallmg_1729676062110_WhatsApp_Image_20241020_at_103027_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676062110_WhatsApp_Image_20241020_at_103027_AM.jpeg",
  "orientation": "landscape"
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c93",
  "name":
"externallmg_1729676062174_WhatsApp_Image_20241020_at_103029_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676062174_WhatsApp_Image_20241020_at_103029_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c94",
  "name":
"externallmg_1729676062245_WhatsApp_Image_20241020_at_103030_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676062245_WhatsApp_Image_20241020_at_103030_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c95",
  "name":
"externallmg_1729676062335_WhatsApp_Image_20241020_at_103032_AM_1.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676062335_WhatsApp_Image_20241020_at_103032_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c96",
  "name":
"externallmg_1729676062376_WhatsApp_Image_20241020_at_103032_AM.jpeg",
  "path": "cases/6718951203856193623095f9/
externallmg_1729676062376_WhatsApp_Image_20241020_at_103032_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718c31efd14bf9350aa4c97",
  "name":
"externallmg_1729676062441_WhatsApp_Image_20241020_at_103033_AM_2.jpeg",
```

```

    "path": "cases/6718951203856193623095f9/
externallmg_1729676062441_WhatsApp_Image_20241020_at_103033_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718c31efd14bf9350aa4c98",
    "name":
"externallmg_1729676062507_WhatsApp_Image_20241020_at_103034_AM.jpeg",
    "path": "cases/6718951203856193623095f9/
externallmg_1729676062507_WhatsApp_Image_20241020_at_103034_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-23T06:17:54.443Z",
"updatedAt": "2024-10-23T09:34:22.694Z",
"__v": 0,
"updatedBy": "62720e52afd7d55eddedc887",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "Shirdi Sai Electricals Limited",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			