

```
{
  "typeOfReport": {
    "label": "Bungalow",
    "value": "Bungalow"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63fc957bce84bf289baa55ec"
    },
    "firstName": "Walmik",
    "type": "CREDITOFFICER",
    "_id": "65269eb2703d7c40db9b5919",
    "lastName": "Wagh",
    "mobileNo": "",
    "workMobileNo": "8424998009",
    "email": "1sbi.05168@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
  }
}
```

```
"discussWithPerson": "Walmik",
"expectedFees": null,
"quotedAmount": "9000"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63fc957bce84bf289baa55ec",
  "name": "SARB Churchgate",
  "branchCode": "",
  "mobileNo": "02222053163",
  "alternateMobileNo": "",
  "email": "sarc.mumbai@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "6th Floor, International 16, Maharshi Karve Road, Churchgate, Mumbai -
400020, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
```

```
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f91822f3dd69653a5922e3",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "Prayush ",
    "email": "prayush@vastukala.org",
    "lastName": "Parekh ",
    "mobileNo": "9767983840",
    "designation": "",
    "shortName": "PPP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
    }
  ]
}
```

```
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.01597075940834",
  "longitude": "73.50738527376944"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.50738527376944,
    19.01597075940834
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-26",
      "remark": "saleability is very low in that area"
    }
  ]
},
"schedule": []
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Jambrung",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Raigad",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Karjat",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "193",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Elegant Phase I",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```

```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "63-B",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```



```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410201",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
```

```
"isDisplay": false
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
```

```
"coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "671c7529038561936233e235",
"ownerName": "Bansi Amit Kumar Makwana",
"ownerPhoneNo": "0000000000",
"appAddress": "Plot no 193, Bunglow no 63 B Jambrung Village.Karjat ",
"remark": "saleability is very low in that area",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/671c7529038561936233e235/document_1729918232536_1729918230591_Bansi_Amit_Kumar_MakwanaOld_Valuation_Report_SARB.pdf",
    "fileName": "document_1729918232536_1729918230591_Bansi_Amit_Kumar_MakwanaOld_Valuation_Report_SARB.pdf",
    "id": "100024",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Sat Oct 26 2024 04:50:49 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/671c7529038561936233e235/document_1729933797234_1729933795255_1729933419497000800_attach_139492262169950180.pdf",
    "fileName": "document_1729933797234_1729933795255_1729933419497000800_attach_139492262169950180.pdf",
    "id": "666755",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Sat Oct 26 2024 09:11:45 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
}
],
"caseNumber": "012101",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "414678",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 26 2024 04:50:49 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Bansi Amit Kumar Makwana",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "655556"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c0ef",
    "name": "externalImg_1729933526243_1729933523240_image_0.jpeg",
    "path": "cases/671c7529038561936233e235/externalImg_1729933526243_1729933523240_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c0f0",
    "name": "externalImg_1729933526468_1729933523240_image_1.jpeg",
    "path": "cases/671c7529038561936233e235/externalImg_1729933526468_1729933523240_image_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0f1",
  "name": "externallmg_1729933526695_1729933523240_image_2.jpeg",
  "path": "cases/671c7529038561936233e235/
externallmg_1729933526695_1729933523240_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0f2",
  "name": "externallmg_1729933527134_1729933523240_image_3.jpeg",
  "path": "cases/671c7529038561936233e235/
externallmg_1729933527134_1729933523240_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0f3",
  "name": "externallmg_1729933527219_1729933523240_image_4.jpeg",
  "path": "cases/671c7529038561936233e235/
externallmg_1729933527219_1729933523240_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0f4",
  "name": "externallmg_1729933527439_1729933523240_image_5.jpeg",
  "path": "cases/671c7529038561936233e235/
externallmg_1729933527439_1729933523240_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0f5",
  "name": "externallmg_1729933527654_1729933523240_image_6.jpeg",
  "path": "cases/671c7529038561936233e235/
externallmg_1729933527654_1729933523240_image_6.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c0f6",
    "name": "externallmg_1729933527852_1729933523240_image_7.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933527852_1729933523240_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c0f7",
    "name": "externallmg_1729933528033_1729933523240_image_8.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933528033_1729933523240_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c0f8",
    "name": "externallmg_1729933528546_1729933523240_image_9.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933528546_1729933523240_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c0f9",
    "name": "externallmg_1729933529079_1729933523240_image_10.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933529079_1729933523240_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c0fa",
    "name": "externallmg_1729933529385_1729933523240_image_11.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933529385_1729933523240_image_11.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0fb",
  "name": "externalimg_1729933529632_1729933523240_image_12.jpeg",
  "path": "cases/671c7529038561936233e235/
externalimg_1729933529632_1729933523240_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0fc",
  "name": "externalimg_1729933529868_1729933523240_image_13.jpeg",
  "path": "cases/671c7529038561936233e235/
externalimg_1729933529868_1729933523240_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0fd",
  "name": "externalimg_1729933530064_1729933523240_image_14.jpeg",
  "path": "cases/671c7529038561936233e235/
externalimg_1729933530064_1729933523240_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0fe",
  "name": "externalimg_1729933530512_1729933523240_image_15.jpeg",
  "path": "cases/671c7529038561936233e235/
externalimg_1729933530512_1729933523240_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671cb0dc857cdb68fa98c0ff",
  "name": "externalimg_1729933530752_1729933523240_image_16.jpeg",
  "path": "cases/671c7529038561936233e235/
externalimg_1729933530752_1729933523240_image_16.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c100",
    "name": "externallmg_1729933530996_1729933523240_image_17.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933530996_1729933523240_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c101",
    "name": "externallmg_1729933531420_1729933523240_image_18.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933531420_1729933523240_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671cb0dc857cdb68fa98c102",
    "name": "externallmg_1729933531674_1729933523240_image_19.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933531674_1729933523240_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d07",
    "name": "externallmg_1729933490699_1729933487931_image_0.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933490699_1729933487931_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d08",
    "name": "externallmg_1729933490892_1729933487931_image_1.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933490892_1729933487931_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "671cb0b90385619362344d09",
    "name": "externallmg_1729933491040_1729933487931_image_2.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933491040_1729933487931_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d0a",
    "name": "externallmg_1729933491093_1729933487931_image_3.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933491093_1729933487931_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d0b",
    "name": "externallmg_1729933491295_1729933487931_image_4.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933491295_1729933487931_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d0c",
    "name": "externallmg_1729933491694_1729933487931_image_5.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933491694_1729933487931_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d0d",
    "name": "externallmg_1729933492115_1729933487931_image_6.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933492115_1729933487931_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "671cb0b90385619362344d0e",
    "name": "externallmg_1729933492475_1729933487931_image_7.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933492475_1729933487931_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d0f",
    "name": "externallmg_1729933493073_1729933487931_image_8.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933493073_1729933487931_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d10",
    "name": "externallmg_1729933494500_1729933487931_image_9.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933494500_1729933487931_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d11",
    "name": "externallmg_1729933494518_1729933487931_image_10.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933494518_1729933487931_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d12",
    "name": "externallmg_1729933494823_1729933487931_image_11.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933494823_1729933487931_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d13",
```



```
    "name": "externallmg_1729933494837_1729933487931_image_12.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933494837_1729933487931_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d14",
    "name": "externallmg_1729933494905_1729933487932_image_13.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933494905_1729933487932_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d15",
    "name": "externallmg_1729933494943_1729933487932_image_14.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933494943_1729933487932_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d16",
    "name": "externallmg_1729933495053_1729933487932_image_15.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933495053_1729933487932_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d17",
    "name": "externallmg_1729933495284_1729933487932_image_16.jpeg",
    "path": "cases/671c7529038561936233e235/
externallmg_1729933495284_1729933487932_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671cb0b90385619362344d18",
    "name": "externallmg_1729933496339_1729933487932_image_17.jpeg",
```

```

    "path": "cases/671c7529038561936233e235/
externallmg_1729933496339_1729933487932_image_17.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-26T04:50:49.913Z",
"updatedAt": "2024-10-26T09:11:45.229Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Bungalow No. 63-B, Ground Floor, Elegant Phase I, Plot
No. 193, Village - Jambrung, Taluka - Karjat, District - Raigad, 410201",
"updatedBy": "60af3d172ffdf65bcd6585cd",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Bansi Amit Kumar Makwana",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			