

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "640b6f5d4dda382753e5c230"
    },
    "firstName": "Parag ",
    "type": "CREDITOFFICER",
    "_id": "640b6f5d4dda382753e5c232",
    "lastName": "Patel",
    "mobileNo": "",
    "workMobileNo": "9987354946",
    "email": "bo088210@pnb.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "15000000",
    "discussWithPerson": "Parag ",
    "expectedFees": 7500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "640b6f5d4dda382753e5c230",
  "name": "Mira Road East Branch",
  "branchCode": "",
  "mobileNo": "02225126616",
  "alternateMobileNo": "",
  "email": "bo088210@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mira Road East Branch, Shop No 1 yo 5, Shanti Plaza, Sector 11, Shanti
Nagar, Mira Road ( East), Thane 401107"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "66850df5d9f18310ed2e5d98",
"role": "SITEENGINEER",
"firstName": "Krishna",
"email": "krishnagawade9@gmail.com",
"lastName": "Gawde",
"mobileNo": "9821646373",
"designation": "Site Engg",
"shortName": "Krishna",
"workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": ""
}
```

```
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ],
      "shortName": "SBC",
      "workWithDocumentMaker": "",
      "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
    }
  ]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
```

```
"latitude": "19.27498146767099",
"longitude": "72.86712553703202"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86712553703202,
    19.27498146767099
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "28/10/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Penkarpada",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "21",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Srishti",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Srishti Complex",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "E",
```

```
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Sector 2A",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "233(pt), 235(pt) & 256(pt)",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "66(pt), 68(pt), 69(pt)",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```



```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "2102",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Poonam Estate Cluster 2",
  "west": "Srishti Road",
  "south": "Srishti Phase 1",
  "east": "Open Land"
},
"asPerDocumentAgreement": {
  "north": "Partly touching to Wing F and partly New S. No. 66(pt) of Village
Penkarpada",
  "west": "New S. No. 66(pt) of Village Penkarpada\n",
  "south": "New S. No. 66(pt) of Village Penkarpada\n",
  "east": "New S. No. 66(pt) of Village Penkarpada\n"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building Under Construction",
    "east": "Building Under Construction",
    "south": "Building Under Construction",
    "west": "Building Under Construction"
  },
  "asPerDocument": {
    "north": "Building Under Construction",
    "east": "Building Under Construction",
    "south": "Building Under Construction",
    "west": "Building Under Construction"
  },
  "isDisplay": true,
```

```
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of residential flat is Living Room + 2 Bedrooms + Kitchen + 2 Toilets + Passage + Balcony Area (i.e 2 BHK with 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MBMBP/NR1561/2023-24 dated 14.08.2023 issued by Mira Bhayandar Municipal Corporation.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "No",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "94500",
```

```
"landRate": "36400",
"igrImage": "cases/671f3b737e54a9c809b13f89/igr_1730201309598_Image.png",
"squareMeterGuideLineRate": "108675.00",
"squareFeetGuideLineRate": "10096.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "0",
  "rate": "94500.00",
  "squareMeterGuideLineRate": "108675.00",
  "squareFeetGuideLineRate": "10096.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Building Under Construction",
  "taxPaidHolderName": "Building Under Construction",
  "taxAmount": "Building Under Construction",
  "electricityServiceConnectionNo": "Building Under Construction",
  "meterCardHolderName": "Building Under Construction",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "Proposed_R.C.C._Slab",
"label": "Proposed R.C.C. Slab"
},
"partitions": {
"value": "Proposed_6"_Thk._Brick_Masonry",
"label": "Proposed 6" Thk. Brick Masonery"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"carParking": "Proposed One Vehicle Parking Space",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Proposed_Plain_Looking",
"label": "Proposed Plain Looking"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2026",
"fullDate": "1/1/2026"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "Proposed_R.C.C_Framed_Structure",
"label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
"value": "Proposed_R.C.C_Foundation",
"label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
```

```
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"groundStilt": {
  "value": "Proposed_Ground",
  "label": "Proposed Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "2",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "33",
"flatFloorNo": "21",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "774.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/671f3b737e54a9c809b13f89/
routeMap_1730205927946_Image.png",
    "routeLat": "19.272219",
    "routeLng": "72.868913",
    "stationName": "Mira Road",
    "routeDistance": "2.2 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```



```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "tclcd",
    "name": "tclcd",
    "image": "cases/671f3b737e54a9c809b13f89/
routeMap_1730205842167_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "01",
"othersRate": "400000",
"totalothersRate": "400000",
"finaltotal": "13072000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "13743800.00",
"finalValue": "12672000.00",
"purchaseValueDocument": {
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "257140",
  "path": "cases/671f3b737e54a9c809b13f89/
document_1730100068796_1730100015407_Kartik_munjaj_agreement.pdf",
  "fileName":
"document_1730100068796_1730100015407_Kartik_munjaj_agreement.pdf",
  "documentDate": "17/10/2024",
  "amount": "12816300/-",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "Eversmile Properties Private Limited",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Kartik Munjal, Mr. Ravi Munjal & Mrs. Neena Munjal",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "19204/2024"
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "5.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7818342.00",
  "selectedBuildUpValue": "774.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6720d7e021492f3332ed490d",
      "name": "externallmg_1730205664199_externallmg_1730185482252_WhatsApp_I
mage_20241029_at_121130_2.jpeg",
      "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664199_external
lmg_1730185482252_WhatsApp_Image_20241029_at_121130_2.jpeg",
      "orientation": "landscape"
    }
  ],
}
```

```
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6720d7e021492f3332ed490e",
    "name": "externallmg_1730205664218_externallmg_1730185482275_WhatsApp_I
mage_20241029_at_121130.jpeg",
    "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664218_extern
lmg_1730185482275_WhatsApp_Image_20241029_at_121130.jpeg",
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6720d7e021492f3332ed4907",
    "name": "externallmg_1730205664083_externallmg_1730185482077_WhatsApp_I
mage_20241029_at_121128_1.jpeg",
    "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664083_extern
lmg_1730185482077_WhatsApp_Image_20241029_at_121128_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6720d7e021492f3332ed490a",
    "name": "externallmg_1730205664147_externallmg_1730185482168_WhatsApp_I
mage_20241029_at_121129_1.jpeg",
    "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664147_extern
lmg_1730185482168_WhatsApp_Image_20241029_at_121129_1.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16889.00",
    "max": "19380.00"
  },
  "builtUpRateRange": {
    "min": "15354.00",
    "max": "17619.00"
  },
  "saleableRateRange": {
    "min": "0.00",
```

```
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
```



```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "704.00",
"empanelmentNo": [
  "REF:ZO: SAMD:1138"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "671f3b737e54a9c809b13f89",
"ownerName": "Mr. Kartik Munjal",
"ownerPhoneNo": "9820344800",
"appAddress": "FLAT NO 2102 SECTOR 2A WING E SHRISHTI SECTOR 2A
SHRISHTI COMPLEX PENKARPADA MIRA ROAD EAST THANE ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },
  "inputs": {
```

```
"documentDate": "17/10/2024",
"amount": "12816300/-",
"from": {
  "value": "Promoter",
  "label": "Promoter"
},
"Promoter": "Eversmile Properties Private Limited",
"to": {
  "value": "Purchaser",
  "label": "Purchaser"
},
"Purchaser": "Mr. Kartik Munjal, Mr. Ravi Munjal & Mrs. Neena Munjal",
"number": {
  "value": "No",
  "label": "No"
},
"No": "19204/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "257140",
"path": "cases/671f3b737e54a9c809b13f89/
document_1730100068796_1730100015407_Kartik_munjal_agreement.pdf",
"fileName":
"document_1730100068796_1730100015407_Kartik_munjal_agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/08/2023",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MBMBP/NR1561/2023-24"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1730207219897_Plan.pdf",
```

```
"path": "cases/671f3b737e54a9c809b13f89/document_1730207219897_Plan.pdf",
"id": "515739",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Tue Oct 29 2024 13:07:00 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012118",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
{
"id": "849247",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Mon Oct 28 2024 07:21:23 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Kartik Munjal",
"phone": "9820344800",
"ownershipShare": "",
"email": "",
"id": "745342"
},
{
"name": "Mr. Ravi Munjal ",
"phone": "",
"email": "",
"ownershipShare": "",
"id": "486419"
},
{
"name": "Mrs. Neena Munjal",
"phone": "",
"email": "",
"ownershipShare": "",
"id": "920267"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
```

```
"typeOfDocument": {
  "value": "60af48bf2ffdf65bcd6585fa",
  "label": "Agreement for sale"
},
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "890555",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "704",
"squareMeterArea": "65.40",
"docFinalBuiltUp": "774.40",
"docFinalBuiltUpSquareMeter": "71.94",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "645.00",
      "squareMeterArea": "59.92",
      "expectedRate": "18449.61",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "709.50",
      "squareMeterArea": "65.91",
      "expectedRate": "16772.37",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "6720c74f21492f3332ed3241",
    "property": "Flat",
    "area": "645",
    "builtUpPercentage": "10",
```

```
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "11900000",
"expectedRate": "18449.61",
"builtUpExpectedRate": "16772.37",
"image": "cases/671f3b737e54a9c809b13f89/
indicator_1730200344443_Image.png",
"squareMeter": "59.92",
"id": "995027"
},
{
  "carpetArea": {
    "area": "645.00",
    "squareMeterArea": "59.92",
    "expectedRate": "19379.84",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "709.50",
    "squareMeterArea": "65.91",
    "expectedRate": "17618.04",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6720c74f21492f3332ed3242",
  "property": "Flat",
  "area": "645",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "12500000",
  "expectedRate": "19379.84",
  "builtUpExpectedRate": "17618.04",
  "image": "cases/671f3b737e54a9c809b13f89/
indicator_1730200367381_Image.png",
```

```
"squareMeter": "59.92",
"id": "447346"
},
{
  "carpetArea": {
    "area": "894.00",
    "squareMeterArea": "83.06",
    "expectedRate": "16888.93",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "983.40",
    "squareMeterArea": "91.36",
    "expectedRate": "15353.57",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6720c74f21492f3332ed3243",
  "property": "Flat",
  "area": "894",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "15098700.00",
  "expectedRate": "16888.93",
  "builtUpExpectedRate": "15353.57",
  "image": "cases/671f3b737e54a9c809b13f89/
indicator_1730201189491_Image.png",
  "squareMeter": "83.06",
  "id": "555501"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6720890ac7eda319f46324ff",
```

```
"name":
"externallmg_1730185482064_WhatsApp_Image_20241029_at_121127.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/
externallmg_1730185482064_WhatsApp_Image_20241029_at_121127.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720890ac7eda319f4632508",
  "name":
"externallmg_1730185482279_WhatsApp_Image_20241029_at_123141.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/
externallmg_1730185482279_WhatsApp_Image_20241029_at_123141.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed4907",
  "name": "externallmg_1730205664083_externallmg_1730185482077_WhatsApp_I
mage_20241029_at_121128_1.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664083_externall
mg_1730185482077_WhatsApp_Image_20241029_at_121128_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed4908",
  "name": "externallmg_1730205664100_externallmg_1730185482107_WhatsApp_I
mage_20241029_at_121128_2.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664100_externall
mg_1730185482107_WhatsApp_Image_20241029_at_121128_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed4909",
  "name": "externallmg_1730205664132_externallmg_1730185482146_WhatsApp_I
mage_20241029_at_121128.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664132_externall
mg_1730185482146_WhatsApp_Image_20241029_at_121128.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed490a",
  "name": "externallmg_1730205664147_externallmg_1730185482168_WhatsApp_I
mage_20241029_at_121129_1.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664147_externall
mg_1730185482168_WhatsApp_Image_20241029_at_121129_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed490b",
  "name": "externallmg_1730205664151_externallmg_1730185482193_WhatsApp_I
mage_20241029_at_121129.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664151_externall
mg_1730185482193_WhatsApp_Image_20241029_at_121129.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed490c",
  "name": "externallmg_1730205664173_externallmg_1730185482225_WhatsApp_I
mage_20241029_at_121130_1.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664173_externall
mg_1730185482225_WhatsApp_Image_20241029_at_121130_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed490d",
  "name": "externallmg_1730205664199_externallmg_1730185482252_WhatsApp_I
mage_20241029_at_121130_2.jpeg",
  "path": "cases/671f3b737e54a9c809b13f89/externallmg_1730205664199_externall
mg_1730185482252_WhatsApp_Image_20241029_at_121130_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6720d7e021492f3332ed490e",
  "name": "externallmg_1730205664218_externallmg_1730185482275_WhatsApp_I
mage_20241029_at_121130.jpeg",
```



```
    "path": "cases/671f3b737e54a9c809b13f89/externalmg_1730205664218_external  
mg_1730185482275_WhatsApp_Image_20241029_at_121130.jpeg",  
    "orientation": "landscape"  
  }  
],  
"externalDocuments": [],  
"processingDocuments": [  
  {  
    "originalname": "1722850876713_igr1.pdf",  
    "filename": "1730108564918_1722850876713_igr1.pdf",  
    "path": "cases/671f3b737e54a9c809b13f89/  
processingDocuments/1730108564918_1722850876713_igr1.pdf",  
    "size": "154400",  
    "createdAt": "Mon Oct 28 2024 09:42:45 GMT+0000 (Coordinated Universal Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "1722850876768_igr2.pdf",  
    "filename": "1730108564934_1722850876768_igr2.pdf",  
    "path": "cases/671f3b737e54a9c809b13f89/  
processingDocuments/1730108564934_1722850876768_igr2.pdf",  
    "size": "160861",  
    "createdAt": "Mon Oct 28 2024 09:42:45 GMT+0000 (Coordinated Universal Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "1722850877709_reference_reprot.pdf",  
    "filename": "1730108564951_1722850877709_reference_reprot.pdf",  
    "path": "cases/671f3b737e54a9c809b13f89/  
processingDocuments/1730108564951_1722850877709_reference_reprot.pdf",  
    "size": "1006198",  
    "createdAt": "Mon Oct 28 2024 09:42:45 GMT+0000 (Coordinated Universal Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "igr1.pdf",  
    "filename": "1730108565062_igr1.pdf",  
    "path": "cases/671f3b737e54a9c809b13f89/  
processingDocuments/1730108565062_igr1.pdf",  
    "size": "165840",  
    "createdAt": "Mon Oct 28 2024 09:42:45 GMT+0000 (Coordinated Universal Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "igr2.pdf",  
    "filename": "1730108565086_igr2.pdf",
```

```
    "path": "cases/671f3b737e54a9c809b13f89/
processingDocuments/1730108565086_igr2.pdf",
    "size": "159309",
    "createdAt": "Mon Oct 28 2024 09:42:45 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr3.pdf",
    "filename": "1730108565091_igr3.pdf",
    "path": "cases/671f3b737e54a9c809b13f89/
processingDocuments/1730108565091_igr3.pdf",
    "size": "156460",
    "createdAt": "Mon Oct 28 2024 09:42:45 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Calculation (2) - kartik.xlsx",
    "filename": "1730201390454_Calculation_2__kartik.xlsx",
    "path": "cases/671f3b737e54a9c809b13f89/
processingDocuments/1730201390454_Calculation_2__kartik.xlsx",
    "size": "16154",
    "createdAt": "Tue Oct 29 2024 11:29:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr4.pdf",
    "filename": "1730201390455_igr4.pdf",
    "path": "cases/671f3b737e54a9c809b13f89/
processingDocuments/1730201390455_igr4.pdf",
    "size": "152802",
    "createdAt": "Tue Oct 29 2024 11:29:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Plan.pdf",
    "filename": "1730201390466_Plan.pdf",
    "path": "cases/671f3b737e54a9c809b13f89/
processingDocuments/1730201390466_Plan.pdf",
    "size": "1464924",
    "createdAt": "Tue Oct 29 2024 11:29:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Srishti Namaah.pdf",
    "filename": "1730201390550_Srishti_Namaah.pdf",
    "path": "cases/671f3b737e54a9c809b13f89/
processingDocuments/1730201390550_Srishti_Namaah.pdf",
```

```
"size": "1123396",
"createdAt": "Tue Oct 29 2024 11:29:50 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - kartik.xlsx",
  "filename": "1730201390578_Summary__kartik.xlsx",
  "path": "cases/671f3b737e54a9c809b13f89/
processingDocuments/1730201390578_Summary__kartik.xlsx",
  "size": "2339857",
  "createdAt": "Tue Oct 29 2024 11:29:50 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6720baf321492f3332ed0ae3",
    "note": "value shared",
    "taskId": "671f3e941a3e43c859d49134",
    "createdAt": "2024-10-29T10:37:39.218Z"
  }
],
"createdAt": "2024-10-28T07:21:23.805Z",
"updatedAt": "2024-10-29T13:27:36.355Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2102, 21st Floor, Wing - E, Srishti, Sector 2A,
Srishti Complex, Village - Penkarpada, Taluka - Thane, District - Thane, Mira Road
(East), PIN - 401 107, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
```

```
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Siddharth Thomar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"rerald": "",
"siteVisitContactNo": "9137593076",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 704.00",
"flatRate": "18000",
"landOtherRate": "15000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
```

```
"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
}
```

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
