

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6728735421492f3332edab29"
    },
    "firstName": "Shivkumar",
    "type": "CREDITOFFICER",
    "_id": "6728736d21492f3332edab56",
    "email": "Shivkumar1.Chandsure@axisbank.com",
    "lastName": "Chandsure",
    "mobileNo": "",
    "workMobileNo": "9145702020"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "64b7ca68d0368073e3fa808a",
  "name": "Nanded",
  "shortName": "NED",
  "email": "nanded@vastukala.org",
  "address": "Shop No 24, Stadium Complex, Gokul Nagar Station Road,
Nanded-431602",
  "city": "nanded"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1818",
  "type": "BANK",
  "name": "Axis Bank",
  "displayName": "Axis Bank",
  "initial": "Axis",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6728735421492f3332edab29",
  "name": "Kalamandir Branch",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "Shivkumar1.Chandsure@axisbank.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Nikhil Heights, Vazirabad Bus Stand Road, Kalamandir Nanded 431601"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f90d72f3dd69653a5918b8",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6716528ee73f0c3db52c7d2a",
    "role": "SITEENGINEER",
```

```
"firstName": "Mohammad Shareq",
"email": "mdshareq@vastukala.co.in",
"lastName": "Pasha",
"mobileNo": "7020555018",
"shortName": "MSN",
"workWithDocumentMaker": "6084131a13f01f158c6ea1f3"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6716528ee73f0c3db52c7d2a",
  "role": "SITEENGINEER",
  "firstName": "Mohammad Shareq",
  "email": "mdshareq@vastukala.co.in",
  "lastName": "Pasha",
  "mobileNo": "7020555018",
  "designation": "",
  "shortName": "MSN",
  "workWithDocumentMaker": "6084131a13f01f158c6ea1f3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.599638845725117",
  "longitude": "77.57357752028315"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
```

```
    "dateTime": "29/10/2024 09:16 am"
  },
  {
    "dateTime": "29/10/2024 12:00 am"
  },
  {
    "dateTime": "29/10/2024 12:00 am"
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Khanapur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nanded",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Degloor",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "B-1",
  "label": true
},
"buildingName": {
  "status": false,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Khanapur Industrial Area ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "MIDC",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
}
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67205be3b0d38719f5b0ce6f",
"ownerName": "M/S Venkateshwara Dal Industries ",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9422185107",
"contactPersonName": "Rajiv S/O Venkatrao Achintalwar",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "M/S Venkateshwara Dal Industries ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "569958"
  }
],
"caseReferredBy": "6716528ee73f0c3db52c7d2a",
"relationWithOwner": "Contact Person",
"fullAddress": "Industrial Land and Building No. Ground Floor, Plot No. B-1, Khanapur
Industrial Area , MIDC, Village - Khanapur, Taluka - Degloor, District - Nanded, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1730173914521_04.pdf",
"path": "cases/67205be3b0d38719f5b0ce6f/document_1730173914521_04.pdf",
"id": "244350",
"uploadedBy": "6006d4ce5080a310ac1fdfc2",
"createdAt": "Tue Oct 29 2024 03:52:03 GMT+0000 (Coordinated Universal Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "012140",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "747473",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Oct 29 2024 03:52:03 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c4fccfae933db22c65da",
    "name": "externallmg_r_1733739763202_IMG_20241023_171953.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739763202_IMG_20241023_171953.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65db",
  "name": "externallmg_r_1733739763267_IMG_20241023_172007.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739763267_IMG_20241023_172007.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65dc",
  "name": "externallmg_r_1733739763343_IMG_20241023_172015.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739763343_IMG_20241023_172015.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65dd",
  "name": "externallmg_r_1733739763829_IMG_20241023_172017.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739763829_IMG_20241023_172017.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65de",
  "name": "externallmg_r_1733739763884_IMG_20241023_172105.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739763884_IMG_20241023_172105.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65df",
  "name": "externallmg_r_1733739764401_IMG_20241023_172115.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739764401_IMG_20241023_172115.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e0",
  "name": "externallmg_r_1733739764484_IMG_20241023_172146.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739764484_IMG_20241023_172146.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e1",
  "name": "externallmg_r_1733739765240_IMG_20241023_172148.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739765240_IMG_20241023_172148.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e2",
  "name": "externallmg_r_1733739765335_IMG_20241023_172151.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739765335_IMG_20241023_172151.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e3",
  "name": "externallmg_r_1733739766179_IMG_20241023_172200.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739766179_IMG_20241023_172200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e4",
  "name": "externallmg_r_1733739766251_IMG_20241023_172214.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739766251_IMG_20241023_172214.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e5",
  "name": "externallmg_r_1733739767115_IMG_20241023_172216.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739767115_IMG_20241023_172216.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e6",
  "name": "externallmg_r_1733739767203_IMG_20241023_172220.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739767203_IMG_20241023_172220.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c4fccfae933db22c65e7",
  "name": "externallmg_r_1733739768099_IMG_20241023_172221.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739768099_IMG_20241023_172221.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c51fbefd7f3db908242c",
  "name": "externallmg_r_1733739797972_IMG_20241023_172241.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739797972_IMG_20241023_172241.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c51fbefd7f3db908242d",
  "name": "externallmg_r_1733739798629_IMG_20241023_172243.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739798629_IMG_20241023_172243.jpg",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6756c51fbefd7f3db908242e",
"name": "externallmg_r_1733739797749_IMG_20241023_172235.jpg",
"path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739797749_IMG_20241023_172235.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6756c51fbefd7f3db908242f",
"name": "externallmg_r_1733739797632_IMG_20241023_172223.jpg",
"path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739797632_IMG_20241023_172223.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6756c51fbefd7f3db9082430",
"name": "externallmg_r_1733739799074_IMG_20241023_172314.jpg",
"path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739799074_IMG_20241023_172314.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6756c51fbefd7f3db9082431",
"name": "externallmg_r_1733739799011_IMG_20241023_172245.jpg",
"path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739799011_IMG_20241023_172245.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6756c51fbefd7f3db9082432",
"name": "externallmg_r_1733739799705_IMG_20241023_172316.jpg",
"path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739799705_IMG_20241023_172316.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6756c51fbefd7f3db9082433",
  "name": "externallmg_r_1733739800014_IMG_20241023_172320.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739800014_IMG_20241023_172320.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c51fbefd7f3db9082434",
  "name": "externallmg_r_1733739800079_IMG_20241023_172324.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739800079_IMG_20241023_172324.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c51fbefd7f3db9082435",
  "name": "externallmg_r_1733739800646_IMG_20241023_172425.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739800646_IMG_20241023_172425.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c51fbefd7f3db9082436",
  "name": "externallmg_r_1733739800775_IMG_20241023_172429.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739800775_IMG_20241023_172429.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c51fbefd7f3db9082437",
  "name": "externallmg_r_1733739801513_IMG_20241023_172436.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739801513_IMG_20241023_172436.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "6756c51befd7f3db9082438",
    "name": "externallmg_r_1733739801631_IMG_20241023_172438.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739801631_IMG_20241023_172438.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c51befd7f3db9082439",
    "name": "externallmg_r_1733739802567_IMG_20241023_172449.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739802567_IMG_20241023_172449.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824db",
    "name": "externallmg_r_1733739830234_IMG_20241023_172601.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739830234_IMG_20241023_172601.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824dc",
    "name": "externallmg_r_1733739830481_IMG_20241023_172627.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739830481_IMG_20241023_172627.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824dd",
    "name": "externallmg_r_1733739830390_IMG_20241023_172603.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739830390_IMG_20241023_172603.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824de",
```

```
    "name": "externallmg_r_1733739831656_IMG_20241023_172641.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739831656_IMG_20241023_172641.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824df",
    "name": "externallmg_r_1733739832752_IMG_20241023_172714.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739832752_IMG_20241023_172714.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e0",
    "name": "externallmg_r_1733739833827_IMG_20241023_172734.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739833827_IMG_20241023_172734.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e1",
    "name": "externallmg_r_1733739831725_IMG_20241023_172652.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739831725_IMG_20241023_172652.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e2",
    "name": "externallmg_r_1733739832636_IMG_20241023_172701.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739832636_IMG_20241023_172701.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e3",
    "name": "externallmg_r_1733739834268_IMG_20241023_172736.jpg",
```

```
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739834268_IMG_20241023_172736.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e4",
    "name": "externallmg_r_1733739835156_IMG_20241023_172758.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739835156_IMG_20241023_172758.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e5",
    "name": "externallmg_r_1733739835408_IMG_20241023_172759.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739835408_IMG_20241023_172759.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e6",
    "name": "externallmg_r_1733739834339_IMG_20241023_172738.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739834339_IMG_20241023_172738.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e7",
    "name": "externallmg_r_1733739836190_IMG_20241023_172921.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739836190_IMG_20241023_172921.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756c541befd7f3db90824e8",
    "name": "externallmg_r_1733739836257_IMG_20241023_173004.jpg",
    "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739836257_IMG_20241023_173004.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c550821be57904f187f6",
  "name": "externallmg_r_1733739852293_IMG_20241023_173051.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739852293_IMG_20241023_173051.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c550821be57904f187f7",
  "name": "externallmg_r_1733739852980_IMG_20241023_173144.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739852980_IMG_20241023_173144.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c550821be57904f187f8",
  "name": "externallmg_r_1733739852236_IMG_20241023_173038.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739852236_IMG_20241023_173038.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c550821be57904f187f9",
  "name": "externallmg_r_1733739852370_IMG_20241023_173143.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739852370_IMG_20241023_173143.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756c550821be57904f187fa",
  "name": "externallmg_r_1733739853416_IMG_20241023_173305.jpg",
  "path": "cases/67205be3b0d38719f5b0ce6f/
externallmg_r_1733739853416_IMG_20241023_173305.jpg",
  "orientation": "landscape"
}
```

```
}  
],  
"externalDocuments": [],  
"processingDocuments": [],  
"leadRemarks": [],  
"audioRemarks": [],  
"remarks": [],  
"createdAt": "2024-10-29T03:52:03.318Z",  
"updatedAt": "2024-12-09T10:24:16.033Z",  
"__v": 0,  
"addressForMap": "",  
"updatedBy": "60016f965256c07aec8e6dd6",  
"reId": ""  
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			