

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fe"
    },
    "firstName": "Rahul ",
    "type": "CREDITOFFICER",
    "_id": "64eef816eb1f822256dc83b9",
    "lastName": "Lokhare",
    "mobileNo": "",
    "workMobileNo": "9702436421",
    "email": "rahul.lokare@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "200000000",
    "discussWithPerson": "Rahul ",
    "expectedFees": 100000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fe",
  "branchCode": "000072",
  "type": "BRANCH",
  "name": "Shivsagar Estate Branch Worli (South) ",
  "email": "sbi.01154@sbi.co.in",
  "mobileNo": "24921772 / 24980675 ",
  "alternateMobileNo": "24937708 / 24968939",
  "address": "Devchand House, Ground Floor, Dr. Annie Besant Road, Worli, Mumbai -
400 018, State - Maharashtra, Country - India\r\n",
  "ledgerName": "STATE BANK OF INDIA - WORLI SHIVSAGAR",
  "fax": "24973911",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
```

```
"latitude": "18.083997589436912",
"longitude": "73.46791559204513"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.46791559204513,
    18.083997589436912
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/11/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Kamble",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mahad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Mahad",
  "label": true
},
"plotNo": {
```

```
"status": true,
"name": "Plot No.",
"key": "plotNo",
"value": "A-15-1,2",
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```

```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
```



```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mahad",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
```

```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```



```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "672c99bf52140a502a6a2432",
"ownerName": "Shree Hari Chemicals ",
"ownerPhoneNo": "9821381615",
"appAddress": "Mahad industrial area, plot no - A - 8, plot A- 9, plot no - A - 13, plot
no - A- 15/1 & plot no A - 15/2, village - kamble tarfe, Birwadi, Mahad, Raigad ",
"remark": "urgent basis \n charges - as per schedule + traveling ",
"documents": [
  {
    "documentType": {
      "value": "60ae1297aa6d152c1801b459",
      "label": "Lease Agreement"
    },
    "inputs": {
      "from": {
        "value": "Administrator",
        "label": "Administrator"
      }
    }
  }
],
```

```
"Administrator": "MIDC",
"to": {
  "value": "Lessee",
  "label": "Lessee"
},
"Lessee": "Shree Hari Chemicals"
},
"isHardCopy": false,
"displayStatus": false,
"id": "638804",
"path": "cases/672c99bf52140a502a6a2432/
document_1731045496274_1731045492737_Plot_no_A_15__1__A__15__2.pdf",
"fileName":
"document_1731045496274_1731045492737_Plot_no_A_15__1__A__15__2.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "000"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733461149434_OC.pdf",
  "path": "cases/672c99bf52140a502a6a2432/document_1733461149434_OC.pdf",
  "id": "730601",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Fri Dec 06 2024 05:04:27 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae125faa6d152c1801b35b",
    "label": "Property Tax Receipt"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "000"
  },
```

```
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1733461170388_PT.pdf",
"path": "cases/672c99bf52140a502a6a2432/document_1733461170388_PT.pdf",
"id": "440525",
"uploadedBy": "65dee3f79a876858ab30487f",
"createdAt": "Fri Dec 06 2024 05:04:27 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae126aaa6d152c1801b38c",
    "label": "Water bill"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "000"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733461185545_Woter_Bill.pdf",
  "path": "cases/672c99bf52140a502a6a2432/
document_1733461185545_Woter_Bill.pdf",
  "id": "733265",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Fri Dec 06 2024 05:04:27 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1290aa6d152c1801b43c",
    "label": "Insurance Policies"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "0000"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733461211232_Insurance__Fire_Policy.pdf",
  "path": "cases/672c99bf52140a502a6a2432/
document_1733461211232_Insurance__Fire_Policy.pdf",
```

```
"id": "282957",
"uploadedBy": "65dee3f79a876858ab30487f",
"createdAt": "Fri Dec 06 2024 05:04:27 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "remark": "Pollution Control Board NOC\n"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733461467551_Pollution_Control_Board.pdf",
  "path": "cases/672c99bf52140a502a6a2432/
document_1733461467551_Pollution_Control_Board.pdf",
  "id": "426584",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Fri Dec 06 2024 05:04:27 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012223",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "426625",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 07 2024 10:43:11 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shree Hari Chemicals ",
    "phone": "9821381615",
    "ownershipShare": "",
    "email": "",
    "id": "584682"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283b8cfae933db22a7bcd",
    "name": "externalImg_1733460919845_IMG20241204WA0096.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460919845_IMG20241204WA0096.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283b8cfae933db22a7bce",
    "name": "externalImg_1733460919850_IMG20241204WA0097.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460919850_IMG20241204WA0097.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283b8cfae933db22a7bcf",
    "name": "externalImg_1733460919853_IMG20241204WA0098.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460919853_IMG20241204WA0098.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283b8cfae933db22a7bd0",
    "name": "externalImg_1733460919875_IMG20241204WA0099.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460919875_IMG20241204WA0099.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283b8cfae933db22a7bd1",
    "name": "externalImg_1733460919880_IMG20241204WA0100.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460919880_IMG20241204WA0100.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283b8cfae933db22a7bd2",
  "name": "externallmg_1733460919905_IMG20241204WA0101.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460919905_IMG20241204WA0101.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283b8cfae933db22a7bd3",
  "name": "externallmg_1733460919907_IMG20241204WA0102.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460919907_IMG20241204WA0102.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b2a",
  "name": "externallmg_1733460929976_IMG20241206WA0050.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460929976_IMG20241206WA0050.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b2b",
  "name": "externallmg_1733460929985_IMG20241206WA0051.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460929985_IMG20241206WA0051.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b2c",
  "name": "externallmg_1733460929991_IMG20241206WA0052.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460929991_IMG20241206WA0052.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283c2befd7f3db9059b2d",
      "name": "externallmg_1733460930036_IMG20241206WA0053.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930036_IMG20241206WA0053.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283c2befd7f3db9059b2e",
      "name": "externallmg_1733460930041_IMG20241206WA0054.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930041_IMG20241206WA0054.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283c2befd7f3db9059b2f",
      "name": "externallmg_1733460930081_IMG20241206WA0055.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930081_IMG20241206WA0055.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283c2befd7f3db9059b30",
      "name": "externallmg_1733460930087_IMG20241206WA0056.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930087_IMG20241206WA0056.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283c2befd7f3db9059b31",
      "name": "externallmg_1733460930122_IMG20241206WA0057.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930122_IMG20241206WA0057.jpg",
      "orientation": "landscape"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b32",
  "name": "externallmg_1733460930126_IMG20241206WA0058.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930126_IMG20241206WA0058.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b33",
  "name": "externallmg_1733460930160_IMG20241206WA0059.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930160_IMG20241206WA0059.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b34",
  "name": "externallmg_1733460930165_IMG20241206WA0060.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930165_IMG20241206WA0060.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b35",
  "name": "externallmg_1733460930201_IMG20241206WA0061.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930201_IMG20241206WA0061.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283c2befd7f3db9059b36",
  "name": "externallmg_1733460930207_IMG20241206WA0062.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930207_IMG20241206WA0062.jpg",
  "orientation": "landscape"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283c2befd7f3db9059b37",
    "name": "externallmg_1733460930250_IMG20241206WA0063.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930250_IMG20241206WA0063.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283c2befd7f3db9059b38",
    "name": "externallmg_1733460930257_IMG20241206WA0064.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930257_IMG20241206WA0064.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283c2befd7f3db9059b39",
    "name": "externallmg_1733460930288_IMG20241206WA0065.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460930288_IMG20241206WA0065.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbef7f3db9059b7e",
    "name": "externallmg_1733460939998_IMG20241206WA0294.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460939998_IMG20241206WA0294.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbef7f3db9059b7f",
    "name": "externallmg_1733460940003_IMG20241206WA0297.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460940003_IMG20241206WA0297.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "675283ccbefd7f3db9059b80",
    "name": "externalimg_1733460940007_IMG20241206WA0298.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940007_IMG20241206WA0298.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b81",
    "name": "externalimg_1733460940041_IMG20241206WA0299.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940041_IMG20241206WA0299.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b82",
    "name": "externalimg_1733460940045_IMG20241206WA0301.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940045_IMG20241206WA0301.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b83",
    "name": "externalimg_1733460940083_IMG20241206WA0302.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940083_IMG20241206WA0302.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b84",
    "name": "externalimg_1733460940105_IMG20241206WA0303.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940105_IMG20241206WA0303.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "675283ccbefd7f3db9059b85",
    "name": "externalimg_1733460940109_IMG20241206WA0304.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940109_IMG20241206WA0304.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b86",
    "name": "externalimg_1733460940140_IMG20241206WA0305.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940140_IMG20241206WA0305.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b87",
    "name": "externalimg_1733460940144_IMG20241206WA0306.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940144_IMG20241206WA0306.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b88",
    "name": "externalimg_1733460940176_IMG20241206WA0307.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940176_IMG20241206WA0307.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b89",
    "name": "externalimg_1733460940182_IMG20241206WA0308.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460940182_IMG20241206WA0308.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b8a",
```

```
    "name": "externalImg_1733460940209_IMG20241206WA0309.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460940209_IMG20241206WA0309.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b8b",
    "name": "externalImg_1733460940214_IMG20241206WA0310.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460940214_IMG20241206WA0310.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b8c",
    "name": "externalImg_1733460940245_IMG20241206WA0311.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460940245_IMG20241206WA0311.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283ccbefd7f3db9059b8d",
    "name": "externalImg_1733460940251_IMG20241206WA0312.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460940251_IMG20241206WA0312.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283d8cfae933db22a7c70",
    "name": "externalImg_1733460951526_IMG20241206WA0313.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460951526_IMG20241206WA0313.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283d8cfae933db22a7c71",
    "name": "externalImg_1733460951537_IMG20241206WA0314.jpg",
```

```
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951537_IMG20241206WA0314.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283d8cfae933db22a7c72",
    "name": "externallmg_1733460951541_IMG20241206WA0315.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951541_IMG20241206WA0315.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283d8cfae933db22a7c73",
    "name": "externallmg_1733460951577_IMG20241206WA0316.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951577_IMG20241206WA0316.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283d8cfae933db22a7c74",
    "name": "externallmg_1733460951584_IMG20241206WA0317.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951584_IMG20241206WA0317.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283d8cfae933db22a7c75",
    "name": "externallmg_1733460951619_IMG20241206WA0318.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951619_IMG20241206WA0318.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283d8cfae933db22a7c76",
    "name": "externallmg_1733460951624_IMG20241206WA0319.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951624_IMG20241206WA0319.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283d8cfae933db22a7c77",
  "name": "externallmg_1733460951657_IMG20241206WA0320.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951657_IMG20241206WA0320.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283d8cfae933db22a7c78",
  "name": "externallmg_1733460951662_IMG20241206WA0321.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951662_IMG20241206WA0321.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283d8cfae933db22a7c79",
  "name": "externallmg_1733460951690_IMG20241206WA0322.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951690_IMG20241206WA0322.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283d8cfae933db22a7c7a",
  "name": "externallmg_1733460951698_IMG20241206WA0323.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951698_IMG20241206WA0323.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283d8cfae933db22a7c7b",
  "name": "externallmg_1733460951735_IMG20241206WA0324.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951735_IMG20241206WA0324.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283d8cfae933db22a7c7c",
      "name": "externallmg_1733460951739_IMG20241206WA0325.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951739_IMG20241206WA0325.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283d8cfae933db22a7c7d",
      "name": "externallmg_1733460951775_IMG20241206WA0326.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951775_IMG20241206WA0326.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283d8cfae933db22a7c7e",
      "name": "externallmg_1733460951779_IMG20241206WA0327.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951779_IMG20241206WA0327.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283d8cfae933db22a7c7f",
      "name": "externallmg_1733460951809_IMG20241206WA0328.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460951809_IMG20241206WA0328.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675283e3cfae933db22a7cf4",
      "name": "externallmg_1733460963412_IMG20241206WA0329.jpg",
      "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963412_IMG20241206WA0329.jpg",
      "orientation": "landscape"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283e3cfae933db22a7cf5",
  "name": "externallmg_1733460963425_IMG20241206WA0330.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963425_IMG20241206WA0330.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283e3cfae933db22a7cf6",
  "name": "externallmg_1733460963430_IMG20241206WA0331.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963430_IMG20241206WA0331.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283e3cfae933db22a7cf7",
  "name": "externallmg_1733460963460_IMG20241206WA0332.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963460_IMG20241206WA0332.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283e3cfae933db22a7cf8",
  "name": "externallmg_1733460963466_IMG20241206WA0333.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963466_IMG20241206WA0333.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283e3cfae933db22a7cf9",
  "name": "externallmg_1733460963493_IMG20241206WA0334.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963493_IMG20241206WA0334.jpg",
  "orientation": "portrait"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7cfa",
    "name": "externallmg_1733460963515_IMG20241206WA0335.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963515_IMG20241206WA0335.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7cfb",
    "name": "externallmg_1733460963520_IMG20241206WA0336.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963520_IMG20241206WA0336.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7cfc",
    "name": "externallmg_1733460963554_IMG20241206WA0337.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963554_IMG20241206WA0337.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7cfd",
    "name": "externallmg_1733460963558_IMG20241206WA0338.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963558_IMG20241206WA0338.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7cfe",
    "name": "externallmg_1733460963588_IMG20241206WA0339.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460963588_IMG20241206WA0339.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "675283e3cfae933db22a7cff",
    "name": "externalimg_1733460963603_IMG20241206WA0340.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460963603_IMG20241206WA0340.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7d00",
    "name": "externalimg_1733460963609_IMG20241206WA0341.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460963609_IMG20241206WA0341.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7d01",
    "name": "externalimg_1733460963640_IMG20241206WA0342.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460963640_IMG20241206WA0342.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7d02",
    "name": "externalimg_1733460963644_IMG20241206WA0343.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460963644_IMG20241206WA0343.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283e3cfae933db22a7d03",
    "name": "externalimg_1733460963681_IMG20241206WA0346.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460963681_IMG20241206WA0346.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "675283f5cfae933db22a7d90",
    "name": "externalimg_1733460981012_IMG20241206WA0313.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460981012_IMG20241206WA0313.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d91",
    "name": "externalimg_1733460981023_IMG20241206WA0314.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460981023_IMG20241206WA0314.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d92",
    "name": "externalimg_1733460981031_IMG20241206WA0315.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460981031_IMG20241206WA0315.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d93",
    "name": "externalimg_1733460981061_IMG20241206WA0316.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460981061_IMG20241206WA0316.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d94",
    "name": "externalimg_1733460981067_IMG20241206WA0317.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalimg_1733460981067_IMG20241206WA0317.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d95",
```

```
    "name": "externalImg_1733460981103_IMG20241206WA0318.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460981103_IMG20241206WA0318.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d96",
    "name": "externalImg_1733460981107_IMG20241206WA0319.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460981107_IMG20241206WA0319.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d97",
    "name": "externalImg_1733460981141_IMG20241206WA0320.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460981141_IMG20241206WA0320.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d98",
    "name": "externalImg_1733460981146_IMG20241206WA0321.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460981146_IMG20241206WA0321.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d99",
    "name": "externalImg_1733460981173_IMG20241206WA0322.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460981173_IMG20241206WA0322.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d9a",
    "name": "externalImg_1733460981179_IMG20241206WA0323.jpg",
```

```
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460981179_IMG20241206WA0323.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d9b",
    "name": "externallmg_1733460981218_IMG20241206WA0324.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460981218_IMG20241206WA0324.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d9c",
    "name": "externallmg_1733460981223_IMG20241206WA0325.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460981223_IMG20241206WA0325.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d9d",
    "name": "externallmg_1733460981261_IMG20241206WA0326.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460981261_IMG20241206WA0326.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d9e",
    "name": "externallmg_1733460981267_IMG20241206WA0327.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460981267_IMG20241206WA0327.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675283f5cfae933db22a7d9f",
    "name": "externallmg_1733460981306_IMG20241206WA0328.jpg",
    "path": "cases/672c99bf52140a502a6a2432/
externallmg_1733460981306_IMG20241206WA0328.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283f5cfae933db22a7da0",
  "name": "externalImg_1733460981311_IMG20241206WA0347.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460981311_IMG20241206WA0347.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675283f5cfae933db22a7da1",
  "name": "externalImg_1733460981373_IMG20241206WA0348.jpg",
  "path": "cases/672c99bf52140a502a6a2432/
externalImg_1733460981373_IMG20241206WA0348.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-07T10:43:11.565Z",
"updatedAt": "2024-12-06T05:04:27.702Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "65dee3f79a876858ab30487f",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Land and Building No. Ground Floor, Plot No. A-15-1,2,
Village - Kamble, Mahad, Taluka - Mahad, District - Mahad",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Shree Hari Chemicals ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
```

"relationWithOwner": "self",  
"reald": "",  
"siteVisitContactNo": "9821381615"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			