

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8fa"
    },
    "firstName": "Amrish Kumar",
    "type": "CREDITOFFICER",
    "_id": "659294c9545844510d0e60d7",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "8757380668",
    "email": "1agmmums1067@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "110000000",
    "discussWithPerson": "Amrish Kumar",
    "expectedFees": 55000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8fa",
  "branchCode": "000018",
  "type": "BRANCH",
  "name": "Nariman Point Branch",
  "email": "agmmums1067@centralbank.co.in",
  "mobileNo": "(+91-22) 66387501",
  "alternateMobileNo": "",
  "address": "Chandermukhi, Ground Floor, Barrister Rajni Patel Marg, Mahatma Phule
Nagar, Nariman Point, Mumbai - 400 021, State - Maharashtra, Country - India.",
  "ledgerName": "CENTRAL BANK OF INDIA - NARIMAN POINT",
  "fax": "(+91-22)66361919, 22852657",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
```

```
"latitude": "19.41763518174726",
"longitude": "72.86449313812587"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86449313812587,
    19.41763518174726
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "WALIV",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "3",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "PALGHAR",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "VASAI",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3",
```

```
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "HANSA BUILDING",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "DHUMAL NAGAR",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "VASAI EAST",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```



```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "672de07b0db8518c410fe079",
"ownerName": "Deepak Babulal Trivedi ",
"ownerPhoneNo": "7506140005",
"appAddress": "plot No 03\nBuilding no 3\nDhamal Nagar \nwaliv \nThane 401208\n",
"remark": "contact Mehul \n9529259889",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/672de07b0db8518c410fe079/
document_1731059724465_1731059719752_VASAI_AGREEMENT.pdf",
    "fileName":
"document_1731059724465_1731059719752_VASAI_AGREEMENT.pdf",
    "id": "926514",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Fri Nov 08 2024 09:57:15 GMT+0000 (Coordinated Universal Time)"
  },
}
```

```
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/672de07b0db8518c410fe079/
document_1731059783178_1731059781354_VASAI_CHAIN_AGGREMENT.pdf",
  "fileName":
"document_1731059783178_1731059781354_VASAI_CHAIN_AGGREMENT.pdf",
  "id": "593502",
  "uploadedBy": "62727444afd7d55eddee092c",
  "createdAt": "Fri Nov 08 2024 09:57:15 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/672de07b0db8518c410fe079/document_1731059810563_17310598
07446_PLAN_APPROVAL_LETTER_UMIYA_GARMENTS.pdf",
  "fileName": "document_1731059810563_1731059807446_PLAN_APPROVAL_LET
TER_UMIYA_GARMENTS.pdf",
  "id": "220372",
  "uploadedBy": "62727444afd7d55eddee092c",
  "createdAt": "Fri Nov 08 2024 09:57:15 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012254",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "353401",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Nov 08 2024 09:57:15 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Deepak Babulal Trivedi ",
    "phone": "7506140005",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "989257"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "672f384c661d798c171b5a59",
    "name": "externallmg_1731147562472_1731147556189_image_0.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147562472_1731147556189_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "672f384c661d798c171b5a5a",
    "name": "externallmg_1731147563750_1731147556189_image_1.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147563750_1731147556189_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "672f384c661d798c171b5a5b",
    "name": "externallmg_1731147572041_1731147556189_image_2.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147572041_1731147556189_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "672f384c661d798c171b5a5c",
    "name": "externallmg_1731147578435_1731147556189_image_3.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147578435_1731147556189_image_3.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a5d",
  "name": "externallmg_1731147586835_1731147556189_image_4.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147586835_1731147556189_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a5e",
  "name": "externallmg_1731147597845_1731147556189_image_5.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147597845_1731147556189_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a5f",
  "name": "externallmg_1731147598341_1731147556189_image_6.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147598341_1731147556189_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a60",
  "name": "externallmg_1731147603210_1731147556189_image_7.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147603210_1731147556189_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a61",
  "name": "externallmg_1731147616776_1731147556189_image_8.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147616776_1731147556189_image_8.jpeg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "672f384c661d798c171b5a62",
      "name": "externallmg_1731147619990_1731147556189_image_9.jpeg",
      "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147619990_1731147556189_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "672f384c661d798c171b5a63",
      "name": "externallmg_1731147650600_1731147556189_image_10.jpeg",
      "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147650600_1731147556189_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "672f384c661d798c171b5a64",
      "name": "externallmg_1731147654515_1731147556189_image_11.jpeg",
      "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147654515_1731147556189_image_11.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "672f384c661d798c171b5a65",
      "name": "externallmg_1731147667005_1731147556189_image_12.jpeg",
      "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147667005_1731147556189_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "672f384c661d798c171b5a66",
      "name": "externallmg_1731147688631_1731147556189_image_13.jpeg",
      "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147688631_1731147556189_image_13.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a67",
  "name": "externallmg_1731147742972_1731147556189_image_14.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147742972_1731147556189_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a68",
  "name": "externallmg_1731147770004_1731147556189_image_15.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147770004_1731147556189_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a69",
  "name": "externallmg_1731147819987_1731147556189_image_16.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147819987_1731147556189_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a6a",
  "name": "externallmg_1731147836048_1731147556189_image_17.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147836048_1731147556189_image_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "672f384c661d798c171b5a6b",
  "name": "externallmg_1731147840843_1731147556189_image_18.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147840843_1731147556189_image_18.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "672f384c661d798c171b5a6c",
    "name": "externallmg_1731147850862_1731147556189_image_19.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147850862_1731147556189_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107daa",
    "name": "externallmg_1731147908991_1731147905332_image_0.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147908991_1731147905332_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107dab",
    "name": "externallmg_1731147910234_1731147905332_image_1.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147910234_1731147905332_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107dac",
    "name": "externallmg_1731147911771_1731147905332_image_2.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147911771_1731147905332_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107dad",
    "name": "externallmg_1731147914254_1731147905332_image_3.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147914254_1731147905332_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "672f389c0db8518c41107dae",
  "name": "externallmg_1731147914601_1731147905332_image_4.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147914601_1731147905332_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672f389c0db8518c41107daf",
  "name": "externallmg_1731147916178_1731147905332_image_5.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147916178_1731147905332_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672f389c0db8518c41107db0",
  "name": "externallmg_1731147916808_1731147905332_image_6.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147916808_1731147905332_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672f389c0db8518c41107db1",
  "name": "externallmg_1731147917424_1731147905332_image_7.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147917424_1731147905332_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672f389c0db8518c41107db2",
  "name": "externallmg_1731147917789_1731147905332_image_8.jpeg",
  "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147917789_1731147905332_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "672f389c0db8518c41107db3",
    "name": "externallmg_1731147918299_1731147905332_image_9.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147918299_1731147905332_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107db4",
    "name": "externallmg_1731147919219_1731147905332_image_10.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147919219_1731147905332_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107db5",
    "name": "externallmg_1731147919984_1731147905332_image_11.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147919984_1731147905332_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107db6",
    "name": "externallmg_1731147920569_1731147905332_image_12.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147920569_1731147905332_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107db7",
    "name": "externallmg_1731147921173_1731147905332_image_13.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147921173_1731147905332_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107db8",
```

```
    "name": "externallmg_1731147922344_1731147905332_image_14.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147922344_1731147905332_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107db9",
    "name": "externallmg_1731147923308_1731147905332_image_15.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147923308_1731147905332_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107dba",
    "name": "externallmg_1731147923634_1731147905332_image_16.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147923634_1731147905332_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107dbb",
    "name": "externallmg_1731147923969_1731147905332_image_17.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147923969_1731147905332_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107dbc",
    "name": "externallmg_1731147924519_1731147905332_image_18.jpeg",
    "path": "cases/672de07b0db8518c410fe079/
externallmg_1731147924519_1731147905332_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672f389c0db8518c41107dbd",
    "name": "externallmg_1731147926044_1731147905332_image_19.jpeg",
```

"path": "cases/672de07b0db8518c410fe079/
externallmg_1731147926044_1731147905332_image_19.jpeg",
"orientation": "landscape"

}

],

"externalDocuments": [],

"processingDocuments": [],

"leadRemarks": [],

"audioRemarks": [],

"remarks": [],

"createdAt": "2024-11-08T09:57:15.850Z",

"updatedAt": "2024-11-09T10:25:32.633Z",

"__v": 0,

"assignmentType": {

"value": "Commercial",

"label": "Commercial"

},

"fullAddress": "Industrial Land and Building No. Ground Floor, Building No 3, Plot No.
3, HANSA BUILDING, DHUMAL NAGAR, Village - WALIV, VASAI EAST, Taluka -
VASAI, District - PALGHAR, State - Maharashtra, India",

"updatedBy": "65dee3f79a876858ab30487f",

"addressForMap": "",

"caseReferredBy": "62727444afd7d55eddee092c",

"contactPersonName": "Deepak Babulal Trivedi ",

"email": "",

"isExternal": "false",

"isUrgent": "false",

"ownershipShare": "",

"proposePurchaserName": "",

"purchaseValueAsPerDocument": "",

"relationWithOwner": "self",

"rerald": "",

"siteVisitContactNo": "7506140005"

}

Name	Length	Width	Total
------	--------	-------	-------

Composition :

Other

Composition :
