

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Abhijit",
    "type": "CREDITOFFICER",
    "_id": "66581caa2611441081269f7e",
    "lastName": "Adsul",
    "mobileNo": "",
    "workMobileNo": "9833817601",
    "email": "abhijeet.adsul@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Abhijit",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
```

```
{
  "value": "IBBI/RV/07/2018/10366",
  "label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
],
```

```
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.473527156800113",
  "longitude": "72.81967880282257"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81967880282257,
    19.473527156800113
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/11/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Naringi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mayur Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "406",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "28.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "712.5",
  "depreciatedCostOfConstruction": "5287.50",
  "depreciatedBuildingRate": "1787.5"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "44800",
  "landRate": "9310",
  "igrImage": "cases/672e1e57661d798c171ad0dc/igr_1731321648771_Image.png",
  "squareMeterGuideLineRate": "35840.00",
  "squareFeetGuideLineRate": "3330.00"
},
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "81",
  "rate": "2861.00",
  "squareFeetGuideLineRate": "2861.00",
  "squareMeterGuideLineRate": "30799.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "dateOfConstruction": {
    "fullDate": "1/1/2005",
    "date": "1",
```

```
"month": "1",
"year": "2005"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "19",
"totalLifeBuilding": "60",
"estimatedAge": "41"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1001350.00",
  "selectedBuildUpValue": "350.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5749.00",
```

```
"max": "7385.00"
},
"builtUpRateRange": {
  "min": "4791.00",
  "max": "6154.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "350.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "672e1e57661d798c171ad0dc",
"ownerName": "Sandip Duryodhan Kharat And Vanita Sandip Kharat",
"ownerPhoneNo": "9834473064",
"appAddress": "Flat no. 406, 4th floor, wing - B, Building no. 2, Mayur Apartment,
Village - Naringi, Vasai",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/672e1e57661d798c171ad0dc/
document_1731075639092_1731075637710_Adobe_Scan_Nov_08_2024.pdf",
  "fileName":
"document_1731075639092_1731075637710_Adobe_Scan_Nov_08_2024.pdf",
  "id": "127340",
  "uploadedBy": "60b7177d2ffdf65bcd65882a",
  "createdAt": "Fri Nov 08 2024 14:21:10 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012264",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "192918",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Nov 08 2024 14:21:10 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Sandip Duryodhan Kharat And Vanita Sandip Kharat",
    "phone": "9834473064",
    "ownershipShare": "",
    "email": "",
    "id": "200874"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
  },
]
```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "32.52",
"totalAreaDocument": "350.00",
"docBuiltpPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "511402"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "233.33",
    "squareMeterArea": "21.68",
    "expectedRate": "6428.66",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "280.00",
    "squareMeterArea": "26.01",
    "expectedRate": "5357.14",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "6731e11aa6ce923fcbf33a9a",
  "property": "Sainath Nagar, Virar East",
  "area": "280",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
```

```
"source": "Housing.Com",
"expectedPrice": "1500000",
"expectedRate": "6428.66",
"builtUpExpectedRate": "1500000",
"image": "cases/672e1e57661d798c171ad0dc/
indicator_1731321194231_Image.png",
"squareMeter": "26.01",
"id": "625253"
},
{
"carpetArea": {
"area": "380.00",
"squareMeterArea": "35.30",
"expectedRate": "6184.21",
"percentage": ""
},
"builtUpArea": {
"area": "456.00",
"squareMeterArea": "42.36",
"expectedRate": "5153.51",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6731e11aa6ce923fcfb33a9b",
"property": "Hariom Apartment, Virar East",
"area": "380",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Ground",
"source": "https://www.99acres.com/",
"expectedPrice": "2350000",
"expectedRate": "6184.21",
"builtUpExpectedRate": "5153.51",
"image": "cases/672e1e57661d798c171ad0dc/
indicator_1731321240785_Image.png",
"squareMeter": "35.30",
"id": "613152"
},
```

```
{
  "carpetArea": {
    "area": "233.33",
    "squareMeterArea": "21.68",
    "expectedRate": "6214.37",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "280.00",
    "squareMeterArea": "26.01",
    "expectedRate": "5178.57",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6731e11aa6ce923fcbf33a9c",
  "property": "Onkar Darshan, Sainath Nagar, Virar East",
  "area": "280",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "4",
  "source": "Index_no.2",
  "expectedPrice": "1450000",
  "expectedRate": "6214.37",
  "builtUpExpectedRate": "1450000",
  "image": "cases/672e1e57661d798c171ad0dc/
indicator_1731321316971_Image.png",
  "squareMeter": "26.01",
  "id": "404525"
},
{
  "carpetArea": {
    "area": "258.33",
    "squareMeterArea": "24.00",
    "expectedRate": "5748.46",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "310.00",
```

```
"squareMeterArea": "28.80",
"expectedRate": "4790.32",
"percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "6731e11aa6ce923fcbf33a9d",
"property": "Sainath Nagar, Virar East ",
"area": "310",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "3",
"source": "Index_no.2",
"expectedPrice": "1485000",
"expectedRate": "5748.46",
"builtUpExpectedRate": "1485000",
"image": "cases/672e1e57661d798c171ad0dc/
indicator_1731321368857_Image.png",
"squareMeter": "28.80",
"id": "944271"
},
{
  "carpetArea": {
    "area": "541.67",
    "squareMeterArea": "50.32",
    "expectedRate": "7384.57",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "650.00",
    "squareMeterArea": "60.39",
    "expectedRate": "6153.85",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```

```
    },
    "printlnReport": true,
    "_id": "6731e11aa6ce923fcbf33a9e",
    "property": "Chandansar Road, Virar East",
    "area": "650",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "https://www.99acres.com/",
    "expectedPrice": "4000000",
    "expectedRate": "7384.57",
    "builtUpExpectedRate": "4000000",
    "image": "cases/672e1e57661d798c171ad0dc/
indicator_1731322124724_Image.png",
    "squareMeter": "60.39",
    "id": "307397"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df8004b",
    "name":
"externallmg_1731381228441_WhatsApp_Image_20241111_at_152652.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228441_WhatsApp_Image_20241111_at_152652.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df8004c",
    "name":
"externallmg_1731381228452_WhatsApp_Image_20241111_at_152655.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228452_WhatsApp_Image_20241111_at_152655.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df8004d",
    "name":
"externallmg_1731381228459_WhatsApp_Image_20241111_at_152656_1.jpeg",
```



```
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228459_WhatsApp_Image_20241111_at_152656_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df8004e",
    "name":
"externallmg_1731381228490_WhatsApp_Image_20241111_at_152656_2.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228490_WhatsApp_Image_20241111_at_152656_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df8004f",
    "name":
"externallmg_1731381228512_WhatsApp_Image_20241111_at_152656.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228512_WhatsApp_Image_20241111_at_152656.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df80050",
    "name":
"externallmg_1731381228517_WhatsApp_Image_20241111_at_152657_1.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228517_WhatsApp_Image_20241111_at_152657_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df80051",
    "name":
"externallmg_1731381228538_WhatsApp_Image_20241111_at_152657_2.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228538_WhatsApp_Image_20241111_at_152657_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6732c7eca4f8826d7df80052",
    "name":
"externallmg_1731381228555_WhatsApp_Image_20241111_at_152657.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228555_WhatsApp_Image_20241111_at_152657.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df80053",
    "name":
"externallmg_1731381228559_WhatsApp_Image_20241111_at_152658_1.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228559_WhatsApp_Image_20241111_at_152658_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df80054",
    "name":
"externallmg_1731381228584_WhatsApp_Image_20241111_at_152658_2.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228584_WhatsApp_Image_20241111_at_152658_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df80055",
    "name":
"externallmg_1731381228589_WhatsApp_Image_20241111_at_152658.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228589_WhatsApp_Image_20241111_at_152658.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6732c7eca4f8826d7df80056",
    "name":
"externallmg_1731381228612_WhatsApp_Image_20241111_at_152659_1.jpeg",
    "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228612_WhatsApp_Image_20241111_at_152659_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6732c7eca4f8826d7df80057",
  "name":
  "externallmg_1731381228619_WhatsApp_Image_20241111_at_152659_2.jpeg",
  "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228619_WhatsApp_Image_20241111_at_152659_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6732c7eca4f8826d7df80058",
  "name":
  "externallmg_1731381228646_WhatsApp_Image_20241111_at_152659.jpeg",
  "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228646_WhatsApp_Image_20241111_at_152659.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6732c7eca4f8826d7df80059",
  "name":
  "externallmg_1731381228652_WhatsApp_Image_20241111_at_152700.jpeg",
  "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228652_WhatsApp_Image_20241111_at_152700.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6732c7eca4f8826d7df8005a",
  "name":
  "externallmg_1731381228702_WhatsApp_Image_20241111_at_152643.jpeg",
  "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228702_WhatsApp_Image_20241111_at_152643.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6732c7eca4f8826d7df8005b",
```

```
"name":
"externallmg_1731381228720_WhatsApp_Image_20241111_at_152646.jpeg",
  "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228720_WhatsApp_Image_20241111_at_152646.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6732c7eca4f8826d7df8005c",
  "name":
"externallmg_1731381228724_WhatsApp_Image_20241111_at_152650.jpeg",
  "path": "cases/672e1e57661d798c171ad0dc/
externallmg_1731381228724_WhatsApp_Image_20241111_at_152650.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6731e12fa6ce923fcbf33aad",
    "note": "Rate verification done, pending for visit",
    "taskId": "672ed3640db8518c41100cb4",
    "createdAt": "2024-11-11T10:49:19.453Z"
  },
  {
    "createdBy": {
      "_id": "6006d4ce5080a310ac1fdcf2",
      "role": "ADMIN",
      "firstName": "Jagdish ",
      "lastName": "Bhatt",
      "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\
```

```
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "SITE_INSPECTION",
  "display": true,
  "status": true,
  "_id": "6732c796fa78fd6d3dd6e8f6",
  "note": "Additional Photos (Task Reopen)",
  "taskId": "672ed3640db8518c41100cb8",
  "createdAt": "2024-11-12T03:12:22.843Z"
}
],
"createdAt": "2024-11-08T14:21:11.022Z",
"updatedAt": "2024-11-12T03:13:48.945Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 406, 4th Floor, Building No 2, Wing - B, Mayur
Apartment, Village - Naringi",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Sandip Duryodhan Kharat And Vanita Sandip Kharat",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9834473064",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 350.00",
"flatRate": "6000",
"landOtherRate": "3500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
```

}
}

Name

Length

Width

Total

Composition :

Other

Composition :
