

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "645f0853ee6a9735bf7688e8"
    },
    "firstName": "Rajeevkumar ",
    "type": "CREDITOFFICER",
    "_id": "645f0853ee6a9735bf7688ea",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "9827114321",
    "email": "indiranagar.pune@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "645f0853ee6a9735bf7688e8",
  "name": "Indira Nagar Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903\t",
  "alternateMobileNo": "",
  "email": "indiranagar.pune@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bungalow No 23, Shree Samartha Kripa, Gurukrinear Rathachakara
Chowk,\nIndira Nagar, Nashik-422 009, State - Maharashtra,Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fc92f7ce84bf289baa53f9",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
```

```
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.943560352278187",
  "longitude": "73.75456332909756"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-11",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-11",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pathardi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Nashik",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ekta Greenville",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mumbai Agra Road",
```



```
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Radisson Blu Hotel & Spa",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "F",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "231",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```

```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422010",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  }
},
```

```

"doors": {
  "value": "Teak_Wood_/ _Glass_Door",
  "label": "Teak Wood / Glass Door"
},
"windows": {
  "value": "Wooden_frame_openable_widow_with_M._S._Grill",
  "label": "Wooden frame openable widow with M. S. Grill"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "S. No. 230",
    "west": "S. No. 287 & Dadasaheb Phalke Smarak",
    "south": "S. No. 236,235 & 232",
    "east": "S. No. 228"
  },
  "asPerDocumentAgreement": {

```

```
"north": "S. No. 230",
"west": "S. No. 287 & Dadasaheb Phalke Smarak",
"south": "S. No. 236,235 & 232",
"east": "S. No. 228"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "12 M. Road",
    "east": "E-603",
    "south": "F-601",
    "west": "G-603"
  },
  "asPerDocument": {
    "north": "12 M. Road",
    "east": "E-603",
    "south": "F-601",
    "west": "G-603"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": " Copy of Approved Building Plan Accompanying
Commencement Certificate No.B5/08/3281 Dated 04.06.2018 issued by Nashik
Municipal Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "NA",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
```

```
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "210",
  "depreciatedCostOfConstruction": "5590.00",
  "depreciatedBuildingRate": "1790"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "36000",
  "landRate": "13200",
  "igrImage": "cases/6733047164a18d994dad532/igr_1731393013910_Image.png",
  "squareMeterGuideLineRate": "37800.00",
  "squareFeetGuideLineRate": "3512.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "93",
  "rate": "3352.00",
  "squareFeetGuideLineRate": "3352.00",
  "squareMeterGuideLineRate": "36078.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Posh",
    "label": "Posh"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "6700",
  "assessmentNo": "Details Not Provided",
```

```
"taxPaidHolderName": "Details Not Provided",
"taxAmount": "Details Not Provided",
"electricityServiceConnectionNo": "Details Not Provided",
"meterCardHolderName": "Details Not Provided",
"undividedAreaOfLandAsPerSaleDeed": "NA",
"floorSpaceIndex": "as per NMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "NA",
  "negativeFactorsOfAffectMarketValue": "na"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
```

```
"year": "2017",
"fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
}
```



```
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "53",
"ageOfBuilding": "7",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "697.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
}
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6733047164a18d994dad532/
routeMap_1731395086839_Image.png",
    "routeLat": "19.943557",
    "routeLng": "73.754570",
    "stationName": "Nashik Road",
    "routeDistance": "12.2 KM",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "v7at3l",
      "name": "v7at3l",
      "image": "cases/6733047164a18d994dad532/
routeMap_1731395698427_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",

```

```
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3247790.00",
"finalValue": "3247790.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValueDocument": null,
"purchaseValueDocument": {
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1731391259498_Flat_No_603.pdf",
  "path": "cases/6733047164a18d994dad532/
document_1731391259498_Flat_No_603.pdf",
  "id": "381345",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Nov 12 2024 06:11:59 GMT+0000 (Coordinated Universal Time)",
  "documentDate": "30/10/2010",
  "amount": "1221775",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
}
```

```
"Developers": "M/s. Ekta Housing Private Ltd.",
"to": {
  "value": "buyer",
  "label": "buyer"
},
"buyer": "Shri. Kapil Ashok Narang, Sau. Anjali Ashok Narang & Sau. Priti Kapil
Narang",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "1829/2011"
},
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Nov 12 2024 08:51:47 GMT+0000 (Coordinated Universal Time)",
  "number": "2309008",
  "dayCount": "12",
  "monthCount": "93",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2337014.00",
  "selectedBuildUpValue": "697.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67330d0de5acdaa8942e6106",
      "name":
"externallmg_1731398924698_WhatsApp_Image_20240827_at_124351_PM.jpeg",
      "path": "cases/6733047164a18d994dad532/
externallmg_1731398924698_WhatsApp_Image_20240827_at_124351_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67330d0de5acdaa8942e6104",
      "name":
"externallmg_1731398924519_WhatsApp_Image_20240827_at_124351_PM_1.jpeg",
      "path": "cases/6733047164a18d994dad532/
externallmg_1731398924519_WhatsApp_Image_20240827_at_124351_PM_1.jpeg",
      "orientation": "landscape"
    }
  ],
  {
    "status": false,
    "_id": "67330d0de5acdaa8942e6106",
    "name":
"externallmg_1731398924698_WhatsApp_Image_20240827_at_124351_PM.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398924698_WhatsApp_Image_20240827_at_124351_PM.jpeg",
    "orientation": "landscape"
  }
}
```

```
    },
    {
      "status": false,
      "_id": "67330d03cc9490a85abf74de",
      "name":
"externallmg_1731398914736_WhatsApp_Image_20240827_at_124334_PM.jpeg",
      "path": "cases/6733047164a18d994dad532/
externallmg_1731398914736_WhatsApp_Image_20240827_at_124334_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67330d03cc9490a85abf74d9",
      "name":
"externallmg_1731398914646_WhatsApp_Image_20240827_at_124331_PM_1.jpeg",
      "path": "cases/6733047164a18d994dad532/
externallmg_1731398914646_WhatsApp_Image_20240827_at_124331_PM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "67330d03cc9490a85abf74da",
      "name":
"externallmg_1731398914677_WhatsApp_Image_20240827_at_124331_PM.jpeg",
      "path": "cases/6733047164a18d994dad532/
externallmg_1731398914677_WhatsApp_Image_20240827_at_124331_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "67330d03cc9490a85abf74da",
      "name": "Living Room",
      "path": "cases/6733047164a18d994dad532/
externallmg_1731398914677_WhatsApp_Image_20240827_at_124331_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67330d03cc9490a85abf74d9",
      "name": "Living Room",
      "path": "cases/6733047164a18d994dad532/
externallmg_1731398914646_WhatsApp_Image_20240827_at_124331_PM_1.jpeg",
```



```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67330d03cc9490a85abf74ea",
    "name": "Living Room",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914873_WhatsApp_Image_20240827_at_124349_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67330d03cc9490a85abf74e3",
    "name": "Kitchen",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914805_WhatsApp_Image_20240827_at_124336_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67330d03cc9490a85abf74e4",
    "name": "Bedroom",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914808_WhatsApp_Image_20240827_at_124347_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67330d03cc9490a85abf74e1",
    "name": "Balcony",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914781_WhatsApp_Image_20240827_at_124336_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67330d03cc9490a85abf74e6",
    "name": "Balcony",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914829_WhatsApp_Image_20240827_at_124348_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67330d03cc9490a85abf74df",
    "name": "Balcony",
```

```
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914757_WhatsApp_Image_20240827_at_124335_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67330d03cc9490a85abf74e2",
    "name": "Passage",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914785_WhatsApp_Image_20240827_at_124336_PM_2.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5435.00",
    "max": "7603.00"
  },
  "builtUpRateRange": {
    "min": "4529.00",
    "max": "6336.00"
  },
  "saleableRateRange": {
    "min": "3775.00",
    "max": "5280.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "581.00",
"empanelmentNo": [
  "NZO/CR/22-23/39"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6733047164a18d994dad532",
"ownerName": "Shri. Kapil Ashok Narang, Sau. Anjali Ashok Narang & Sau. Priti Kapil Narang",
"ownerPhoneNo": "9820891386",
"fullAddress": "Residential Flat No. 604, 6th Floor, Wing - F, Ekta Greenville, Near Radisson Blu Hotel & Spa, Mumbai Agra Road, Village - Pathardi, Taluka - Nashik, District - Nashik, Nashik, 422010, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "04/06/2018",
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "B5/08/3281"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1731391633753_ekta_Greenville_plan.pdf",
    "path": "cases/6733047164a18d994dad532/document_1731391633753_ekta_Greenville_plan.pdf",
    "id": "958237",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Nov 12 2024 06:11:59 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "27/07/2017",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "Javak No. NRV /B5 /19461 / 3208"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1731391751728_1066742.pdf",
  "path": "cases/6733047164a18d994dad532/
document_1731391751728_1066742.pdf",
  "id": "384521",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Nov 12 2024 06:11:59 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "30/10/2010",
    "amount": "1161775",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "M/s. Ekta Housing Private Ltd.",
    "to": {
      "value": "buyer",
      "label": "buyer"
    },
    "buyer": "Shri. Kapil Ashok Narang, Sau. Anjali Ashok Narang & Sau. Priti Kapil
Narang",
```

```
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "12044/2010"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1731399296255_604_FLAT_.pdf",
  "path": "cases/6733047164a18d994dad532/
document_1731399296255_604_FLAT_.pdf",
  "id": "442371",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Nov 12 2024 08:15:08 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "012303",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "107209",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 12 2024 06:11:59 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri. Kapil Ashok Narang, Sau. Anjali Ashok Narang & Sau. Priti Kapil
Narang",
    "phone": "9820891386",
    "ownershipShare": "",
    "email": "",
    "id": "327768"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "186773",
  "name": "Living Room",
  "length": "13.67",
  "length1": "13",
  "length2": "8",
  "width": "10.75",
  "width1": "10",
  "width2": "9",
  "totalArea": "146.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "146.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "12.33",
  "length1": "12",
  "length2": "4",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "120.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
```



```

    "totalArea": "61.75",
    "images": [],
    "extraAreas": [],
    "finalArea": "61.75"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "3",
    "name": "WC",
    "length": "5.08",
    "length1": "5",
    "length2": "1",
    "width": "6.67",
    "width1": "6",
    "width2": "8",
    "totalArea": "33.89",
    "images": [],
    "extraAreas": [],
    "finalArea": "33.89"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "4",
    "name": "Toilet",
    "length": "10.33",
    "length1": "10",
    "length2": "4",
    "width": "6.50",
    "width1": "6",
    "width2": "6",
    "totalArea": "67.17",
    "images": [],
    "extraAreas": [],
    "finalArea": "67.17"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "5",
"name": "Passage",
"length": "4.00",
"length1": "4",
"length2": "00",
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "32.00",
"images": [],
"extraAreas": [],
"finalArea": "32.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Dining",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "60.67",
  "images": [],
  "finalArea": "60.67",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "25.35",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "25.35"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Balcony",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "48.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "48.21"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "53.98",
    "totalAreaDocument": "581",
    "docBultupPercentage": "20",
    "docFinalBultUp": "697.20",
    "docFinalBultUpSquareMeter": "64.77",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "382732"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "644.00",
      "squareMeterArea": "59.83",
      "expectedRate": "5434.78",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "772.80",
      "squareMeterArea": "71.80",
      "expectedRate": "4528.99",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "927.36",
      "squareMeterArea": "86.15",
      "expectedRate": "3774.15",
      "percentage": "20"
    },
    "printlnReport": true,
    "_id": "6732f6152612196d3c3bad25",
    "property": "Flat",
    "area": "644",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "7",
    "source": "magic_bricks",
    "expectedPrice": "3500000",
    "expectedRate": "5434.78",
    "builtUpExpectedRate": "4528.99",
    "image": "cases/6733047164a18d994dad532/
indicator_1731392897391_Image.png",
    "squareMeter": "59.83",
    "id": "302061"
  },
  {
    "carpetArea": {
      "area": "513.00",
      "squareMeterArea": "47.66",
      "expectedRate": "7602.34",
      "percentage": ""
    },
  },

```

```
"builtUpArea": {
  "area": "615.60",
  "squareMeterArea": "57.19",
  "expectedRate": "6335.28",
  "percentage": "20"
},
"saleableArea": {
  "area": "738.72",
  "squareMeterArea": "68.63",
  "expectedRate": "5279.40",
  "percentage": "20"
},
"printInReport": true,
"_id": "6732f6152612196d3c3bad26",
"property": "Flat",
"area": "513",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "3",
"source": "magic_bricks",
"expectedPrice": "3900000",
"expectedRate": "7602.34",
"builtUpExpectedRate": "6335.28",
"image": "cases/6733047164a18d994dad532/
indicator_1731392930196_Image.png",
"squareMeter": "47.66",
"id": "901217"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d03cc9490a85abf74d9",
    "name":
"externallmg_1731398914646_WhatsApp_Image_20240827_at_124331_PM_1.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914646_WhatsApp_Image_20240827_at_124331_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d03cc9490a85abf74da",
```

```
    "name":
"externallmg_1731398914677_WhatsApp_Image_20240827_at_124331_PM.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914677_WhatsApp_Image_20240827_at_124331_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74db",
  "name":
"externallmg_1731398914681_WhatsApp_Image_20240827_at_124332_PM.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914681_WhatsApp_Image_20240827_at_124332_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74dc",
  "name":
"externallmg_1731398914697_WhatsApp_Image_20240827_at_124333_PM.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914697_WhatsApp_Image_20240827_at_124333_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74dd",
  "name":
"externallmg_1731398914722_WhatsApp_Image_20240827_at_124334_PM_1.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914722_WhatsApp_Image_20240827_at_124334_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74de",
  "name":
"externallmg_1731398914736_WhatsApp_Image_20240827_at_124334_PM.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914736_WhatsApp_Image_20240827_at_124334_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74df",
  "name":
"externallmg_1731398914757_WhatsApp_Image_20240827_at_124335_PM_1.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914757_WhatsApp_Image_20240827_at_124335_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74e0",
  "name":
"externallmg_1731398914762_WhatsApp_Image_20240827_at_124335_PM.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914762_WhatsApp_Image_20240827_at_124335_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74e1",
  "name":
"externallmg_1731398914781_WhatsApp_Image_20240827_at_124336_PM_1.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914781_WhatsApp_Image_20240827_at_124336_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74e2",
  "name":
"externallmg_1731398914785_WhatsApp_Image_20240827_at_124336_PM_2.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914785_WhatsApp_Image_20240827_at_124336_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74e3",
  "name":
"externallmg_1731398914805_WhatsApp_Image_20240827_at_124336_PM.jpeg",
```

```
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914805_WhatsApp_Image_20240827_at_124336_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d03cc9490a85abf74e4",
    "name":
"externallmg_1731398914808_WhatsApp_Image_20240827_at_124347_PM_1.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914808_WhatsApp_Image_20240827_at_124347_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d03cc9490a85abf74e5",
    "name":
"externallmg_1731398914826_WhatsApp_Image_20240827_at_124347_PM.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914826_WhatsApp_Image_20240827_at_124347_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d03cc9490a85abf74e6",
    "name":
"externallmg_1731398914829_WhatsApp_Image_20240827_at_124348_PM_1.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914829_WhatsApp_Image_20240827_at_124348_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d03cc9490a85abf74e7",
    "name":
"externallmg_1731398914847_WhatsApp_Image_20240827_at_124348_PM.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398914847_WhatsApp_Image_20240827_at_124348_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "67330d03cc9490a85abf74e8",
  "name":
"externallmg_1731398914850_WhatsApp_Image_20240827_at_124349_PM_1.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914850_WhatsApp_Image_20240827_at_124349_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74e9",
  "name":
"externallmg_1731398914868_WhatsApp_Image_20240827_at_124349_PM_2.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914868_WhatsApp_Image_20240827_at_124349_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74ea",
  "name":
"externallmg_1731398914873_WhatsApp_Image_20240827_at_124349_PM.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914873_WhatsApp_Image_20240827_at_124349_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d03cc9490a85abf74eb",
  "name":
"externallmg_1731398914899_WhatsApp_Image_20240827_at_124350_PM_1.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398914899_WhatsApp_Image_20240827_at_124350_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67330d0de5acdaa8942e6103",
  "name":
"externallmg_1731398922826_WhatsApp_Image_20240827_at_124350_PM.jpeg",
  "path": "cases/6733047164a18d994dad532/
externallmg_1731398922826_WhatsApp_Image_20240827_at_124350_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d0de5acdaa8942e6104",
    "name":
"externallmg_1731398924519_WhatsApp_Image_20240827_at_124351_PM_1.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398924519_WhatsApp_Image_20240827_at_124351_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d0de5acdaa8942e6105",
    "name":
"externallmg_1731398924620_WhatsApp_Image_20240827_at_124351_PM_2.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398924620_WhatsApp_Image_20240827_at_124351_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67330d0de5acdaa8942e6106",
    "name":
"externallmg_1731398924698_WhatsApp_Image_20240827_at_124351_PM.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731398924698_WhatsApp_Image_20240827_at_124351_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673310c05064deaad8e21ab0",
    "name":
"externallmg_1731399871464_WhatsApp_Image_20240827_at_124330_PM.jpeg",
    "path": "cases/6733047164a18d994dad532/
externallmg_1731399871464_WhatsApp_Image_20240827_at_124330_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
```

```
    "originalname": "calc.xlsx",
    "filename": "1731393065953_calc.xlsx",
    "path": "cases/6733047164a18d994dad532/
processingDocuments/1731393065953_calc.xlsx",
    "size": "406698",
    "createdAt": "Tue Nov 12 2024 06:31:06 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "BOI - Kapil Narang flat no 604.pdf",
    "filename": "1731400999284_BOI__Kapil_Narang_flat_no_604.pdf",
    "path": "cases/6733047164a18d994dad532/
processingDocuments/1731400999284_BOI__Kapil_Narang_flat_no_604.pdf",
    "size": "5284604",
    "createdAt": "Tue Nov 12 2024 08:43:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-12T07:32:01.481Z",
"updatedAt": "2024-11-12T08:56:08.156Z",
"__v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Shri. Kapil Ashok Narang, Sau. Anjali Ashok Narang & Sau.
Priti Kapil Narang",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9820891386",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 581.00",
"flatRate": "5800",
```

```
"landOtherRate": "3800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Toilet + Passage
+ Dining + 2 Balcony",
"carpetTotal": "596.21",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "715.45",
"finalCarpetArea": "596.21",
"finalSalableArea": "787.00",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Nov 12 2024 06:31:29 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-11-11",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"invoiceId": null
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	13'8"	10'9"	146.92
Bedroom	12'4"	9'9"	120.25
Kitchen	9'6"	6'6"	61.75
WC	5'1"	6'8"	33.89
Toilet	10'4"	6'6"	67.17
Passage	4'00"	8'00"	32.00
Dining	9'4"	6'6"	60.67
Balcony	4'2"	6'1"	25.35
Balcony	7'5"	6'6"	48.21
Other Composition :			