

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
```

```
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.980913",
  "longitude": "73.726488"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "26/10/2024 12:00 am"
    },
    {
      "dateTime": "26/10/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-26",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-26",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Satpur",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Anuveena Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bajrang Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Ambad Satpur Link Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```



```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "465/3/4",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422010",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood",
    "label": "Proposed Teak wood"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "18.00 Meter Wide DP Road",
    "west": "Survey No.464",
    "south": "Survey No.441",
    "east": "Plot No.2"
  },
  "asPerDocumentAgreement": {
    "north": "18.00 Meter Wide DP Road",
    "west": "Survey No.464",
    "south": "Survey No.441",
    "east": "Plot No.2"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Staircase & Flat No.205",
      "east": "Side Marginal Space",
      "south": "Side Marginal Space",
      "west": "Lift"
    },
    "asPerDocument": {
```

```
    "north": "Staircase & Flat No.205",
    "east": "Side Marginal Space",
    "south": "Side Marginal Space",
    "west": "Lift"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": " Copy of Building Plan Document No.B1/BP/12 Dated
25.06.2024,Issued by Nashik Municipal Corporation,Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
}
```

```
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "27000",
  "landRate": "4600",
  "igrImage": "cases/671c99e303856193623425f1/igr_1729928159794_Image.png",
  "squareMeterGuideLineRate": "27000.00",
  "squareFeetGuideLineRate": "2508.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "27000.00",
  "squareMeterGuideLineRate": "27000.00",
  "squareFeetGuideLineRate": "2508.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "NA",
```

```
"negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2026",
    "fullDate": "1/1/2026"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Yes",
  "label": "Yes"
},
"sewerageSystem": {
  "value": "Proposed_Concealed_",
  "label": "Proposed Concealed "
},
"walls": {
  "value": "PROPOSED,_Yes",
  "label": "PROPOSED, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "PROPOSED,_Yes",
```



```
"label": "PROPOSED, Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "528.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/671c99e303856193623425f1/
routeMap_1729929799714_Image.png",
    "routeLat": "19.980913",
    "routeLng": "73.726488",
    "stationName": "Nashik Road",
    "routeDistance": "16.6",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
```

```
"coordinates": [
  0,
  0
],
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "n0pt6r",
    "name": "n0pt6r",
    "image": "cases/671c99e303856193623425f1/
routeMap_1729929725875_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```

```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3024000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValue": "0",
"finalValue": "3024000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Oct 26 2024 09:14:44 GMT+0000 (Coordinated Universal Time)",
  "number": "2308862",
  "dayCount": "9",
  "monthCount": "402",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "6",
    "percentage": "34.285714285714285",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "6",
  "percentage": "6.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "4",
  "percentage": "4.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "4",
  "percentage": "2.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "56.29",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "1324224.00",
  "selectedBuildUpValue": "528.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "671ca25c857cdb68fa98afb6",
      "name":
"externallmg_1729929817739_WhatsApp_Image_20241025_at_13310_PM.jpeg",
      "path": "cases/671c99e303856193623425f1/
externallmg_1729929817739_WhatsApp_Image_20241025_at_13310_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "671ca25c857cdb68fa98afae",
      "name":
"externallmg_1729929813061_WhatsApp_Image_20241025_at_13307_PM.jpeg",
      "path": "cases/671c99e303856193623425f1/
externallmg_1729929813061_WhatsApp_Image_20241025_at_13307_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  {
    "status": false,
    "_id": "671ca25c857cdb68fa98afaf",
    "name":
"externallmg_1729929813106_WhatsApp_Image_20241025_at_13308_PM_1.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929813106_WhatsApp_Image_20241025_at_13308_PM_1.jpeg",
    "orientation": "landscape"
  }
}
```

```
    },
    {
      "status": false,
      "_id": "671ca25c857cdb68fa98afb0",
      "name":
"externallmg_1729929813134_WhatsApp_Image_20241025_at_13308_PM_2.jpeg",
      "path": "cases/671c99e303856193623425f1/
externallmg_1729929813134_WhatsApp_Image_20241025_at_13308_PM_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "671ca25c857cdb68fa98afac",
      "name":
"externallmg_1729929813014_WhatsApp_Image_20241025_at_13305_PM.jpeg",
      "path": "cases/671c99e303856193623425f1/
externallmg_1729929813014_WhatsApp_Image_20241025_at_13305_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "671ca25c857cdb68fa98afab",
      "name":
"externallmg_1729929813000_WhatsApp_Image_20241025_at_13302_PM.jpeg",
      "path": "cases/671c99e303856193623425f1/
externallmg_1729929813000_WhatsApp_Image_20241025_at_13302_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "671ca25c857cdb68fa98afaa",
      "name":
"externallmg_1729929812970_WhatsApp_Image_20241025_at_13300_PM.jpeg",
      "path": "cases/671c99e303856193623425f1/
externallmg_1729929812970_WhatsApp_Image_20241025_at_13300_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "671ca25c857cdb68fa98afa9",
      "name":
"externallmg_1729929812926_WhatsApp_Image_20241025_at_13258_PM.jpeg",
      "path": "cases/671c99e303856193623425f1/
externallmg_1729929812926_WhatsApp_Image_20241025_at_13258_PM.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "status": false,
  "_id": "671ca25c857cdb68fa98afb2",
  "name":
"externallmg_1729929813188_WhatsApp_Image_20241025_at_13309_PM_1.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929813188_WhatsApp_Image_20241025_at_13309_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "671ca25c857cdb68fa98afb3",
  "name":
"externallmg_1729929813195_WhatsApp_Image_20241025_at_13309_PM_2.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929813195_WhatsApp_Image_20241025_at_13309_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "671ca25c857cdb68fa98afb4",
  "name":
"externallmg_1729929813244_WhatsApp_Image_20241025_at_13309_PM.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929813244_WhatsApp_Image_20241025_at_13309_PM.jpeg",
  "orientation": "landscape"
}
],
"compositionImages": [],
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "4359.00",
    "max": "5375.00"
  },
  "builtUpRateRange": {
    "min": "3633.00",
    "max": "4480.00"
  },
  "saleableRateRange": {
    "min": "3027.00",
    "max": "3733.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```



```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "480.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "671c99e303856193623425f1",
"ownerName": "Shri.Akash Dhondiram Jagdale",
"ownerPhoneNo": "8956585003",
"fullAddress": "Residential Flat No. 201, 2nd Floor, Anuveena Heights, Plot No. 1,
Bajrang Nagar, Ambad Satpur Link Road, Village - Satpur, Taluka - Nashik , District -
Nashik , 422010, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "23/10/2024",
      "from": {
        "value": "Seller",
        "label": "Seller"
      }
    }
  }
]
```

```
},
"Seller": "Sau.Vaishali Sushil Anturlikar & Shri.Sushil Suresh Anturlikar",
"to": {
  "value": "The_Apartment_Owner",
  "label": "The Apartment Owner"
},
"The_Apartment_Owner": "Shri.Akash Dhondiram Jagdale",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "11790"
},
"isHardCopy": false,
"displayStatus": true,
"id": "296537",
"path": "cases/671c99e303856193623425f1/
document_1729927365324_Agreement.pdf",
"fileName": "document_1729927365324_Agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "25/06/2024",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "LND/BP/B1/BP/12"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1729927438266_commencement_certificate.pdf",
  "path": "cases/671c99e303856193623425f1/
document_1729927438266_commencement_certificate.pdf",
  "id": "769786",
  "uploadedBy": "636a1ad14d42487767af3f91",
  "createdAt": "Sat Oct 26 2024 07:27:31 GMT+0000 (Coordinated Universal Time)"
},
```

```
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "documentDate": "25/06/2024",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "B1/BP/12"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1729927517432_Plan.pdf",
  "path": "cases/671c99e303856193623425f1/document_1729927517432_Plan.pdf",
  "id": "356288",
  "uploadedBy": "636a1ad14d42487767af3f91",
  "createdAt": "Sat Oct 26 2024 07:27:31 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "21/10/2024",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51600077677"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1729927612444_Agreement.pdf",
  "path": "cases/671c99e303856193623425f1/
document_1729927612444_Agreement.pdf",
```

```
"id": "709069",
"uploadedBy": "636a1ad14d42487767af3f91",
"createdAt": "Sat Oct 26 2024 07:27:31 GMT+0000 (Coordinated Universal Time)"
},
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "012105",
"createdBy": "636a1ad14d42487767af3f91",
"caseHistory": [
  {
    "id": "838989",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 26 2024 07:27:31 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri.Akash Dhondiram Jagdale",
    "phone": "8956585003",
    "ownershipShare": "",
    "email": "",
    "id": "770440"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "44.59",
    "totalAreaDocument": "480",
  }
]
```

```
"docBuiltpPercentage": "10",
"docFinalBuiltp": "528.00",
"docFinalBuiltpSquareMeter": "49.05",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "980738"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "734.17",
"squareMeterArea": "68.21",
"expectedRate": "4358.66",
"percentage": ""
},
"builtUpArea": {
"area": "881.00",
"squareMeterArea": "81.85",
"expectedRate": "3632.24",
"percentage": "20"
},
"saleableArea": {
"area": "1057.20",
"squareMeterArea": "98.22",
"expectedRate": "3026.86",
"percentage": "20"
},
"printlnReport": true,
"_id": "671c9c28857cdb68fa98a7cd",
"property": "Flat",
"area": "881",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "3200000",
"expectedRate": "4358.66",
"builtUpExpectedRate": "3200000",
"image": "cases/671c99e303856193623425f1/
indicator_1729927884976_Image.png",
"squareMeter": "81.85",
```

```
"id": "379323"
},
{
  "carpetArea": {
    "area": "855.83",
    "squareMeterArea": "79.51",
    "expectedRate": "5374.90",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1027.00",
    "squareMeterArea": "95.41",
    "expectedRate": "4479.07",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1232.40",
    "squareMeterArea": "114.49",
    "expectedRate": "3732.55",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "671c9c28857cdb68fa98a7ce",
  "property": "Flat",
  "area": "1027",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4600000",
  "expectedRate": "5374.90",
  "builtUpExpectedRate": "4600000",
  "image": "cases/671c99e303856193623425f1/
indicator_1729928006043_Image.png",
  "squareMeter": "95.41",
  "id": "229221"
},
{
  "carpetArea": {
    "area": "708.33",
    "squareMeterArea": "65.81",
    "expectedRate": "5082.38",
    "percentage": ""
  },
  },
```



```
"builtUpArea": {
  "area": "850.00",
  "squareMeterArea": "78.97",
  "expectedRate": "4235.29",
  "percentage": "20"
},
"saleableArea": {
  "area": "1020.00",
  "squareMeterArea": "94.76",
  "expectedRate": "3529.41",
  "percentage": "20"
},
"printInReport": true,
"_id": "671c9c28857cdb68fa98a7cf",
"property": "Flat",
"area": "850",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "3600000",
"expectedRate": "5082.38",
"builtUpExpectedRate": "3600000",
"image": "cases/671c99e303856193623425f1/
indicator_1729928105612_Image.png",
"squareMeter": "78.97",
"id": "187721"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671ca25c857cdb68fa98afa9",
  "name":
"externallmg_1729929812926_WhatsApp_Image_20241025_at_13258_PM.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929812926_WhatsApp_Image_20241025_at_13258_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671ca25c857cdb68fa98afaa",
```

```
    "name":
"externallmg_1729929812970_WhatsApp_Image_20241025_at_13300_PM.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929812970_WhatsApp_Image_20241025_at_13300_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671ca25c857cdb68fa98afab",
    "name":
"externallmg_1729929813000_WhatsApp_Image_20241025_at_13302_PM.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929813000_WhatsApp_Image_20241025_at_13302_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671ca25c857cdb68fa98afac",
    "name":
"externallmg_1729929813014_WhatsApp_Image_20241025_at_13305_PM.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929813014_WhatsApp_Image_20241025_at_13305_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671ca25c857cdb68fa98afae",
    "name":
"externallmg_1729929813061_WhatsApp_Image_20241025_at_13307_PM.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929813061_WhatsApp_Image_20241025_at_13307_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671ca25c857cdb68fa98afaf",
    "name":
"externallmg_1729929813106_WhatsApp_Image_20241025_at_13308_PM_1.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929813106_WhatsApp_Image_20241025_at_13308_PM_1.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671ca25c857cdb68fa98afb0",
  "name":
"externallmg_1729929813134_WhatsApp_Image_20241025_at_13308_PM_2.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929813134_WhatsApp_Image_20241025_at_13308_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671ca25c857cdb68fa98afb1",
  "name":
"externallmg_1729929813141_WhatsApp_Image_20241025_at_13308_PM.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929813141_WhatsApp_Image_20241025_at_13308_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671ca25c857cdb68fa98afb2",
  "name":
"externallmg_1729929813188_WhatsApp_Image_20241025_at_13309_PM_1.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929813188_WhatsApp_Image_20241025_at_13309_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671ca25c857cdb68fa98afb3",
  "name":
"externallmg_1729929813195_WhatsApp_Image_20241025_at_13309_PM_2.jpeg",
  "path": "cases/671c99e303856193623425f1/
externallmg_1729929813195_WhatsApp_Image_20241025_at_13309_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671ca25c857cdb68fa98afb4",
  "name":
"externallmg_1729929813244_WhatsApp_Image_20241025_at_13309_PM.jpeg",
```

```
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929813244_WhatsApp_Image_20241025_at_13309_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671ca25c857cdb68fa98afb5",
    "name":
"externallmg_1729929813250_WhatsApp_Image_20241025_at_13310_PM_2.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929813250_WhatsApp_Image_20241025_at_13310_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671ca25c857cdb68fa98afb6",
    "name":
"externallmg_1729929817739_WhatsApp_Image_20241025_at_13310_PM.jpeg",
    "path": "cases/671c99e303856193623425f1/
externallmg_1729929817739_WhatsApp_Image_20241025_at_13310_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Akash Jagdale.xlsx",
    "filename": "1729930014250_Akash_Jagdale.xlsx",
    "path": "cases/671c99e303856193623425f1/
processingDocuments/1729930014250_Akash_Jagdale.xlsx",
    "size": "753460",
    "createdAt": "Sat Oct 26 2024 08:06:56 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  },
  {
    "originalname": "BOB - Shri.Akash Dhondiram Jagdale.pdf",
    "filename": "1729930014752_BOB__ShriAkash__Dhondiram_Jagdale.pdf",
    "path": "cases/671c99e303856193623425f1/
processingDocuments/1729930014752_BOB__ShriAkash__Dhondiram_Jagdale.pdf",
    "size": "7123100",
    "createdAt": "Sat Oct 26 2024 08:06:56 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  }
],
```

```
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-26T07:27:31.459Z",
"updatedAt": "2024-10-26T09:22:47.095Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"contactPersonName": "Shri.Akash Dhondiram Jagdale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "2800000",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "8956585003",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 480.00",
"flatRate": "6300",
"landOtherRate": "4300",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
```

```
"label": "Free Hold",
"value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Sat Oct 26 2024 07:41:35 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-10-26"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			