

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6732d8f6a4f8826d7df80508"
    },
    "firstName": "Arjun",
    "type": "CREDITOFFICER",
    "_id": "6732d9172612196d3c3b7d19",
    "email": "arjun.parab@cosmosbank.in",
    "lastName": "Parab",
    "mobileNo": "",
    "workMobileNo": "9820772448"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9000000",
    "discussWithPerson": "Arjun",
    "expectedFees": 4500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6732d8f6a4f8826d7df80508",
  "name": "Eksar Road Branch",
  "branchCode": "",
  "mobileNo": "02228934913",
  "alternateMobileNo": "",
  "email": "arjun.parab@cosmosbank.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Akshar Apartment, Eksar Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
```

```
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "66891578194f4629de0af6da",
"role": "SITEENGINEER",
"firstName": "Govind",
"email": "govindpande23@gmail.com",
"lastName": "Pande",
"mobileNo": "9096192041",
"designation": "Site Engg",
"shortName": "Deepak",
"workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
```

```
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      },
      {
        "title": {
```

```
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.232299361892917",
  "longitude": "72.82897681840872"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82897681840872,
    19.232299361892917
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    },
    {
      "dateTime": "12/11/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
```

```
    "status": "COMPLETED",
    "dateTime": "2024-11-12",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Borivali ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "108, RSC - 16",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gorai (1) Akshay Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
}
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gorai 1",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```



```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "19/610",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "D-5",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "R/Central",
  "label": true
},
"khataNo": {
```

```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 091",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (West)",
```

```
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "MS_Rolling_Shutter",
    "label": "MS Rolling Shutter"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Open_plumbing_with_C.P._fittings._Casing_Capping_wiring",
    "label": "Open plumbing with C.P. fittings. Casing Capping wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  }
},
```

```
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road ",
  "west": "RSC Road No. 16",
  "south": "Another Room ",
  "east": "Open Plot "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": false
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
```

```

        "title": "Private Cars",
        "status": true
    }
},
"extraDetailOfProperty": "The Composition of Residential Room is 3 Rooms + 1 Toilet
+ Loft Area.\n",
"dateOfIssusApprovePlan": "The property is constructed by MHADA & MHADA itself
is an issuing authority.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
    "value": "ordinary",
    "label": "Ordinary"
},
"compoundWall": "All external walls are 9\" thick and partition walls are 6\" thick"
},
"landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
},
"apfDetails": {
    "buildings": [],
    "compositions": []
},
"compositeRate": {
    "remark": "",
    "depreciationPercentage": "51",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "buildingServicesDepreciatedRate": "1173",
    "depreciatedCostOfConstruction": "22827.00",
    "depreciatedBuildingRate": "1127"
},
"igrRate": {
    "propertyName": "Residential",
    "rate": "141110",
    "landRate": "65140",
    "igrImage": "cases/67331f84c3f75eaa95df7f08/igr_1731477815810_Image.png",
    "squareMeterGuideLineRate": "141110.00",
    "squareFeetGuideLineRate": "13110.00"
},
"igrFinalRate": {
    "floorRatePercentage": "0",
    "depreciationPercentage": "66",

```

```
"rate": "10710.00",
"squareFeetGuideLineRate": "10710.00",
"squareMeterGuideLineRate": "115280.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_use",
    "label": "Commercial use"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MHADA norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
```

```
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Car Parking Space",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "1990",
"fullDate": "1/1/1990"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "Load-bearing_structure",
"label": "Load-bearing structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
}
```

```
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_agreement",
```



```
    "label": "As per agreement"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "26",
  "ageOfBuilding": "34",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "1",
  "flatFloorNo": "Ground",
  "noOfLifts": "",
  "noOfDwellingUnitsInBuilding": "35"
},
"finalPlinthArea": {
  "area": "431.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67331f84c3f75eaa95df7f08/
routeMap_1731483090027_Image.png",
    "routeLat": "19.228022",
    "routeLng": "72.830501",
    "stationName": "Shimpoli",
    "routeDistance": "1.5 Km. ",
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
```

```
    "id": "f4ei7l",
    "name": "f4ei7l",
    "image": "cases/67331f84c3f75eaa95df7f08/
routeMap_1731482904382_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "991300.00",
    "depreciationPercentage": "51",
    "depreciatedCostOfConstruction": "505563.00",
    "totalFairMarketValue": "9838437.00"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "10344000.00",
  "finalValue": "10344000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
```

```
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4616010.00",
  "selectedBuildUpValue": "431.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "673434addccb46c198abefe0",
  "name":
"externallmg_1731474604526_WhatsApp_Image_20241113_at_103637_1.jpeg",
  "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604526_WhatsApp_Image_20241113_at_103637_1.jpeg",
  "orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "673434addccb46c198abefe0",
    "name":
"externallmg_1731474604526_WhatsApp_Image_20241113_at_103637_1.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604526_WhatsApp_Image_20241113_at_103637_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673434addccb46c198abefe8",
    "name":
"externallmg_1731474604776_WhatsApp_Image_20241113_at_103641_1.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604776_WhatsApp_Image_20241113_at_103641_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673434addccb46c198abefe7",
    "name":
"externallmg_1731474604722_WhatsApp_Image_20241113_at_103640.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604722_WhatsApp_Image_20241113_at_103640.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673434addccb46c198abefe9",
    "name":
"externallmg_1731474604779_WhatsApp_Image_20241113_at_103641_2.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604779_WhatsApp_Image_20241113_at_103641_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673434addccb46c198abefea",
    "name":
"externallmg_1731474604799_WhatsApp_Image_20241113_at_103641.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604799_WhatsApp_Image_20241113_at_103641.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673434addccb46c198abefe4",
    "name":
"externallmg_1731474604647_WhatsApp_Image_20241113_at_103639_1.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604647_WhatsApp_Image_20241113_at_103639_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24000.00",
    "max": "32119.00"
  },
  "builtUpRateRange": {
    "min": "20000.00",
    "max": "26766.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "431.00",
"empanelmentNo": [
  "HO/Credit/87/2022-23"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67331f84c3f75eaa95df7f08",
"ownerName": "Smt. Sunita Naresh Kolge ",
"ownerPhoneNo": "9619068939",
"appAddress": "Room No D-:5 Gorai 1 Akshay CHSL Plot no 108 RSC 16 Gorai
Borivali West Mumbai 400091",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "08/10/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Suchita Arjun Palav ",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      }
    }
  }
],
```

```
"Transferee": "Smt. Sunita Naresh Kolge ",
"number": {
  "value": "No",
  "label": "No"
},
"No": "20054 / 2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "460893",
"path": "cases/67331f84c3f75eaa95df7f08/document_1731403703044_1731403700
248_Cb_Ekasar_road_Borivali_West_Sunita_Kolge.pdf",
"fileName": "document_1731403703044_1731403700248_Cb_Ekasar_road_Borival
i_West_Sunita_Kolge.pdf"
},
{
  "documentType": {
    "value": "60ae1254aa6d152c1801b325",
    "label": "Society NOC Letter "
  },
  "inputs": {
    "documentDate": "05/10/2024",
    "remark": " in the name of Smt. Sunita Naresh Kolge issued by Gorai (1) Akshay
Co-Op. Hsg. Soc. Ltd",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "-"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "224556",
  "path": "cases/67331f84c3f75eaa95df7f08/document_1731480735673_209854.pdf",
  "fileName": "document_1731480735673_209854.pdf"
}
],
"caseNumber": "012313",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "469859",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 12 2024 09:27:32 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Smt. Sunita Naresh Kolge ",
    "phone": "9619068939",
    "ownershipShare": "",
    "email": "",
    "id": "472311"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "959045",
    "name": "Bedroom",
    "length": "32.00",
    "length1": "32",
    "length2": "00",
    "width": "12.25",
    "width1": "12",
    "width2": "3",
    "totalArea": "392.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "392.00"
  }
],
```

```
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
],
```

```
"id": "0",
"length": "7.33",
"length1": "7",
"length2": "4",
"width": "12.25",
"width1": "12",
"width2": "3",
"totalArea": "89.83",
"images": [],
"extraAreas": [],
"finalArea": "89.83",
"percentageBeforeTotal": "89.83",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "40.04",
  "totalAreaDocument": "431",
  "docBUILTUPPercentage": "",
  "docFinalBUILTUP": "0.00",
  "docFinalBUILTUPSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "205381"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "291.67",
    "squareMeterArea": "27.10",
    "expectedRate": "23999.73",
    "percentage": ""
  }
}
```

```
},
"builtUpArea": {
  "area": "350.00",
  "squareMeterArea": "32.52",
  "expectedRate": "20000.00",
  "percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "6734415b0b8f93c1cf1c53a8",
"property": "Gorai 1 Borivali West",
"area": "350",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "Ground",
"source": "Nobroker.com",
"expectedPrice": "7000000",
"expectedRate": "23999.73",
"builtUpExpectedRate": "7000000",
"image": "cases/67331f84c3f75eaa95df7f08/indicator_1731477012844_Image.png",
"squareMeter": "32.52",
"id": "923442"
},
{
  "carpetArea": {
    "area": "250.00",
    "squareMeterArea": "23.23",
    "expectedRate": "30000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "300.00",
    "squareMeterArea": "27.87",
    "expectedRate": "25000.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
```

```
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6734415b0b8f93c1cf1c53a9",
  "property": "Gorai 1 Borivali West",
  "area": "300",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Ground",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7500000",
  "expectedRate": "30000.00",
  "builtUpExpectedRate": "7500000",
  "image": "cases/67331f84c3f75eaa95df7f08/indicator_1731477049459_Image.png",
  "squareMeter": "27.87",
  "id": "664201"
},
{
  "carpetArea": {
    "area": "216.67",
    "squareMeterArea": "20.13",
    "expectedRate": "31384.13",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "260.00",
    "squareMeterArea": "24.15",
    "expectedRate": "26153.85",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6734415b0b8f93c1cf1c53aa",
  "property": "Gorai 1, Borivali West",
  "area": "260",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Built_Up",
"floor": "Ground",
"source": "https://www.99acres.com/",
"expectedPrice": "6800000",
"expectedRate": "31384.13",
"builtUpExpectedRate": "6800000",
"image": "cases/67331f84c3f75eaa95df7f08/indicator_1731477108549_Image.png",
"squareMeter": "24.15",
"id": "762194"
},
{
  "carpetArea": {
    "area": "224.17",
    "squareMeterArea": "20.83",
    "expectedRate": "32118.48",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "269.00",
    "squareMeterArea": "24.99",
    "expectedRate": "26765.80",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6734415b0b8f93c1cf1c53ab",
  "property": "Gorai 1, Borivali West",
  "area": "269",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "Ground",
  "source": "Index_no.2",
  "expectedPrice": "7200000",
  "expectedRate": "32118.48",
  "builtUpExpectedRate": "7200000",
  "image": "cases/67331f84c3f75eaa95df7f08/indicator_1731477294100_Image.png",
  "squareMeter": "24.99",
  "id": "748244"
},
```



```
{
  "carpetArea": {
    "area": "224.17",
    "squareMeterArea": "20.83",
    "expectedRate": "28995.85",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "269.00",
    "squareMeterArea": "24.99",
    "expectedRate": "24163.57",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6734415b0b8f93c1cf1c53ac",
  "property": "Gorai 1 Borivali West",
  "area": "269",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "Ground",
  "source": "Index_no.2",
  "expectedPrice": "6500000",
  "expectedRate": "28995.85",
  "builtUpExpectedRate": "6500000",
  "image": "cases/67331f84c3f75eaa95df7f08/indicator_1731477474061_Image.png",
  "squareMeter": "24.99",
  "id": "691788"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673434addccb46c198abefdf",
    "name":
      "externallmg_1731474604518_WhatsApp_Image_20241113_at_103635.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604518_WhatsApp_Image_20241113_at_103635.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673434addccb46c198abefe0",
    "name":
"externallmg_1731474604526_WhatsApp_Image_20241113_at_103637_1.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604526_WhatsApp_Image_20241113_at_103637_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673434addccb46c198abefe1",
    "name":
"externallmg_1731474604534_WhatsApp_Image_20241113_at_103637.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604534_WhatsApp_Image_20241113_at_103637.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673434addccb46c198abefe2",
    "name":
"externallmg_1731474604584_WhatsApp_Image_20241113_at_103638_1.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604584_WhatsApp_Image_20241113_at_103638_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673434addccb46c198abefe3",
    "name":
"externallmg_1731474604592_WhatsApp_Image_20241113_at_103638.jpeg",
    "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604592_WhatsApp_Image_20241113_at_103638.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673434addccb46c198abefe4",
```

```
    "name":  
    "externallmg_1731474604647_WhatsApp_Image_20241113_at_103639_1.jpeg",  
    "path": "cases/67331f84c3f75eaa95df7f08/  
externallmg_1731474604647_WhatsApp_Image_20241113_at_103639_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "673434addccb46c198abefe5",  
    "name":  
    "externallmg_1731474604654_WhatsApp_Image_20241113_at_103639.jpeg",  
    "path": "cases/67331f84c3f75eaa95df7f08/  
externallmg_1731474604654_WhatsApp_Image_20241113_at_103639.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "673434addccb46c198abefe6",  
    "name":  
    "externallmg_1731474604721_WhatsApp_Image_20241113_at_103640_1.jpeg",  
    "path": "cases/67331f84c3f75eaa95df7f08/  
externallmg_1731474604721_WhatsApp_Image_20241113_at_103640_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "673434addccb46c198abefe7",  
    "name":  
    "externallmg_1731474604722_WhatsApp_Image_20241113_at_103640.jpeg",  
    "path": "cases/67331f84c3f75eaa95df7f08/  
externallmg_1731474604722_WhatsApp_Image_20241113_at_103640.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "673434addccb46c198abefe8",  
    "name":  
    "externallmg_1731474604776_WhatsApp_Image_20241113_at_103641_1.jpeg",  
    "path": "cases/67331f84c3f75eaa95df7f08/  
externallmg_1731474604776_WhatsApp_Image_20241113_at_103641_1.jpeg",  
    "orientation": "portrait"  
  },  
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673434addccb46c198abefe9",
  "name":
"externallmg_1731474604779_WhatsApp_Image_20241113_at_103641_2.jpeg",
  "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604779_WhatsApp_Image_20241113_at_103641_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673434addccb46c198abefea",
  "name":
"externallmg_1731474604799_WhatsApp_Image_20241113_at_103641.jpeg",
  "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604799_WhatsApp_Image_20241113_at_103641.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673434addccb46c198abefeb",
  "name":
"externallmg_1731474604833_WhatsApp_Image_20241113_at_103642_1.jpeg",
  "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604833_WhatsApp_Image_20241113_at_103642_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673434addccb46c198abefec",
  "name":
"externallmg_1731474604842_WhatsApp_Image_20241113_at_103642.jpeg",
  "path": "cases/67331f84c3f75eaa95df7f08/
externallmg_1731474604842_WhatsApp_Image_20241113_at_103642.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673434addccb46c198abefed",
  "name":
"externallmg_1731474604874_WhatsApp_Image_20241113_at_103648.jpeg",
```

```
    "path": "cases/67331f84c3f75eaa95df7f08/
externalImg_1731474604874_WhatsApp_Image_20241113_at_103648.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "673441590b8f93c1cf1c53a3",
    "note": "Pending for bank confirmation",
    "taskId": "673330065064deaad8e25fd7",
    "createdAt": "2024-11-13T06:04:09.854Z"
  }
],
"createdAt": "2024-11-12T09:27:32.664Z",
"updatedAt": "2024-11-13T07:37:23.912Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62fe044a48a26047e6552796",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. D-5, Ground Floor, Gorai (1) Akshay Co-Op. Hsg.
Soc. Ltd., Plot No. 108, RSC - 16, Gorai 1, Village - Borivali , Municipality Ward No. R/
Central, Borivali (West), Taluka - Borivali , District - Mumbai Suburban, PIN - 400 091,
State - Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Smt. Sunita Naresh Kolge ",
"email": "",
"isExternal": "false",
```

```
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"rerald": "",
"siteVisitContactNo": "9619068939",
"buildingServicesRate": "2300",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 431.00",
"flatRate": "24000",
"landOtherRate": "21700",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "392.00",
"extendOfSiteRemark": "",
"finalBuiltupArea": "530.01",
"finalCarpetArea": "481.83",
"finalSalableArea": "583.01",
"otherCarpetTotal": "89.83",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 392.00\nLoft Area in Sq. Ft. =
90.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "89.83",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
```

```

    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Nov 13 2024 06:41:13 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-11-12"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Bedroom	32'00"	12'3"	392.00
Other Composition :			
Flower Bed Area	7'4"	12'3"	89.83