

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Shatrughan",
    "type": "CREDITOFFICER",
    "_id": "662777af7f34894a8aa36307",
    "lastName": "Kubal",
    "mobileNo": "",
    "workMobileNo": "9867282485",
    "email": "Shatrughan.kubal@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Shatrughan",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordination",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.199250669153198",
  "longitude": "73.11768086477365"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
73.11768086477365,
19.199250669153198
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-14",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Sonarpada",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Emerald",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A-3",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "88/14A & 88/15",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "701",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 203",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivali (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Sole_Ownership",
"label": "Sole Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Kalyan_Dombivali_Municipal_Corporation",
"label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Open Plot ",
"west": "Wing - D",
"south": "Internal Road ",
"east": "Wing - B"
},
"asPerDocumentAgreement": {
"north": "Details not available ",
"west": "Details not available ",
"south": "Details not available ",
"east": "Details not available "
},
"unitBoundaries": {
"asPerActual": {
"north": "Marginal Space ",
"east": "Flat No. 702",
"south": "Staircase & Flat No. 704",
"west": "Marginal Space "
},
"asPerDocument": {
"north": "Marginal Space ",
"east": "Flat No. 702",
"south": "Staircase & Flat No. 704",
"west": "Marginal Space "
},
"setDisplay": false,
"title": "Boundaries of The Flat"
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. KDMC / TPD / BP /
27 Village / 2021 - 22 / 09 / 319 dated 25.11.2022 issued by KDMC.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Building is under construction ",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": " Residential Flat",
  "rate": "41200",
  "landRate": "9600",
  "igrImage": "cases/67341e060b8f93c1cf1c3316/igr_1731584815824_Image.png",
  "squareMeterGuideLineRate": "43260.00",
```

```
"squareFeetGuideLineRate": "4019.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "41200.00",
  "squareMeterGuideLineRate": "43260.00",
  "squareFeetGuideLineRate": "4019.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per KDMC norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
}
```

```
"partitions": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Stilt Car Parking Space ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
}
```

```
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
```



```
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "As_per_RERA_Certificate",
"label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "513.70",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/67341e060b8f93c1cf1c3316/
routeMap_1731662296831_Image.png",
"routeLat": "19.197889",
"routeLng": "73.104694",
"stationName": "Dombivali",
"routeDistance": "3.1 Km. ",
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
0
],
"type": "Point"
},
"showLocation": {
```

```
"latlng": false,
"finallatlng": false
},
"locationMapImg": [
  {
    "id": "eazi8r",
    "name": "eazi8r",
    "image": "cases/67341e060b8f93c1cf1c3316/
routeMap_1731662070314_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "4296400.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4296400.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "9",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "9",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "9",
    "percentage": "7.00",
```

```
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "9",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "9",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "9",
  "percentage": "10.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "9",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "82.50",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2064560.00",
"selectedBuildUpValue": "513.70",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6735836fdca8ac11abc28ed8",
      "name": "externallmg_r_1731560280508_1731560274714_image_3.jpg",
      "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560280508_1731560274714_image_3.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6735836fdca8ac11abc28ed9",
      "name": "externallmg_r_1731560281669_1731560274714_image_4.jpg",
      "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560281669_1731560274714_image_4.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6735836fdca8ac11abc28edd",
      "name": "externallmg_r_1731560284716_1731560274714_image_6.jpg",
      "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560284716_1731560274714_image_6.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6735836fdca8ac11abc28ee0",
      "name": "externallmg_r_1731560289617_1731560274714_image_10.jpg",
      "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560289617_1731560274714_image_10.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6735836fdca8ac11abc28ee1",
      "name": "externallmg_r_1731560288017_1731560274714_image_9.jpg",
      "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560288017_1731560274714_image_9.jpg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6735836fdca8ac11abc28ee3",
  "name": "externallmg_r_1731560295200_1731560274714_image_12.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560295200_1731560274714_image_12.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6735836fdca8ac11abc28ee4",
  "name": "externallmg_r_1731560295502_1731560274714_image_13.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560295502_1731560274714_image_13.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6735836fdca8ac11abc28ed8",
  "name": "externallmg_r_1731560280508_1731560274714_image_3.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560280508_1731560274714_image_3.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6735836fdca8ac11abc28ee2",
  "name": "externallmg_r_1731560292055_1731560274714_image_11.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560292055_1731560274714_image_11.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6735836fdca8ac11abc28edf",
  "name": "externallmg_r_1731560287149_1731560274714_image_8.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560287149_1731560274714_image_8.jpg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "7816.00",
  "max": "11621.00"
},
"builtUpRateRange": {
  "min": "7106.00",
  "max": "10564.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "467.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67341e060b8f93c1cf1c3316",
"ownerName": "Mr. Ganesh Nivrutti Berade ",
"ownerPhoneNo": "9136740630",
```

```
"appAddress": "Flat no. A-3-701, 7th Floor, Emerald A-3, Sonarpada, Dombivali East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "30/09/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. APR Realty ",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Ganesh Nivrutti Berade ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "19312 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "669582",
    "path": "cases/67341e060b8f93c1cf1c3316/
document_1731468803506_156421.pdf",
    "fileName": "document_1731468803506_156421.pdf"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "25/11/2022",
      "nameOfApprovingAuthority": {
        "value": "Kalyan_Dombivli_Municipal_Corporation",
        "label": "Kalyan Dombivli Municipal Corporation"
      },
      "remark": " (As downloaded from RERA site)",
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "KDMC / TPD / BP / 27 Village / 2021 - 22 / 09 / 319"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1731655254396_Plan.pdf",
"path": "cases/67341e060b8f93c1cf1c3316/document_1731655254396_Plan.pdf",
"id": "447269",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Nov 15 2024 07:20:54 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "25/11/2022",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "remark": " (As downloaded from RERA site)",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / TPD / BP / 27 Village / 2021-22 / 09 / 319"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1731655336756_CC.pdf",
"path": "cases/67341e060b8f93c1cf1c3316/document_1731655336756_CC.pdf",
"id": "836124",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Nov 15 2024 07:22:17 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "06/03/2023",
```

```
"nameOfApprovingAuthority": {
  "value": "Maharashtra_Real_Estate_Regulatory_Authority",
  "label": "Maharashtra Real Estate Regulatory Authority"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "P51700049954"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1731655390341_RERA.pdf",
"path": "cases/67341e060b8f93c1cf1c3316/document_1731655390341_RERA.pdf",
"id": "921490",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Nov 15 2024 07:23:10 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012333",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "731626",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 13 2024 03:33:26 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ganesh Nivrutti Berade ",
    "phone": "9136740630",
    "ownershipShare": "",
    "email": "",
    "id": "147231"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
],
```

```
"id": "649345",
"name": "Bedroom",
"length": "8.58",
"length1": "8",
"length2": "7",
"width": "10.58",
"width1": "10",
"width2": "7",
"totalArea": "90.84",
"images": [],
"extraAreas": [],
"finalArea": "90.84"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "WC",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "26.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "24.69",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "24.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "19.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "63.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "63.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
```

```
"length": "10.42",
"length1": "10",
"length2": "5",
"width": "12.92",
"width1": "12",
"width2": "11",
"totalArea": "134.55",
"images": [],
"extraAreas": [],
"finalArea": "134.55"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "8.50",
  "length1": "8",
  "length2": "6",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "31.17",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "67370c5fd1078a4ea7f54fba",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "6.00",
      "length1": "6",
```



```
    "length2": "00",
    "width": "6.92",
    "width1": "6",
    "width2": "11",
    "totalArea": "41.50"
  }
],
"finalArea": "72.67",
"percentageBeforeTotal": "72.67",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "14.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.33",
  "percentageBeforeTotal": "14.33",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },

```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "822926",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "467",
"squareMeterArea": "43.39",
"docFinalBuiltUp": "513.7",
"docFinalBuiltUpSquareMeter": "47.729",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "458.00",
      "squareMeterArea": "42.55",
      "expectedRate": "11620.09",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "503.80",
      "squareMeterArea": "46.80",
      "expectedRate": "10563.72",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "6735e33ce077c54e53225427",
  "property": "Residential Flat",
  "area": "458",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": ""
```

```
"source": "Housing.Com",
"expectedPrice": "5322000",
"expectedRate": "11620.09",
"builtUpExpectedRate": "10563.72",
"image": "cases/67341e060b8f93c1cf1c3316/
indicator_1731584565853_Image.png",
"squareMeter": "42.55",
"id": "379950"
},
{
"carpetArea": {
"area": "722.00",
"squareMeterArea": "67.08",
"expectedRate": "9987.53",
"percentage": ""
},
"builtUpArea": {
"area": "794.20",
"squareMeterArea": "73.78",
"expectedRate": "9079.58",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6735e33ce077c54e53225428",
"property": "Residential Flat",
"area": "722",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Dwello.com",
"expectedPrice": "7211000",
"expectedRate": "9987.53",
"builtUpExpectedRate": "9079.58",
"image": "cases/67341e060b8f93c1cf1c3316/
indicator_1731584612823_Image.png",
"squareMeter": "67.08",
"id": "498968"
},
```

```
{
  "carpetArea": {
    "area": "491.00",
    "squareMeterArea": "45.62",
    "expectedRate": "7815.68",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "540.10",
    "squareMeterArea": "50.18",
    "expectedRate": "7105.17",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "6735e33ce077c54e53225429",
  "property": " Residential Flat",
  "area": "491",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3837500",
  "expectedRate": "7815.68",
  "builtUpExpectedRate": "7105.17",
  "image": "cases/67341e060b8f93c1cf1c3316/
indicator_1731584665875_Image.png",
  "squareMeter": "45.62",
  "id": "464433"
},
{
  "carpetArea": {
    "area": "442.00",
    "squareMeterArea": "41.06",
    "expectedRate": "8348.42",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "486.20",
```

```
    "squareMeterArea": "45.17",
    "expectedRate": "7589.47",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6735e33ce077c54e5322542a",
  "property": "Residential Flat",
  "area": "442",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3690000",
  "expectedRate": "8348.42",
  "builtUpExpectedRate": "7589.47",
  "image": "cases/67341e060b8f93c1cf1c3316/
indicator_1731584699738_Image.png",
  "squareMeter": "41.06",
  "id": "133788"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6735836fdca8ac11abc28ed7",
    "name": "externalImg_1731560277689_1731560274714_image_1.png",
    "path": "cases/67341e060b8f93c1cf1c3316/
externalImg_1731560277689_1731560274714_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6735836fdca8ac11abc28ed8",
    "name": "externalImg_r_1731560280508_1731560274714_image_3.jpg",
    "path": "cases/67341e060b8f93c1cf1c3316/
externalImg_r_1731560280508_1731560274714_image_3.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28ed9",
  "name": "externallmg_r_1731560281669_1731560274714_image_4.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560281669_1731560274714_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28eda",
  "name": "externallmg_r_1731560278947_1731560274714_image_2.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560278947_1731560274714_image_2.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28edb",
  "name": "externallmg_r_1731560276872_1731560274714_image_0.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560276872_1731560274714_image_0.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28edc",
  "name": "externallmg_r_1731560283109_1731560274714_image_5.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560283109_1731560274714_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28edd",
  "name": "externallmg_r_1731560284716_1731560274714_image_6.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560284716_1731560274714_image_6.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6735836fdca8ac11abc28ede",
    "name": "externallmg_r_1731560286242_1731560274714_image_7.jpg",
    "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560286242_1731560274714_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6735836fdca8ac11abc28edf",
    "name": "externallmg_r_1731560287149_1731560274714_image_8.jpg",
    "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560287149_1731560274714_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6735836fdca8ac11abc28ee0",
    "name": "externallmg_r_1731560289617_1731560274714_image_10.jpg",
    "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560289617_1731560274714_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6735836fdca8ac11abc28ee1",
    "name": "externallmg_r_1731560288017_1731560274714_image_9.jpg",
    "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560288017_1731560274714_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6735836fdca8ac11abc28ee2",
    "name": "externallmg_r_1731560292055_1731560274714_image_11.jpg",
    "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560292055_1731560274714_image_11.jpg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28ee3",
  "name": "externallmg_r_1731560295200_1731560274714_image_12.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560295200_1731560274714_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28ee4",
  "name": "externallmg_r_1731560295502_1731560274714_image_13.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560295502_1731560274714_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28ee5",
  "name": "externallmg_r_1731560296676_1731560274714_image_14.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560296676_1731560274714_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6735836fdca8ac11abc28ee6",
  "name": "externallmg_r_1731560298222_1731560274714_image_15.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560298222_1731560274714_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "673583375a7fb811aa4cb0ca",
  "name": "externallmg_r_1731560244294_1731560243216_image_0.jpg",
  "path": "cases/67341e060b8f93c1cf1c3316/
externallmg_r_1731560244294_1731560243216_image_0.jpg",
  "orientation": "landscape"
}
],
```



```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1731584876014_Calculation_Sheet_NEW.xlsx",
    "path": "cases/67341e060b8f93c1cf1c3316/
processingDocuments/1731584876014_Calculation_Sheet_NEW.xlsx",
    "size": "3172556",
    "createdAt": "Thu Nov 14 2024 11:47:56 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1731662615450_CC.pdf",
    "path": "cases/67341e060b8f93c1cf1c3316/
processingDocuments/1731662615450_CC.pdf",
    "size": "1838073",
    "createdAt": "Fri Nov 15 2024 09:23:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Plan.pdf",
    "filename": "1731662615571_Plan.pdf",
    "path": "cases/67341e060b8f93c1cf1c3316/
processingDocuments/1731662615571_Plan.pdf",
    "size": "886606",
    "createdAt": "Fri Nov 15 2024 09:23:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "RERA.pdf",
    "filename": "1731662615677_RERA.pdf",
    "path": "cases/67341e060b8f93c1cf1c3316/
processingDocuments/1731662615677_RERA.pdf",
    "size": "149760",
    "createdAt": "Fri Nov 15 2024 09:23:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-13T03:33:26.689Z",
"updatedAt": "2024-11-15T09:41:27.344Z",
"__v": 0,
"assignmentType": {
```

```
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 701, 7th Floor, Wing - A-3, Emerald, Village -
Sonarpada, Dombivali (East), Taluka - Kalyan, District - Thane, PIN - 421 203, State -
Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Gaurav Masal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person ",
"reald": "",
"siteVisitContactNo": "9664942018",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 467.00",
"flatRate": "9200",
"landOtherRate": "6700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
},
"roadFacing": false,
"mall": false
},
"siteVisitDate": "2024-11-14",
"builtupPercentage": "10",
"carpetTotal": "358.83",
"extendOfSiteRemark": "\nAll the above areas are within 4% of the Agreement for Sale
Area. The above calculations and detailed measurements taken by us prove that the
Agreement for Sale area is not exorbitantly inflated. Hence, valuation is prepared based
on the Agreement for Sale area",
"finalBuiltupArea": "490.41",
"finalCarpetArea": "445.83",
"finalSalableArea": "539.45",
```

"otherCarpetTotal": "87",
 "salablePercentage": "10",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 359.00\nBalcony Area in Sq. Ft.
 = 73.00\nDry Balcony Area in Sq. Ft. = 14.00\n\n",
 "toBeAdded": "",
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom +
 Passage",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "87.00",
 "otherCompositionSaleableTotal": "0.00",
 "finalSaleablePercentage": "0"

Name	Length	Width	Total
Composition :			
Bedroom	8'7"	10'7"	90.84
WC	6'8"	4'00"	26.67
Bathroom	6'7"	3'9"	24.69
Passage	5'7"	3'5"	19.08
Kitchen	7'00"	9'00"	63.00
Living Room	10'5"	12'11"	134.55
Other Composition :			
Balcony Area	8'6"	3'8"	31.17
Dry Balcony Area	4'00"	3'7"	14.33