

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "firstName": "Neha",
    "type": "CREDITOFFICER",
    "_id": "653656df2a1baf5f34c1383b",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8286400657",
    "email": "1sbi.17889@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Neha",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "651e5a18b98e691677d9b737",
  "role": "PICKUPPERSON",
  "firstName": "Akshay",
  "email": "akshayomsairam966@gmail.com",
  "lastName": "Dawkhar",
  "mobileNo": "9167084090",
  "shortName": "Aks",
  "workWithDocumentMaker": "62727444afd7d55eddee092c",
  "profilePhoto": "users/651e5a18b98e691677d9b737/
profilePhoto_1701151775714_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": []
},
"clientType": {
"label": "BANK",
"value": "BANK"
},
"location": {
"latitude": "19.276923829039696",
"longitude": "72.85930604591353"
},
"geo": {
"type": "Point",
"coordinates": [
72.85930604591353,
19.276923829039696
]
},
"siteVisit": {
"siteVisitStatus": true,
"schedule": [
{
"dateTime": "14/11/2024 12:00 am"
}
],
"visitedDate": [
{
"status": "COMPLETED",
"dateTime": "2024-11-15",
"remark": "MANUAL_IN_TASK"
}
]
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Penkarpada",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Mira Road (East)",
"label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sector 2A",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
```

```
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "F",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "\\\"Srishti Sector 2A\\\" in Complex \\\"Srishti\\\"",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "233(pt), 235(pt), 256(pt)",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "66(pt), 68(pt), 69(pt)",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```



```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  }
},
}
```

```
"doors": {
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
  "label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
  "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
},
"finishing": {
  "value": "Proposed_Cement_Plastering",
  "label": "Proposed Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Poonam Estate Cluster 2",
    "west": "Road",
    "south": "Srishti Phase 1",
    "east": "Open Plot"
  },
}
```

```
"asPerDocumentAgreement": {
  "north": "By Old Survey No. 230 at Village Penkarpada",
  "west": "Partly by 30m Wide Road & by Old Survey No. 235(Pt) at Village
Penkarpada",
  "south": "By 30m Wide Road at Village Penkarpada",
  "east": "Partly by Old Survey No. 190, 150, 236 at Village\nPenkarpada"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building Under Construction",
    "east": "Building Under Construction",
    "south": "Building Under Construction",
    "west": "Building Under Construction"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "2 BHK",
"dateOfIssusApprovePlan": "Yes",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
```

```
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Building Under Construction",
  "taxPaidHolderName": "Building Under Construction",
  "taxAmount": "Building Under Construction",
  "electricityServiceConnectionNo": "Building Under Construction",
  "meterCardHolderName": "Building Under Construction",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  }
}
```

```
},
"partitions": {
  "value": "Proposed_6\"_Thk._Brick_Masonry",
  "label": "Proposed 6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Covered Parking Space",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Proposed_Plain_Looking",
  "label": "Proposed Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2028",
  "fullDate": "1/1/2028"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Information_Not_Available",
```

```
"label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
}
```

```
"groundStilt": {
  "value": "Proposed_Ground",
  "label": "Proposed Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "2",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "33",
"flatFloorNo": "1",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
  "area": "740.30",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6735be2177990f3be011472f/
routeMap_1732009444118_Image.png",
    "routeLat": "19.271917",
    "routeLng": "72.869556",
    "stationName": "Mira Road",
    "routeDistance": "2.1 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
```

```
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "sh122w",
    "name": "sh122w",
    "image": "cases/6735be2177990f3be011472f/
routeMap_1732009329190_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "4",
```



```
"percentage": "4.102564102564102",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "14.10",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "740.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "673c3740572e264e52148687",
      "name":
"externallmg_1731999552156_WhatsApp_Image_20241119_at_120243.jpeg",
      "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552156_WhatsApp_Image_20241119_at_120243.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "673c3740572e264e52148689",
      "name":
"externallmg_1731999552199_WhatsApp_Image_20241119_at_120244_2.jpeg",
      "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552199_WhatsApp_Image_20241119_at_120244_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "673c3740572e264e52148683",
      "name":
"externallmg_1731999552075_WhatsApp_Image_20241119_at_120242_1.jpeg",
      "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552075_WhatsApp_Image_20241119_at_120242_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "673c3740572e264e5214868b",
    "name":
"externallmg_1731999552247_WhatsApp_Image_20241119_at_120245_1.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552247_WhatsApp_Image_20241119_at_120245_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673c3740572e264e5214868a",
    "name":
"externallmg_1731999552203_WhatsApp_Image_20241119_at_120244.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552203_WhatsApp_Image_20241119_at_120244.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "673.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6735be2177990f3be011472f",
"ownerName": "Eversmile Properties Private Limited",
"ownerPhoneNo": "8920470838",
"appAddress": "103, on 1st habitable floor, Sector 2A - Wing F in Complex \"Srisht
Village Penkarpada Mira Taluka and District Thane",
"remark": "1.14 RV",
"documents": [
  {
    "documentType": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "inputs": {
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Eversmile Properties Private Limited",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Ms. Mansi Singh"
    }
  },
  "isHardCopy": false,
```

```
    "displayStatus": true,
    "id": "651210",
    "path": "cases/6735be2177990f3be011472f/
document_1731575242278_1731573709897_F103__Mansi_Singh__Draft_AFS.pdf",
    "fileName":
"document_1731575242278_1731573709897_F103__Mansi_Singh__Draft_AFS.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "17/10/2023",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "P51700053195"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1732010549415_P51700053195.pdf",
    "path": "cases/6735be2177990f3be011472f/
document_1732010549415_P51700053195.pdf",
    "id": "119201",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Tue Nov 19 2024 10:02:29 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "14/08/2023",
      "nameOfApprovingAuthority": {
        "value": "Mira_Bhayander_Municipal_Corporation",
        "label": "Mira Bhayander Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "MNP/NR/1561/2023-2024"
    }
  },
}
```



```
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1732010613178_1_Commencement_Certificates___NA_Order_for_plotted_development_1.pdf",
    "path": "cases/6735be2177990f3be011472f/document_1732010613178_1_Commencement_Certificates___NA_Order_for_plotted_development_1.pdf",
    "id": "566581",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Tue Nov 19 2024 10:03:33 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "012381",
"createdBy": "651e5a18b98e691677d9b737",
"caseHistory": [
  {
    "id": "310562",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 14 2024 09:08:49 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Eversmile Properties Private Limited",
    "phone": "8920470838",
    "ownershipShare": "",
    "email": "",
    "id": "292940"
  }
],
"proposePurchasers": [
  {
    "name": "Ms. Mansi Singh",
    "phone": "",
    "email": "",
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1256aa6d152c1801b330",
    }
  }
]
```

```
    "label": "Draft Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "968348",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "673",
  "squareMeterArea": "62.52",
  "docFinalBuiltUp": "740.3",
  "docFinalBuiltUpSquareMeter": "68.772",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673c3740572e264e52148682",
    "name":
"externallmg_1731999552069_WhatsApp_Image_20241119_at_120233.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552069_WhatsApp_Image_20241119_at_120233.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673c3740572e264e52148683",
    "name":
"externallmg_1731999552075_WhatsApp_Image_20241119_at_120242_1.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552075_WhatsApp_Image_20241119_at_120242_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673c3740572e264e52148684",
    "name":
"externallmg_1731999552081_WhatsApp_Image_20241119_at_120242.jpeg",
```

```
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552081_WhatsApp_Image_20241119_at_120242.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673c3740572e264e52148685",
    "name":
"externallmg_1731999552111_WhatsApp_Image_20241119_at_120243_1.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552111_WhatsApp_Image_20241119_at_120243_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673c3740572e264e52148686",
    "name":
"externallmg_1731999552115_WhatsApp_Image_20241119_at_120243_2.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552115_WhatsApp_Image_20241119_at_120243_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673c3740572e264e52148687",
    "name":
"externallmg_1731999552156_WhatsApp_Image_20241119_at_120243.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552156_WhatsApp_Image_20241119_at_120243.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673c3740572e264e52148688",
    "name":
"externallmg_1731999552160_WhatsApp_Image_20241119_at_120244_1.jpeg",
    "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552160_WhatsApp_Image_20241119_at_120244_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "673c3740572e264e52148689",
  "name":
"externallmg_1731999552199_WhatsApp_Image_20241119_at_120244_2.jpeg",
  "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552199_WhatsApp_Image_20241119_at_120244_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c3740572e264e5214868a",
  "name":
"externallmg_1731999552203_WhatsApp_Image_20241119_at_120244.jpeg",
  "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552203_WhatsApp_Image_20241119_at_120244.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c3740572e264e5214868b",
  "name":
"externallmg_1731999552247_WhatsApp_Image_20241119_at_120245_1.jpeg",
  "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552247_WhatsApp_Image_20241119_at_120245_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c3740572e264e5214868c",
  "name":
"externallmg_1731999552251_WhatsApp_Image_20241119_at_120245_2.jpeg",
  "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552251_WhatsApp_Image_20241119_at_120245_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c3740572e264e5214868d",
  "name":
"externallmg_1731999552280_WhatsApp_Image_20241119_at_120245.jpeg",
  "path": "cases/6735be2177990f3be011472f/
externallmg_1731999552280_WhatsApp_Image_20241119_at_120245.jpeg",
```

```
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "673c379fe077c54e53253175",
    "note": "Value given for confirmation ",
    "taskId": "6735cce6d1078a4ea7f4befe",
    "createdAt": "2024-11-19T07:00:47.541Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "673c39dc572e264e52148acc",
    "note": "Value given for confirmation",
    "taskId": "6735cce6d1078a4ea7f4befe",
    "createdAt": "2024-11-19T07:10:20.138Z"
  }
],
"createdAt": "2024-11-14T09:08:49.348Z",
"updatedAt": "2024-11-19T10:17:31.911Z",
"__v": 0,
```

```

"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 103, 1st Floor, Wing - F, Sector 2A, \"Srishti Sector 2A\" in Complex \"Srishti\", Village - Penkarpada, Taluka - Thane, District - Thane, Mira Road (East), PIN - 401 107, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Siddharth Sharma",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Ms. Mansi Singh",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"rerald": "",
"siteVisitContactNo": "9137693076",
"reportGeneratedDate": "Tue Nov 19 2024 09:22:39 GMT+0000 (Coordinated Universal Time)",
"siteVisitDate": "2024-11-15",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 639.00\nBalcony (Open) Area in Sq. Ft. = 34.00\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 673.00"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
