

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "firstName": "Shubham ",
    "type": "CREDITOFFICER",
    "_id": "659e41f902c44c777bae2b5c",
    "lastName": "Lokhande",
    "mobileNo": "",
    "workMobileNo": "9689386608",
    "email": "2cord.21117@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2430628",
    "discussWithPerson": "Shubham ",
    "expectedFees": 1215.314,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Baor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.08054182608578",
  "longitude": "73.10889894806645"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10889894806645,
    19.08054182608578
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "14/11/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
}
```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Koynavele",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Riverside",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```



```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "917",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410208",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Koynavele",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
```

```
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6735da35572e264e52122e3a",
"ownerName": "Jinu kuttanil Jacob And Jerin Mary Jinu",
"ownerPhoneNo": "7736266394",
"appAddress": "flat no .917 .9 th floor Riverside village koyavele panvel ",
"remark": "Bankar shubham sir ",
"documents": [
```

```
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6735da35572e264e52122e3a/
document_1731582484767_1731582482028_ScanningFile_21.pdf",
  "fileName": "document_1731582484767_1731582482028_ScanningFile_21.pdf",
  "id": "566286",
  "uploadedBy": "60b7189d2ffdf65bcd65882b",
  "createdAt": "Thu Nov 14 2024 11:08:37 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012388",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "941519",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 14 2024 11:08:37 GMT+0000 (Coordinated Universal Time)"
  }
]
],
"owners": [
  {
    "name": "Jinu kuttanil Jacob And Jerin Mary Jinu",
    "phone": "7736266394",
    "ownershipShare": "",
    "email": "",
    "id": "916192"
  }
]
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "67380b0bd1078a4ea7f5aeb7",
    "name": "externallmg_1731726089765_IMG_20241115_0333.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089765_IMG_20241115_0333.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aeb8",
    "name": "externallmg_1731726089771_IMG_20241115_0671.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089771_IMG_20241115_0671.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aeb9",
    "name": "externallmg_1731726089798_IMG_20241115_0983.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089798_IMG_20241115_0983.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aeba",
    "name": "externallmg_1731726089824_IMG_20241115_52852.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089824_IMG_20241115_52852.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aebb",
    "name": "externallmg_1731726089827_IMG_20241115_53139.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089827_IMG_20241115_53139.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aebc",
```

```
    "name": "externallmg_1731726089840_IMG_20241115_53508.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089840_IMG_20241115_53508.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aebd",
    "name": "externallmg_1731726089871_IMG_20241115_54598.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089871_IMG_20241115_54598.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aebe",
    "name": "externallmg_1731726089879_IMG_20241115_54988.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089879_IMG_20241115_54988.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aebf",
    "name": "externallmg_1731726089909_IMG_20241115_55395.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089909_IMG_20241115_55395.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aec0",
    "name": "externallmg_1731726089913_IMG_20241115_55810.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089913_IMG_20241115_55810.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aec1",
    "name": "externallmg_1731726089947_IMG_20241115_56335.jpg",
```

```
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089947_IMG_20241115_56335.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aec2",
    "name": "externallmg_1731726089950_IMG_20241115_56605.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089950_IMG_20241115_56605.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aec3",
    "name": "externallmg_1731726089972_IMG_20241115_56868.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089972_IMG_20241115_56868.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aec4",
    "name": "externallmg_1731726089979_IMG_20241115_57176.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726089979_IMG_20241115_57176.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aec5",
    "name": "externallmg_1731726090001_IMG_20241115_57467.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726090001_IMG_20241115_57467.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b0bd1078a4ea7f5aec6",
    "name": "externallmg_1731726090005_IMG_20241115_59440.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726090005_IMG_20241115_59440.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b0bd1078a4ea7f5aec7",
  "name": "externallmg_1731726090027_IMG_20241115_59714.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726090027_IMG_20241115_59714.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b0bd1078a4ea7f5aec8",
  "name": "externallmg_1731726090031_IMG_20241115_223746.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726090031_IMG_20241115_223746.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b0bd1078a4ea7f5aec9",
  "name": "externallmg_1731726090069_IMG_20241115_224846.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726090069_IMG_20241115_224846.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b0bd1078a4ea7f5aeca",
  "name": "externallmg_r_1731726090116_IMG20241115173154.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_r_1731726090116_IMG20241115173154.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351c1",
  "name": "externallmg_1731726113497_Screenshot_2024111517362499_3d9111e2
d3171bf4882369f490c087b4.jpg",
  "path": "cases/6735da35572e264e52122e3a/externallmg_1731726113497_Screens
hot_2024111517362499_3d9111e2d3171bf4882369f490c087b4.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351c2",
  "name": "externallmg_1731726113976_IMG_20241115_00.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726113976_IMG_20241115_00.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351c3",
  "name": "externallmg_1731726113980_IMG_20241115_5698.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726113980_IMG_20241115_5698.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351c4",
  "name": "externallmg_1731726114110_IMG_20241115_51664.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114110_IMG_20241115_51664.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351c5",
  "name": "externallmg_1731726114113_IMG_20241115_52439.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114113_IMG_20241115_52439.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351c6",
  "name": "externallmg_1731726114128_IMG_20241115_53845.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114128_IMG_20241115_53845.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b23e077c54e532351c7",
    "name": "externallmg_1731726114132_IMG_20241115_54228.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114132_IMG_20241115_54228.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b23e077c54e532351c8",
    "name": "externallmg_1731726114150_IMG_20241115_57882.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114150_IMG_20241115_57882.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b23e077c54e532351c9",
    "name": "externallmg_1731726114152_IMG_20241115_58209.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114152_IMG_20241115_58209.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b23e077c54e532351ca",
    "name": "externallmg_1731726114169_IMG_20241115_58503.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114169_IMG_20241115_58503.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67380b23e077c54e532351cb",
    "name": "externallmg_1731726114196_IMG_20241115_58802.jpg",
    "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114196_IMG_20241115_58802.jpg",
    "orientation": "portrait"
  },
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351cc",
  "name": "externallmg_1731726114199_IMG_20241115_59118.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_1731726114199_IMG_20241115_59118.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351cd",
  "name": "externallmg_r_1731726112960_IMG20241115173202.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_r_1731726112960_IMG20241115173202.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351ce",
  "name": "externallmg_r_1731726113461_IMG20241115223615.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_r_1731726113461_IMG20241115223615.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351cf",
  "name": "externallmg_r_1731726112994_IMG20241115173221.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_r_1731726112994_IMG20241115173221.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67380b23e077c54e532351d0",
  "name": "externallmg_r_1731726112879_IMG20241115173154.jpg",
  "path": "cases/6735da35572e264e52122e3a/
externallmg_r_1731726112879_IMG20241115173154.jpg",
  "orientation": "landscape"
}
],
```

```

"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-14T11:08:37.678Z",
"updatedAt": "2024-11-16T03:01:55.189Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 917, 9th Floor, Riverside, Village - Koynavele,
Koynavele, 410208",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Jinu kuttanil Jacob And Jerin Mary Jinu",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "7736266394"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			