

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Shailesh",
    "type": "CREDITOFFICER",
    "_id": "6646d7b96f40574290c0f910",
    "lastName": "SSL",
    "mobileNo": "",
    "workMobileNo": "8850421348",
    "email": "shailesh.ssl@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Shailesh",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "FRONTDESK",
  "firstName": "Bhavika",
```

```
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
}_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.180874893702924",
  "longitude": "73.07531939292994"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
73.07531939292994,
19.180874893702924
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-19",
      "remark": "Rent confirm with Shyam "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-18",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-19",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Usarghar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "My City Phase II Cluster 05 (1 - 6)",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "CL05 - 02",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "17/1, 17/2, 17/3/A, 17/3/B, 17/4, 17/5, 37/1 & Others",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "108",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421201",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivali (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "doors": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "windows": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "fittings": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "finishing": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Semi_Urban",
    "label": "Semi Urban"
  },
  "townplanApprovedByList": {
    "value": "Mumbai_Metropolitan_Region_Development_Authority",
    "label": "Mumbai Metropolitan Region Development Authority"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Tower T - 3",
    "west": "Internal Road & Open Plot",
    "south": "Cluster - IV",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
```

```

    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per site inspection the composition of flat is 1 Bedroom
+ Living Room + Kitchen + 2 Toilets (i.e 1 BHK + 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Building approved plan were not provided & not
verified",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "At the time of visit internal inspection was not allowed hence our report is
based on external site visit only.",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},

```

```
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "63900",
  "landRate": "9600",
  "igrImage": "cases/673afb7ce077c54e53248987/igr_1732014802237_Image.png",
  "squareMeterGuideLineRate": "63900.00",
  "squareFeetGuideLineRate": "5937.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "63900.00",
  "squareMeterGuideLineRate": "63900.00",
  "squareFeetGuideLineRate": "5937.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "Rs. 15,000/- Expected rental income per month.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MMRDA norms",
  "tenantName": "",
  "maintenanceOfFlat": "External Visit Only"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developing area",
  "negativeFactorsOfAffectMarketValue": "No"
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "load_bearings",
    "label": "Load Bearing"
  },
  "qualityOfConstruction": {
```

```
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
}
```



```
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "25",
"flatFloorNo": "1",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "496.10",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/673afb7ce077c54e53248987/
routeMap_1732172997671_Image.png",
    "routeLat": "19.179390",
    "routeLng": "73.074446",
    "stationName": "Dombivali",
    "routeDistance": "6.3 Km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
```

```
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "f1q41g",
    "name": "f1q41g",
    "image": "cases/673afb7ce077c54e53248987/
routeMap_1732172957586_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
```

```
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5412000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "5412000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2945346.00",
  "selectedBuildUpValue": "496.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "673c44f7d1078a4ea7f743fb",
      "name": "externallmg_r_1732003055815_1732003045600_image_8.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003055815_1732003045600_image_8.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "673c44f7d1078a4ea7f743f9",
      "name": "externallmg_r_1732003053434_1732003045600_image_6.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003053434_1732003045600_image_6.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "673c44f7d1078a4ea7f743fc",
      "name": "externallmg_r_1732003054408_1732003045600_image_7.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003054408_1732003045600_image_7.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "673c44f7d1078a4ea7f743fe",
      "name": "externallmg_r_1732003058036_1732003045600_image_10.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003058036_1732003045600_image_10.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
```

```
    "_id": "673c44f7d1078a4ea7f743f7",
    "name": "externallmg_r_1732003051022_1732003045600_image_3.jpg",
    "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003051022_1732003045600_image_3.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11057.00",
    "max": "13320.00"
  },
  "builtUpRateRange": {
    "min": "10052.00",
    "max": "12109.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "451.00",
```

```
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "673afb7ce077c54e53248987",
"ownerName": "Mr. Rohit Hanumant Pachimbare, Mr. Rupesh Hanumant Pachimbare
& Mrs. Meera Hanumant Pachimbare",
"ownerPhoneNo": "8850261947",
"appAddress": "Flat no. 108, 1st Floor, Tower - 2, My City Phase 2, Runwal garden,
Usarghar Kalyan Dombivali ",
"remark": "Rent confirm with Shyam ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "26/10/2021",
      "from": {
        "value": "Owner",
        "label": "Owner"
      },
      "Owner": "Horizon Projects Private Limited",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Rohit Hanumant Pachimbare, Mr. Rupesh Hanumant Pachimbare
& Mrs. Meera Hanumant Pachimbare",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "13386/2021"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "567559",
    "path": "cases/673afb7ce077c54e53248987/
document_1731918662924_1731918660231_Racpc_SionRohit_Pachimbare.pdf",
```

```
"fileName":
"document_1731918662924_1731918660231_Racpc_SionRohit_Pachimbare.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "17/10/2017",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SROT / 27 VILLAGES / 2401 / BP / USARGHAR 03 / VOL - II / 1473 / 2017 "
},
"isHardCopy": false,
"displayStatus": false,
"id": "517067",
"path": "cases/673afb7ce077c54e53248987/
document_1732167863143_154351.pdf",
"fileName": "document_1732167863143_154351.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700019085"
},
"isHardCopy": false,
"displayStatus": false,
```

```
"id": "903958",
"path": "cases/673afb7ce077c54e53248987/
document_1732168346508_113839.pdf",
"fileName": "document_1732168346508_113839.pdf"
}
],
"caseNumber": "012438",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
"id": "441685",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Mon Nov 18 2024 08:31:56 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Rohit Hanumant Pachimbare, Mr. Rupesh Hanumant Pachimbare &
Mrs. Meera Hanumant Pachimbare",
"phone": "8850261947",
"ownershipShare": "",
"email": "",
"id": "571395"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
},
{id": "289264",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "451",
"squareMeterArea": "41.9",
"docFinalBuiltUp": "496.1",
```

```
"docFinalBuiltUpSquareMeter": "46.089999999999996",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "570.00",
"squareMeterArea": "52.95",
"expectedRate": "11289.96",
"percentage": ""
},
"builtUpArea": {
"area": "627.00",
"squareMeterArea": "58.25",
"expectedRate": "10263.60",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "673c72d8e077c54e532589c7",
"property": "Residential Flat",
"area": "570",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "6435280",
"expectedRate": "11289.96",
"builtUpExpectedRate": "10263.60",
"image": "cases/673afb7ce077c54e53248987/
indicator_1732014660100_Image.png",
"squareMeter": "52.95",
"id": "832107"
},
```

```
{
  "carpetArea": {
    "area": "570.00",
    "squareMeterArea": "52.95",
    "expectedRate": "11056.11",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "627.00",
    "squareMeterArea": "58.25",
    "expectedRate": "10051.01",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "673c72d8e077c54e532589c8",
  "property": "Residential Flat",
  "area": "570",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "6301984",
  "expectedRate": "11056.11",
  "builtUpExpectedRate": "10051.01",
  "image": "cases/673afb7ce077c54e53248987/
indicator_1732014688684_Image.png",
  "squareMeter": "52.95",
  "id": "376112"
},
{
  "carpetArea": {
    "area": "576.00",
    "squareMeterArea": "53.51",
    "expectedRate": "12673.61",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "633.60",
```

```
"squareMeterArea": "58.86",
"expectedRate": "11521.46",
"percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "673c72d8e077c54e532589c9",
"property": "Residential Flat",
"area": "576",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "7300000",
"expectedRate": "12673.61",
"builtUpExpectedRate": "11521.46",
"image": "cases/673afb7ce077c54e53248987/
indicator_1732014721409_Image.png",
"squareMeter": "53.51",
"id": "324023"
},
{
  "carpetArea": {
    "area": "510.53",
    "squareMeterArea": "47.43",
    "expectedRate": "13319.49",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "561.58",
    "squareMeterArea": "52.17",
    "expectedRate": "12108.69",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```

```
},
"printlnReport": true,
"_id": "673eddbd572e264e5215224e",
"property": "Residential Flat",
"area": "510.53",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "6800000",
"expectedRate": "13319.49",
"builtUpExpectedRate": "12108.69",
"image": "cases/673afb7ce077c54e53248987/
indicator_1732014752876_Image.png",
"squareMeter": "47.43",
"id": "808795"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "673c44f7d1078a4ea7f743f4",
"name": "externalImg_1732003049902_1732003045600_image_1.png",
"path": "cases/673afb7ce077c54e53248987/
externalImg_1732003049902_1732003045600_image_1.png",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "673c44f7d1078a4ea7f743f5",
"name": "externalImg_r_1732003052026_1732003045600_image_4.jpg",
"path": "cases/673afb7ce077c54e53248987/
externalImg_r_1732003052026_1732003045600_image_4.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "673c44f7d1078a4ea7f743f6",
"name": "externalImg_r_1732003050096_1732003045600_image_2.jpg",
"path": "cases/673afb7ce077c54e53248987/
externalImg_r_1732003050096_1732003045600_image_2.jpg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c44f7d1078a4ea7f743f7",
  "name": "externallmg_r_1732003051022_1732003045600_image_3.jpg",
  "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003051022_1732003045600_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c44f7d1078a4ea7f743f8",
  "name": "externallmg_r_1732003048841_1732003045600_image_0.jpg",
  "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003048841_1732003045600_image_0.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c44f7d1078a4ea7f743f9",
  "name": "externallmg_r_1732003053434_1732003045600_image_6.jpg",
  "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003053434_1732003045600_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c44f7d1078a4ea7f743fa",
  "name": "externallmg_r_1732003052784_1732003045600_image_5.jpg",
  "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003052784_1732003045600_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673c44f7d1078a4ea7f743fb",
  "name": "externallmg_r_1732003055815_1732003045600_image_8.jpg",
  "path": "cases/673afb7ce077c54e53248987/
externallmg_r_1732003055815_1732003045600_image_8.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "673c44f7d1078a4ea7f743fc",
      "name": "externalImg_r_1732003054408_1732003045600_image_7.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externalImg_r_1732003054408_1732003045600_image_7.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "673c44f7d1078a4ea7f743fd",
      "name": "externalImg_r_1732003056806_1732003045600_image_9.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externalImg_r_1732003056806_1732003045600_image_9.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "673c44f7d1078a4ea7f743fe",
      "name": "externalImg_r_1732003058036_1732003045600_image_10.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externalImg_r_1732003058036_1732003045600_image_10.jpg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "673c44db572e264e52149432",
      "name": "externalImg_r_1732003033037_1732003031525_image_0.jpg",
      "path": "cases/673afb7ce077c54e53248987/
externalImg_r_1732003033037_1732003031525_image_0.jpg",
      "orientation": "landscape"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalName": "AGR.pdf",
      "filename": "1732014818610_AGR.pdf",
      "path": "cases/673afb7ce077c54e53248987/
processingDocuments/1732014818610_AGR.pdf",
      "size": "8047359",
```

```
"createdAt": "Tue Nov 19 2024 11:13:40 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1732003049902_1732003045600_image_1.png",
  "filename":
"1732014818773_externallmg_1732003049902_1732003045600_image_1.png",
  "path": "cases/673afb7ce077c54e53248987/processingDocuments/1732014818773_externallmg_1732003049902_1732003045600_image_1.png",
  "size": "112973",
  "createdAt": "Tue Nov 19 2024 11:13:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_r_1732003033037_1732003031525_image_0.jpg",
  "filename":
"1732014818779_externallmg_r_1732003033037_1732003031525_image_0.jpg",
  "path": "cases/673afb7ce077c54e53248987/processingDocuments/1732014818779_externallmg_r_1732003033037_1732003031525_image_0.jpg",
  "size": "2175884",
  "createdAt": "Tue Nov 19 2024 11:13:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_r_1732003048841_1732003045600_image_0.jpg",
  "filename":
"1732014819526_externallmg_r_1732003048841_1732003045600_image_0.jpg",
  "path": "cases/673afb7ce077c54e53248987/processingDocuments/1732014819526_externallmg_r_1732003048841_1732003045600_image_0.jpg",
  "size": "2175884",
  "createdAt": "Tue Nov 19 2024 11:13:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1732014819574_IGR01.pdf",
  "path": "cases/673afb7ce077c54e53248987/processingDocuments/1732014819574_IGR01.pdf",
  "size": "158679",
  "createdAt": "Tue Nov 19 2024 11:13:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1732014819907_IGR02.pdf",
  "path": "cases/673afb7ce077c54e53248987/processingDocuments/1732014819907_IGR02.pdf",
```

```
"size": "157230",
"createdAt": "Tue Nov 19 2024 11:13:40 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=Rohit.xlsx",
"filename": "1732014819928_Summary_NewRohit.xlsx",
"path": "cases/673afb7ce077c54e53248987/
processingDocuments/1732014819928_Summary_NewRohit.xlsx",
"size": "983572",
"createdAt": "Tue Nov 19 2024 11:13:40 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-18T08:31:56.244Z",
"updatedAt": "2024-11-21T07:14:53.774Z",
"__v": 0,
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 108, 1st Floor, Wing - CL05 - 02, My City Phase II
Cluster 05 (1 - 6), Village - Usarghar, Dombivali (East), Taluka - Kalyan, District -
Thane, 421201, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Nidhesh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"rerald": "",
"siteVisitContactNo": "8097499140",
"siteVisitDate": "2024-11-19",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
```

```
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 451.00",
"flatRate": "12000",
"landOtherRate": "9500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 409.00\nUtility Area in Sq. Ft. =
42.00\n\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Nov 21 2024 04:52:16 GMT+0000 (Coordinated
Universal Time)"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			