

```
{
  "typeOfReport": {
    "value": "Office",
    "label": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "671869b5fd14bf9350a9d942"
    },
    "firstName": "Ashvin",
    "type": "CREDITOFFICER",
    "_id": "671869d80385619362305525",
    "email": "ashvin.raut@sbi.co.in",
    "lastName": "Raut",
    "mobileNo": "",
    "workMobileNo": "7768845649"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "64b7ca68d0368073e3fa808a",
  "name": "Nanded",
  "shortName": "NED",
  "email": "nanded@vastukala.org",
  "address": "Shop No 24, Stadium Complex, Gokul Nagar Station Road,
Nanded-431602",
  "city": "nanded"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "671869b5fd14bf9350a9d942",
  "name": "R B O Region 1 Nanded",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "ashvin.raut@sbi.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SBI Building, Industrial Area, Shivaji Nagar Main Road, Nanded 431602
Maharashtra"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
```

```
"role": "VALUER",
"firstName": "Sharadkumar",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "6006d4ce5080a310ac1fdcf2",
"role": "ADMIN",
"firstName": "Jagdish ",
"email": "jagdish.bhatt@vastukala.org",
"lastName": "Bhatt",
"mobileNo": "8425864014",
"designation": "",
"shortName": "JB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
```

```
{
  "title": {
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.212965428702013",
  "longitude": "72.96010272745754"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Majiwade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ashar Metro Towers Wing-C Apartment (Mhada)",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Vartak Nagar",
  "label": false
},
"street2": {
  "status": false,
```

```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```

```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "117",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```



```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    }
  }
}
```

```
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
  },
  "apfDetails": {
    "buildings": [],
    "compositions": []
  },
  "igrFinalRate": {
    "floorRatePercentage": "0.00"
  },
  "outgoingDetail": {
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "isSiteVisitAllowed": true
  },
  "finalPlinthArea": {
    "area": "0.00"
  },
  "routeMap": {
    "routeMapDetail": {
      "routeMapImg": "",
      "routeLat": "",
      "routeLng": "",
      "stationName": "",
      "routeDistance": ""
    },
    "finalLatLng": {
      "coordinates": []
    },
    "locationMapImg": []
  },
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    }
  }
}
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
```



```
"_id": "673f27fc572e264e5215911c",
"ownerName": "M/S. SRK Agro Food And Fuel Pvt. Ltd (Commercial Office) Raosaheb
Dhondibaji Kawale",
"ownerPhoneNo": "8208930634",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8208930634",
"contactPersonName": "M/S. SRK Agro Food And Fuel Pvt. Ltd (Commercial Office)
Raosaheb Dhondibaji Kawale",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "M/S. SRK Agro Food And Fuel Pvt. Ltd (Commercial Office) Raosaheb
Dhondibaji Kawale",
    "phone": "8208930634",
    "ownershipShare": "",
    "email": "",
    "id": "978329"
  }
],
"caseReferredBy": "6084131a13f01f158c6ea1f3",
"relationWithOwner": "self",
"fullAddress": "Commercial Office No. 117, 1st Floor, Ashar Metro Towers Wing-C
Apartment (Mhada), Vartak Nagar, Village - Majiwade, Thane West, Taluka - Thane,
District - Thane, Thane, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1732192248981_Raosaheb_Kawale_at_mumbai_shop_no_
117_at_majiwade_tal__Di_Thane.pdf",
    "path": "cases/673f27fc572e264e5215911c/document_1732192248981_Raosaheb_
Kawale_at_mumbai_shop_no_117_at_majiwade_tal__Di_Thane.pdf",
    "id": "757320",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Nov 21 2024 12:30:52 GMT+0000 (Coordinated Universal Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
```

```
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"reald": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "012497",
"createdBy": "6006d4ce5080a310ac1fd2c",
"caseHistory": [
  {
    "id": "872276",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Thu Nov 21 2024 12:30:52 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67454ea6e077c54e5328cdd9",
    "name":
"externallmg_1732595366496_WhatsApp_Image_20241126_at_093425.jpeg",
    "path": "cases/673f27fc572e264e5215911c/
externallmg_1732595366496_WhatsApp_Image_20241126_at_093425.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67454ea6e077c54e5328cdda",
    "name":
"externallmg_1732595366498_WhatsApp_Image_20241126_at_093426.jpeg",
    "path": "cases/673f27fc572e264e5215911c/
externallmg_1732595366498_WhatsApp_Image_20241126_at_093426.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67454ea6e077c54e5328cddb",
    "name":
"externallmg_1732595366514_WhatsApp_Image_20241126_at_093427_1.jpeg",
    "path": "cases/673f27fc572e264e5215911c/
externallmg_1732595366514_WhatsApp_Image_20241126_at_093427_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67454ea6e077c54e5328cddc",
    "name":
"externallmg_1732595366518_WhatsApp_Image_20241126_at_093427.jpeg",
    "path": "cases/673f27fc572e264e5215911c/
externallmg_1732595366518_WhatsApp_Image_20241126_at_093427.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67454ea6e077c54e5328cddd",
    "name":
"externallmg_1732595366536_WhatsApp_Image_20241126_at_093428_1.jpeg",
    "path": "cases/673f27fc572e264e5215911c/
externallmg_1732595366536_WhatsApp_Image_20241126_at_093428_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67454ea6e077c54e5328cdde",
    "name":
"externallmg_1732595366538_WhatsApp_Image_20241126_at_093428.jpeg",
    "path": "cases/673f27fc572e264e5215911c/
externallmg_1732595366538_WhatsApp_Image_20241126_at_093428.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67454ea6e077c54e5328cddf",
    "name":
"externallmg_1732595366542_WhatsApp_Image_20241126_at_093429.jpeg",
    "path": "cases/673f27fc572e264e5215911c/
externallmg_1732595366542_WhatsApp_Image_20241126_at_093429.jpeg",
```

```
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-21T12:30:52.668Z",
"updatedAt": "2024-11-26T04:29:26.728Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdcf2"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			