

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8c3"
    },
    "firstName": "Sushmita Rivankar",
    "type": "CREDITOFFICER",
    "_id": "64c762ee05efe8082a8ca605",
    "lastName": "Rivankar",
    "mobileNo": "",
    "workMobileNo": "8591333808",
    "email": "sushmita.rivankar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Sushmita Rivankar",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8c3",
  "branchCode": "11688",
  "type": "BRANCH",
  "name": "SME Backbay Reclamation Branch",
  "email": "sbi.11688@sbi.co.in",
  "mobileNo": "22819539",
  "alternateMobileNo": "",
  "address": "Mittal Court, 'B' Wing, Ground Floor, Nariman Point, Mumbai - 400 021,
State - Maharashtra, Country - India.",
  "ledgerName": "Vishok Kumar",
  "fax": "22023508",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
```

```
"latitude": "20.165600547702194",
"longitude": "72.78533066718661"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.78533066718661,
    20.165600547702194
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "25/11/2024 12:00 am"
    },
    {
      "dateTime": "25/11/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Solsumba",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Valsad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Umbergaon",
```

```
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "280/1",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Umbergaon Notifies Industrial Area",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
```

```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```



```
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "396165",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Umbergaon",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
  }
}
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
```

```
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
```

```
"title": "Interior Decorations",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```



```
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67442301d1078a4ea7f99e60",
"ownerName": "Vaibhav Fitting India Pvt Ltd ",
"ownerPhoneNo": "0000000000",
"appAddress": "Plot no 280/1,Umbergaon Notified Industrial Area,GIDC,Solsumba
Village,Umbergaon",
"remark": "Cont Person Hitesh Mav\nMob no-9033601441\n",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
"path": "cases/67442301d1078a4ea7f99e60/document_1732518130652_1732518127798_1731586138569007100_attach_139508789395690180.pdf",
"fileName": "document_1732518130652_1732518127798_1731586138569007100_attach_139508789395690180.pdf",
"id": "568034",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Mon Nov 25 2024 07:10:56 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Previous Valuation Report",
    "value": "60ae1248aa6d152c1801b2ee"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67442301d1078a4ea7f99e60/document_1732518215623_1732518203505_Vaibhav_Fitting_India_LtdSBI_SME_Backbay_Reclamation.pdf",
  "fileName": "document_1732518215623_1732518203505_Vaibhav_Fitting_India_LtdSBI_SME_Backbay_Reclamation.pdf",
  "id": "745380",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Mon Nov 25 2024 07:10:56 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Previous Valuation Report",
    "value": "60ae1248aa6d152c1801b2ee"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67442301d1078a4ea7f99e60/document_1732518330393_1732518327722_Vaibhav_FittingLB_Valuation_Report.pdf",
  "fileName": "document_1732518330393_1732518327722_Vaibhav_FittingLB_Valuation_Report.pdf",
  "id": "293944",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Mon Nov 25 2024 07:10:56 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Approved Building Plan",
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67442301d1078a4ea7f99e60/document_1732518691531_17325186
```

```
89371_PDF_GO_MYSCAN_20241123_0001.PDF",
  "fileName": "document_1732518691531_1732518689371_PDF_GO_MYSCAN_202
41123_0001.PDF",
  "id": "532527",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Mon Nov 25 2024 07:12:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Approved Building Plan",
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67442301d1078a4ea7f99e60/document_1732518719283_17325187
16876_1731992191939000900_attach_139512849930360030.pdf",
  "fileName": "document_1732518719283_1732518716876_1731992191939000900_
attach_139512849930360030.pdf",
  "id": "572524",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Mon Nov 25 2024 07:12:04 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012559",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "305947",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Nov 25 2024 07:10:57 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Vaibhav Fitting India Pvt Ltd ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "224407"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c91f",
    "name": "externallmg_1732718872034_1732718865167_image_0.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718872034_1732718865167_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c920",
    "name": "externallmg_1732718872202_1732718865167_image_1.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718872202_1732718865167_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c921",
    "name": "externallmg_1732718872378_1732718865167_image_2.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718872378_1732718865167_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c922",
    "name": "externallmg_1732718872572_1732718865167_image_3.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718872572_1732718865167_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c923",
    "name": "externallmg_1732718872742_1732718865167_image_4.jpeg",
```

```
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718872742_1732718865167_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c924",
    "name": "externallmg_1732718872922_1732718865167_image_5.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718872922_1732718865167_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c925",
    "name": "externallmg_1732718873128_1732718865167_image_6.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718873128_1732718865167_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c926",
    "name": "externallmg_1732718873283_1732718865167_image_7.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718873283_1732718865167_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c927",
    "name": "externallmg_1732718873503_1732718865167_image_8.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718873503_1732718865167_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6747311b520246c6c062c928",
    "name": "externallmg_1732718873756_1732718865167_image_9.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718873756_1732718865167_image_9.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6747311b520246c6c062c929",
  "name": "externallmg_1732718873954_1732718865167_image_10.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718873954_1732718865167_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6747311b520246c6c062c92a",
  "name": "externallmg_1732718874094_1732718865167_image_11.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874094_1732718865167_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6747311b520246c6c062c92b",
  "name": "externallmg_1732718874137_1732718865167_image_12.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874137_1732718865167_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6747311b520246c6c062c92c",
  "name": "externallmg_1732718874341_1732718865167_image_13.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874341_1732718865167_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6747311b520246c6c062c92d",
  "name": "externallmg_1732718874521_1732718865167_image_14.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874521_1732718865167_image_14.jpeg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6747311b520246c6c062c92e",
      "name": "externallmg_1732718874571_1732718865167_image_15.jpeg",
      "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874571_1732718865167_image_15.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6747311b520246c6c062c92f",
      "name": "externallmg_1732718874674_1732718865167_image_16.jpeg",
      "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874674_1732718865167_image_16.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6747311b520246c6c062c930",
      "name": "externallmg_1732718874735_1732718865167_image_17.jpeg",
      "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874735_1732718865167_image_17.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6747311b520246c6c062c931",
      "name": "externallmg_1732718874932_1732718865167_image_18.jpeg",
      "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718874932_1732718865167_image_18.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6747311b520246c6c062c932",
      "name": "externallmg_1732718875110_1732718865167_image_19.jpeg",
      "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718875110_1732718865167_image_19.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747313d520246c6c062c979",
  "name": "externallmg_1732718906725_1732718903568_image_0.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718906725_1732718903568_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747313d520246c6c062c97a",
  "name": "externallmg_1732718906808_1732718903568_image_1.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718906808_1732718903568_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747313d520246c6c062c97b",
  "name": "externallmg_1732718906946_1732718903568_image_2.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718906946_1732718903568_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747313d520246c6c062c97c",
  "name": "externallmg_1732718907100_1732718903568_image_3.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907100_1732718903568_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747313d520246c6c062c97d",
  "name": "externallmg_1732718907237_1732718903568_image_4.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907237_1732718903568_image_4.jpeg",
  "orientation": "landscape"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c97e",
    "name": "externallmg_1732718907348_1732718903568_image_5.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907348_1732718903568_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c97f",
    "name": "externallmg_1732718907465_1732718903568_image_6.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907465_1732718903568_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c980",
    "name": "externallmg_1732718907568_1732718903568_image_7.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907568_1732718903568_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c981",
    "name": "externallmg_1732718907780_1732718903568_image_8.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907780_1732718903568_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c982",
    "name": "externallmg_1732718907876_1732718903568_image_9.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907876_1732718903568_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6747313d520246c6c062c983",
    "name": "externallmg_1732718907920_1732718903568_image_10.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718907920_1732718903568_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c984",
    "name": "externallmg_1732718908046_1732718903568_image_11.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908046_1732718903568_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c985",
    "name": "externallmg_1732718908132_1732718903568_image_12.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908132_1732718903568_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c986",
    "name": "externallmg_1732718908197_1732718903568_image_13.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908197_1732718903568_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c987",
    "name": "externallmg_1732718908281_1732718903568_image_14.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908281_1732718903568_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6747313d520246c6c062c988",
    "name": "externallmg_1732718908383_1732718903568_image_15.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908383_1732718903568_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c989",
    "name": "externallmg_1732718908450_1732718903568_image_16.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908450_1732718903568_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c98a",
    "name": "externallmg_1732718908550_1732718903568_image_17.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908550_1732718903568_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c98b",
    "name": "externallmg_1732718908706_1732718903568_image_18.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908706_1732718903568_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747313d520246c6c062c98c",
    "name": "externallmg_1732718908854_1732718903568_image_19.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718908854_1732718903568_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa268",
```

```
    "name": "externallmg_1732718946358_1732718942441_image_0.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718946358_1732718942441_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa269",
    "name": "externallmg_1732718946466_1732718942441_image_1.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718946466_1732718942441_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa26a",
    "name": "externallmg_1732718946553_1732718942441_image_2.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718946553_1732718942441_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa26b",
    "name": "externallmg_1732718946671_1732718942441_image_3.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718946671_1732718942441_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa26c",
    "name": "externallmg_1732718946788_1732718942441_image_4.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718946788_1732718942441_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa26d",
    "name": "externallmg_1732718946877_1732718942441_image_5.jpeg",
```

```
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718946877_1732718942441_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa26e",
    "name": "externallmg_1732718946963_1732718942441_image_6.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718946963_1732718942441_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa26f",
    "name": "externallmg_1732718947036_1732718942441_image_7.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947036_1732718942441_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa270",
    "name": "externallmg_1732718947151_1732718942441_image_8.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947151_1732718942441_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa271",
    "name": "externallmg_1732718947216_1732718942441_image_9.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947216_1732718942441_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa272",
    "name": "externallmg_1732718947344_1732718942441_image_10.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947344_1732718942441_image_10.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473164e077c54e532aa273",
  "name": "externallmg_1732718947460_1732718942441_image_11.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947460_1732718942441_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473164e077c54e532aa274",
  "name": "externallmg_1732718947533_1732718942441_image_12.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947533_1732718942441_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473164e077c54e532aa275",
  "name": "externallmg_1732718947609_1732718942442_image_13.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947609_1732718942442_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473164e077c54e532aa276",
  "name": "externallmg_1732718947705_1732718942442_image_14.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947705_1732718942442_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473164e077c54e532aa277",
  "name": "externallmg_1732718947810_1732718942442_image_15.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947810_1732718942442_image_15.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa278",
    "name": "externallmg_1732718947950_1732718942442_image_16.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718947950_1732718942442_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa279",
    "name": "externallmg_1732718948050_1732718942442_image_17.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718948050_1732718942442_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa27a",
    "name": "externallmg_1732718948140_1732718942442_image_18.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718948140_1732718942442_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473164e077c54e532aa27b",
    "name": "externallmg_1732718948226_1732718942442_image_19.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718948226_1732718942442_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473188e077c54e532aa2dd",
    "name": "externallmg_1732718982836_1732718979157_image_0.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718982836_1732718979157_image_0.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473188e077c54e532aa2de",
  "name": "externallmg_1732718982934_1732718979157_image_1.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718982934_1732718979157_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473188e077c54e532aa2df",
  "name": "externallmg_1732718983015_1732718979157_image_2.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983015_1732718979157_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473188e077c54e532aa2e0",
  "name": "externallmg_1732718983204_1732718979157_image_3.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983204_1732718979157_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473188e077c54e532aa2e1",
  "name": "externallmg_1732718983259_1732718979157_image_4.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983259_1732718979157_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67473188e077c54e532aa2e2",
  "name": "externallmg_1732718983300_1732718979157_image_5.jpeg",
  "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983300_1732718979157_image_5.jpeg",
  "orientation": "landscape"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473188e077c54e532aa2e3",
    "name": "externallmg_1732718983394_1732718979157_image_6.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983394_1732718979157_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473188e077c54e532aa2e4",
    "name": "externallmg_1732718983557_1732718979157_image_7.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983557_1732718979157_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473188e077c54e532aa2e5",
    "name": "externallmg_1732718983639_1732718979157_image_8.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983639_1732718979157_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473188e077c54e532aa2e6",
    "name": "externallmg_1732718983676_1732718979157_image_9.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983676_1732718979157_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67473188e077c54e532aa2e7",
    "name": "externallmg_1732718983822_1732718979157_image_10.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externallmg_1732718983822_1732718979157_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "67473188e077c54e532aa2e8",
    "name": "externalImg_1732718983906_1732718979157_image_11.jpeg",
    "path": "cases/67442301d1078a4ea7f99e60/
externalImg_1732718983906_1732718979157_image_11.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-25T07:10:57.063Z",
"updatedAt": "2024-11-27T14:49:44.452Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "65dee3f79a876858ab30487f",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Land and Building No. Ground Floor, Plot No. 280/1,
Umbergaon Notifies Industrial Area, Village - Solsumba, Umbergaon, Taluka -
Umbergaon, District - Valsad, 396165, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Hitesh Mav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"reId": "",
"siteVisitContactNo": "9033601441"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
