

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Rohan ",
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Rohan ",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
```

```
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.183134314568427",
  "longitude": "73.08761856377888"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
73.08761856377888,
19.183134314568427
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-26",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-25",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gharivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "29",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": ".35",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Runwal Gardens Phase 4 Bldg. No. 35 - 36",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kalyan - Shilphata Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "4/1, 4/2, 4/3, 4/4, 4/5, 4/6, 4/9, 4/10, 4/11, 5/1, 5/2 & Others of Village -
Gharivali & Survey No. 44/1, 44/2, 44/3, 44/4, 44/5 & Others of Village - Usarghar",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2908",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 201",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Kalyan_Dombivali_Municipal_Corporation",
"label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Internal Road & CRM Office",
"west": "Building No. 34",
"south": "Building No. 36",
"east": "Internal Road"
},
"asPerDocumentAgreement": {
"north": "By property bearing S. Nos. 42A, 42B & Ors. at Village - Gharivali",
"west": "By Property bearing S. Nos. 43, 93 & Ors. at Village - Usarghar",
"south": "By Plot bearing S. No. 2, 3, 37 & Ors. at Village - Gharivali",
"east": "By 30.00 mt. wide Kalyan - Shil Road"
},
"unitBoundaries": {
"asPerActual": {
"north": "Building is under construction",
"east": "Building is under construction",
"south": "Building is under construction",
"west": "Building is under construction"
},
"asPerDocument": {
"north": "Flat No. 2907",
```

```
"east": "Flat No. 2909",
"south": "Marginal Space",
"west": "Marginal Space"
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Plan, the composition of Residential Flat will be 2 Bedrooms + Living Room + Kitchen + 2 Toilets + Balcony Area + Utility Area.",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Document No.SROT / Growth Centre / 2401 / BP / ITP - Usarghar - Gharivali - Sagaon - 01 / Site - A / Vol - 31 / 720 / 2021 Dated 05.08.2021 issued by MMRDA ",
"approvePlanVerified": "N.A., as the building is under construction",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "At the time of visit, Builder has not allowed for Internal site inspection, measurement and Internal Photographs of the property. The details about the work progress status has been provided by Customer Relationship Manager - Mr. Ashish Ghogale (Contact No. 7977732370).",
  "depreciationPercentage": ""
}
```

```
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "63900",
  "landRate": "9600",
  "igrImage": "cases/6744525de34a0461d8c0fad7/igr_1732680863736_Image.png",
  "squareMeterGuideLineRate": "73485.00",
  "squareFeetGuideLineRate": "6827.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "0",
  "rate": "63900.00",
  "squareMeterGuideLineRate": "73485.00",
  "squareFeetGuideLineRate": "6827.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "22,000/- (Expected rental income per month after completion\nof construction works)",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MMRDA / KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
```

```
"marketabilityList": {
  "value": "Good",
  "label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Basement + Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2026",
    "fullDate": "1/1/2026"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  }
}
```

```
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
```



```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "32",
"flatFloorNo": "29",
"noOfLifts": "6",
"noOfDwellingUnitsInBuilding": "9"
},
"finalPlinthArea": {
"area": "752.40",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/6744525de34a0461d8c0fad7/
routeMap_1732684411165_Image.png",
"routeLat": "19.182285",
"routeLng": "73.087170",
"stationName": "Dombivli",
"routeDistance": "4.9 Km.",
"routeStation": {
```

```
    "value": "Railway_Station",
    "label": "Railway Station"
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "1myqgb",
    "name": "1myqgb",
    "image": "cases/6744525de34a0461d8c0fad7/
routeMap_1732684343437_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
```

```
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8550000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "8550000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Nov 27 2024 08:31:32 GMT+0000 (Coordinated Universal Time)",
  "number": "2309223",
  "dayCount": "9",
  "monthCount": "308",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "23",
"percentage": "26.285714285714285",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "23",
  "percentage": "4.60",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "23",
  "percentage": "4.60",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "23",
  "percentage": "2.30",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
```

```
"status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "47.79",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5136635.00",
  "selectedBuildUpValue": "752.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6745da3ae34a0461d8c1f0cf",
      "name": "externallmg_r_1732631090682_1732631072790_image_6.jpg",
      "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631090682_1732631072790_image_6.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6745da3ae34a0461d8c1f0d1",
      "name": "externallmg_r_1732631092832_1732631072790_image_8.jpg",
      "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631092832_1732631072790_image_8.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6745da3ae34a0461d8c1f0d3",
      "name": "externallmg_r_1732631094004_1732631072790_image_9.jpg",
      "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631094004_1732631072790_image_9.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0d2",
    "name": "externallmg_r_1732631091835_1732631072790_image_7.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631091835_1732631072790_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0cb",
    "name": "externallmg_r_1732631085455_1732631072790_image_2.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631085455_1732631072790_image_2.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11482.00",
    "max": "12975.00"
  },
  "builtUpRateRange": {
    "min": "10438.00",
    "max": "11796.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "684.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6744525de34a0461d8c0fad7",
"ownerName": "Anil Kumar Kota & Swapna Kota",
"ownerPhoneNo": "9323736346",
"appAddress": "Flat no. 2908, 29th Floor, Building no. 35, Runwal Garden Phase 4,
Usarghar Kalyan Dombivali ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Index - II",
      "value": "60ae1287aa6d152c1801b415"
    },
    "inputs": {
      "documentDate": "22/11/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Runwal Residency Private Limited",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Anil Kumar Kota & Swapna Kota",
      "number": {
```

```
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "16706/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "243227",
"path": "cases/6744525de34a0461d8c0fad7/
document_1732530772060_27052.pdf",
"fileName": "document_1732530772060_27052.pdf"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "22/11/2024",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "Runwal Residency Private Limited",
    "to": {
      "value": "Allottee",
      "label": "Allottee"
    },
    "Allottee": "Anil Kumar Kota & Swapna Kota",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "16706/2024"
},
"isHardCopy": false,
"displayStatus": true,
"fileName":
"document_1732689771851_1732680959633_Adobe_Scan_26_Nov_2024_4.pdf",
"path": "cases/6744525de34a0461d8c0fad7/
document_1732689771851_1732680959633_Adobe_Scan_26_Nov_2024_4.pdf",
"id": "743494",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Nov 27 2024 06:42:55 GMT+0000 (Coordinated Universal Time)"
},
{
```

```
"documentType": {
  "value": "60ae129faa6d152c1801b47d",
  "label": "RERA Certificate"
},
"inputs": {
  "documentDate": "15/10/2021",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P51700031319"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1732689814547_rera.pdf",
"path": "cases/6744525de34a0461d8c0fad7/document_1732689814547_rera.pdf",
"id": "743581",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Nov 27 2024 06:43:34 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "SROT / Growth Centre / 2401 / BP / ITP - Usarghar - Gharivali -
Sagaon - 01 / Site - A / Vol - 31 / 720 / 2021 Dated 05.08.2021"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1732689841725_cc.pdf",
  "path": "cases/6744525de34a0461d8c0fad7/document_1732689841725_cc.pdf",
  "id": "105469",
```

```
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Nov 27 2024 06:44:02 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "SROT / Growth Centre / 2401 / BP / ITP - Usarghar - Gharivali -
Sagaon - 01 / Site - A / Vol - 31 / 720 / 2021 Dated 05.08.2021"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1732689861388_29th.pdf",
  "path": "cases/6744525de34a0461d8c0fad7/document_1732689861388_29th.pdf",
  "id": "598607",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Nov 27 2024 06:44:22 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012575",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "335273",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Nov 25 2024 10:33:01 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Anil Kumar Kota & Swapna Kota",
    "phone": "9323736346",
    "ownershipShare": "",
    "email": "",
    "id": "550450"
  }
]
```

```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "177674",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "684",
    "squareMeterArea": "63.55",
    "docFinalBuiltUp": "752.4",
    "docFinalBuiltUpSquareMeter": "69.905",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "632.00",
      "squareMeterArea": "58.71",
      "expectedRate": "12974.68",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "695.20",
      "squareMeterArea": "64.59",
      "expectedRate": "11795.17",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",

```

```
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67469cc9e077c54e5329c558",
"property": "Runwal Garden, Dombivali East",
"area": "632",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Higher",
"source": "square_yards",
"expectedPrice": "8200000",
"expectedRate": "12974.68",
"builtUpExpectedRate": "11795.17",
"image": "cases/6744525de34a0461d8c0fad7/
indicator_1732680568557_Image.png",
"squareMeter": "58.71",
"id": "479188"
},
{
"carpetArea": {
"area": "918.00",
"squareMeterArea": "85.29",
"expectedRate": "12527.23",
"percentage": ""
},
"builtUpArea": {
"area": "1009.80",
"squareMeterArea": "93.81",
"expectedRate": "11388.39",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67469cc9e077c54e5329c559",
"property": "Runwal Garden, Dombivali East",
"area": "918",
"builtUpPercentage": "10",
```

```
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "19",
"source": "https://www.99acres.com/",
"expectedPrice": "11500000",
"expectedRate": "12527.23",
"builtUpExpectedRate": "11388.39",
"image": "cases/6744525de34a0461d8c0fad7/
indicator_1732680608524_Image.png",
"squareMeter": "85.29",
"id": "125899"
},
{
"carpetArea": {
"area": "614.00",
"squareMeterArea": "57.04",
"expectedRate": "11545.60",
"percentage": ""
},
"builtUpArea": {
"area": "675.40",
"squareMeterArea": "62.75",
"expectedRate": "10496.00",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67469cc9e077c54e5329c55a",
"property": "Runwal Garden, Dombivali East",
"area": "614",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "4",
"source": "Index_no.2",
"expectedPrice": "7089000",
"expectedRate": "11545.60",
"builtUpExpectedRate": "10496.00",
"image": "cases/6744525de34a0461d8c0fad7/
indicator_1732680712114_Image.png",
```



```
"squareMeter": "57.04",
"id": "144157"
},
{
  "carpetArea": {
    "area": "350.00",
    "squareMeterArea": "32.52",
    "expectedRate": "11481.43",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "385.00",
    "squareMeterArea": "35.77",
    "expectedRate": "10437.66",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67469cc9e077c54e5329c55b",
  "property": "Runwal Garden, Dombivali East",
  "area": "350",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "18",
  "source": "Index_no.2",
  "expectedPrice": "4018500",
  "expectedRate": "11481.43",
  "builtUpExpectedRate": "10437.66",
  "image": "cases/6744525de34a0461d8c0fad7/
indicator_1732680797032_Image.png",
  "squareMeter": "32.52",
  "id": "350871"
},
{
  "carpetArea": {
    "area": "505.00",
    "squareMeterArea": "46.92",
    "expectedRate": "12079.21",
    "percentage": ""
  },
```

```
    },
    "builtUpArea": {
      "area": "555.50",
      "squareMeterArea": "51.61",
      "expectedRate": "10981.10",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printInReport": true,
    "_id": "67469cc9e077c54e5329c55c",
    "property": "Runwal Garden, Dombivali East",
    "area": "505",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "17",
    "source": "magic_bricks",
    "expectedPrice": "6100000",
    "expectedRate": "12079.21",
    "builtUpExpectedRate": "10981.10",
    "image": "cases/6744525de34a0461d8c0fad7/
indicator_1732680828017_Image.png",
    "squareMeter": "46.92",
    "id": "204728"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0ca",
    "name": "externalImg_1732631083224_1732631072790_image_0.png",
    "path": "cases/6744525de34a0461d8c0fad7/
externalImg_1732631083224_1732631072790_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0cb",
```

```
    "name": "externallmg_r_1732631085455_1732631072790_image_2.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631085455_1732631072790_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0cc",
    "name": "externallmg_r_1732631086659_1732631072790_image_3.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631086659_1732631072790_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0cd",
    "name": "externallmg_r_1732631084354_1732631072790_image_1.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631084354_1732631072790_image_1.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0ce",
    "name": "externallmg_r_1732631088116_1732631072790_image_4.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631088116_1732631072790_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0cf",
    "name": "externallmg_r_1732631090682_1732631072790_image_6.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631090682_1732631072790_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0d0",
    "name": "externallmg_r_1732631089420_1732631072790_image_5.jpg",
```

```
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631089420_1732631072790_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0d1",
    "name": "externallmg_r_1732631092832_1732631072790_image_8.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631092832_1732631072790_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0d2",
    "name": "externallmg_r_1732631091835_1732631072790_image_7.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631091835_1732631072790_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6745da3ae34a0461d8c1f0d3",
    "name": "externallmg_r_1732631094004_1732631072790_image_9.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631094004_1732631072790_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6745da0ed1078a4ea7facc11",
    "name": "externallmg_r_1732631052563_1732631051860_image_0.jpg",
    "path": "cases/6744525de34a0461d8c0fad7/
externallmg_r_1732631052563_1732631051860_image_0.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "11000.pdf",
    "filename": "1732680935715_11000.pdf",
```

```
    "path": "cases/6744525de34a0461d8c0fad7/
processingDocuments/1732680935715_11000.pdf",
    "size": "233464",
    "createdAt": "Wed Nov 27 2024 04:15:38 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1722838296456_1718776194681_1716026508753_17153236343
39_1711606660630_1700891975573_1695465043548_1694516251783_16942415908
59_Calculation_1_2.xlsx",
    "filename": "1732680935820_1722838296456_1718776194681_1716026508753_1
715323634339_1711606660630_1700891975573_1695465043548_1694516251783_1
694241590859_Calculation_1_2.xlsx",
    "path": "cases/6744525de34a0461d8c0fad7/processingDocuments/1732680935820
_1722838296456_1718776194681_1716026508753_1715323634339_1711606660630
_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2
.xlsx",
    "size": "3835640",
    "createdAt": "Wed Nov 27 2024 04:15:38 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_10687.pdf",
    "filename": "1732680937884_igr_10687.pdf",
    "path": "cases/6744525de34a0461d8c0fad7/
processingDocuments/1732680937884_igr_10687.pdf",
    "size": "204424",
    "createdAt": "Wed Nov 27 2024 04:15:38 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Adobe Scan 26 Nov 2024 (4).pdf",
    "filename": "1732680959633_Adobe_Scan_26_Nov_2024_4.pdf",
    "path": "cases/6744525de34a0461d8c0fad7/
processingDocuments/1732680959633_Adobe_Scan_26_Nov_2024_4.pdf",
    "size": "3575575",
    "createdAt": "Wed Nov 27 2024 04:16:00 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-25T10:33:02.024Z",
"updatedAt": "2024-11-27T08:41:55.912Z",
"__v": 0,
```

```
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2908, 29th Floor, Building No .35, Runwal Gardens
Phase 4 Bldg. No. 35 - 36, Kalyan - Shilphata Road, Village - Gharivali, Dombivli (East),
Taluka - Kalyan, District - Thane, PIN Code - 421 201, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Ashish Ghogale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Customer Relationship Manager",
"rerald": "",
"siteVisitContactNo": "7977732370",
"buildingServicesRate": "2600",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 684.00",
"flatRate": "12500",
"landOtherRate": "9900",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
```

```

    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "\nCarpet Area in Sq. Ft. = 646.00\nDeck Area in Sq. Ft. =
25.00\nUtility Area in Sq. Ft. = 13.00\nTotal Carpet Area in Sq. Ft. = 684.00\n(Area as
per Agreement for Sale)\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"reportGeneratedDate": "Wed Nov 27 2024 06:39:51 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-11-25"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			