

```
{
  "typeOfReport": {
    "value": "Plant_&_Machinery",
    "label": "Plant & Machinery"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646869f246e69b7878e9c07a"
    },
    "firstName": "Mr. Satish",
    "type": "CREDITOFFICER",
    "_id": "646869f246e69b7878e9c07c",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "9769699931",
    "email": "satish.sambare@siemens.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "646867a446e69b7878e9b892",
  "type": "INSTITUTION",
  "name": "Siemens Financial Services Private Limited",
  "displayName": "",
  "initial": "SFS"
},
"branch": {
  "_id": "646869f246e69b7878e9c07a",
  "name": "SFS COF E RU-IN RM AM",
  "branchCode": "",
  "mobileNo": "9769699930",
  "alternateMobileNo": "",
  "email": "satish.sambare@siemens.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Thane Belapur Road\n400708 Thane, India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "6468691f46e69b7878e9be2e",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
    "role": "FRONTDESK",
```

```
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddedd82",
"profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"checker": {
```

```
"type": "EMPLOYEE",
"_id": "62720b21afd7d55eddedc545",
"role": "MAKER+CHECKER",
"firstName": "Avinash",
"email": "avinash.pandey@vastukala.org",
"lastName": "Pandey",
"mobileNo": "9021605621",
"designation": "",
"shortName": "AV",
"workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
```

```
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "INSTITUTION",
  "label": "INSTITUTION"
},
"location": {
  "latitude": "22.140858261615897",
  "longitude": "70.74278042425352"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Khamba",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Rajkot",
```

```
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "12 & 13",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Avadh Industrial Park - A",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
```

```
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "896 & 897",
  "label": true
}
```



```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```

```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code- 360 311",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
```

```
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
```

```
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
```

```
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
```

```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67455610e077c54e5328dd6b",
"ownerName": "Samay Surgical Pvt Ltd ",
"ownerPhoneNo": "0000000000",
"fullAddress": "Industrial Plant & Machinery No. Ground Floor, Avadh Industrial Park -
A, Plot No. 12 & 13, New/Current Survey No. 896 & 897, Village - Khamba, District -
Rajkot, PIN Code- 360 311, State - Gujarat, India",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "012585",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "327470",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 26 2024 05:01:04 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Samay Surgical Pvt Ltd ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "278374"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e4f",
    "name": "externalimg_r_1732774507971_IMG_6375.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774507971_IMG_6375.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e50",
    "name": "externalimg_r_1732774507953_IMG_6374.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774507953_IMG_6374.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e51",
    "name": "externalimg_r_1732774507988_IMG_6376.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774507988_IMG_6376.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e52",
    "name": "externalimg_r_1732774507999_IMG_6377.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774507999_IMG_6377.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e53",
    "name": "externalimg_r_1732774508020_IMG_6378.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774508020_IMG_6378.JPG",
    "orientation": "landscape"
  },
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a6c520246c6c0630e54",
  "name": "externallmg_r_1732774508056_IMG_6380.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508056_IMG_6380.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a6c520246c6c0630e55",
  "name": "externallmg_r_1732774508087_IMG_6381.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508087_IMG_6381.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a6c520246c6c0630e56",
  "name": "externallmg_r_1732774508050_IMG_6379.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508050_IMG_6379.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a6c520246c6c0630e57",
  "name": "externallmg_r_1732774508095_IMG_6382.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508095_IMG_6382.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a6c520246c6c0630e58",
  "name": "externallmg_r_1732774508134_IMG_6383.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508134_IMG_6383.JPG",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e59",
    "name": "externallmg_r_1732774508141_IMG_6385.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508141_IMG_6385.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e5a",
    "name": "externallmg_r_1732774508183_IMG_6386.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508183_IMG_6386.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e5b",
    "name": "externallmg_r_1732774508188_IMG_6387.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508188_IMG_6387.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a6c520246c6c0630e5c",
    "name": "externallmg_r_1732774508224_IMG_6388.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774508224_IMG_6388.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a98520246c6c0630eb4",
    "name": "externallmg_r_1732774550628_IMG_6403.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774550628_IMG_6403.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67480a98520246c6c0630eb5",
  "name": "externalimg_r_1732774550784_IMG_6404.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774550784_IMG_6404.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a98520246c6c0630eb6",
  "name": "externalimg_r_1732774550933_IMG_6405.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774550933_IMG_6405.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a98520246c6c0630eb7",
  "name": "externalimg_r_1732774551029_IMG_6406.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774551029_IMG_6406.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a98520246c6c0630eb8",
  "name": "externalimg_r_1732774551090_IMG_6407.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774551090_IMG_6407.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480a98520246c6c0630eb9",
  "name": "externalimg_r_1732774551149_IMG_6408.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774551149_IMG_6408.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67480a98520246c6c0630eba",
    "name": "externallmg_r_1732774551220_IMG_6409.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774551220_IMG_6409.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a98520246c6c0630ebb",
    "name": "externallmg_r_1732774551296_IMG_6410.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774551296_IMG_6410.JPG",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a98520246c6c0630ebc",
    "name": "externallmg_r_1732774551390_IMG_6411.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774551390_IMG_6411.JPG",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a98520246c6c0630ebd",
    "name": "externallmg_r_1732774551618_IMG_6414.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774551618_IMG_6414.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a98520246c6c0630ebe",
    "name": "externallmg_r_1732774551477_IMG_6412.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774551477_IMG_6412.JPG",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a98520246c6c0630ebf",
```

```
    "name": "externallmg_r_1732774551563_IMG_6413.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774551563_IMG_6413.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480a98520246c6c0630ec0",
    "name": "externallmg_r_1732774551720_IMG_6415.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774551720_IMG_6415.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc63d",
    "name": "externallmg_r_1732774564785_IMG_6365.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774564785_IMG_6365.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc63e",
    "name": "externallmg_r_1732774564886_IMG_6369.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774564886_IMG_6369.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc63f",
    "name": "externallmg_r_1732774564824_IMG_6366.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774564824_IMG_6366.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc640",
    "name": "externallmg_r_1732774564855_IMG_6367.JPG",
```



```
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774564855_IMG_6367.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc641",
    "name": "externallmg_r_1732774565000_IMG_6372.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774565000_IMG_6372.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc642",
    "name": "externallmg_r_1732774564969_IMG_6371.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774564969_IMG_6371.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc643",
    "name": "externallmg_r_1732774564922_IMG_6370.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774564922_IMG_6370.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480aa5d1078a4ea7fbc644",
    "name": "externallmg_r_1732774565020_IMG_6373.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774565020_IMG_6373.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480ab3d1078a4ea7fbc672",
    "name": "externallmg_r_1732774579216_IMG_6429.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774579216_IMG_6429.JPG",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ab3d1078a4ea7fbc673",
  "name": "externallmg_r_1732774579222_IMG_6430.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774579222_IMG_6430.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ab3d1078a4ea7fbc674",
  "name": "externallmg_r_1732774579207_IMG_6428.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774579207_IMG_6428.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ab3d1078a4ea7fbc675",
  "name": "externallmg_r_1732774579234_IMG_6431.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774579234_IMG_6431.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ab3d1078a4ea7fbc676",
  "name": "externallmg_r_1732774579241_IMG_6432.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774579241_IMG_6432.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ab3d1078a4ea7fbc677",
  "name": "externallmg_r_1732774579262_IMG_6434.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774579262_IMG_6434.JPG",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ab3d1078a4ea7fbc678",
  "name": "externallmg_r_1732774579255_IMG_6433.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774579255_IMG_6433.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f24",
  "name": "externallmg_r_1732774593319_IMG_6392.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593319_IMG_6392.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f25",
  "name": "externallmg_r_1732774593290_IMG_6389.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593290_IMG_6389.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f26",
  "name": "externallmg_r_1732774593297_IMG_6390.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593297_IMG_6390.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f27",
  "name": "externallmg_r_1732774593310_IMG_6391.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593310_IMG_6391.JPG",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f28",
  "name": "externallmg_r_1732774593337_IMG_6393.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593337_IMG_6393.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f29",
  "name": "externallmg_r_1732774593367_IMG_6396.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593367_IMG_6396.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f2a",
  "name": "externallmg_r_1732774593340_IMG_6394.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593340_IMG_6394.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f2b",
  "name": "externallmg_r_1732774593364_IMG_6395.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593364_IMG_6395.JPG",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ac1520246c6c0630f2c",
  "name": "externallmg_r_1732774593411_IMG_6399.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593411_IMG_6399.JPG",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67480ac1520246c6c0630f2d",
"name": "externallmg_r_1732774593389_IMG_6397.JPG",
"path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593389_IMG_6397.JPG",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67480ac1520246c6c0630f2e",
"name": "externallmg_r_1732774593392_IMG_6398.JPG",
"path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593392_IMG_6398.JPG",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67480ac1520246c6c0630f2f",
"name": "externallmg_r_1732774593417_IMG_6400.JPG",
"path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774593417_IMG_6400.JPG",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67480ad2e077c54e532af7d6",
"name": "externallmg_r_1732774609945_IMG_6417.JPG",
"path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774609945_IMG_6417.JPG",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67480ad2e077c54e532af7d7",
"name": "externallmg_r_1732774609967_IMG_6418.JPG",
"path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774609967_IMG_6418.JPG",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67480ad2e077c54e532af7d8",
  "name": "externallmg_r_1732774610028_IMG_6420.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774610028_IMG_6420.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ad2e077c54e532af7d9",
  "name": "externallmg_r_1732774609994_IMG_6419.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774609994_IMG_6419.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ad2e077c54e532af7da",
  "name": "externallmg_r_1732774610032_IMG_6421.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774610032_IMG_6421.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ad2e077c54e532af7db",
  "name": "externallmg_r_1732774610081_IMG_6423.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774610081_IMG_6423.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67480ad2e077c54e532af7dc",
  "name": "externallmg_r_1732774610131_IMG_6424.JPG",
  "path": "cases/67455610e077c54e5328dd6b/
externallmg_r_1732774610131_IMG_6424.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67480ad2e077c54e532af7dd",
    "name": "externalimg_r_1732774610073_IMG_6422.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774610073_IMG_6422.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480ad2e077c54e532af7de",
    "name": "externalimg_r_1732774610198_IMG_6426.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774610198_IMG_6426.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67480ad2e077c54e532af7df",
    "name": "externalimg_r_1732774610190_IMG_6425.JPG",
    "path": "cases/67455610e077c54e5328dd6b/
externalimg_r_1732774610190_IMG_6425.JPG",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-26T05:01:04.429Z",
"updatedAt": "2024-11-28T06:16:50.674Z",
"__v": 0,
"updatedBy": "62720b21afd7d55eddedc545",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "Mr. Nikunj Dedaniya ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Representative ",
"rerald": "",
"siteVisitContactNo": "9429115008"
```

}

Name

Length

Width

Total

Composition :

Other

Composition :
