

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "647ed1960ab64c23c9fcf71d",
```

```
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
```

```
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.974060",
  "longitude": "73.803459"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "27/11/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-25",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Wadala",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Prabhu - Platinum Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pujya Sri Sri Ravishankar Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Sanjeevani Blood Centre, Tagore Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```



```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "15",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 422 006",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
```

```
"label": "sole ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Nashik_Municipal_Corporation_",
  "label": "Nashik Municipal Corporation "
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "By Plot No. 8",
  "west": "By Adjacent S.No. 22/2/1",
  "south": "By 18.00 Mtr. Wide D.P. Road",
  "east": "By 6.00 Mtr. Wide Colony Road"
},
"asPerDocumentAgreement": {
  "north": "By Plot No. 8",
  "west": "By Adjacent S.No. 22/2/1",
  "south": "By 18.00 Mtr. Wide D.P. Road",
  "east": "By 6.00 Mtr. Wide Colony Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "By Marginal Distance ",
    "east": "By Marginal Distance & Colony Road",
    "south": "By Lift & Flat No. 13 & 14",
    "west": "By Marginal Distance "
  },
  "asPerDocument": {
    "north": "By Marginal Distance ",
    "east": "By Marginal Distance & Colony Road",
    "south": "By Lift & Flat No. 13 & 14",
    "west": "By Marginal Distance "
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
```

```
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Accompanying
Commencement Certificate No. A2/ 287/ 2963/ 10 dated.15.10.2010, issued by
Executive Engineer Town Planning Nashik Municipal Corporation, Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Yes - Internal Change Done on Site Terrace Area is
Converted Into Bedroom",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": " Yes - Internal Change Done on Site Terrace Area is Converted Into
Bedroom.",
  "depreciationPercentage": "18",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "5040",
  "depreciatedBuildingRate": "1640"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "36500",
  "landRate": "12300",
```

```
"igrImage": "cases/6746ad39d1078a4ea7faeff7/igr_1732685649254_Image.png",
"squareMeterGuideLineRate": "38325.00",
"squareFeetGuideLineRate": "3561.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "88",
  "rate": "3270.00",
  "squareFeetGuideLineRate": "3270.00",
  "squareMeterGuideLineRate": "35202.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details Not Available",
  "taxPaidHolderName": "Details Not Available",
  "taxAmount": "Details Not Available",
  "electricityServiceConnectionNo": "Details Not Available",
  "meterCardHolderName": "Details Not Available",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As Per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2012",
  "fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
```

```
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "0",
"label": "No"
}
```



```
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "48",
"ageOfBuilding": "12",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "1128.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6746ad39d1078a4ea7faeff7/
routeMap_1732686852171_Image.png",
    "routeLat": "19.974060",
    "routeLng": "73.803459",
    "stationName": "Nashik Road",
    "routeDistance": "6.0",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
}
```

```
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "u12v0o",
    "name": "u12v0o",
    "image": "cases/6746ad39d1078a4ea7faeff7/
routeMap_1732686803887_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
```

```
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4737600.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4737600.00",
"purchaseValueDocument": {
  "documentType": {
    "value": "60ae1269aa6d152c1801b389",
    "label": "Deed of Apartment"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1732684950836_Bharat_Kale.pdf",
  "path": "cases/6746ad39d1078a4ea7faeff7/
document_1732684950836_Bharat_Kale.pdf",
  "id": "847537",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Nov 27 2024 05:25:13 GMT+0000 (Coordinated Universal Time)",
  "documentDate": "28/05/2013",
  "amount": "2600000",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "M/s. Pacific Builders",
  "to": {
    "value": "buyer",
    "label": "buyer"
  },
  "buyer": "MR. Bharat Baburao Kale"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3688560.00",
  "selectedBuildUpValue": "1128.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6746ad84d1078a4ea7faf15b",
      "name":
"externalImg_1732685187721_WhatsApp_Image_20241125_at_34638_PM.jpeg",
      "path": "cases/6746ad39d1078a4ea7faeff7/
externalImg_1732685187721_WhatsApp_Image_20241125_at_34638_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
}
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "4741.00",
    "max": "6101.00"
  },
  "builtUpRateRange": {
    "min": "3951.00",
    "max": "5084.00"
  },
  "saleableRateRange": {
    "min": "3293.00",
    "max": "4237.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "940.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6746ad39d1078a4ea7faeff7",
```

```
"ownerName": "MR. Bharat Baburao Kale",
"ownerPhoneNo": "8788076389",
"fullAddress": "Residential Flat No. 15, 5th Floor, Prabhu - Platinum Apartment, Near
Sanjeevani Blood Centre, Tagore Nagar, Pujya Sri Sri Ravishankar Marg, Village -
Wadala, Taluka - Nashik, District - Nashik, Nashik, PIN Code - 422 006, State -
Maharashtra, Country - India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "inputs": {
      "documentDate": "28/05/2013",
      "amount": "2600000",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Pacific Builders",
      "to": {
        "value": "buyer",
        "label": "buyer"
      },
      "buyer": "MR. Bharat Baburao Kale"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1732684950836_Bharat_Kale.pdf",
    "path": "cases/6746ad39d1078a4ea7faeff7/
document_1732684950836_Bharat_Kale.pdf",
    "id": "847537",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Wed Nov 27 2024 05:25:13 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "15/10/2010",
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      }
    }
  }
]
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "A2/ 287/ 2963/ 10"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1732685007973_Adobe_Scan_25_Nov_2024_1.pdf",
  "path": "cases/6746ad39d1078a4ea7faeff7/
document_1732685007973_Adobe_Scan_25_Nov_2024_1.pdf",
  "id": "742165",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Nov 27 2024 05:25:13 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "21/05/2012",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "Javak No. NRV/ A4/ 11721/ 972"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1732685100848_Adobe_Scan_25_Nov_2024_1.pdf",
  "path": "cases/6746ad39d1078a4ea7faeff7/
document_1732685100848_Adobe_Scan_25_Nov_2024_1.pdf",
  "id": "740504",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Nov 27 2024 05:25:13 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"caseNumber": "012623",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "172469",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 27 2024 05:25:13 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "MR. Bharat Baburao Kale",
    "phone": "8788076389",
    "ownershipShare": "",
    "email": "",
    "id": "729475"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Living Room",
    "length": "17.42",
    "length1": "17",
    "length2": "5",
    "width": "11.08",
    "width1": "11",
    "width2": "1",
    "totalArea": "193.03",
    "images": [],
    "finalArea": "193.03",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
],
```

```
"id": "11",
"name": "Kitchen",
"length": "11.67",
"length1": "11",
"length2": "8",
"width": "10.58",
"width1": "10",
"width2": "7",
"totalArea": "123.47",
"images": [],
"finalArea": "123.47",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "12.25",
  "length1": "12",
  "length2": "3",
  "width": "11.08",
  "width1": "11",
  "width2": "1",
  "totalArea": "135.77",
  "images": [],
  "finalArea": "135.77",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "10.67",
  "width1": "10",
  "width2": "8",
  "totalArea": "124.44",
  "images": [],
```

```
"finalArea": "124.44",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "12.08",
  "length1": "12",
  "length2": "1",
  "width": "11.08",
  "width1": "11",
  "width2": "1",
  "totalArea": "133.92",
  "images": [],
  "finalArea": "133.92",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "6.50",
  "length1": "6",
  "length2": "6",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "27.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
```

```
"length": "7.33",
"length1": "7",
"length2": "4",
"width": "4.58",
"width1": "4",
"width2": "7",
"totalArea": "33.61",
"images": [],
"extraAreas": [],
"finalArea": "33.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "39.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "14.33",
  "length1": "14",
  "length2": "4",
  "width": "6.17",
  "width1": "6",
  "width2": "2",
  "totalArea": "88.39",
  "images": [],
  "finalArea": "88.39",
  "extraAreas": []
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "22.80",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.80"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Passage",
  "length": "9.08",
  "length1": "9",
  "length2": "1",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "28.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.76"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
  },

```



```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Carpet",
"squareMeterArea": "87.33",
"totalAreaDocument": "940",
"docBuiltpUpPercentage": "20",
"docFinalBuiltpUp": "1128.00",
"docFinalBuiltpUpSquareMeter": "104.79",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "539916"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "850.00",
    "squareMeterArea": "78.97",
    "expectedRate": "5294.12",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1020.00",
    "squareMeterArea": "94.76",
    "expectedRate": "4411.76",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1224.00",
    "squareMeterArea": "113.71",
    "expectedRate": "3676.47",
    "percentage": "20"
  },
  "printInReport": true,
  "_id": "6746af8d520246c6c062399f",
  "property": "Flat",
  "area": "1020",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": ""
}
```

```
"source": "Housing.Com",
"expectedPrice": "4500000",
"expectedRate": "5294.12",
"builtUpExpectedRate": "4500000",
"image": "cases/6746ad39d1078a4ea7faeff7/
indicator_1732685356608_Image.png",
"squareMeter": "94.76",
"id": "574644"
},
{
"carpetArea": {
"area": "675.00",
"squareMeterArea": "62.71",
"expectedRate": "4740.74",
"percentage": ""
},
"builtUpArea": {
"area": "810.00",
"squareMeterArea": "75.25",
"expectedRate": "3950.62",
"percentage": "20"
},
"saleableArea": {
"area": "972.00",
"squareMeterArea": "90.30",
"expectedRate": "3292.18",
"percentage": "20"
},
"printlnReport": true,
"_id": "6746af8d520246c6c06239a0",
"property": "Flat",
"area": "810",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "3200000",
"expectedRate": "4740.74",
"builtUpExpectedRate": "3200000",
"image": "cases/6746ad39d1078a4ea7faeff7/
indicator_1732685426687_Image.png",
"squareMeter": "75.25",
"id": "668284"
},
```

```
{
  "carpetArea": {
    "area": "377.00",
    "squareMeterArea": "35.02",
    "expectedRate": "6100.80",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "452.40",
    "squareMeterArea": "42.03",
    "expectedRate": "5084.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "542.88",
    "squareMeterArea": "50.44",
    "expectedRate": "4236.66",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6746af8d520246c6c06239a1",
  "property": "flat",
  "area": "377",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "2300000",
  "expectedRate": "6100.80",
  "builtUpExpectedRate": "5084.00",
  "image": "cases/6746ad39d1078a4ea7faeff7/
indicator_1732685547918_Image.png",
  "squareMeter": "35.02",
  "id": "992355"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746ad84d1078a4ea7faf14b",
    "name":
"externalImg_1732685185533_WhatsApp_Image_20241125_at_34630_PM.jpeg",
    "path": "cases/6746ad39d1078a4ea7faeff7/
externalImg_1732685185533_WhatsApp_Image_20241125_at_34630_PM.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf14c",
  "name":
"externallmg_1732685185633_WhatsApp_Image_20241125_at_34631_PM.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685185633_WhatsApp_Image_20241125_at_34631_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf14d",
  "name":
"externallmg_1732685185761_WhatsApp_Image_20241125_at_34632_PM_1.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685185761_WhatsApp_Image_20241125_at_34632_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf14e",
  "name":
"externallmg_1732685185934_WhatsApp_Image_20241125_at_34632_PM.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685185934_WhatsApp_Image_20241125_at_34632_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf14f",
  "name":
"externallmg_1732685186098_WhatsApp_Image_20241125_at_34633_PM_1.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186098_WhatsApp_Image_20241125_at_34633_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf150",
```

```
    "name":
"externallmg_1732685186218_WhatsApp_Image_20241125_at_34633_PM_2.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186218_WhatsApp_Image_20241125_at_34633_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf151",
  "name":
"externallmg_1732685186318_WhatsApp_Image_20241125_at_34633_PM.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186318_WhatsApp_Image_20241125_at_34633_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf152",
  "name":
"externallmg_1732685186436_WhatsApp_Image_20241125_at_34634_PM_1.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186436_WhatsApp_Image_20241125_at_34634_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf153",
  "name":
"externallmg_1732685186537_WhatsApp_Image_20241125_at_34634_PM.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186537_WhatsApp_Image_20241125_at_34634_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf154",
  "name":
"externallmg_1732685186634_WhatsApp_Image_20241125_at_34635_PM_1.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186634_WhatsApp_Image_20241125_at_34635_PM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf155",
  "name":
"externallmg_1732685186831_WhatsApp_Image_20241125_at_34635_PM.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186831_WhatsApp_Image_20241125_at_34635_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf156",
  "name":
"externallmg_1732685186950_WhatsApp_Image_20241125_at_34636_PM_1.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685186950_WhatsApp_Image_20241125_at_34636_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf157",
  "name":
"externallmg_1732685187068_WhatsApp_Image_20241125_at_34636_PM.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685187068_WhatsApp_Image_20241125_at_34636_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf158",
  "name":
"externallmg_1732685187227_WhatsApp_Image_20241125_at_34637_PM_1.jpeg",
  "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685187227_WhatsApp_Image_20241125_at_34637_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746ad84d1078a4ea7faf159",
  "name":
"externallmg_1732685187405_WhatsApp_Image_20241125_at_34637_PM.jpeg",
```

```
    "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685187405_WhatsApp_Image_20241125_at_34637_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746ad84d1078a4ea7faf15a",
    "name":
"externallmg_1732685187505_WhatsApp_Image_20241125_at_34638_PM_1.jpeg",
    "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685187505_WhatsApp_Image_20241125_at_34638_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746ad84d1078a4ea7faf15b",
    "name":
"externallmg_1732685187721_WhatsApp_Image_20241125_at_34638_PM.jpeg",
    "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685187721_WhatsApp_Image_20241125_at_34638_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746ad84d1078a4ea7faf15c",
    "name":
"externallmg_1732685187976_WhatsApp_Image_20241125_at_34639_PM.jpeg",
    "path": "cases/6746ad39d1078a4ea7faeff7/
externallmg_1732685187976_WhatsApp_Image_20241125_at_34639_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Bharat Kale Cal.xlsx",
    "filename": "1732685775075_Bharat_Kale_Cal.xlsx",
    "path": "cases/6746ad39d1078a4ea7faeff7/
processingDocuments/1732685775075_Bharat_Kale_Cal.xlsx",
    "size": "689425",
    "createdAt": "Wed Nov 27 2024 05:36:15 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  }
]
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-27T05:25:13.646Z",
"updatedAt": "2024-11-27T05:56:15.480Z",
"__v": 0,
"updatedBy": "647ed1960ab64c23c9fcf71d",
"addressForMap": "",
"caseReferredBy": "647ed1960ab64c23c9fcf71d",
"contactPersonName": "MR. Bharat Baburao Kale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"rerald": "",
"siteVisitContactNo": "8788076389",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Deed of Apartment",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 940.00",
"flatRate": "5400",
"landOtherRate": "3400",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Bathroom + Toilet +
Balcony + 2 Passage",
"carpetTotal": "950.38",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1045.42",
"finalCarpetArea": "950.38",
"finalSalableArea": "1149.96",
"salablePercentage": "10",
```



```

"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Nov 27 2024 05:36:34 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-11-25"
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'5"	11'1"	193.03
Kitchen	11'8"	10'7"	123.47
Bedroom	12'3"	11'1"	135.77
Bedroom	11'8"	10'8"	124.44
Bedroom	12'1"	11'1"	133.92
Bathroom	6'6"	4'2"	27.08
Bathroom	7'4"	4'7"	33.61
Toilet	7'4"	5'4"	39.11
Balcony	14'4"	6'2"	88.39
Passage	5'7"	4'1"	22.80
Passage	9'1"	3'2"	28.76

Other
Composition :
