

```
{
  "typeOfReport": {
    "label": "Gala",
    "value": "Gala"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b89a"
    },
    "firstName": "Khushboo ",
    "type": "CREDITOFFICER",
    "_id": "65a63a1402c44c777bb6c154",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "7899979298",
    "email": "khushboo.yadav@sbi.co.in"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "15000000",
    "discussWithPerson": "Abhisha madam",
    "expectedFees": 7500,
    "quotedAmount": "6000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b89a",
  "branchCode": "000106",
  "type": "BRANCH",
  "name": "Bassein Taluka Industrial Estate Branch",
  "email": "sbi.06839@sbi.co.in",
  "mobileNo": "02502456981",
  "alternateMobileNo": "",
  "address": "Bassein Taluka Industrial Estate Branch, Govrai Pada Vasai (East),\r
\nThane - 401 208, State - Maharashtra, Country - India.",
  "ledgerName": "STATE BANK OF INDIA - VASAI",
  "fax": "0250-2455149",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "FRONTDESK",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
```

```
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.21097908183774",
  "longitude": "72.961708370525"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.961708370525,
    19.21097908183774
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "27/11/2024 12:00 am"
    },
    {
      "dateTime": "27/11/2024 12:00 am"
    },
    {
      "dateTime": "27/11/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-26",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-25",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-24",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Majiwade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "3 (Krishna Building)",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Laxmi Industrial Premises Co - Op. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pokhran Road No 1",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Vartak Nagar",
  "label": false
}
```



```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "215",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "1 (Part), 7 ( Part)",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "213",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400606",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "WoodenFlooring",
    "label": "Wooden Flooring"
  },
  "doors": {
    "value": "Aluminium_frame_Glass_door_with_MS_Rolling_Shutter",
    "label": "Aluminium frame Glass door with MS Rolling Shutter"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
}
```

```
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "company_ownership",
    "label": "company ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Semi_Urban",
    "label": "Semi Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Krishna Koyna Apratment",
    "west": "Akruti Rentals ",
    "south": "Godavari - Laxmi Industrial Premises ",
    "east": " Narmada - Laxmi Industrial Premises "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
```

```
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
```

```
"depreciationPercentage": "49.50000000000001",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "15362.5",
"depreciatedBuildingRate": "1262.4999999999998"
},
"igrRate": {
  "propertyName": "Industrial",
  "rate": "135300",
  "landRate": "42300",
  "igrImage": "cases/6746b0eed1078a4ea7faf631/igr_1736231717047_Image.png",
  "squareMeterGuideLineRate": "135300.00",
  "squareFeetGuideLineRate": "12570.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "67",
  "rate": "9719.00",
  "squareMeterGuideLineRate": "104610.00",
  "squareFeetGuideLineRate": "9719.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Industrial",
    "label": "Industrial"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per TMC corporation",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
```

```
"marketabilityList": {
  "value": "Good",
  "label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in Developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1992",
    "fullDate": "1/1/1992"
  },
  "planningArea": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  }
}
```

```
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
```



```
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "27",
"ageOfBuilding": "33",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "16"
},
"finalPlinthArea": {
"area": "510.04",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/6746b0eed1078a4ea7faf631/
routeMap_1733723626446_Image.png",
"routeLat": "19.210487",
"routeLng": "72.960687",
"stationName": "Thane",
"routeDistance": "3.7 Km",
"routeStation": {
"value": "Railway_Station",
```

```
    "label": "Railway Station"
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "910qme",
    "name": "910qme",
    "image": "cases/6746b0eed1078a4ea7faf631/
routeMap_1733723500780_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8603280.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8603280.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "5442640.00",
  "selectedBuildUpValue": "560.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6746baf1e077c54e5329fde0",
      "name":
"externallmg_1732688624810_WhatsApp_Image_20241127_at_114211.jpeg",
      "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624810_WhatsApp_Image_20241127_at_114211.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "6746baf1e077c54e5329fde8",
      "name": "Working Area",
      "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624882_WhatsApp_Image_20241127_at_114217.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6746baf1e077c54e5329fde7",
      "name": "Working Area",
      "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624867_WhatsApp_Image_20241127_at_114215.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
    "status": false,
    "_id": "6746baf1e077c54e5329fdeb",
    "name": "Working Area",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624910_WhatsApp_Image_20241127_at_114220.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6746baf1e077c54e5329fdec",
    "name": "Working Area",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624928_WhatsApp_Image_20241127_at_114221.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6746baf1e077c54e5329fdef",
    "name": "Working Area",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624947_WhatsApp_Image_20241127_at_114223.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6746baf1e077c54e5329fde5",
    "name": "Working Area",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624852_WhatsApp_Image_20241127_at_114215_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6746baf1e077c54e5329fde6",
    "name": "Working Area",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624864_WhatsApp_Image_20241127_at_114215_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6746baf1e077c54e5329fde2",
    "name": "Working Area",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624833_WhatsApp_Image_20241127_at_114213_1.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "status": false,
      "_id": "6746baf1e077c54e5329fdde",
      "name": "Working Area",
      "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624780_WhatsApp_Image_20241127_at_114210_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6746baf1e077c54e5329fddd",
      "name": "Working Area",
      "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624775_WhatsApp_Image_20241127_at_114210_1.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6746baf1e077c54e5329fde1",
      "name": "Working Area",
      "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624815_WhatsApp_Image_20241127_at_114212.jpeg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16822.00",
    "max": "21334.00"
  },
  "builtUpRateRange": {
    "min": "14018.00",
    "max": "17778.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "560.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6746b0eed1078a4ea7faf631",
"ownerName": "M/s. Peleecon Linkers",
"ownerPhoneNo": "9820095454",
"appAddress": "GALA NO 213 2ND FLOOR BLDG NO 3 KRISHNA LAXMI
INDUSTRIAL PREMISES CHS LTD POKHRAN ROAD NO 1 VARTAK NAGAR THANE
WEST THANE 400606",
"remark": "contact Milind hebli shrilakshmi 9820095454",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "24/05/1996",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Bhuvanendra Construction Company ",
      "to": {
```

```
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "M/s. Peleecon Linkers",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "000"
},
"isHardCopy": false,
"displayStatus": true,
"id": "887400",
"path": "cases/6746b0eed1078a4ea7faf631/
document_1732685810331_1732685808652_agreement_of_peleecon.pdf",
"fileName":
"document_1732685810331_1732685808652_agreement_of_peleecon.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "22/12/1992",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "85128"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1736232546625_CamScanner_12052024_1841.pdf",
  "path": "cases/6746b0eed1078a4ea7faf631/
document_1736232546625_CamScanner_12052024_1841.pdf",
  "id": "999754",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Tue Jan 07 2025 06:49:06 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
```

```
    "value": "60ae1253aa6d152c1801b320",
    "label": "Society N. O. C. Certificate"
  },
  "inputs": {
    "documentDate": "28/12/2024",
    "remark": "issued by \"Laxmi Industrial Premises Co - Op. Soc. Ltd.\""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1736232640358_138091.pdf",
  "path": "cases/6746b0eed1078a4ea7faf631/
document_1736232640358_138091.pdf",
  "id": "121126",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Tue Jan 07 2025 06:50:40 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012626",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "540985",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 27 2024 05:41:02 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "M/s. Peleecon Linkers",
    "phone": "9820095454",
    "ownershipShare": "",
    "email": "",
    "id": "742944"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "668963",
    "name": "Working Area",
```

```
"length": "107.00",
"length1": "107",
"length2": "0",
"width": "4.33",
"width1": "4",
"width2": "4",
"totalArea": "463.67",
"images": [],
"extraAreas": [],
"finalArea": "463.67"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "52.03",
  "totalAreaDocument": "560",
  "docBultupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "675119"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "466.67",
    "squareMeterArea": "43.36",
    "expectedRate": "16821.31",
    "percentage": ""
  },
  "builtUpArea": {
```

```
    "area": "560.00",
    "squareMeterArea": "52.03",
    "expectedRate": "14017.86",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "677ccb2a4526f50b5ab553a4",
  "property": "Industrial ",
  "area": "560",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "7850000",
  "expectedRate": "16821.31",
  "builtUpExpectedRate": "7850000",
  "image": "cases/6746b0eed1078a4ea7faf631/
indicator_1736231615917_Image.png",
  "squareMeter": "52.03",
  "id": "263964"
},
{
  "carpetArea": {
    "area": "466.67",
    "squareMeterArea": "43.36",
    "expectedRate": "16821.31",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "560.00",
    "squareMeterArea": "52.03",
    "expectedRate": "14017.86",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
```

```
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "677ccb2a4526f50b5ab553a5",
  "property": "Industrial",
  "area": "560",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "7850000",
  "expectedRate": "16821.31",
  "builtUpExpectedRate": "7850000",
  "image": "cases/6746b0eed1078a4ea7faf631/
indicator_1736231647153_Image.png",
  "squareMeter": "52.03",
  "id": "785113"
},
{
  "carpetArea": {
    "area": "375.00",
    "squareMeterArea": "34.84",
    "expectedRate": "21333.33",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "450.00",
    "squareMeterArea": "41.81",
    "expectedRate": "17777.78",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "677ccb2a4526f50b5ab553a6",
  "property": "Industrial",
  "area": "450",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```



```
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "8000000",
"expectedRate": "21333.33",
"builtUpExpectedRate": "8000000",
"image": "cases/6746b0eed1078a4ea7faf631/
indicator_1736231665672_Image.png",
"squareMeter": "41.81",
"id": "263577"
},
{
"carpetArea": {
"area": "560.00",
"squareMeterArea": "52.03",
"expectedRate": "19642.86",
"percentage": ""
},
"builtUpArea": {
"area": "620",
"squareMeterArea": "57.60",
"expectedRate": "17741.94",
"percentage": ""
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "677ccb2a4526f50b5ab553a7",
"property": "Industrial",
"area": "560",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "11000000",
"expectedRate": "19642.86",
"builtUpExpectedRate": "17741.94",
"image": "cases/6746b0eed1078a4ea7faf631/
indicator_1736231693434_Image.png",
"squareMeter": "52.03",
```

```
    "id": "690950"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746bae6e077c54e5329fda3",
    "name":
"externalImg_1732688614278_WhatsApp_Image_20241127_at_114208.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externalImg_1732688614278_WhatsApp_Image_20241127_at_114208.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746bae6e077c54e5329fda4",
    "name":
"externalImg_1732688614281_WhatsApp_Image_20241127_at_114209.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externalImg_1732688614281_WhatsApp_Image_20241127_at_114209.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746baf1e077c54e5329fddd",
    "name":
"externalImg_1732688624775_WhatsApp_Image_20241127_at_114210_1.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externalImg_1732688624775_WhatsApp_Image_20241127_at_114210_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746baf1e077c54e5329fdde",
    "name":
"externalImg_1732688624780_WhatsApp_Image_20241127_at_114210_2.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externalImg_1732688624780_WhatsApp_Image_20241127_at_114210_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6746baf1e077c54e5329fddf",
    "name":
"externallmg_1732688624784_WhatsApp_Image_20241127_at_114210.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624784_WhatsApp_Image_20241127_at_114210.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746baf1e077c54e5329fde0",
    "name":
"externallmg_1732688624810_WhatsApp_Image_20241127_at_114211.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624810_WhatsApp_Image_20241127_at_114211.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746baf1e077c54e5329fde1",
    "name":
"externallmg_1732688624815_WhatsApp_Image_20241127_at_114212.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624815_WhatsApp_Image_20241127_at_114212.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746baf1e077c54e5329fde2",
    "name":
"externallmg_1732688624833_WhatsApp_Image_20241127_at_114213_1.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624833_WhatsApp_Image_20241127_at_114213_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6746baf1e077c54e5329fde3",
    "name":
"externallmg_1732688624836_WhatsApp_Image_20241127_at_114213.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624836_WhatsApp_Image_20241127_at_114213.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fde4",
  "name":
"externallmg_1732688624850_WhatsApp_Image_20241127_at_114214.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624850_WhatsApp_Image_20241127_at_114214.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fde5",
  "name":
"externallmg_1732688624852_WhatsApp_Image_20241127_at_114215_1.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624852_WhatsApp_Image_20241127_at_114215_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fde6",
  "name":
"externallmg_1732688624864_WhatsApp_Image_20241127_at_114215_2.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624864_WhatsApp_Image_20241127_at_114215_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fde7",
  "name":
"externallmg_1732688624867_WhatsApp_Image_20241127_at_114215.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624867_WhatsApp_Image_20241127_at_114215.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fde8",
```

```
"name":
"externallmg_1732688624882_WhatsApp_Image_20241127_at_114217.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624882_WhatsApp_Image_20241127_at_114217.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fde9",
  "name":
"externallmg_1732688624887_WhatsApp_Image_20241127_at_114219.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624887_WhatsApp_Image_20241127_at_114219.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fdea",
  "name":
"externallmg_1732688624907_WhatsApp_Image_20241127_at_114220_1.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624907_WhatsApp_Image_20241127_at_114220_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fdeb",
  "name":
"externallmg_1732688624910_WhatsApp_Image_20241127_at_114220.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624910_WhatsApp_Image_20241127_at_114220.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fdec",
  "name":
"externallmg_1732688624928_WhatsApp_Image_20241127_at_114221.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624928_WhatsApp_Image_20241127_at_114221.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fded",
  "name":
"externallmg_1732688624932_WhatsApp_Image_20241127_at_114222_1.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624932_WhatsApp_Image_20241127_at_114222_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fdee",
  "name":
"externallmg_1732688624945_WhatsApp_Image_20241127_at_114222.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624945_WhatsApp_Image_20241127_at_114222.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6746baf1e077c54e5329fdef",
  "name":
"externallmg_1732688624947_WhatsApp_Image_20241127_at_114223.jpeg",
  "path": "cases/6746b0eed1078a4ea7faf631/
externallmg_1732688624947_WhatsApp_Image_20241127_at_114223.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "WhatsApp Image 2025-01-07 at 12.14.23 PM.jpeg",
    "filename": "1736232947967_WhatsApp_Image_20250107_at_121423_PM.jpeg",
    "path": "cases/6746b0eed1078a4ea7faf631/processingDocuments/1736232947967
_WhatsApp_Image_20250107_at_121423_PM.jpeg",
    "size": "138091",
    "createdAt": "Tue Jan 07 2025 06:55:48 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62691c48afd7d55eddecfda3"
  },
  {
    "originalname": "CamScanner 12-05-2024 18.41.pdf",
    "filename": "1736232962228_CamScanner_12052024_1841.pdf",
    "path": "cases/6746b0eed1078a4ea7faf631/
processingDocuments/1736232962228_CamScanner_12052024_1841.pdf",
```

```
    "size": "564606",
    "createdAt": "Tue Jan 07 2025 06:56:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62691c48afd7d55eddecfda3"
  },
  {
    "originalname":
"document_1732685837185_1732685835501_pelecon_linkers_Old_valuation_report
(2).pdf",
    "filename": "1736232962298_document_1732685837185_1732685835501_pelecon
_linkers_Old_valuation_report_2.pdf",
    "path": "cases/6746b0eed1078a4ea7faf631/processingDocuments/1736232962298
_document_1732685837185_1732685835501_pelecon_linkers_Old_valuation_report_2
.pdf",
    "size": "3177027",
    "createdAt": "Tue Jan 07 2025 06:56:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62691c48afd7d55eddecfda3"
  },
  {
    "originalname":
"document_1732685810331_1732685808652_agreement_of_peleecon (4).pdf",
    "filename": "1736232962495_document_1732685810331_1732685808652_agreem
ent_of_peleecon_4.pdf",
    "path": "cases/6746b0eed1078a4ea7faf631/processingDocuments/1736232962495
_document_1732685810331_1732685808652_agreement_of_peleecon_4.pdf",
    "size": "3768096",
    "createdAt": "Tue Jan 07 2025 06:56:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62691c48afd7d55eddecfda3"
  },
  {
    "originalname": "IGR-01 (4).pdf",
    "filename": "1736233017920_IGR01_4.pdf",
    "path": "cases/6746b0eed1078a4ea7faf631/
processingDocuments/1736233017920_IGR01_4.pdf",
    "size": "140919",
    "createdAt": "Tue Jan 07 2025 06:56:58 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62691c48afd7d55eddecfda3"
  },
  {
    "originalname": "IGR-02 (5).pdf",
    "filename": "1736233017927_IGR02_5.pdf",
    "path": "cases/6746b0eed1078a4ea7faf631/
processingDocuments/1736233017927_IGR02_5.pdf",
    "size": "140913",
    "createdAt": "Tue Jan 07 2025 06:56:58 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62691c48afd7d55eddecfda3"
  },
}
```

```
{
  "originalname": "IGR-03.pdf",
  "filename": "1736233017939_IGR03.pdf",
  "path": "cases/6746b0eed1078a4ea7faf631/
processingDocuments/1736233017939_IGR03.pdf",
  "size": "140957",
  "createdAt": "Tue Jan 07 2025 06:56:58 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62691c48afd7d55eddecfda3"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1736233017965_IGR04.pdf",
  "path": "cases/6746b0eed1078a4ea7faf631/
processingDocuments/1736233017965_IGR04.pdf",
  "size": "140959",
  "createdAt": "Tue Jan 07 2025 06:56:58 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62691c48afd7d55eddecfda3"
},
{
  "originalname": "Summary New=pelecon.xlsx",
  "filename": "1736233017970_Summary_Newpelecon.xlsx",
  "path": "cases/6746b0eed1078a4ea7faf631/
processingDocuments/1736233017970_Summary_Newpelecon.xlsx",
  "size": "1620553",
  "createdAt": "Tue Jan 07 2025 06:56:58 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62691c48afd7d55eddecfda3"
},
{
  "originalname": "PREVIOUS REPORT - ARCHINOVA.pdf",
  "filename": "1736233018159_PREVIOUS_REPORT__ARCHINOVA.pdf",
  "path": "cases/6746b0eed1078a4ea7faf631/
processingDocuments/1736233018159_PREVIOUS_REPORT__ARCHINOVA.pdf",
  "size": "3177027",
  "createdAt": "Tue Jan 07 2025 06:56:58 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62691c48afd7d55eddecfda3"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
```



```
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "674953cee077c54e532bd0f5",
  "note": "Pending for OC",
  "taskId": "6746b8a7e077c54e5329f9d7",
  "createdAt": "2024-11-29T05:40:30.428Z"
}
],
"createdAt": "2024-11-27T05:41:02.034Z",
"updatedAt": "2025-01-07T07:09:23.236Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Industrial Gala No. 213, 2nd Floor, Building No 3 (Krishna Building),
Laxmi Industrial Premises Co - Op. Soc. Ltd. , New/Current Survey No. 215, Hissa No. 1
(Part), 7 ( Part), Pokhran Road No 1, Vartak Nagar, Village - Majiwade, Thane (West),
Taluka - Thane, District - Thane, 400606, State - Maharashtra, India",
"updatedAtBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Anil Poojari",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner Representative",
"rerald": "",
"siteVisitContactNo": "9819992841",
"briefDescOfProperty": "Working Area",
"carpetTotal": "463.67",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "510.04",
"finalCarpetArea": "463.67",
"finalSalableArea": "561.04",
"salablePercentage": "10",
"toBeAdded": "",
```

```
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "10",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 560.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Jan 07 2025 00:00:00 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-11-24",
"buildingServicesRate": "2500",
"flatRate": "16600",
"landOtherRate": "14100",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Working Area	107'0"	4'4"	463.67
<hr/>			
Other			
Composition :			
<hr/>			