

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b265fb191f7b344b008c29"
    },
    "firstName": "Saurabh",
    "type": "CREDITOFFICER",
    "_id": "666156281daaad305a6d8f5d",
    "lastName": "Negi",
    "mobileNo": "",
    "workMobileNo": "8928822578",
    "email": "sbi.17879@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454645",
    "discussWithPerson": "Saurabh",
    "expectedFees": 3227.3225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b265fb191f7b344b008c29",
  "name": "SME MIDC ANDHERI (EAST)",
  "branchCode": "",
  "mobileNo": "022-28329368",
  "alternateMobileNo": "",
  "email": "sbi.17879@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Plot No. B-1, MIDC Industrial Area, Central Road, Andheri (East),
Mumbai. "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62723addafd7d55eddeddfe4",
"role": "PICKUPPERSON",
"firstName": "Ramkrishna ",
"email": "rampatakar1991@gmail.com",
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
```

```
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "20.32615884303546",
  "longitude": "72.96348177035097"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.96348177035097,
    20.32615884303546
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dadra",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": true,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "G",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Zero Tax Industrial Estate",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "396230",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
```

```
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6746cadfd1078a4ea7fb18f0",
"ownerName": "Cruise Electricals Pvt Ltd ",
"ownerPhoneNo": "7045959281",
"appAddress": "Bldg no - G , Part - II, Zero Tax industrial estate, Survey no - 221/1,
village - Dadra, near - Dadra check post, Dadra Nagar haveli, silvasa ",
"remark": "visit - 30 /11/2024",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6746cadfd1078a4ea7fb18f0/
document_1732692695067_1732692691836_saurabh_3__Page_1.pdf",
    "fileName":
"document_1732692695067_1732692691836_saurabh_3__Page_1.pdf",
    "id": "916239",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Nov 27 2024 07:31:43 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
  }
]
```

```
"fileName":
"document_1733482172754_Property_Documents__Seagull_Colling_Pvt_Ltddoc.pdf",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
document_1733482172754_Property_Documents__Seagull_Colling_Pvt_Ltddoc.pdf",
  "id": "613266",
  "uploadedBy": "60f91822f3dd69653a5922e3",
  "createdAt": "Fri Dec 06 2024 10:50:11 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012634",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
{
  "id": "234356",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Wed Nov 27 2024 07:31:43 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
  "name": "Cruise Electricals Pvt Ltd ",
  "phone": "7045959281",
  "ownershipShare": "",
  "email": "",
  "id": "582241"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67567386cfae933db22be0d2",
  "name":
"externalImg_1733718906217_20241204_123716PMBByGPSMapCamera.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externalImg_1733718906217_20241204_123716PMBByGPSMapCamera.jpg",
  "orientation": "landscape"
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67567386cfae933db22be0d3",
      "name":
"externallmg_1733718906294_20241204_123718PMBByGPSMapCamera.jpg",
      "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_1733718906294_20241204_123718PMBByGPSMapCamera.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67567386cfae933db22be0d4",
      "name": "externallmg_r_1733718906380_IMG_20241204_122633.jpg",
      "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718906380_IMG_20241204_122633.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67567386cfae933db22be0d5",
      "name": "externallmg_r_1733718907203_IMG_20241204_122639.jpg",
      "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718907203_IMG_20241204_122639.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67567386cfae933db22be0d6",
      "name": "externallmg_r_1733718906693_IMG_20241204_122635.jpg",
      "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718906693_IMG_20241204_122635.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67567386cfae933db22be0d7",
      "name": "externallmg_r_1733718907770_IMG_20241204_122641.jpg",
      "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718907770_IMG_20241204_122641.jpg",
      "orientation": "landscape"
    }
  ]
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0d8",
    "name": "externallmg_r_1733718908170_IMG_20241204_122643.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718908170_IMG_20241204_122643.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0d9",
    "name": "externallmg_r_1733718908468_IMG_20241204_122649.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718908468_IMG_20241204_122649.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0da",
    "name": "externallmg_r_1733718909585_IMG_20241204_122706.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718909585_IMG_20241204_122706.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0db",
    "name": "externallmg_r_1733718909139_IMG_20241204_122654.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718909139_IMG_20241204_122654.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0dc",
    "name": "externallmg_r_1733718909879_IMG_20241204_122712.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718909879_IMG_20241204_122712.jpg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67567386cfae933db22be0dd",
  "name": "externallmg_r_1733718910377_IMG_20241204_122715.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718910377_IMG_20241204_122715.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67567386cfae933db22be0de",
  "name": "externallmg_r_1733718911187_IMG_20241204_122719.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718911187_IMG_20241204_122719.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67567386cfae933db22be0df",
  "name": "externallmg_r_1733718910661_IMG_20241204_122718.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718910661_IMG_20241204_122718.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67567386cfae933db22be0e0",
  "name": "externallmg_r_1733718911300_IMG_20241204_122722.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718911300_IMG_20241204_122722.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67567386cfae933db22be0e1",
  "name": "externallmg_r_1733718911846_IMG_20241204_122731.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718911846_IMG_20241204_122731.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0e2",
    "name": "externallmg_r_1733718912324_IMG_20241204_122733.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718912324_IMG_20241204_122733.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0e3",
    "name": "externallmg_r_1733718912444_IMG_20241204_122735.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718912444_IMG_20241204_122735.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0e4",
    "name": "externallmg_r_1733718912978_IMG_20241204_122740.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718912978_IMG_20241204_122740.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567386cfae933db22be0e5",
    "name": "externallmg_r_1733718913116_IMG_20241204_122742.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718913116_IMG_20241204_122742.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a02",
    "name": "externallmg_r_1733718938025_IMG_20241204_122751.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718938025_IMG_20241204_122751.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "675673a9befd7f3db9077a03",
  "name": "externallmg_r_1733718937665_IMG_20241204_122747.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718937665_IMG_20241204_122747.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675673a9befd7f3db9077a04",
  "name": "externallmg_r_1733718938439_IMG_20241204_122911.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718938439_IMG_20241204_122911.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675673a9befd7f3db9077a05",
  "name": "externallmg_r_1733718938693_IMG_20241204_122913.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718938693_IMG_20241204_122913.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675673a9befd7f3db9077a06",
  "name": "externallmg_r_1733718939650_IMG_20241204_123114.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718939650_IMG_20241204_123114.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675673a9befd7f3db9077a07",
  "name": "externallmg_r_1733718939208_IMG_20241204_122914.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718939208_IMG_20241204_122914.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "675673a9befd7f3db9077a08",
    "name": "externallmg_r_1733718940894_IMG_20241204_123117.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718940894_IMG_20241204_123117.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a09",
    "name": "externallmg_r_1733718940247_IMG_20241204_123115.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718940247_IMG_20241204_123115.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a0a",
    "name": "externallmg_r_1733718942237_IMG_20241204_123120.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718942237_IMG_20241204_123120.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a0b",
    "name": "externallmg_r_1733718941418_IMG_20241204_123118.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718941418_IMG_20241204_123118.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a0c",
    "name": "externallmg_r_1733718943285_IMG_20241204_123127.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718943285_IMG_20241204_123127.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a0d",
```

```
    "name": "externalimg_r_1733718942659_IMG_20241204_123123.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externalimg_r_1733718942659_IMG_20241204_123123.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a0e",
    "name": "externalimg_r_1733718944657_IMG_20241204_123133.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externalimg_r_1733718944657_IMG_20241204_123133.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a0f",
    "name": "externalimg_r_1733718943652_IMG_20241204_123130.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externalimg_r_1733718943652_IMG_20241204_123130.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a10",
    "name": "externalimg_r_1733718944928_IMG_20241204_123144.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externalimg_r_1733718944928_IMG_20241204_123144.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a11",
    "name": "externalimg_r_1733718945566_IMG_20241204_123200.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externalimg_r_1733718945566_IMG_20241204_123200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a12",
    "name": "externalimg_r_1733718945954_IMG_20241204_123214.jpg",
```

```
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718945954_IMG_20241204_123214.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a13",
    "name": "externallmg_r_1733718946124_IMG_20241204_123224.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718946124_IMG_20241204_123224.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a14",
    "name": "externallmg_r_1733718947094_IMG_20241204_123233.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718947094_IMG_20241204_123233.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675673a9befd7f3db9077a15",
    "name": "externallmg_r_1733718946694_IMG_20241204_123227.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733718946694_IMG_20241204_123227.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be70a",
    "name": "externallmg_1733719575270_IMG_20241204_123627.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_1733719575270_IMG_20241204_123627.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be70b",
    "name": "externallmg_1733719575619_IMG_20241204_123627__01.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_1733719575619_IMG_20241204_123627__01.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be70c",
  "name": "externallmg_r_1733719566155_IMG_20241204_123239.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719566155_IMG_20241204_123239.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be70d",
  "name": "externallmg_r_1733719565830_IMG_20241204_123234.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719565830_IMG_20241204_123234.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be70e",
  "name": "externallmg_r_1733719567301_IMG_20241204_123251.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719567301_IMG_20241204_123251.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be70f",
  "name": "externallmg_r_1733719566761_IMG_20241204_123249.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719566761_IMG_20241204_123249.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be710",
  "name": "externallmg_r_1733719568941_IMG_20241204_123416.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719568941_IMG_20241204_123416.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be711",
    "name": "externallmg_r_1733719568513_IMG_20241204_123413.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719568513_IMG_20241204_123413.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be712",
    "name": "externallmg_r_1733719567698_IMG_20241204_123407.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719567698_IMG_20241204_123407.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be713",
    "name": "externallmg_r_1733719569349_IMG_20241204_123417.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719569349_IMG_20241204_123417.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be714",
    "name": "externallmg_r_1733719571362_IMG_20241204_123515.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719571362_IMG_20241204_123515.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be715",
    "name": "externallmg_r_1733719570552_IMG_20241204_123513.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719570552_IMG_20241204_123513.jpg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be716",
  "name": "externallmg_r_1733719570110_IMG_20241204_123505.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719570110_IMG_20241204_123505.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be717",
  "name": "externallmg_r_1733719571700_IMG_20241204_123516.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719571700_IMG_20241204_123516.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be718",
  "name": "externallmg_r_1733719572604_IMG_20241204_123552.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719572604_IMG_20241204_123552.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be719",
  "name": "externallmg_r_1733719572263_IMG_20241204_123525.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719572263_IMG_20241204_123525.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756761ecfae933db22be71a",
  "name": "externallmg_r_1733719573187_IMG_20241204_123554.jpg",
  "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719573187_IMG_20241204_123554.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be71b",
    "name": "externallmg_r_1733719573656_IMG_20241204_123613.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719573656_IMG_20241204_123613.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be71c",
    "name": "externallmg_r_1733719574266_IMG_20241204_123614.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719574266_IMG_20241204_123614.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756761ecfae933db22be71d",
    "name": "externallmg_r_1733719574619_IMG_20241204_123619.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_r_1733719574619_IMG_20241204_123619.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756762acfae933db22be766",
    "name": "externallmg_1733719593900_Screenshot_2024120412385209_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/externallmg_1733719593900_Screensh
ot_2024120412385209_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67567633befd7f3db90780ed",
    "name": "externallmg_1733719603224_IMG20241206WA0158.jpg",
    "path": "cases/6746cadfd1078a4ea7fb18f0/
externallmg_1733719603224_IMG20241206WA0158.jpg",
    "orientation": "portrait"
  }
],
```

```

"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-27T07:31:43.340Z",
"updatedAt": "2024-12-09T04:46:43.344Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f91822f3dd69653a5922e3",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Land and Building No. 1st Floor, Building No G, Zero Tax
Industrial Estate, Village - Dadra, 396230, State - Dadra & Nagar Haveli",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Cruise Electricals Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "7045959281"

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			