

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b899"
    },
    "firstName": "Rupali",
    "type": "CREDITOFFICER",
    "_id": "671cb0fbfd14bf9350accfa5",
    "email": "rupali.vivalkar@sbi.co.in",
    "lastName": "Tambe",
    "mobileNo": "",
    "workMobileNo": "9619123122"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b899",
  "branchCode": "000127",
  "type": "BRANCH",
  "name": "RACPC Thane ",
  "email": "rasecc.thane@sbi.co.in",
  "mobileNo": "02220812026",
  "alternateMobileNo": "02220812027",
  "address": "Retail Assets Centralized, Processing Centre,Dosti Pinnacle , Plot no
E7,Near New Passport Office,Gate No-3,Road No 22,Panchpakhadi Village Wagle Indl
Estate,Thane- 400604\r\n",
  "ledgerName": "STATE BANK OF INDIA - THANE RACPC",
  "fax": "2538 2750 ",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
```

```
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.213458298071767",
  "longitude": "72.98637473759952"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.98637473759952,
    19.213458298071767
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "28/11/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-11-29T09:53:13.741Z",
```

```
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-11-29",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "14000",
  "lumpsumValue": "1",
  "rateMax": "16000",
  "areaType": {
    "Name": "Built Up",
    "Value": "Built Up",
    "name": "Built Up",
    "value": "Built Up"
  }
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Majiwada",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Thane ",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aphrodite A/B/C/D Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Eastern Express Highway ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": true,
"name": "Wing",
"key": "wing",
"value": "D",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Lodha Paradise",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "10/2A, 10/2B, 10/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 601",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "Vitrified_Tile_Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "label": "Concealed Plumbing with Conduit & Concealed Electrical wiring",
    "value": "Concealed_Plumbing_with_Conduit_&_Concealed_Electrical_wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
```

```
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot and Nala",
    "west": "Internal Road ",
    "south": "Wing - C",
    "east": "Open Plot and Nala"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space ",
      "east": "Lift",
      "south": "Flat No. 403",
      "west": "Flat No. 401"
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    }
  },
}
```

```
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "714",
  "depreciatedCostOfConstruction": "15286.00",
  "depreciatedBuildingRate": "2086"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "137600",
```

```
"landRate": "41400",
"igrImage": "cases/6747fbf2d1078a4ea7fba120/igr_1732946333493_Image.png",
"squareMeterGuideLineRate": "137600.00",
"squareFeetGuideLineRate": "12783.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "83",
  "rate": "11264.00",
  "squareFeetGuideLineRate": "11264.00",
  "squareMeterGuideLineRate": "121246.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Consumer No. 000036022680 ",
  "meterCardHolderName": "Mrs. Poonam Pundalik Vishe",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per TMC norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"label": "6\" Thk. Brick Masonery",
"value": "6\"_Thk._Brick_Masonery"
},
"waterTank": {
"label": "Municipal Water Supply",
"value": "MunicipalWaterSupply"
},
"pavementLaid": {
"label": "No",
"value": "No"
},
"carParking": "Stilt / Open Car Parking Space",
"constructionWorkStatus": {
"label": "Completed",
"value": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2007",
"fullDate": "1/1/2007"
},
"planningArea": {
"label": "Residential",
"value": "Residential"
},
"typeOfStructure": {
"label": "R.C.C. Framed Structure",
"value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"label": "Normal",
"value": "Normal"
},
}
```

```
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
```



```
    "label": "Yes"
  },
  "groundStilt": {
    "label": "Stilt",
    "value": "stilt"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_site_information",
    "label": "As per site information"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "43",
  "ageOfBuilding": "17",
  "noOfBasement": "0",
  "noOfPodium": "0",
  "noOfAmenityFloors": "0",
  "noOfFloors": "7",
  "flatFloorNo": "4",
  "noOfLifts": "1",
  "noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "783.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6747fbf2d1078a4ea7fba120/
routeMap_1732952838790_Image.png",
    "routeLat": "19.213529",
    "routeLng": "72.986173",
    "stationName": "Thane",
    "routeDistance": "4.3 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "z6hq6d",
    "name": "z6hq6d",
    "image": "cases/6747fbf2d1078a4ea7fba120/
routeMap_1732952763279_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11968938.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "11968938.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Nov 30 2024 12:52:03 GMT+0000 (Coordinated Universal Time)",
  "number": "2309302",
  "dayCount": "26",
  "monthCount": "387",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "8819712.00",
  "selectedBuildUpValue": "783.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "674aa047d1078a4ea7fd082e",
      "name":
"externallmg_1732943943196_WhatsApp_Image_20241129_at_143056_1.jpeg",
      "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943196_WhatsApp_Image_20241129_at_143056_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "674aa047d1078a4ea7fd082f",
      "name":
"externallmg_1732943943213_WhatsApp_Image_20241129_at_143056.jpeg",
      "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943213_WhatsApp_Image_20241129_at_143056.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "674aa047d1078a4ea7fd082e",
      "name":
"externallmg_1732943943196_WhatsApp_Image_20241129_at_143056_1.jpeg",
      "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943196_WhatsApp_Image_20241129_at_143056_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "674aa05a520246c6c0645c29",
      "name":
"externallmg_1732943961716_WhatsApp_Image_20241129_at_143105.jpeg",
```

```
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961716_WhatsApp_Image_20241129_at_143105.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674aa05a520246c6c0645c2d",
    "name":
"externallmg_1732943961738_WhatsApp_Image_20241129_at_143107_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961738_WhatsApp_Image_20241129_at_143107_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674aa05a520246c6c0645c2e",
    "name":
"externallmg_1732943961754_WhatsApp_Image_20241129_at_143107.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961754_WhatsApp_Image_20241129_at_143107.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674aa05a520246c6c0645c2b",
    "name":
"externallmg_1732943961723_WhatsApp_Image_20241129_at_143106_2.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961723_WhatsApp_Image_20241129_at_143106_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674aa05a520246c6c0645c30",
    "name":
"externallmg_1732943961778_WhatsApp_Image_20241129_at_143108.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961778_WhatsApp_Image_20241129_at_143108.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674aa05a520246c6c0645c2f",
    "name":
"externallmg_1732943961756_WhatsApp_Image_20241129_at_143108_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961756_WhatsApp_Image_20241129_at_143108_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674aa05a520246c6c0645c2c",
    "name":
"externallmg_1732943961736_WhatsApp_Image_20241129_at_143106.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961736_WhatsApp_Image_20241129_at_143106.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "674aa05a520246c6c0645c2a",
    "name":
"externallmg_1732943961721_WhatsApp_Image_20241129_at_143106_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961721_WhatsApp_Image_20241129_at_143106_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "674aa047d1078a4ea7fd0833",
    "name":
"externallmg_1732943943261_WhatsApp_Image_20241129_at_143059.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943261_WhatsApp_Image_20241129_at_143059.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "674aa047d1078a4ea7fd0831",
    "name":
"externallmg_1732943943235_WhatsApp_Image_20241129_at_143058_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943235_WhatsApp_Image_20241129_at_143058_1.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17640.00",
```



```
"max": "21831.00"
},
"builtUpRateRange": {
  "min": "14700.00",
  "max": "18192.00"
},
"saleableRateRange": {
  "min": "12250.00",
  "max": "15160.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "783.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6747fbf2d1078a4ea7fba120",
"ownerName": "Mrs. Poonam Pundalik Vishe & Mr. Pundalik Bhiva Vishe ",
"ownerPhoneNo": "9901497197",
"appAddress": "flat no - 402, 4th floor, Afrodite Bldg, D wing, Lodha paradise,
Majiwade thane ",
```

```
"remark": "case reference - savita gavari mam.. SBI branch Thane ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "17/06/2005",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Lodha Developers Pvt. Ltd. ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Poonam Pundalik Vishe & Mr. Pundalik Bhiva Vishe ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "4090 / 2005"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1732950883322_Agreement.pdf",
    "path": "cases/6747fbf2d1078a4ea7fba120/
document_1732950883322_Agreement.pdf",
    "id": "362940",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Sat Nov 30 2024 07:14:44 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "6077c791395bc80714864a30",
      "label": "Electricity Bill"
    },
    "inputs": {
      "documentDate": "19/11/2024",
      "number": {
        "value": "Consumer_No",
        "label": "Consumer No"
      },
      "Consumer_No": "000036022680 dated 19.11.2024 in the name of Mrs. Poonam
```

```
Pundalik Vishe"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1732951299321_Light_Bill.pdf",
  "path": "cases/6747fbf2d1078a4ea7fba120/
document_1732951299321_Light_Bill.pdf",
  "id": "602769",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Nov 30 2024 07:21:39 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "01/09/2010",
    "remark": " issued by Aphrodite A/B/C/D Co-Op. Hsg. Soc. Ltd",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mrs. Poonam Pundalik Vishe",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "079"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "752665",
  "path": "cases/6747fbf2d1078a4ea7fba120/document_1732951384856_SC.pdf",
  "fileName": "document_1732951384856_SC.pdf"
}
],
"caseNumber": "012658",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "477987",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 28 2024 05:13:22 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mrs. Poonam Pundalik Vishe & Mr. Pundalik Bhiva Vishe ",
    "phone": "9901497197",
    "ownershipShare": "",
    "email": "",
    "id": "783364"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "67498d67520246c6c06404db",
    "area": "608",
    "providedByName": "Poonam Pundalik vishe And Pundalik Bhuva Vishe",
    "providedByContactNo": "9901497197"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "2.42",
    "length1": "2",
    "length2": "5",
    "width": "3.75",
    "width1": "3",
    "width2": "9",
    "totalArea": "9.06",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "_id": "674abf5cd1078a4ea7fd470d",
  "name": "Extra ",
  "extraAreaType": "Add",
  "length": "91.00",
  "length1": "91",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "91.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "_id": "674abf62d1078a4ea7fd474a",
  "name": "Exta ",
  "extraAreaType": "Add",
  "length": "93.00",
  "length1": "93",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "93.00"
}
],
"finalArea": "193.06"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "41.00",
  "length1": "41",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
```

```
"totalArea": "41.00",
"images": [],
"extraAreas": [],
"finalArea": "41.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "66.28",
  "images": [],
  "extraAreas": [],
  "finalArea": "66.28"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "14.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.69"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```



```
"id": "4",
"name": "Bedroom",
"length": "114.00",
"length1": "114",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "114.00",
"images": [],
"extraAreas": [],
"finalArea": "114.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "12.40",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "674abfde520246c6c0649b96",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "12.75",
      "length1": "12",
      "length2": "9",
      "width": "9.50",
      "width1": "9",
      "width2": "6",
      "totalArea": "121.12"
    }
  ],
}
```

```
"measurementType": {
  "label": "Square Feet",
  "value": "Square_Feet"
},
"_id": "674abfede077c54e532ce2dd",
"name": "Thane ",
"extraAreaType": "Add",
"length": "5.17",
"length1": "5",
"length2": "2",
"width": "1.92",
"width1": "1",
"width2": "11",
"totalArea": "9.90"
}
],
"finalArea": "143.42000000000002"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "16.25",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "674ac017520246c6c0649bc5",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "4.25",
      "length1": "4",
      "length2": "3",
      "width": "2.75",
```

```
"width1": "2",
"width2": "9",
"totalArea": "11.69"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "_id": "674ac021e077c54e532ce335",
  "name": "Thane ",
  "extraAreaType": "Add",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "8.00"
}
],
"finalArea": "35.94"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "819616",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "783",
    "squareMeterArea": "72.74",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
]
```

```
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "765.00",
      "squareMeterArea": "71.07",
      "expectedRate": "21830.07",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "918.00",
      "squareMeterArea": "85.29",
      "expectedRate": "18191.72",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "1101.60",
      "squareMeterArea": "102.34",
      "expectedRate": "15159.77",
      "percentage": "20"
    },
    "printlnReport": true,
    "_id": "674b0dc5d1078a4ea7fdd065",
    "property": "Flat",
    "area": "765",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "magic_bricks",
    "expectedPrice": "16700000",
    "expectedRate": "21830.07",
    "builtUpExpectedRate": "18191.72",
    "image": "cases/6747fbf2d1078a4ea7fba120/
indicator_1732971803223_Image.png",
    "squareMeter": "71.07",
    "id": "333343"
  },
  {
    "carpetArea": {
      "area": "430.00",
      "squareMeterArea": "39.95",
      "expectedRate": "19767.44",
```

```
    "percentage": ""
  },
  "builtUpArea": {
    "area": "516.00",
    "squareMeterArea": "47.94",
    "expectedRate": "16472.87",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "619.20",
    "squareMeterArea": "57.53",
    "expectedRate": "13727.39",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "674b0dc5d1078a4ea7fdd066",
  "property": "Flat",
  "area": "430",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "8500000",
  "expectedRate": "19767.44",
  "builtUpExpectedRate": "16472.87",
  "image": "cases/6747fbf2d1078a4ea7fba120/
indicator_1732971973458_Image.png",
  "squareMeter": "39.95",
  "id": "118968"
},
{
  "carpetArea": {
    "area": "737.00",
    "squareMeterArea": "68.47",
    "expectedRate": "17639.08",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "884.40",
    "squareMeterArea": "82.16",
    "expectedRate": "14699.23",
    "percentage": "20"
  },
  "saleableArea": {
```

```
"area": "1061.28",
"squareMeterArea": "98.60",
"expectedRate": "12249.36",
"percentage": "20"
},
"printlnReport": true,
"_id": "674aaa2ce077c54e532ca6f3",
"property": "Flat",
"area": "737",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "13000000",
"expectedRate": "17639.08",
"builtUpExpectedRate": "14699.23",
"image": "cases/6747fbf2d1078a4ea7fba120/
indicator_1732946214149_Image.png",
"squareMeter": "68.47",
"id": "742335"
},
{
"carpetArea": {
"area": "762.00",
"squareMeterArea": "70.79",
"expectedRate": "18766.40",
"percentage": ""
},
"builtUpArea": {
"area": "914.40",
"squareMeterArea": "84.95",
"expectedRate": "15638.67",
"percentage": "20"
},
"saleableArea": {
"area": "1097.28",
"squareMeterArea": "101.94",
"expectedRate": "13032.23",
"percentage": "20"
},
"printlnReport": true,
"_id": "674b0dc5d1078a4ea7fdd068",
"property": "Flat",
"area": "762",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "14300000",
"expectedRate": "18766.40",
"builtUpExpectedRate": "15638.67",
"image": "cases/6747fbf2d1078a4ea7fba120/
indicator_1732971606677_Image.png",
"squareMeter": "70.79",
"id": "410713"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "674aa047d1078a4ea7fd082c",
"name":
"externallmg_1732943943189_WhatsApp_Image_20241129_at_143055_1.jpeg",
"path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943189_WhatsApp_Image_20241129_at_143055_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "674aa047d1078a4ea7fd082d",
"name":
"externallmg_1732943943192_WhatsApp_Image_20241129_at_143055.jpeg",
"path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943192_WhatsApp_Image_20241129_at_143055.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "674aa047d1078a4ea7fd082e",
"name":
"externallmg_1732943943196_WhatsApp_Image_20241129_at_143056_1.jpeg",
"path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943196_WhatsApp_Image_20241129_at_143056_1.jpeg",
"orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674aa047d1078a4ea7fd082f",
  "name":
"externallmg_1732943943213_WhatsApp_Image_20241129_at_143056.jpeg",
  "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943213_WhatsApp_Image_20241129_at_143056.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674aa047d1078a4ea7fd0830",
  "name":
"externallmg_1732943943216_WhatsApp_Image_20241129_at_143057.jpeg",
  "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943216_WhatsApp_Image_20241129_at_143057.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674aa047d1078a4ea7fd0831",
  "name":
"externallmg_1732943943235_WhatsApp_Image_20241129_at_143058_1.jpeg",
  "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943235_WhatsApp_Image_20241129_at_143058_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674aa047d1078a4ea7fd0832",
  "name":
"externallmg_1732943943240_WhatsApp_Image_20241129_at_143058.jpeg",
  "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943240_WhatsApp_Image_20241129_at_143058.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674aa047d1078a4ea7fd0833",
  "name":
"externallmg_1732943943261_WhatsApp_Image_20241129_at_143059.jpeg",
```



```
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943261_WhatsApp_Image_20241129_at_143059.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa047d1078a4ea7fd0834",
    "name":
"externallmg_1732943943264_WhatsApp_Image_20241129_at_143102.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943264_WhatsApp_Image_20241129_at_143102.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa047d1078a4ea7fd0835",
    "name":
"externallmg_1732943943279_WhatsApp_Image_20241129_at_143105_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943943279_WhatsApp_Image_20241129_at_143105_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c29",
    "name":
"externallmg_1732943961716_WhatsApp_Image_20241129_at_143105.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961716_WhatsApp_Image_20241129_at_143105.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c2a",
    "name":
"externallmg_1732943961721_WhatsApp_Image_20241129_at_143106_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961721_WhatsApp_Image_20241129_at_143106_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "674aa05a520246c6c0645c2b",
    "name":
"externallmg_1732943961723_WhatsApp_Image_20241129_at_143106_2.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961723_WhatsApp_Image_20241129_at_143106_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c2c",
    "name":
"externallmg_1732943961736_WhatsApp_Image_20241129_at_143106.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961736_WhatsApp_Image_20241129_at_143106.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c2d",
    "name":
"externallmg_1732943961738_WhatsApp_Image_20241129_at_143107_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961738_WhatsApp_Image_20241129_at_143107_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c2e",
    "name":
"externallmg_1732943961754_WhatsApp_Image_20241129_at_143107.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961754_WhatsApp_Image_20241129_at_143107.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c2f",
    "name":
"externallmg_1732943961756_WhatsApp_Image_20241129_at_143108_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961756_WhatsApp_Image_20241129_at_143108_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c30",
    "name":
"externallmg_1732943961778_WhatsApp_Image_20241129_at_143108.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961778_WhatsApp_Image_20241129_at_143108.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c31",
    "name":
"externallmg_1732943961782_WhatsApp_Image_20241129_at_143111_1.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961782_WhatsApp_Image_20241129_at_143111_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c32",
    "name":
"externallmg_1732943961800_WhatsApp_Image_20241129_at_143111_2.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961800_WhatsApp_Image_20241129_at_143111_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c33",
    "name":
"externallmg_1732943961804_WhatsApp_Image_20241129_at_143111.jpeg",
    "path": "cases/6747fbf2d1078a4ea7fba120/
externallmg_1732943961804_WhatsApp_Image_20241129_at_143111.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674aa05a520246c6c0645c34",
```

```
"name":
"externalImg_1732943961822_WhatsApp_Image_20241129_at_143112.jpeg",
  "path": "cases/6747fbf2d1078a4ea7fba120/
externalImg_1732943961822_WhatsApp_Image_20241129_at_143112.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalName": "Poonam vishe - Flat No. 402 - State Bank of India ( RACPC
Thane ).xlsx",
  "filename": "1732946472325_Poonam_vishe___Flat_No_402__State_Bank_of_Indi
a__RACPC_Thane_.xlsx",
  "path": "cases/6747fbf2d1078a4ea7fba120/processingDocuments/1732946472325_
Poonam_vishe___Flat_No_402__State_Bank_of_India__RACPC_Thane_.xlsx",
  "size": "1677801",
  "createdAt": "Sat Nov 30 2024 06:01:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67485e9d520246c6c06381f6",
  "note": "Value given for confirmation",
  "taskId": "6747fbf3e077c54e532acc50",
  "createdAt": "2024-11-28T12:14:21.085Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdfc2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
```

```
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fd2c2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "SITE_INSPECTION",
  "display": true,
  "status": true,
  "_id": "674aa00b520246c6c0645b8f",
  "note": "Photos Uploded (Task Reopen)",
  "taskId": "67486997520246c6c0638f4f",
  "createdAt": "2024-11-30T05:18:03.975Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "674aa618d1078a4ea7fd129a",
  "note": "value confirmed (Task Reopen)",
  "taskId": "67477bf3e077c54e532acc50",
  "createdAt": "2024-11-30T05:43:52.837Z"
}
],
"createdAt": "2024-11-28T05:13:22.758Z",
"updatedAt": "2024-11-30T13:06:13.654Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 402, 4th Floor, Wing - D, Aphrodite A/B/C/D Co-Op.
Hsg. Soc. Ltd., Lodha Paradise, Eastern Express Highway , Village - Majiwada, Thane
(West), Taluka - Thane , District - Thane , PIN - 400 601, State - Maharashtra, Country
- India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mrs. Poonam Pundalik Vishe ",
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"rerald": "",
"siteVisitContactNo": "9901497197",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "608.39",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2024-11-29",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 783.00",
"flatRate": "16000",
"landOtherRate": "13200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "669.23",
"finalCarpetArea": "608.39",
"finalSalableArea": "736.15",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
```

```

    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Nov 30 2024 12:51:41 GMT+0000 (Coordinated
Universal Time)"
}

```

Name	Length	Width	Total
Composition :			
Living Room	2'5"	3'9"	9.06
Passage	41'00"	1'00"	41.00
Kitchen	9'7"	6'11"	66.28
Toilet	3'9"	3'11"	14.69
Bedroom	114'00"	1'00"	114.00
Bedroom	3'11"	3'2"	12.40
Toilet	3'9"	4'4"	16.25
Other Composition :			