

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "firstName": "Amit",
    "type": "CREDITOFFICER",
    "_id": "6646d7ab6f40574290c0f8aa",
    "lastName": "Chirmule",
    "mobileNo": "",
    "workMobileNo": "7588898471",
    "email": "thane@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "000",
    "discussWithPerson": "Amit",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/64abdb2806d6ec174986d16b/
profilePhoto_1731563513029_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.202282164551395",
  "longitude": "72.9786534751219"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.9786534751219,
    19.202282164551395
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-28T08:00:44.272Z",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-28",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "40000",
  "lumpsumValue": "1",
  "rateMax": "41000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "Single_Unit",
  "label": "Single Unit"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kolbad & Panchpakhadi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Srushti Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Comrade Rajaram Vishnu Rawool Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```



```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "201/8 & 202/8",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "8",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 601",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified tile flooring",
    "value": "Vitrified_tile_flooring"
  },
  "doors": {
    "value": "Wooden_Frame_Glass_door_with_MS_Rolling_Shutter",
    "label": "Wooden Frame Glass door with MS Rolling Shutter"
  },
  "windows": {
    "label": "N.A.",
    "value": "N.A."
  }
},
```

```
"fittings": {
  "label": "Concealed Electrification",
  "value": "Concealed_Electrification"
},
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Celling",
  "label": "Cement Plastering with POP false Celling"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Kolungade CHS",
    "west": "Open Space",
    "south": "Comrade Rajaram Vishnu Rawool Marg",
    "east": "Maa Anusaya Tower"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
```

```

    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "The composition of shop is Single unit.",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "ordinary",
  "label": "Ordinary"
},
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
}

```

```
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "38000",
  "depreciatedBuildingRate": "2200"
},
"igrRate": {
  "propertyName": "Shop",
  "rate": "225100",
  "landRate": "62900",
  "igrImage": "cases/6748056f520246c6c06301b6/igr_1732860987050_Image.png",
  "squareMeterGuideLineRate": "225100.00",
  "squareFeetGuideLineRate": "20912.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "92",
  "rate": "19707.00",
  "squareFeetGuideLineRate": "19707.00",
  "squareMeterGuideLineRate": "212124.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_use",
    "label": "Commercial use"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": "28,875.00 Present rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
```

```
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "Mrs. Sabita Catherine / Rented Since – 5 Years",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2016",
    "fullDate": "1/1/2016"
  },
}
```

```
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
```



```
"label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "6",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "13"
},
"finalPlinthArea": {
  "area": "265.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Transfer"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "cases/6748056f520246c6c06301b6/
routeMap_1732865350145_Image.png",
"routeLat": "19.204200",
"routeLng": "72.975502",
"stationName": "Thane",
"routeDistance": "2.2 Km",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "ikptp",
    "name": "ikptp",
    "image": "cases/6748056f520246c6c06301b6/
routeMap_1732865107784_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "662500.00",
    "depreciationPercentage": "12",
    "depreciatedCostOfConstruction": "79500.00",
    "totalFairMarketValue": "10070000.00"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
```

```
"totalKitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalSuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalInteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalElectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalExtraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalPotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalOthersRate": "0",
"finalTotal": "10149500.00",
"finalValue": "10149500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Nov 29 2024 10:19:30 GMT+0000 (Coordinated Universal Time)",
  "number": "2309270",
  "dayCount": "11",
  "monthCount": "355",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5222355.00",
  "selectedBuildUpValue": "265.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "674832b9e077c54e532b33fb",
      "name":
"externallmg_1732784825499_WhatsApp_Image_20241128_at_14211_PM_1.jpeg",
      "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825499_WhatsApp_Image_20241128_at_14211_PM_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "674832b9e077c54e532b33fb",
      "name":
"externallmg_1732784825499_WhatsApp_Image_20241128_at_14211_PM_1.jpeg",
```

```
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825499_WhatsApp_Image_20241128_at_14211_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b3406",
    "name":
"externallmg_1732784825684_WhatsApp_Image_20241128_at_14216_PM.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825684_WhatsApp_Image_20241128_at_14216_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b33ff",
    "name":
"externallmg_1732784825597_WhatsApp_Image_20241128_at_14213_PM_1.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825597_WhatsApp_Image_20241128_at_14213_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b3403",
    "name":
"externallmg_1732784825640_WhatsApp_Image_20241128_at_14214_PM.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825640_WhatsApp_Image_20241128_at_14214_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b3404",
    "name":
"externallmg_1732784825654_WhatsApp_Image_20241128_at_14215_PM_1.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825654_WhatsApp_Image_20241128_at_14215_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b3405",
    "name":
"externallmg_1732784825665_WhatsApp_Image_20241128_at_14215_PM.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825665_WhatsApp_Image_20241128_at_14215_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b3401",
    "name":
"externallmg_1732784825625_WhatsApp_Image_20241128_at_14214_PM_1.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825625_WhatsApp_Image_20241128_at_14214_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b3402",
    "name":
"externallmg_1732784825632_WhatsApp_Image_20241128_at_14214_PM_2.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825632_WhatsApp_Image_20241128_at_14214_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "674832b9e077c54e532b3400",
    "name":
"externallmg_1732784825608_WhatsApp_Image_20241128_at_14213_PM.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825608_WhatsApp_Image_20241128_at_14213_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "43952.00",
    "max": "52000.00"
  },
  "builtUpRateRange": {
    "min": "36627.00",
    "max": "43334.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```



```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```

```
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "265.00",
"empanelmentNo": [
  "HO/Credit/87/2022-23"
],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6748056f520246c6c06301b6",
"ownerName": "Mr. Dinesh Lakhiram Agrawal & Mr. Harsh Dlnesh Agrawal ",
"ownerPhoneNo": "9819147770",
"appAddress": "shop no. 8 , sree srushti, co.opp.hsg. soc.ltd\nkolbad, Thane ",
"remark": "payment from client ",
"documents": [
  {
    "documentType": {
      "value": "60ae129baa6d152c1801b46c",
      "label": "Agreement For Transfer"
    },
    "inputs": {
      "documentDate": "25/11/2024",
      "from": {
```

```
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mrs. Sabita Catherine Nevita DSA (Nee Sabita Menezes), Mr. Ajit Savio Menezes, Mrs. Shalini Rodney Coutinho, Mr. Sunil Menezes & Mr. Arun Menezes",
  "to": {
    "value": "transferee",
    "label": "transferee"
  },
  "transferee": "Mr. Dinesh Lakhiram Agrawal and Mr. Harsh Dinesh Agrawal"
},
"isHardCopy": false,
"displayStatus": true,
"id": "997466",
"path": "cases/6748056f520246c6c06301b6/
document_1732773132665_1732773129628_Dinesh_Agarwal_.pdf",
"fileName": "document_1732773132665_1732773129628_Dinesh_Agarwal_.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "25/09/2003",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "V_P_No_",
      "label": "V.P. No."
    },
    "V_P_No_": "2000 / 14 / TMC / TDD / 2427"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1732871650607_190994.pdf",
  "path": "cases/6748056f520246c6c06301b6/
document_1732871650607_190994.pdf",
  "id": "278640",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Nov 29 2024 09:14:11 GMT+0000 (Coordinated Universal Time)"
},
{
```

```
"documentType": {
  "value": "60ae124baa6d152c1801b2fd",
  "label": "Occupancy Certificate"
},
"inputs": {
  "documentDate": "02/09/2016",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "number": {
    "value": "V_P_No_",
    "label": "V.P. No."
  },
  "V_P_No_": "2000 / 14 / TMC / TDD / 105"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1732871709111_97427.pdf",
"path": "cases/6748056f520246c6c06301b6/
document_1732871709111_97427.pdf",
"id": "179671",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Fri Nov 29 2024 09:15:09 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae125eaa6d152c1801b353",
    "label": "Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/10/2024",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    },
    "remark": "in the name of Shri. Roy Menenzes",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "402"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1732871827257_156137.pdf",
```

```
    "path": "cases/6748056f520246c6c06301b6/
document_1732871827257_156137.pdf",
    "id": "976959",
    "uploadedBy": "627222afafd7d55eddedd82",
    "createdAt": "Fri Nov 29 2024 09:17:07 GMT+0000 (Coordinated Universal Time)"
  }
],
"gstNo": "",
"caseNumber": "012660",
"createdBy": "64abdb2806d6ec174986d16b",
"caseHistory": [
  {
    "id": "347525",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 28 2024 05:53:51 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Dinesh Lakhiram Agrawal & Mr. Harsh DInesh Agrawal ",
    "phone": "9819147770",
    "ownershipShare": "",
    "email": "",
    "id": "744690"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "674822dce077c54e532b2249",
    "area": "226",
    "providedByName": "Mr. Dinesh Lakhiram Agrawal and Mr. Harsh DInesh Agrawal ",
    "providedByContactNo": "9819147770"
  }
],
"composition": [
  {
```

```
"measurementType": {
  "label": "Square Feet",
  "value": "Square_Feet"
},
"id": "2",
"name": "Shop",
"length": "226.00",
"length1": "226",
"length2": "0",
"width": "1.00",
"width1": "1",
"width2": "0",
"totalArea": "226.00",
"images": [],
"finalArea": "226.00",
"extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae129baa6d152c1801b46c",
    "label": "Agreement For Transfer"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "21.93",
  "totalAreaDocument": "236",
  "docBultupPercentage": "20",
  "docFinalBultUp": "283.20",
  "docFinalBultUpSquareMeter": "26.31",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "660094"
},
{
  "typeOfDocument": {
    "value": "60ae129baa6d152c1801b46c",
    "label": "Agreement For Transfer"
  },
}
```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "24.62",
"totalAreaDocument": "265",
"docBuiltpupPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "0",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "967073"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "250.00",
    "squareMeterArea": "23.23",
    "expectedRate": "50000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "300.00",
    "squareMeterArea": "27.87",
    "expectedRate": "41666.67",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "67495c6cd1078a4ea7fc7f75",
  "property": "Shop",
  "area": "250",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": ""
}
```



```
"source": "square_yards",
"expectedPrice": "12500000",
"expectedRate": "50000.00",
"builtUpExpectedRate": "41666.67",
"image": "cases/6748056f520246c6c06301b6/
indicator_1732860791803_Image.png",
"squareMeter": "23.23",
"id": "184262"
},
{
"carpetArea": {
"area": "250.00",
"squareMeterArea": "23.23",
"expectedRate": "52000.00",
"percentage": ""
},
"builtUpArea": {
"area": "300.00",
"squareMeterArea": "27.87",
"expectedRate": "43333.33",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67495c6cd1078a4ea7fc7f76",
"property": "Shop",
"area": "300",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Thane_homes",
"expectedPrice": "13000000",
"expectedRate": "52000.00",
"builtUpExpectedRate": "13000000",
"image": "cases/6748056f520246c6c06301b6/
indicator_1732860826402_Image.png",
"squareMeter": "27.87",
"id": "185764"
},
```

```
{
  "carpetArea": {
    "area": "205.00",
    "squareMeterArea": "19.05",
    "expectedRate": "43951.22",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "246.00",
    "squareMeterArea": "22.85",
    "expectedRate": "36626.02",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67495c6cd1078a4ea7fc7f77",
  "property": "Shop",
  "area": "205",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "9010000",
  "expectedRate": "43951.22",
  "builtUpExpectedRate": "36626.02",
  "image": "cases/6748056f520246c6c06301b6/
indicator_1732860860162_Image.png",
  "squareMeter": "19.05",
  "id": "298791"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674832b9e077c54e532b33fb",
    "name":
"externalImg_1732784825499_WhatsApp_Image_20241128_at_14211_PM_1.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externalImg_1732784825499_WhatsApp_Image_20241128_at_14211_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674832b9e077c54e532b33fc",
    "name":
"externallmg_1732784825516_WhatsApp_Image_20241128_at_14211_PM.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825516_WhatsApp_Image_20241128_at_14211_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674832b9e077c54e532b33fd",
    "name":
"externallmg_1732784825544_WhatsApp_Image_20241128_at_14212_PM_1.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825544_WhatsApp_Image_20241128_at_14212_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674832b9e077c54e532b33fe",
    "name":
"externallmg_1732784825572_WhatsApp_Image_20241128_at_14212_PM.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825572_WhatsApp_Image_20241128_at_14212_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674832b9e077c54e532b33ff",
    "name":
"externallmg_1732784825597_WhatsApp_Image_20241128_at_14213_PM_1.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825597_WhatsApp_Image_20241128_at_14213_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674832b9e077c54e532b3400",
```

```
    "name":
"externallmg_1732784825608_WhatsApp_Image_20241128_at_14213_PM.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825608_WhatsApp_Image_20241128_at_14213_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3401",
  "name":
"externallmg_1732784825625_WhatsApp_Image_20241128_at_14214_PM_1.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825625_WhatsApp_Image_20241128_at_14214_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3402",
  "name":
"externallmg_1732784825632_WhatsApp_Image_20241128_at_14214_PM_2.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825632_WhatsApp_Image_20241128_at_14214_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3403",
  "name":
"externallmg_1732784825640_WhatsApp_Image_20241128_at_14214_PM.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825640_WhatsApp_Image_20241128_at_14214_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3404",
  "name":
"externallmg_1732784825654_WhatsApp_Image_20241128_at_14215_PM_1.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825654_WhatsApp_Image_20241128_at_14215_PM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3405",
  "name":
"externallmg_1732784825665_WhatsApp_Image_20241128_at_14215_PM.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825665_WhatsApp_Image_20241128_at_14215_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3406",
  "name":
"externallmg_1732784825684_WhatsApp_Image_20241128_at_14216_PM.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825684_WhatsApp_Image_20241128_at_14216_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3407",
  "name":
"externallmg_1732784825689_WhatsApp_Image_20241128_at_14217_PM_1.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825689_WhatsApp_Image_20241128_at_14217_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3408",
  "name":
"externallmg_1732784825712_WhatsApp_Image_20241128_at_14217_PM.jpeg",
  "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825712_WhatsApp_Image_20241128_at_14217_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674832b9e077c54e532b3409",
  "name":
"externallmg_1732784825717_WhatsApp_Image_20241128_at_15403_PM.jpeg",
```

```
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825717_WhatsApp_Image_20241128_at_15403_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674832b9e077c54e532b340a",
    "name":
"externallmg_1732784825746_WhatsApp_Image_20241128_at_15405_PM_1.jpeg",
    "path": "cases/6748056f520246c6c06301b6/
externallmg_1732784825746_WhatsApp_Image_20241128_at_15405_PM_1.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "cosmos - Dinesh.xlsx",
    "filename": "1732861009848_cosmos__Dinesh.xlsx",
    "path": "cases/6748056f520246c6c06301b6/
processingDocuments/1732861009848_cosmos__Dinesh.xlsx",
    "size": "16835",
    "createdAt": "Fri Nov 29 2024 06:16:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "reference report.pdf",
    "filename": "1732861009849_reference_report.pdf",
    "path": "cases/6748056f520246c6c06301b6/
processingDocuments/1732861009849_reference_report.pdf",
    "size": "1177054",
    "createdAt": "Fri Nov 29 2024 06:16:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - Dinesh.xlsx",
    "filename": "1732861009980_Summary__Dinesh.xlsx",
    "path": "cases/6748056f520246c6c06301b6/
processingDocuments/1732861009980_Summary__Dinesh.xlsx",
    "size": "4295986",
    "createdAt": "Fri Nov 29 2024 06:16:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "656aa949cebbe1714411d21b",
      "role": "FRONTDESK",
      "firstName": "Priyanka",
      "lastName": "Pawar",
      "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "6748327be077c54e532b3259",
    "note": "Visit Photo Not Attach (Task Reopen)",
    "taskId": "6748087c520246c6c0630a48",
    "createdAt": "2024-11-28T09:06:03.743Z"
  },
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67495c5fd1078a4ea7fc7f67",
    "note": "Value shared 1 cr.",
    "taskId": "6748087b520246c6c0630a44",
    "createdAt": "2024-11-29T06:17:03.799Z"
  }
],
"createdAt": "2024-11-28T05:53:51.920Z",
"updatedAt": "2024-11-29T10:24:49.780Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Commercial Shop No. 8, Ground Floor, Wing - B, Shree Srushti Co.-Op.
Hsg. Soc. Ltd., CTS No. 201/8 & 202/8, Comrade Rajaram Vishnu Rawool Marg,
```

Village - Kolbad & Panchpakhadi, Taluka - Thane, District - Thane, Thane (West), PIN Code - 400 601, State - Maharashtra, India",

```
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Dinesh Lakhiram Agrawal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9819147770",
"briefDescOfProperty": "Shop",
"carpetTotal": "226.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2024-11-28",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Transfer",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 265.00",
"flatRate": "38300",
"landOtherRate": "35800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": true,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": ""
```



```

    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Nov 29 2024 07:01:49 GMT+0000 (Coordinated Universal Time)",
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"finalBuiltupArea": "248.60",
"finalCarpetArea": "226.00",
"finalSalableArea": "273.46",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": ""
}

```

Name	Length	Width	Total
Composition :			
Shop	226'0"	1'0"	226.00
Other Composition :			