MSME Reg No: UDYAM-MH-18-0083617 An ISO 9001 : 2015 Certified Company CIN: U74120MH2010PTC207869



Vastukala Consultants (I) Pvt. Ltd.

Valuation Report of the Immovable Property



Details of the property under consideration: Name of Owner: Shri. Sainath S/o Pandhari Pujarwad.

M. H. No. 1065/28, Plot No.28, S.No.187/2, Behind Hanuman Temple, Sahara Colony, Mauje Ratnali, Taluka. Dharmabad, Dist. Nanded, State – Maharashtra, Country - India.

Longitude Latitude: 18°53'12.6"N 77°50'26.6"E

Valuation Done for: Axis Bank Branch Aurangabad.



 Chhatrapati Sambhaji Nagar (Aurangabad) : Plot No. 106, N-3, CIDCO,
 Ref

 Aurangabad - 431 005, M.S, INDIA
 Bi

 Email: aurangabad@vastukala.co.in | Tel: +91 240 2485151 +91 91672 04062
 Bi

 Our Pan India Presence at :
 Po

 Nanded
 P Thane
 P Ahmedabad
 P Delhi NCR
 Image: Second Secon

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai**: 400072, (M.S), India

- 🖀 +91 2247495919 对 mumbai@vastukala.co.in
- www.vastukala.co.in



MSME Reg No: UDYAM-MH-18-0083617 An ISO 9001 : 2015 Certified Company CIN: U74120MH2010PTC207869

Vastukala Consultants (I) Pvt. Ltd.

Valuation Report Prepared For: Axis Bank / Aurangabad Branch / Shri. Sainath S/o Pandhari Pujarwad (12698/ 2309339). Page 2 of 11

www.vastukala.co.in

Vastu/Nanded/10/2024/12698/ 2309339 04/3-37-SPPYBS Date: 04.12.2024

Recomme	ended Valuation	of	the Property in Rs				
Recommended rate of the plot per Sqm	Rs.10,000.00	PI	ot Area in Sqm	117.00	11,70,000.00		
Estimated Cost of Construction			uilt up Area in Sqm		28,52,226.00		
		G	round Floor	70.20			
		Fi	rst Floor	70.20			
Estimated Cost of Amenities			ore well		1,00,000.00		
Total Value of Land & Building After 100 % Completion				41,22,226.00			
Stage of Construction			Ground Floor Work is in Progress.				
% Work completed			52 %				
% Disbursement Recommended			55 %				
Value of the property as on the date (52 % Work			27,53,158.00				
Completed) 11,70,000.00 + 52 % (28,52,226.00 +1,00,000.00)							
Distressed value of property (52 % work as on date)			21,43,558.00				
Total Amount of Estimate submitted by client				1			
Total Estimated cost of renovation as per prevailing market rate			N.A.	1			

Remarks:

- Plot & Built-Up Area Considered as per Approved Building Plan. •
- 52 % Work Completed. •
- There is deviation in actual construction & Municipal Sanctioned Plan. Refer Point No 10.13, Page • No. 5 for construction deviation.
- Estimate is as per Municipal Sanction Plan. •

For, Vastukala Consultants (I) Pvt. Ltd.



Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 IBBI Reg. No. IBBI/RV/07/2019/11744



Chhatrapati Sambhaji Nagar (Aurangabad) : Plot No. 106, N-3, CIDCO, Aurangabad - 431 005, M.S, INDIA Email: aurangabad@vastukala.co.in | Tel: +91 240 2485151 +91 91672 04062 Our Pan India Presence at : Nanded ♀Ahmedabad ♀Delhi NCR **Q** Thane OMUMBAI **Q** Nashik Rajkot 💡 Raipur 💡 Aurangabad **Q** Pune 💡 Jaipur ♀Indore

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India

+91 2247495919

- mumbai@vastukala.co.in
- www.vastukala.co.in

VALUATION REPORT (IN RESPECT OF RESIDENTIAL LAND AND BUILDING)

1.	CBB/CCMC/CCSU	As	signment No		-				
			roposal No.		-				
2.	Name of Owner & Addr	ress: M	r. Sainath S/o Pa	andhari Pu	ujarwad.				
		R/	o. 1179, Gokul	Nagar, P	rabhag 3.6, Tal. Dharmabad, Dist.				
		Na	Nanded, State – Maharashtra, Country - India						
			ob. No. +91 9011						
	Name of Borrower & Ac		r. Sainath S/o P		•				
				•	rabhag 3.6, Tal. Dharmabad, Dist.				
		Na	anded, State – M	aharashtra	a, Country – India				
			ah Na 101 001	1107005	\frown				
3.	Name of the Bank Offic		ob. No. +91 901	1137065	(TM)				
5.			re. Padhika Sair	ath Duiar	wad				
4.	Name of the Representative & Mobile No. Mrs. Radhika Sainath Pujarwad. Details of the Property Being Valued								
4.1	•			1 Storied Residential Building.					
4.1	Location of Property	•			5.28, S.No.187/2, Behind Hanuman				
4.2	Location of Property				auje Ratnali, Tal. Dharmabad, Dist.				
			Nanded. State – Maharashtra, Country - India.						
	(Rural / Semi Urban / U		Urban.						
	Documents Provided:								
	Photo Copy of Sale Deed No. 829/2015, dated 22.07.2015, Executed at Joint Sub Registrar, Dharmabad.								
	2 Photo Copy of 31.03.2015.	Dharmabad Nagar parish	arishad, Dharmabad Tax Receipt No 062, Book No.059, dated						
	3 Photo Copy of	7/12 Extract PU-ID:3639	7816034, dated	12.08.2024					
	4 Photo Copy of	N.A. Order No. २०१०/मध	০/मशाका -२/जमा/ एनएपी/टे -१/सीआर-१ १ २, dated 16.07.2012 by I.06.2011by Assistant Director Town Planning, Nanded.						
	District Officer,	Nanded.							
	5 Photo Copy of	N.A Layout dated.04.06.							
		Construction Permission ed 13.08.2024 Chief Offic			//B/2024/APL/00426, Building Permit Council.				
					/B/2024/APL/00426, Building Permit				
		ed 13.08.2024 Chief Offic							
4.4	Plot No / Survey No. /	S.No.187/2.	Road		m. wide Road towards West				
	Gut No. / Khasra No:								
4.5	Colony / Nagar / Sector	Sahara Colony	Locality Landmark	/ Behind	d Hanuman Temple, Sahara Colony.				
4.6	Village/Town/City	Mauje Ratnali.	District:	Nande	d				
4.7	State	Maharashtra	Pin code:	431 809					
4.8	Distance from Area Off	ice	@ 76.8 Km from Nanded Main Branch						
5.			Type of Property						
		Commercial / Industrial)		Residenti	al				
	Level of land with topog			Leveled					
		inicipal / Corporation Lim	Limit Corporation Limit						
	Any construction obser	ved on plot		Yes.					



Since 1989



An ISO 9001 : 2015 Certified Company

	(B) Residential Row House / Fla	Property: (Independe	Independent House construction work in progress.					
		like school, hospital, r	narket (etc (Available	All available nearby.			
	within the radius of Km./ Not Available)							
		I / Industrial Property:	No.					
	a Mall / Gowdow							
6.		Ac	cessibi	lity / Boundarie	es / Others			
6.1	Availability of lo Personal Transp	ocal transport (Metro , ort)	/ Local	Train / Bus /	Local Transport, Bus Stand,	Railway Station.		
6.2	Distance from Nanded Railway station @ 76.8 km.				Bus stop/ Taxi/ Auto Stand @ 1.00 Km			
6.3	Does the approach road to the Property Building is independent and accessible			es.	Will it be able to accommoda a fire extinguisher	ate No.		
6.4	Does the property fall under land locked No.				Does the property falls in a No. community dominated area			
6.5	Cornered / Intern		01		Intermittent			
6.6	Boundaries		er Site		As Per Docum			
	NorthPlot No.27.SouthPlot No.29.				Plot No.27.			
	South East				Plot No.29. Plot No.25.			
		East Plot No.25. West 12.00 m Wide Road.			12.00 m Wide Road.			
6.7		(Posh / Higher Middle			Middle Class	1000.		
0.1	Lower Middle Class / Poor)							
6.8	Quality of Infrastructure in the vicinity (Exce			llent / Good /	Average.			
0.0	Average / Poor)				, workiger			
6.9	Ownership Status of the Property (Free Hold / Reg. Lease				Freehold.			
0.0	Govt. Authority)							
6.10	,	ge of property Re	esidentia	al	Actual usage of property F	Residential		
	(Industrial /				(Industrial / Commercial /			
	Residential / Mix				Residential / Mix)			
6.11		nants in regards to Land	d Use. (it	f anv)	Residential.			
6.12		e (Load Bearing / RCC	•		RCC Framed Structure.			
6.13	Number of floors				Plinth level work in progress.			
		As per S		ed Plan	Proposed Ground Floor + 1 st Floor.			
6.14	Occupancy Deta	ills (Self-Occupied / Rei			Work in progress.			
7.	If the property i			,				
7.1	Name of tenant		N.A.	Number of yea	ars in tenancy	N. A.		
7.2		esistance for valuation:	No.	If yes, from the	N.A.			
7.3	•	ave basic amenities	Yes	Development				
7.0	bood property in		100					
8.	If the property i	s Leasehold		· · · · · ·				
8.1	Name of Lesser		N.A.	Nature of Leas	se:	N.A.		
8.2	Total Period of L		N.A.		e current occupants:	N.A.		
8.3		Does property have basic amenities Yes. Development			I			
			ed / Developing / Developed					



Since 1989



An ISO 9001 : 2015 Certified Company

10.02Plot Area As per Documents110.03Plot Area As per Sanctioned Plan110.04Demarcation at Site1	, Dharmabad				
9.2 Layout Approval Number: Permit No. 757, File No. B/5/17/10-11 Date of Approval 13.12.2011 Expiry Date N.A. 9.3 Building Plan Approval Number: Permit No: CCNDM/B/2024/APL/00426, Bu No.279476, dated 13.08.2024 Chief Officer Municipal Council. Date of Approval 13.08.2024 Expiry Date As per UDCPR valid till construction completed till construction completed tillow 10.01 Plot Area Area 10.02 Plot Area As per Documents 1 10.03 Plot Area As per Sanctioned Plan 1 10.04 Demarcation at Site 1	, Dharmabad				
Date of Approval 13.12.2011 Expiry Date N.A. 9.3 Building Plan Approval Number: Permit No: CCNDM/B/2024/APL/00426, Bu No.279476, dated 13.08.2024 Chief Officer Municipal Council. Date of Approval 13.08.2024 Expiry Date As per UDCPR valid till construction completed 10. Plot Area 10.01 Plot Area 10.02 Plot Area As per Documents 10.03 Plot Area As per Sanctioned Plan 10.04 Demarcation at Site	, Dharmabad				
Expiry Date N.A. 9.3 Building Plan Approval Number: Permit No: CCNDM/B/2024/APL/00426, Bu No.279476, dated 13.08.2024 Chief Officer Municipal Council. Date of Approval 13.08.2024 Expiry Date As per UDCPR valid till construction completed 10. Plot Area 10.02 Plot Area As per Documents 1 10.03 Plot Area As per Sanctioned Plan 1 10.04 Demarcation at Site 1	, Dharmabad				
9.3 Building Plan Approval Number: Permit No: CCNDM/B/2024/APL/00426, Bu No.279476, dated 13.08.2024 Chief Officer Municipal Council. Date of Approval 13.08.2024 Expiry Date As per UDCPR valid till construction completer and till construction completer and till construction completer and till construction completer and the second s	, Dharmabad				
Municipal Council. Date of Approval 13.08.2024 Expiry Date As per UDCPR valid till construction completed in the second secon					
Date of Approval 13.08.2024 Expiry Date As per UDCPR valid till construction completed till constru	etion.				
Expiry Date As per UDCPR valid till construction complete 10. Plot Area 10.01 Plot Area 10.02 Plot Area As per Documents 1 10.03 Plot Area As per Sanctioned Plan 1 10.04 Demarcation at Site 1	etion.				
10.01Plot AreaArea10.02Plot Area As per Documents110.03Plot Area As per Sanctioned Plan110.04Demarcation at Site1					
10.02Plot Area As per Documents110.03Plot Area As per Sanctioned Plan110.04Demarcation at Site1					
10.03 Plot Area As per Sanctioned Plan 1 10.04 Demarcation at Site 1	in Sqm.				
10.04 Demarcation at Site	17.00				
	17.00				
	Yes.				
10.05 Plot Area Considered for Valuation 1	17.00				
10.06 Construction Area Details					
Sr. No. Floor Sanctioned Plan Built up Are	ea in Sqm.				
1.Ground Floor70.20					
2.First Floor70.20					
Total 140.40					
10.07 • Sanctioned Plan Built up Area Considered for Valuation: 140.40 Sqm.					
10.08 Floor wise break up as follows Current Usage					
Floor Actual Built-up Area in Sqm. (Storage / Parking / Commercial	/Residential)				
Ground Floor 70.20 Residential					
First Floor 70.20					
10.9 Amenities Details (if any): Borewell etc.					
10.10 Floor Space Index permissible. Basic FSI 1.10					
Premium FSI 0.30					
TDR 0.60					
Ancillary FSI 60%					
Maximum building					
potential on Plot 2.00					
including in-situ FSI					
10.11 FSI Utilized 1.20					
10.12 Whether the construction is as per approved building plan and / or local building bye laws: • The Construction work is in progress 1 st Floor Slab.					
	• The Construction is not as per the approved building permission plan.				
To assess the Fair Market Value th Permit No: CCNDM/P/2024/APL/00					
Permit No: CCNDM/B/2024/APL/00-	-				
Permit No: CCNDM/B/2024/APL/00 No.279476, dated 13.08.2024 Chief	Plan Built up Area				



Since 1989



An ISO 9001 : 2015 Certified Company

					Ground Floor		70.20	116.64			
					First Floor		70.20	Nil			
					Total Extra Co	onstruction	140.40	116.64			
10.14	Perce	entage of Extra Co	nstructio	on	66.15%						
10.15	Whether the extra construction is				Non-Compour	Non-Compoundable.					
	Compoundable OR Non-Compoundable?										
10.16	6 Quality of construction				Good.						
10.17	Main	tenance of the Pro	perty		Work in Progr	ess.					
10.18		lition of Building			Work in Progr		ars after completion				
10.19	Curre	ent Life of th	e 0 Y	ears.	Projected Futu						
	structure				he						
40.00	<u>. </u>				Structure			<u></u>			
10.20		Revenue / Taxe			Municipal Tax		the Tax Receipt No.				
	Paid	up to (for Land)	ava	ilable	Paid up to (1	or dated	31.03.2015. Rs.74.0	u paid.			
11.	Data	ils of Valuation:			Building)		(TM)				
T1.	S. L	Particulars of	Plinth	Age of	Estimated Cost	Replace	Net Value after	Remarks			
	0. L	Item	/ Built	Building	of	ment	Completion	ixelliarks			
			up	Danang	Construction	Cost	Compion				
			Area								
			In Sq.								
			<u>M.</u>		00.045.00						
	1.	Ground Floor	70.20	0	20,315.00	Nil	14,26,113.00	About 52 %			
	2.	First Floor	70.20	0	20,315.00	Nil	14,26,113.00	Completed			
40	Total (1+2+3) 28,52,226.00										
12.		ils of Amenities	<u> </u>					4 00 000 00			
	1	Bore well with F	ump					1,00,000.00			
							Total	1,00,000.00			
13.		D (1 1			uideline value (A						
4		Particulars		Area in Sq. M.		Rate in R	S.	Value in Rs.			
1	Lanc			117.00		960.00		1,12,320.00			
2	Build	aing		TO				28,52,226.00			
14.		<u> </u>	Eairl	TO		a (After C	(manlation)	29,64,546.00			
14.		Particulars	Fairi	Area in Sq.	Land & Building (After Completion) Rate in Rs. Value in F						
		Failiculais		Miea in Sy. M.		.5.	value III KS.				
1	Lanc			117.00		0	11,70,000.00				
2	Build			117.00		10,000.0		28,52,226.00			
3		nities			-						
5	Aille			TO		1,00,000.00					
45				TO		0		41,22,226.00			
15.					Property (After			Total			
	Cau	romont Cuideline	volue	Land		Building Amenities					
		ernment Guideline	value	1,12,320.00			1 00 000 00	29,64,546.00			
	Market Value 11,70,000.00 Realizable Value			11,70,000.00	28,52,226.	VU	1,00,000.00	<u>41,22,226.00</u> 37,10,003.00			
							32,97,780.00				
	Distressed/Forced Sale Value							52,51,100.00			
	Insur	able Value									
					Remarks						
		 Subject Prope 	rtv unde	r valuation is si	tuated in under d	eveloped la	vout				
•	1 '		ity unde	· valuation 15 SI		evelopeu la	yout.				



Since 1989



An ISO 9001 : 2015 Certified Company

•	To assess the Fair Market Value by Land and Building method, the land rate of Rs.10,000.00 per Sqm is considered which is fair & reasonable.
•	The cost of construction after completion is arrived as per the proposed estimates.
•	The value of construction may deviate due to change in construction specification.

Undertaking:

- I have / our / representative Md. Shareq Salim Md. Jilani Pasha (Technical Assistant) has inspected the subject property on 29.11.2024 along with Owner's Representative Mrs. Radhika Sainath Pujarwad identified the same based on the documents provided.
- 2. I/We have no direct or Indirect interest in the property being valued.
- 3. The information furnished above is true and correct to my/our knowledge
- 4. I/ we have not been dismissed or removed from govt. Service or convicted of an offence connected with any proceedings of income tax act, wealth tax act or gift tax act or have been blacklisted by any bank/ financial institution/ govt. Department/ public sector enterprise/ body corporate etc.
- 5. This valuation is prepared without any prejudice or bias to any person or institution.
- 6. The value of land is taken into account by making due enquires in the locality and ascertaining the sales value of the properties in the locality.
- 7. Any additions/alterations made to the property after the date of valuations shall not fall under the scope of this report.

For, Vastukala Consultants (I) Pvt. Ltd.

Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 IBBI Reg. No. IBBI/RV/07/2019/11744

Vastukala Consultants (

Date: 04.12.2024

Attachments					
Photographs of the Property from inside & outside	:	Attached			
Location sketch for the property:	:	Attached.			
Geo Tagging	:	Attached.			
Topography	:	Levelled Land.			
Government Value Document	:	Attached.			

An ISO 9001 : 2015 Certified Company



Since 1989



Actual Site Photographs






Since 1989



An ISO 9001 : 2015 Certified Company



Route Map of the Property

Longitude Latitude: 18°53'12.6"N 77°50'26.6"E

Vastukala Consultants (I) Pvt. Ltd.

Note:

• Red Pointer shows Approx. Property Location.

Since 1989

• Blue line shows Route from Dharmabad Railway Station @ 1.3 Km.





An ISO 9001 : 2015 Certified Company

Ready Reckoner Rate

4	Department of Registration and Stamp Government of Maharashtra Annual States महाराष्ट्र शासन								
Annual Statement of Rates Ver. 2.0 (बाजारमूल्य दर पत्रक आवृत्ती 2.0)									
Home Valuation Guidelines User Manual									
Year	2024-2025			Language	Enalish				
	Selected District	Nanded							
	Select Taluka								
	Select Village	Mauje : Dharmabad (K	Cvarga Nagarparisł						
	Search By	Survey No.	SubZones						
			खुली f	नेवासी 🗸		* > 0	एकक		
Select	उपविष	भाग	9	अफ़ीस बनिका	दुकाने व	श्रीद्यांगिक	(Rs./)		
<u>SurveyNo</u>	2.21-सिनेमा ते चावडी गल्लीकडे जाणा- (रत्नाव		ोळकत 1950 1	16350 19000	22000	0	चौ. मीटर		
<u>SurveyNo</u>	2.22-सिनेमा ते बसस्टँड कडे जाणाऱ्या	कत 2000 1	16800 19320	22000	0	चौ. मीटर			
<u>SurveyNo</u>	2.23-जिनिंग व प्रसिंग फॅक्टरी पुर्व	1350 1	16800 19320	22000	0	चौ. मीटर			
<u>SurveyNo</u>	2.24-सर्व मिळकती प्र	960 1	18090 20800	22610	0	चौ. मीटर			
<u>SurveyNo</u>	2.25 - रेस्ट हाउस ते राईस मिल पर्यंत रस मि. (मौ.	प्र.चौ. 1220 1	17000 19550	22000	0	चौ. मीटर			
		12345678	<u>9 10</u>						



ASSUMPTIONS, CAVEATS, LIMITATION AND DISCLAIMERS

- 1. We assume no responsibility for matters of legal nature affecting the property appraised or the title thereto, nor do we render our opinion as to the title, which is assumed to be good and marketable.
- 2. The property is valued as though under responsible ownership.
- 3. It is assumed that the property is free of liens and encumbrances.
- 4. It is assumed that there are no hidden or unapparent conditions of the subsoil or structure that would render it more or less valuable. No responsibility is assumed for such conditions or for engineering that might be required to discover such factors.
- 5. The rates for valuation of the property are in accordance with the Govt. approved rates and prevailing market rates

For, Vastukala Consultants (I) Pvt. Ltd.

Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 IBBI Reg. No. IBBI/RV/07/2019/11744

Date: 04.12.2024 Place: Nanded.





