

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fe"
    },
    "firstName": "Rakesh",
    "type": "CREDITOFFICER",
    "_id": "6685100602a43d10c09e3df4",
    "email": "sbi.01154@sbi.co.in",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "8828382556"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6451645",
    "discussWithPerson": "Rakesh",
    "expectedFees": 3225.8225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fe",
  "branchCode": "000072",
  "type": "BRANCH",
  "name": "Shivsagar Estate Branch Worli (South) ",
  "email": "sbi.01154@sbi.co.in",
  "mobileNo": "24921772 / 24980675 ",
  "alternateMobileNo": "24937708 / 24968939",
  "address": "Devchand House, Ground Floor, Dr. Annie Besant Road, Worli, Mumbai -
400 018, State - Maharashtra, Country - India\r\n",
  "ledgerName": "STATE BANK OF INDIA - WORLI SHIVSAGAR",
  "fax": "24973911",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.079704",
  "longitude": "73.154723"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.154723,
    19.079704
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mahad",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Mahad",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Residential Land and Plot No. A-13, Village - Kamble, Mahad",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```



```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
```

```
"documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67513485c5a60c3e016d77b8",
"ownerName": "shree Hari chemicals exports Ltd ",
"ownerPhoneNo": "0000000000",
"appAddress": "Residential Land and Building No. Ground Floor, Plot No. A-13, Village
- Kamble, Mahad, Taluka - Mahad, District - Mahad",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "value": "60ae1297aa6d152c1801b459",
  "label": "Lease Agreement"
},
"inputs": {
  "documentDate": "06/12/2024",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "MIDC",
  "to": {
    "value": "Lessee",
    "label": "Lessee"
  },
  "Lessee": "Shree Hari Chemicals"
},
"isHardCopy": false,
"displayStatus": false,
"id": "142879",
"path": "cases/67513485c5a60c3e016d77b8/
document_1733374992603_1733374990876_Plot_no_A__13.pdf",
"fileName": "document_1733374992603_1733374990876_Plot_no_A__13.pdf"
},
{
  "documentType": {
    "value": "60ae125daa6d152c1801b350",
    "label": "Certificate of Building Completion Year"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733460255007_BCC.pdf",
  "path": "cases/67513485c5a60c3e016d77b8/document_1733460255007_BCC.pdf",
  "id": "125265",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Fri Dec 06 2024 04:46:14 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
}
```

```
    },
    "Document_No": "00000"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733460285571_Light_Bill.pdf",
  "path": "cases/67513485c5a60c3e016d77b8/
document_1733460285571_Light_Bill.pdf",
  "id": "631525",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Fri Dec 06 2024 04:46:14 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124daa6d152c1801b306",
    "label": "Property Tax"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "0000"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733460307685_P_T.pdf",
  "path": "cases/67513485c5a60c3e016d77b8/document_1733460307685_P_T.pdf",
  "id": "269099",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Fri Dec 06 2024 04:46:14 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae126aaa6d152c1801b38c",
    "label": "Water bill"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "000"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
    "fileName": "document_1733460346285_Water_Bill.pdf",
    "path": "cases/67513485c5a60c3e016d77b8/
document_1733460346285_Water_Bill.pdf",
    "id": "677757",
    "uploadedBy": "65dee3f79a876858ab30487f",
    "createdAt": "Fri Dec 06 2024 04:46:14 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b308",
      "label": "Building Plan"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "000000"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1733460374432_124242.pdf",
    "path": "cases/67513485c5a60c3e016d77b8/
document_1733460374432_124242.pdf",
    "id": "961805",
    "uploadedBy": "65dee3f79a876858ab30487f",
    "createdAt": "Fri Dec 06 2024 04:46:14 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "012847",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "893199",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 05 2024 05:05:09 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "shree Hari chemicals exports Ltd ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "387230"
```

```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a750b",
    "name": "externalImg_1733460004758_IMG20241206WA0273.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460004758_IMG20241206WA0273.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a750c",
    "name": "externalImg_1733460004773_IMG20241206WA0274.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460004773_IMG20241206WA0274.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a750d",
    "name": "externalImg_1733460004777_IMG20241206WA0275.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460004777_IMG20241206WA0275.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a750e",
    "name": "externalImg_1733460004805_IMG20241206WA0276.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460004805_IMG20241206WA0276.jpg",
    "orientation": "landscape"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a750f",
    "name": "externalimg_1733460004809_IMG20241206WA0277.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460004809_IMG20241206WA0277.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a7510",
    "name": "externalimg_1733460004843_IMG20241206WA0278.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460004843_IMG20241206WA0278.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a7511",
    "name": "externalimg_1733460004879_IMG20241206WA0279.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460004879_IMG20241206WA0279.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a7512",
    "name": "externalimg_1733460004884_IMG20241206WA0280.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460004884_IMG20241206WA0280.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a7513",
    "name": "externalimg_1733460004913_IMG20241206WA0281.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460004913_IMG20241206WA0281.jpg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67528025cfae933db22a7514",
  "name": "externallmg_1733460004919_IMG20241206WA0282.jpg",
  "path": "cases/67513485c5a60c3e016d77b8/
externallmg_1733460004919_IMG20241206WA0282.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67528025cfae933db22a7515",
  "name": "externallmg_1733460004945_IMG20241206WA0283.jpg",
  "path": "cases/67513485c5a60c3e016d77b8/
externallmg_1733460004945_IMG20241206WA0283.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67528025cfae933db22a7516",
  "name": "externallmg_1733460004949_IMG20241206WA0284.jpg",
  "path": "cases/67513485c5a60c3e016d77b8/
externallmg_1733460004949_IMG20241206WA0284.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67528025cfae933db22a7517",
  "name": "externallmg_1733460004978_IMG20241206WA0285.jpg",
  "path": "cases/67513485c5a60c3e016d77b8/
externallmg_1733460004978_IMG20241206WA0285.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67528025cfae933db22a7518",
  "name": "externallmg_1733460004997_IMG20241206WA0286.jpg",
  "path": "cases/67513485c5a60c3e016d77b8/
externallmg_1733460004997_IMG20241206WA0286.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a7519",
    "name": "externalImg_1733460005000_IMG20241206WA0287.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460005000_IMG20241206WA0287.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528025cfae933db22a751a",
    "name": "externalImg_1733460005022_IMG20241206WA0288.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460005022_IMG20241206WA0288.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528031c5a60c3e016e25a9",
    "name": "externalImg_1733460017746_IMG20241206WA0289.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460017746_IMG20241206WA0289.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528031c5a60c3e016e25aa",
    "name": "externalImg_1733460017750_IMG20241206WA0290.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460017750_IMG20241206WA0290.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528031c5a60c3e016e25ab",
    "name": "externalImg_1733460017756_IMG20241206WA0291.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalImg_1733460017756_IMG20241206WA0291.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "67528031c5a60c3e016e25ac",
    "name": "externalimg_1733460017776_IMG20241206WA0292.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460017776_IMG20241206WA0292.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528031c5a60c3e016e25ad",
    "name": "externalimg_1733460017780_IMG20241206WA0293.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460017780_IMG20241206WA0293.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528031c5a60c3e016e25ae",
    "name": "externalimg_1733460017812_IMG20241206WA0295.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460017812_IMG20241206WA0295.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528031c5a60c3e016e25af",
    "name": "externalimg_1733460017828_IMG20241206WA0296.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460017828_IMG20241206WA0296.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67528031c5a60c3e016e25b0",
    "name": "externalimg_1733460017847_IMG20241206WA0300.jpg",
    "path": "cases/67513485c5a60c3e016d77b8/
externalimg_1733460017847_IMG20241206WA0300.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
```

```

"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-05T05:05:09.957Z",
"updatedAt": "2024-12-06T04:46:14.544Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Land and Building No. Ground Floor, Residential Land and
Plot No. A-13, Village - Kamble, Mahad, Taluka - Mahad, Mahad",
"updatedBy": "65dee3f79a876858ab30487f",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "shree Hari chemicals exports Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			