

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae90ee191f7b344b005666"
    },
    "firstName": "Guruprasad",
    "type": "CREDITOFFICER",
    "_id": "668e1fb802fa372b423a007c",
    "email": "guruprasad.nadkarni@cosmosbank.in",
    "lastName": "Nadkarni",
    "mobileNo": "",
    "workMobileNo": "9869261322"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Guruprasad",
    "expectedFees": 3000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae90ee191f7b344b005666",
  "name": "DAHISAR (EAST) Glorias BRANCH",
  "branchCode": "",
  "mobileNo": "022-28975314",
  "alternateMobileNo": "",
  "email": "guruprasad.nadkarni@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No. 1/2, Gloris Apartment, Hari Shankar Joshi Road, \nDahisar
(East), Mumbai - 400 068"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "66850df5d9f18310ed2e5d98",
"role": "SITEENGINEER",
"firstName": "Krishna",
"email": "krishnagawade9@gmail.com",
"lastName": "Gawde",
"mobileNo": "9821646373",
"designation": "Site Engg",
"shortName": "Krishna",
"workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
```

```
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.222589",
  "longitude": "72.844974"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.844974,
    19.222589
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-06",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Borivali",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "10",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gayatri SRA Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Umeda Ashram Road, Opp. Rajda School, Shimpoli Road No. 1",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "749, 749/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1001",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "PIN - 400 092",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
```

```
"label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Umeda Ashram Road",
  "west": "Sharda CHSL ",
  "south": "Narmada Sagar Apartment ",
  "east": "Shimpoli Cross Road No. 1"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  }
}
```

```
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto",
      "status": true
    },
    "privateCars": {
      "title": "Private Cars",
      "status": true
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is received, we assumed that
the construction is as per Sanction Plan.",
  "approvePlanVerified": "N.A. ",
  "empanelledOfApprovePlan": "N.A. ",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "classOfSanitary": {
    "value": "ordinary",
    "label": "Ordinary"
  },
  "compoundWall": "All external walls are 9\" thick and partition walls are 6\" thick"
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "19.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "526.5",
  "depreciatedCostOfConstruction": "17973.50",
  "depreciatedBuildingRate": "2173.5"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "142570",
```

```
"landRate": "63740",
"igrImage": "cases/675159a8c5a60c3e016da9d4/igr_1733563762054_Image.png",
"squareMeterGuideLineRate": "149699.00",
"squareFeetGuideLineRate": "13907.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "87",
  "rate": "12869.00",
  "squareFeetGuideLineRate": "12869.00",
  "squareMeterGuideLineRate": "138524.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": "12,000.00 (Expected rental income per month)",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2011",
"fullDate": "1/1/2011"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
}
```

```
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
```



```
"label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "47",
"ageOfBuilding": "13",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "10",
"flatFloorNo": "10",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "322.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/675159a8c5a60c3e016da9d4/
routeMap_1733575535521_Image.png",
    "routeLat": "19.224500",
    "routeLng": "72.852694",
    "stationName": "Borivali",
    "routeDistance": "850 M. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "06je24",
    "name": "06je24",
    "image": "cases/675159a8c5a60c3e016da9d4/
routeMap_1733572904453_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "872100.00",
    "depreciationPercentage": "19.5",
    "depreciatedCostOfConstruction": "170059.50",
    "totalFairMarketValue": "4806440.50"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4976500.00",
"finalValue": "4976500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "4154113.00",
  "selectedBuildUpValue": "322.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67544145cfae933db22bce27",
      "name": "externallmg_1733574980611_externallmg_1733552880227_WhatsApp_I
mage_20241207_at_114917_AM.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/externallmg_1733574980611_extern
allmg_1733552880227_WhatsApp_Image_20241207_at_114917_AM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6753eb0dcfae933db22b4fc1",
      "name":
"externallmg_1733552909339_WhatsApp_Image_20241207_at_114930_AM_2.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909339_WhatsApp_Image_20241207_at_114930_AM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6753eb0dcfae933db22b4fc2",
      "name":
"externallmg_1733552909362_WhatsApp_Image_20241207_at_114930_AM.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909362_WhatsApp_Image_20241207_at_114930_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6753eb0dcfae933db22b4fc5",
      "name":
"externallmg_1733552909395_WhatsApp_Image_20241207_at_114933_AM_1.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909395_WhatsApp_Image_20241207_at_114933_AM_1.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "6753eb0dcfae933db22b4fc4",
      "name":
"externallmg_1733552909390_WhatsApp_Image_20241207_at_114932_AM.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909390_WhatsApp_Image_20241207_at_114932_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6753eb0dcfae933db22b4fc9",
      "name":
"externallmg_1733552909444_WhatsApp_Image_20241207_at_114934_AM_2.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909444_WhatsApp_Image_20241207_at_114934_AM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6753eaf0c5a60c3e016f0c86",
      "name":
"externallmg_1733552880243_WhatsApp_Image_20241207_at_114918_AM_1.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880243_WhatsApp_Image_20241207_at_114918_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67543a27c5a60c3e016f85aa",
      "name": "externallmg_1733573158298_Picture2.jpg",
      "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733573158298_Picture2.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67544145cfae933db22bce27",
      "name": "externallmg_1733574980611_externallmg_1733552880227_WhatsApp_I
mage_20241207_at_114917_AM.jpeg",
      "path": "cases/675159a8c5a60c3e016da9d4/externallmg_1733574980611_extern
allmg_1733552880227_WhatsApp_Image_20241207_at_114917_AM.jpeg",
      "orientation": "portrait"
    }
  ],
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16915.00",
    "max": "22223.00"
  },
  "builtUpRateRange": {
    "min": "14096.00",
    "max": "18519.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "269.00",
"empanelmentNo": [
  "HO/Credit/87/2022-23"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
```

```
"invoiceIds": [],
"paymentIds": [],
"_id": "675159a8c5a60c3e016da9d4",
"ownerName": "Mr. Jaywant Bhupendra More ",
"ownerPhoneNo": "9930110498",
"appAddress": "FLAT NO 1001 10TH FLOOR GAYTRI SRA CHS LTD SHIMPOLI
ROAD NO 1 BORIVALI EAST MUMBAI 400092",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "17/10/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Soni Chandu Patel nee Soni Parshuram Taraviya ",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Jaywant Bhupendra More ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "16229 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "164029",
    "path": "cases/675159a8c5a60c3e016da9d4/
document_1733384604691_1733384602032_CamScanner_11062024_1824.pdf",
    "fileName":
"document_1733384604691_1733384602032_CamScanner_11062024_1824.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
```

```
"documentDate": "24/10/2011",
"nameOfApprovingAuthority": {
  "value": "Slum_Rehabilitation_Authority_(SRA)",
  "label": "Slum Rehabilitation Authority (SRA)"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "SRA / ENG / 2154 / RC / ML / AP"
},
"isHardCopy": false,
"displayStatus": true,
"id": "328797",
"path": "cases/675159a8c5a60c3e016da9d4/
document_1733567952188_446349.pdf",
"fileName": "document_1733567952188_446349.pdf"
}
],
"caseNumber": "012859",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "463936",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 05 2024 07:43:35 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Jaywant Bhupendra More ",
    "phone": "9930110498",
    "ownershipShare": "",
    "email": "",
    "id": "691091"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "509351",
"name": "Living Room",
"length": "13.17",
"length1": "13",
"length2": "2",
"width": "8.42",
"width1": "8",
"width2": "5",
"totalArea": "110.82",
"images": [],
"extraAreas": [],
"finalArea": "110.82"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.92",
  "length1": "7",
  "length2": "11",
  "width": "5.42",
  "width1": "5",
  "width2": "5",
  "totalArea": "42.88",
  "images": [],
  "extraAreas": [],
  "finalArea": "42.88"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "WC",
  "length": "4.75",
  "length1": "4",
  "length2": "9",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "14.25",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "14.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "26.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "12.83",
  "length1": "12",
  "length2": "10",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "84.49",
  "images": [],
  "extraAreas": [],
  "finalArea": "84.49"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
```

```
"value": "60ae1254aa6d152c1801b326"
},
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Carpet",
"squareMeterArea": "24.99",
"totalAreaDocument": "269",
"docBUILTUPPercentage": "20",
"docFinalBUILTUP": "322.80",
"docFinalBUILTUPSquareMeter": "29.99",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "197893"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "269.00",
      "squareMeterArea": "24.99",
      "expectedRate": "20446.10",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "322.80",
      "squareMeterArea": "29.99",
      "expectedRate": "17038.41",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "67541598befd7f3db9070220",
    "property": "Shiv Ganesh Sai SRA CHSL., Borivali West",
    "area": "269",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "Middle",
"source": "Nobroker.com",
"expectedPrice": "5500000",
"expectedRate": "20446.10",
"builtUpExpectedRate": "17038.41",
"image": "cases/675159a8c5a60c3e016da9d4/
indicator_1733563198035_Image.png",
"squareMeter": "24.99",
"id": "858187"
},
{
  "carpetArea": {
    "area": "270.00",
    "squareMeterArea": "25.08",
    "expectedRate": "22222.22",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "324.00",
    "squareMeterArea": "30.10",
    "expectedRate": "18518.52",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67541598befd7f3db9070221",
  "property": "Shimpoli, Borivali West",
  "area": "270",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "12",
  "source": "magic_bricks",
  "expectedPrice": "6000000",
  "expectedRate": "22222.22",
  "builtUpExpectedRate": "18518.52",
  "image": "cases/675159a8c5a60c3e016da9d4/
indicator_1733563317937_Image.png",
  "squareMeter": "25.08",
```



```
"id": "738551"
},
{
  "carpetArea": {
    "area": "348.00",
    "squareMeterArea": "32.33",
    "expectedRate": "19655.17",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "417.60",
    "squareMeterArea": "38.80",
    "expectedRate": "16379.31",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67541598befd7f3db9070222",
  "property": "Shimpoli Road, Borivali West",
  "area": "348",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "10",
  "source": "Index_no.2",
  "expectedPrice": "6840000",
  "expectedRate": "19655.17",
  "builtUpExpectedRate": "16379.31",
  "image": "cases/675159a8c5a60c3e016da9d4/
indicator_1733563534989_Image.png",
  "squareMeter": "32.33",
  "id": "849599"
},
{
  "carpetArea": {
    "area": "269.00",
    "squareMeterArea": "24.99",
    "expectedRate": "16914.50",
    "percentage": ""
  },
}
```

```
"builtUpArea": {
  "area": "322.80",
  "squareMeterArea": "29.99",
  "expectedRate": "14095.42",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "67541598befd7f3db9070223",
"property": "Gayatri SRA CHSL., Borivali West",
"area": "269",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "9",
"source": "Index_no.2",
"expectedPrice": "4550000",
"expectedRate": "16914.50",
"builtUpExpectedRate": "14095.42",
"image": "cases/675159a8c5a60c3e016da9d4/
indicator_1733563582048_Image.png",
"squareMeter": "24.99",
"id": "740971"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753ead7c5a60c3e016f0c3f",
  "name":
"externalmg_1733552855308_WhatsApp_Image_20241207_at_114809_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externalmg_1733552855308_WhatsApp_Image_20241207_at_114809_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c7d",
```

```
"name":
"externallmg_1733552880152_WhatsApp_Image_20241207_at_114911_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880152_WhatsApp_Image_20241207_at_114911_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c7e",
  "name":
"externallmg_1733552880156_WhatsApp_Image_20241207_at_114912_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880156_WhatsApp_Image_20241207_at_114912_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c7f",
  "name":
"externallmg_1733552880159_WhatsApp_Image_20241207_at_114913_AM_1.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880159_WhatsApp_Image_20241207_at_114913_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c80",
  "name":
"externallmg_1733552880179_WhatsApp_Image_20241207_at_114913_AM_2.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880179_WhatsApp_Image_20241207_at_114913_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c81",
  "name":
"externallmg_1733552880182_WhatsApp_Image_20241207_at_114913_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880182_WhatsApp_Image_20241207_at_114913_AM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c82",
  "name":
"externallmg_1733552880201_WhatsApp_Image_20241207_at_114914_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880201_WhatsApp_Image_20241207_at_114914_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c83",
  "name":
"externallmg_1733552880205_WhatsApp_Image_20241207_at_114915_AM_1.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880205_WhatsApp_Image_20241207_at_114915_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c84",
  "name":
"externallmg_1733552880223_WhatsApp_Image_20241207_at_114915_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880223_WhatsApp_Image_20241207_at_114915_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c85",
  "name":
"externallmg_1733552880227_WhatsApp_Image_20241207_at_114917_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880227_WhatsApp_Image_20241207_at_114917_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c86",
  "name":
"externallmg_1733552880243_WhatsApp_Image_20241207_at_114918_AM_1.jpeg",
```

```
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880243_WhatsApp_Image_20241207_at_114918_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eaf0c5a60c3e016f0c87",
    "name":
"externallmg_1733552880245_WhatsApp_Image_20241207_at_114918_AM_2.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880245_WhatsApp_Image_20241207_at_114918_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eaf0c5a60c3e016f0c88",
    "name":
"externallmg_1733552880264_WhatsApp_Image_20241207_at_114918_AM.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880264_WhatsApp_Image_20241207_at_114918_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eaf0c5a60c3e016f0c89",
    "name":
"externallmg_1733552880267_WhatsApp_Image_20241207_at_114919_AM.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880267_WhatsApp_Image_20241207_at_114919_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eaf0c5a60c3e016f0c8a",
    "name":
"externallmg_1733552880267_WhatsApp_Image_20241207_at_114920_AM.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880267_WhatsApp_Image_20241207_at_114920_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6753eaf0c5a60c3e016f0c8b",
  "name":
"externallmg_1733552880283_WhatsApp_Image_20241207_at_114921_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880283_WhatsApp_Image_20241207_at_114921_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c8c",
  "name":
"externallmg_1733552880294_WhatsApp_Image_20241207_at_114923_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880294_WhatsApp_Image_20241207_at_114923_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c8d",
  "name":
"externallmg_1733552880296_WhatsApp_Image_20241207_at_114924_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880296_WhatsApp_Image_20241207_at_114924_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eaf0c5a60c3e016f0c8e",
  "name":
"externallmg_1733552880309_WhatsApp_Image_20241207_at_114925_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552880309_WhatsApp_Image_20241207_at_114925_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fbf",
  "name":
"externallmg_1733552909328_WhatsApp_Image_20241207_at_114929_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909328_WhatsApp_Image_20241207_at_114929_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fc0",
    "name":
"externallmg_1733552909334_WhatsApp_Image_20241207_at_114930_AM_1.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909334_WhatsApp_Image_20241207_at_114930_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fc1",
    "name":
"externallmg_1733552909339_WhatsApp_Image_20241207_at_114930_AM_2.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909339_WhatsApp_Image_20241207_at_114930_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fc2",
    "name":
"externallmg_1733552909362_WhatsApp_Image_20241207_at_114930_AM.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909362_WhatsApp_Image_20241207_at_114930_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fc3",
    "name":
"externallmg_1733552909368_WhatsApp_Image_20241207_at_114931_AM.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909368_WhatsApp_Image_20241207_at_114931_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fc4",
```

```
    "name":
"externallmg_1733552909390_WhatsApp_Image_20241207_at_114932_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909390_WhatsApp_Image_20241207_at_114932_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fc5",
  "name":
"externallmg_1733552909395_WhatsApp_Image_20241207_at_114933_AM_1.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909395_WhatsApp_Image_20241207_at_114933_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fc6",
  "name":
"externallmg_1733552909416_WhatsApp_Image_20241207_at_114933_AM_2.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909416_WhatsApp_Image_20241207_at_114933_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fc7",
  "name":
"externallmg_1733552909420_WhatsApp_Image_20241207_at_114933_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909420_WhatsApp_Image_20241207_at_114933_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fc8",
  "name":
"externallmg_1733552909441_WhatsApp_Image_20241207_at_114934_AM_1.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909441_WhatsApp_Image_20241207_at_114934_AM_1.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fc9",
  "name":
"externallmg_1733552909444_WhatsApp_Image_20241207_at_114934_AM_2.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909444_WhatsApp_Image_20241207_at_114934_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fca",
  "name":
"externallmg_1733552909466_WhatsApp_Image_20241207_at_114934_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909466_WhatsApp_Image_20241207_at_114934_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fcb",
  "name":
"externallmg_1733552909470_WhatsApp_Image_20241207_at_114935_AM_1.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909470_WhatsApp_Image_20241207_at_114935_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fcc",
  "name":
"externallmg_1733552909494_WhatsApp_Image_20241207_at_114935_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909494_WhatsApp_Image_20241207_at_114935_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6753eb0dcfae933db22b4fcd",
  "name":
"externallmg_1733552909500_WhatsApp_Image_20241207_at_114936_AM.jpeg",
```

```
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909500_WhatsApp_Image_20241207_at_114936_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fce",
    "name":
"externallmg_1733552909523_WhatsApp_Image_20241207_at_114937_AM_1.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909523_WhatsApp_Image_20241207_at_114937_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fcf",
    "name":
"externallmg_1733552909527_WhatsApp_Image_20241207_at_114937_AM_2.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909527_WhatsApp_Image_20241207_at_114937_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fd0",
    "name":
"externallmg_1733552909546_WhatsApp_Image_20241207_at_114937_AM.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909546_WhatsApp_Image_20241207_at_114937_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6753eb0dcfae933db22b4fd1",
    "name":
"externallmg_1733552909549_WhatsApp_Image_20241207_at_114907_AM.jpeg",
    "path": "cases/675159a8c5a60c3e016da9d4/
externallmg_1733552909549_WhatsApp_Image_20241207_at_114907_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6753eb0dcfae933db22b4fd2",
  "name":
"externalImg_1733552909565_WhatsApp_Image_20241207_at_114910_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externalImg_1733552909565_WhatsApp_Image_20241207_at_114910_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67543a27c5a60c3e016f85aa",
  "name": "externalImg_1733573158298_Picture2.jpg",
  "path": "cases/675159a8c5a60c3e016da9d4/
externalImg_1733573158298_Picture2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67544145cfae933db22bce27",
  "name": "externalImg_1733574980611_externalImg_1733552880227_WhatsApp_I
mage_20241207_at_114917_AM.jpeg",
  "path": "cases/675159a8c5a60c3e016da9d4/externalImg_1733574980611_externalI
mg_1733552880227_WhatsApp_Image_20241207_at_114917_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr_21183.pdf",
    "filename": "1733563811175_igr_21183.pdf",
    "path": "cases/675159a8c5a60c3e016da9d4/
processingDocuments/1733563811175_igr_21183.pdf",
    "size": "162001",
    "createdAt": "Sat Dec 07 2024 09:30:11 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1725358587906_1718776194681_1716026508753_17153236343
39_1711606660630_1700891975573_1695465043548_1694516251783_16942415908
59_Calculation_1_2.xlsx",
    "filename": "1733563811188_1725358587906_1718776194681_1716026508753_1
715323634339_1711606660630_1700891975573_1695465043548_1694516251783_1
694241590859_Calculation_1_2.xlsx",
```

```
    "path": "cases/675159a8c5a60c3e016da9d4/processingDocuments/1733563811188_1725358587906_1718776194681_1716026508753_1715323634339_1711606660630_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "size": "1399945",
    "createdAt": "Sat Dec 07 2024 09:30:11 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_12345.pdf",
    "filename": "1733563811337_igr_12345.pdf",
    "path": "cases/675159a8c5a60c3e016da9d4/processingDocuments/1733563811337_igr_12345.pdf",
    "size": "154294",
    "createdAt": "Sat Dec 07 2024 09:30:11 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_17171.pdf",
    "filename": "1733563811342_igr_17171.pdf",
    "path": "cases/675159a8c5a60c3e016da9d4/processingDocuments/1733563811342_igr_17171.pdf",
    "size": "152395",
    "createdAt": "Sat Dec 07 2024 09:30:11 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-05T07:43:36.025Z",
"updatedAt": "2024-12-07T12:45:35.863Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 1001, 10th Floor, Wing - A, Gayatri SRA Co-Op. Hsg. Soc. Ltd., Umeda Ashram Road, Opp. Rajda School, Shimpoli Road No. 1, Village - Borivali, Borivali (West), Taluka - Borivali, District - Mumbai Suburban , PIN - 400 092, State - Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mrs. Soni Chandu Patel ",
"email": "",
```

```
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Seller",
"rerald": "",
"siteVisitContactNo": "9930110498",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 269.00",
"flatRate": "18500",
"landOtherRate": "15800",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "278.69",
"extendOfSiteRemark": "",
"finalBuiltupArea": "306.56",
"finalCarpetArea": "278.69",
"finalSalableArea": "337.21",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
```

```

    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Dec 07 2024 10:24:18 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-06"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	13'2"	8'5"	110.82
Kitchen	7'11"	5'5"	42.88
WC	4'9"	3'00"	14.25
Bathroom	7'00"	3'9"	26.25
Bedroom	12'10"	6'7"	84.49
Other Composition :			