

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "firstName": "Shravan",
    "type": "CREDITOFFICER",
    "_id": "6620d45d7e1d7332c88013d8",
    "lastName": "kumar",
    "mobileNo": "",
    "workMobileNo": "8424000434",
    "email": "shravankumar@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Shravan",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate No. 1, Horniman Circle, Mumbai
Samachar Marg, Fort, Mumbai, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.249380",
  "longitude": "73.154228"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.154228,
    19.24938
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-09",
      "remark": "Contact Person Tupti Madam 7738361109"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-08",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-08",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-09",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gauripada ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "21",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "H-7",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (West)",
  "label": false
},
"tahsilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ajmera Bliss",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Yogidham, Phase-V",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```



```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "22/1/1, 22/1/8 & Others",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
}
```

```
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Land",
    "west": "Vastu Siddhi CHSL ",
    "south": "Road",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Survey No. 21",
    "west": "Survey No. 24",
    "south": "12 Meter DP Road",
    "east": "Survey No. 22 PT"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
```

```
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
  "north": "",
  "east": "",
  "south": "",
  "west": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "+ Balcony Area.",
"dateOfIssusApprovePlan": "Approved Building Plan No. KDMC/TDD/BP/
KD/2012-13/21/328 dated 01.11.2021 issued by Kalyan Dombivli Municipal Corporation
(KDMC).",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
```

```
"remark": "",
"depreciationPercentage": "0",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"buildingServicesDepreciatedRate": "0",
"depreciatedCostOfConstruction": "10200.00",
"depreciatedBuildingRate": "2800"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "72900",
  "landRate": "20400",
  "igrImage": "cases/6752c9f3c5a60c3e016e919c/igr_1734418676592_Image.png",
  "squareMeterGuideLineRate": "83835.00",
  "squareFeetGuideLineRate": "7789.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "0",
  "rate": "72900.00",
  "squareMeterGuideLineRate": "83835.00",
  "squareFeetGuideLineRate": "7789.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Vacant flat in normal condition"
```

```
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "One Upper Stack Car Parking No. 34",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
```

```
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
},
"protAgainstNatDis": {
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
},
"walls": {
"value": "1",
"label": "Yes"
},
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
},
"maintenancelssues": {
"value": "0",
"label": "No"
}
```



```
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "1",
"totalLifeBuilding": "60",
"estimatedAge": "59",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "21",
"flatFloorNo": "21",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "719.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6752c9f3c5a60c3e016e919c/
routeMap_1734433144922_Image.png",
    "routeLat": "19.249494",
    "routeLng": "73.154139",
    "stationName": "Shahad ",
```

```
"routeDistance": "2 km.",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "sh45vk",
    "name": "sh45vk",
    "image": "cases/6752c9f3c5a60c3e016e919c/
routeMap_1734432860472_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
```

```
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "6670800.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "6670800.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Dec 17 2024 12:37:48 GMT+0000 (Coordinated Universal Time)",
  "number": "2309642",
  "dayCount": "25",
  "monthCount": "340",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5603407.00",
  "selectedBuildUpValue": "719.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "676157d91cc2b79503e884e4",
      "name": "externallmg_r_1734432728767_externallmg_r_1733731955044_1733731953761_image_0.jpg",
      "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728767_externallmg_r_1733731955044_1733731953761_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6756a668befd7f3db907e0f2",
      "name": "externallmg_r_1733731915175_1733731897945_image_7.jpg",
      "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1733731915175_1733731897945_image_7.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "676157d91cc2b79503e884de",
```

```
    "name": "externallmg_r_1734432728675_externallmg_r_1733731928565_1733731897945_image_14.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728675_externallmg_r_1733731928565_1733731897945_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676157d91cc2b79503e884e1",
    "name": "externallmg_r_1734432728744_externallmg_r_1733731935483_1733731897945_image_18.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728744_externallmg_r_1733731935483_1733731897945_image_18.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "676157c61cc2b79503e88403",
    "name": "Bedroom",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709243_externallmg_r_1733731909721_1733731897945_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676157c61cc2b79503e88405",
    "name": "Bedroom",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709239_externallmg_r_1733731907934_1733731897945_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676157d91cc2b79503e884d9",
    "name": "Bedroom",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728653_externallmg_r_1733731922963_1733731897945_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676157d91cc2b79503e884db",
```

```
    "name": "Bedroom",
    "path": "cases/6752c9f3c5a60c3e016e919c/externalimg_r_1734432728638_extern
allmg_r_1733731919474_1733731897945_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676157d91cc2b79503e884da",
    "name": "Bedroom",
    "path": "cases/6752c9f3c5a60c3e016e919c/externalimg_r_1734432728642_extern
allmg_r_1733731921398_1733731897945_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676157d91cc2b79503e884dc",
    "name": "Bedroom",
    "path": "cases/6752c9f3c5a60c3e016e919c/externalimg_r_1734432728656_extern
allmg_r_1733731924601_1733731897945_image_12.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9759.00",
    "max": "11708.00"
  },
  "builtUpRateRange": {
    "min": "8872.00",
    "max": "10644.00"
  },
  "saleableRateRange": {
    "min": "7394.00",
    "max": "8870.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
```



```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "654.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6752c9f3c5a60c3e016e919c",
"ownerName": "Ghaivat Pranali Prakash",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 2103,21Floor,Building H-7,Yogidham,Ajmera
Bliss,Gauripada ,Kalyan ",
"remark": "Contact Person Tupti Madam 7738361109",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "11/10/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Yogi Developers Corporation",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Ghaivat Pranali Prakash & Ketan Prakash Ghayvat",
      "number": {
```

```
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": " 14217/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "244277",
"path": "cases/6752c9f3c5a60c3e016e919c/document_1734413798209_173441379
5799_1734412291478110100_attach_139537050919290040.pdf",
"fileName": "document_1734413798209_1734413795799_1734412291478110100_
attach_139537050919290040.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "23/10/2023",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " KDMCC/CC/PO/2023/APL/00018"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "685954",
  "path": "cases/6752c9f3c5a60c3e016e919c/
document_1734435814781_Part_OC.pdf",
  "fileName": "document_1734435814781_Part_OC.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "01/11/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
```

```
    "label": "Kalyan Dombivli Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": " KDMC/TDD/BP/KD/2012-13/21/328"
},
"isHardCopy": false,
"displayStatus": false,
"id": "851257",
"path": "cases/6752c9f3c5a60c3e016e919c/document_1734436304689_2_Comme
ncement_Certificates__NA_Order_for_plotted_development.pdf",
"fileName": "document_1734436304689_2_Commencement_Certificates__NA_Or
der_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "03/11/2020",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " P51700026925"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "489899",
  "path": "cases/6752c9f3c5a60c3e016e919c/
document_1734436367713_P51700026925.pdf",
  "fileName": "document_1734436367713_P51700026925.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "01/11/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    }
  }
}
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " KDMC/TDD/BP/KD/2012-13/21/328"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "225753",
  "path": "cases/6752c9f3c5a60c3e016e919c/document_1734436804836_2_Building
_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "fileName": "document_1734436804836_2_Building_Plan_Approval___NA_Order_f
or_plotted_development.pdf"
}
],
"caseNumber": "012900",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "928674",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Dec 06 2024 09:54:59 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Ghaivat Pranali Prakash",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "485854"
  },
  {
    "name": "Ketan Prakash Ghayvat",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "826727"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "7",
"name": "Bedroom",
"length": "",
"length1": "12",
"length2": "6",
"width": "",
"width1": "10",
"width2": "0",
"totalArea": "125.00",
"images": [],
"finalArea": "125.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "17.83",
  "length1": "17",
  "length2": "10",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "54.99",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.99"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "6.58",
```

```
"width1": "6",
"width2": "7",
"totalArea": "30.17",
"images": [],
"extraAreas": [],
"finalArea": "30.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "12.17",
  "length1": "12",
  "length2": "2",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "114.57",
  "images": [],
  "extraAreas": [],
  "finalArea": "114.57"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "62.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "62.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
```



```
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "19.00",
  "length1": "19",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "190.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "190.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.17",
  "length1": "7",
  "length2": "2",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "31.65",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.65"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "0",
  "length": "7.25",
  "length1": "7",
  "length2": "3",
  "width": "2.42",
  "width1": "2",
  "width2": "5",
  "totalArea": "17.52",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.52",
  "percentageBeforeTotal": "17.52",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "763549",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "654",
    "squareMeterArea": "60.76",
    "docFinalBuiltUp": "719.4",
    "docFinalBuiltUpSquareMeter": "66.836",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "410.00",
      "squareMeterArea": "38.09",
```

```
    "expectedRate": "11707.32",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "451.00",
    "squareMeterArea": "41.90",
    "expectedRate": "10643.02",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "541.20",
    "squareMeterArea": "50.28",
    "expectedRate": "8869.18",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6761219b2d0531ee4cbafa6f",
  "property": "Flat",
  "area": "410",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "4800000",
  "expectedRate": "11707.32",
  "builtUpExpectedRate": "10643.02",
  "image": "cases/6752c9f3c5a60c3e016e919c/
indicator_1734418375940_Image.png",
  "squareMeter": "38.09",
  "id": "406726"
},
{
  "carpetArea": {
    "area": "531.82",
    "squareMeterArea": "49.41",
    "expectedRate": "10529.88",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "585.00",
    "squareMeterArea": "54.35",
    "expectedRate": "9572.65",
    "percentage": "10"
  },
}
```

```
"saleableArea": {
  "area": "702.00",
  "squareMeterArea": "65.22",
  "expectedRate": "7977.21",
  "percentage": "20"
},
"printlnReport": true,
"_id": "6761219b2d0531ee4cbafa70",
"property": "Flat",
"area": "585",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "5600000",
"expectedRate": "10529.88",
"builtUpExpectedRate": "5600000",
"image": "cases/6752c9f3c5a60c3e016e919c/
indicator_1734418425191_Image.png",
"squareMeter": "54.35",
"id": "490160"
},
{
  "carpetArea": {
    "area": "653.69",
    "squareMeterArea": "60.73",
    "expectedRate": "10160.63",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "719.06",
    "squareMeterArea": "66.80",
    "expectedRate": "9236.93",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "862.87",
    "squareMeterArea": "80.16",
    "expectedRate": "7697.46",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6761743cb3971e94fccc8e75",
  "property": "Flat ",
```

```
"area": "653.69",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "6641905",
"expectedRate": "10160.63",
"builtUpExpectedRate": "9236.93",
"image": "cases/6752c9f3c5a60c3e016e919c/
indicator_1734418591976_Image.png",
"squareMeter": "60.73",
"id": "165279"
},
{
"carpetArea": {
"area": "446.16",
"squareMeterArea": "41.45",
"expectedRate": "9758.94",
"percentage": ""
},
"builtUpArea": {
"area": "490.78",
"squareMeterArea": "45.59",
"expectedRate": "8871.69",
"percentage": "10"
},
"saleableArea": {
"area": "588.94",
"squareMeterArea": "54.71",
"expectedRate": "7393.03",
"percentage": "20"
},
"printlnReport": true,
"_id": "6761219b2d0531ee4cbafa72",
"property": "Flat",
"area": "446.16",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4354050",
"expectedRate": "9758.94",
```

```
    "builtUpExpectedRate": "8871.69",
    "image": "cases/6752c9f3c5a60c3e016e919c/
indicator_1734418638602_Image.png",
    "squareMeter": "41.45",
    "id": "265625"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756a668befd7f3db907e0ea",
    "name": "externallmg_1733731930596_1733731897945_image_15.png",
    "path": "cases/6752c9f3c5a60c3e016e919c/
externallmg_1733731930596_1733731897945_image_15.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756a668befd7f3db907e0ee",
    "name": "externallmg_r_1733731901213_1733731897945_image_0.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/
externallmg_r_1733731901213_1733731897945_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756a668befd7f3db907e0f1",
    "name": "externallmg_r_1733731913435_1733731897945_image_6.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/
externallmg_r_1733731913435_1733731897945_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756a668befd7f3db907e0f2",
    "name": "externallmg_r_1733731915175_1733731897945_image_7.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/
externallmg_r_1733731915175_1733731897945_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "6756a5b7befd7f3db907e07c",
    "name": "externallmg_r_1733731764345_1733731763614_image_0.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/
externallmg_r_1733731764345_1733731763614_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157c61cc2b79503e88402",
    "name": "externallmg_r_1734432709212_externallmg_r_1733731903793_1733731
897945_image_1.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709212_externa
llmg_r_1733731903793_1733731897945_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157c61cc2b79503e88403",
    "name": "externallmg_r_1734432709243_externallmg_r_1733731909721_1733731
897945_image_4.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709243_externa
llmg_r_1733731909721_1733731897945_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157c61cc2b79503e88404",
    "name": "externallmg_r_1734432709216_externallmg_r_1733731906006_1733731
897945_image_2.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709216_externa
llmg_r_1733731906006_1733731897945_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157c61cc2b79503e88405",
    "name": "externallmg_r_1734432709239_externallmg_r_1733731907934_1733731
897945_image_3.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709239_externa
llmg_r_1733731907934_1733731897945_image_3.jpg",
    "orientation": "portrait"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157c61cc2b79503e88406",
  "name": "externallmg_r_1734432709268_externallmg_r_1733731915175_1733731897945_image_7.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709268_externallmg_r_1733731915175_1733731897945_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157c61cc2b79503e88407",
  "name": "externallmg_r_1734432709265_externallmg_r_1733731911731_1733731897945_image_5.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709265_externallmg_r_1733731911731_1733731897945_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157c61cc2b79503e88408",
  "name": "externallmg_r_1734432709300_externallmg_r_1733731917693_1733731897945_image_8.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432709300_externallmg_r_1733731917693_1733731897945_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157d91cc2b79503e884d9",
  "name": "externallmg_r_1734432728653_externallmg_r_1733731922963_1733731897945_image_11.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728653_externallmg_r_1733731922963_1733731897945_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157d91cc2b79503e884da",
  "name": "externallmg_r_1734432728642_externallmg_r_1733731921398_1733731897945_image_9.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728642_externallmg_r_1733731921398_1733731897945_image_9.jpg",
  "orientation": "portrait"
}
```



```
897945_image_10.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728642_externa
llmg_r_1733731921398_1733731897945_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157d91cc2b79503e884db",
  "name": "externallmg_r_1734432728638_externallmg_r_1733731919474_1733731
897945_image_9.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728638_externa
llmg_r_1733731919474_1733731897945_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157d91cc2b79503e884dc",
  "name": "externallmg_r_1734432728656_externallmg_r_1733731924601_1733731
897945_image_12.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728656_externa
llmg_r_1733731924601_1733731897945_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157d91cc2b79503e884dd",
  "name": "externallmg_r_1734432728671_externallmg_r_1733731926447_1733731
897945_image_13.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728671_externa
llmg_r_1733731926447_1733731897945_image_13.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157d91cc2b79503e884de",
  "name": "externallmg_r_1734432728675_externallmg_r_1733731928565_1733731
897945_image_14.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728675_externa
llmg_r_1733731928565_1733731897945_image_14.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157d91cc2b79503e884df",
    "name": "externallmg_r_1734432728691_externallmg_r_1733731930895_1733731
897945_image_16.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728691_externa
llmg_r_1733731930895_1733731897945_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157d91cc2b79503e884e0",
    "name": "externallmg_r_1734432728714_externallmg_r_1733731933392_1733731
897945_image_17.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728714_externa
llmg_r_1733731933392_1733731897945_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157d91cc2b79503e884e1",
    "name": "externallmg_r_1734432728744_externallmg_r_1733731935483_1733731
897945_image_18.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728744_externa
llmg_r_1733731935483_1733731897945_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157d91cc2b79503e884e2",
    "name": "externallmg_r_1734432728818_externallmg_r_1733731957565_1733731
953761_image_1.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728818_externa
llmg_r_1733731957565_1733731953761_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676157d91cc2b79503e884e3",
    "name": "externallmg_r_1734432728764_externallmg_r_1733731937720_1733731
897945_image_19.jpg",
    "path": "cases/6752c9f3c5a60c3e016e919c/externallmg_r_1734432728764_externa
```

```
limg_r_1733731937720_1733731897945_image_19.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676157d91cc2b79503e884e4",
  "name": "externallimg_r_1734432728767_externallimg_r_1733731955044_1733731
953761_image_0.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/externallimg_r_1734432728767_externa
limg_r_1733731955044_1733731953761_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Pranali Prakash Ghayvat - Flat No. 2103 - State Bank of India
( SPL PBB Fort ).xlsx",
    "filename": "1734418805950_Pranali_Prakash_Ghayvat___Flat_No_2103___State_
Bank_of_India___SPL_PBB_Fort_.xlsx",
    "path": "cases/6752c9f3c5a60c3e016e919c/processingDocuments/1734418805950
_Pranali_Prakash_Ghayvat___Flat_No_2103___State_Bank_of_India___SPL_PBB_Fort
_.xlsx",
    "size": "2572161",
    "createdAt": "Tue Dec 17 2024 07:00:06 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "Index II.pdf",
    "filename": "1734438199300_Index_II.pdf",
    "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438199300_Index_II.pdf",
    "size": "672563",
    "createdAt": "Tue Dec 17 2024 12:23:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Part OC.pdf",
    "filename": "1734438199347_Part_OC.pdf",
    "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438199347_Part_OC.pdf",
    "size": "611989",
    "createdAt": "Tue Dec 17 2024 12:23:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
}
```

```
{
  "originalname": "Sale Deed - 2024.pdf",
  "filename": "1734438199438_Sale_Deed__2024.pdf",
  "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438199438_Sale_Deed__2024.pdf",
  "size": "3775529",
  "createdAt": "Tue Dec 17 2024 12:23:20 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sketch & Dimension (1).jpg",
  "filename": "1734438199520_Sketch__Dimension_1.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438199520_Sketch__Dimension_1.jpg",
  "size": "2067275",
  "createdAt": "Tue Dec 17 2024 12:23:20 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sketch & Dimension (2).jpg",
  "filename": "1734438199951_Sketch__Dimension_2.jpg",
  "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438199951_Sketch__Dimension_2.jpg",
  "size": "2062559",
  "createdAt": "Tue Dec 17 2024 12:23:20 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "2 Building Plan Approval _ NA Order for plotted development.pdf",
  "filename": "1734438213389_2_Building_Plan_Approval__NA_Order_for_plotted_
development.pdf",
  "path": "cases/6752c9f3c5a60c3e016e919c/processingDocuments/1734438213389
_2_Building_Plan_Approval__NA_Order_for_plotted_development.pdf",
  "size": "730891",
  "createdAt": "Tue Dec 17 2024 12:23:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Google Location.png",
  "filename": "1734438213457_Google_Location.png",
  "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438213457_Google_Location.png",
  "size": "332084",
  "createdAt": "Tue Dec 17 2024 12:23:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
}
```

```
{
  "originalname": "1 Commencement Certificates _ NA Order for plotted
development.pdf",
  "filename": "1734438234150_1_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
  "path": "cases/6752c9f3c5a60c3e016e919c/processingDocuments/1734438234150
_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
  "size": "90503",
  "createdAt": "Tue Dec 17 2024 12:23:54 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "1 Occupancy Certificate_ Completion Certificate_ Architect's
certificate of completion for plotted development.pdf",
  "filename": "1734438234158_1_Occupancy_Certificate__Completion_Certificate__
Architects_certificate_of_completion_for_plotted_development.pdf",
  "path": "cases/6752c9f3c5a60c3e016e919c/processingDocuments/1734438234158
_1_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_complet
ion_for_plotted_development.pdf",
  "size": "611993",
  "createdAt": "Tue Dec 17 2024 12:23:54 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "2 Commencement Certificates _ NA Order for plotted
development.pdf",
  "filename": "1734438234192_2_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
  "path": "cases/6752c9f3c5a60c3e016e919c/processingDocuments/1734438234192
_2_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
  "size": "393559",
  "createdAt": "Tue Dec 17 2024 12:23:54 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "AJMERA BLISS.pdf",
  "filename": "1734438234245_AJMERA_BLISS.pdf",
  "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438234245_AJMERA_BLISS.pdf",
  "size": "677170",
  "createdAt": "Tue Dec 17 2024 12:23:54 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "P51700026925.pdf",
  "filename": "1734438234272_P51700026925.pdf",
```

```
    "path": "cases/6752c9f3c5a60c3e016e919c/
processingDocuments/1734438234272_P51700026925.pdf",
    "size": "154664",
    "createdAt": "Tue Dec 17 2024 12:23:54 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "675423f8cfae933db22b9d3f",
    "note": "Only Index II received ",
    "taskId": "6752e42ecfae933db22b0211",
    "createdAt": "2024-12-07T10:31:20.150Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67611de38502a1ee4596ab57",
    "note": "Value Given for confirmation",
    "taskId": "6752e42ecfae933db22b0211",
    "createdAt": "2024-12-17T06:44:51.859Z"
  }
],
"createdAt": "2024-12-06T09:54:59.420Z",
```

```
"updatedAt": "2024-12-17T12:53:22.574Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 2103, 21st Floor, Building No H-7, Ajmera Bliss,
Yogidham, Phase-V, Village - Gauripada , Taluka - Kalyan, District - Thane, Kalyan
(West), PIN - 421 301, State - Maharashtra, India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Ms. Trupti Sawant",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"reald": "",
"siteVisitContactNo": "7738361109",
"siteVisitDate": "2024-12-09",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 654.00",
"flatRate": "10200",
"landOtherRate": "7400",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "608.8000000000001",
"otherCarpetTotal": "17.52",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "17.52",
"otherCompositionSaleableTotal": "0.00",
```

```

"builtupPercentage": "10",
"finalBuiltupArea": "688.95",
"finalCarpetArea": "626.32",
"finalSalableArea": "688.95",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 547.00\nEnclosed Balcony Area in
Sq. Ft. = 107.00\n<br />\nAll the above areas are within 4% of the Agreement for Sale
Area. The above calculations and detailed measurements taken by us prove that the
Agreement for Sale area is not exorbitantly inflated. Hence, valuation is prepared based
on the Agreement for Sale area.\n",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 608.80\nEnclosed Balcony Area
in Sq. Ft. = 17.52\n<br />\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Dec 17 2024 10:45:18 GMT+0000 (Coordinated
Universal Time)"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	12'6"	10'0"	125.00
Passage	17'10"	3'1"	54.99
Toilet	4'7"	6'7"	30.17
Bedroom	12'2"	9'5"	114.57

Kitchen	8'11"	7'00"	62.42
Living Room	19'00"	10'00"	190.00
Toilet	7'2"	4'5"	31.65
Other Composition :			
Balcony Area	7'3"	2'5"	17.52