

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7d7"
    },
    "firstName": "Pooja Vijaykumar ",
    "type": "CREDITOFFICER",
    "_id": "6678edd94c08775ede702de8",
    "email": "pooja.suryawanshi@sbi.co.in",
    "lastName": "Suryawanshi",
    "mobileNo": "",
    "workMobileNo": "8459191508"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7d7",
  "branchCode": "000032",
  "type": "BRANCH",
  "name": "Industrial Finance Branch, Malad (West)",
  "email": "team9.04107@sbi.co.in",
  "mobileNo": "022-28826408",
  "alternateMobileNo": "",
  "address": "Industrial Finance Branch, Near Chincholi Phatak Signal, S. V. Road,
Malad (West), Mumbai - 400 064, State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA- IFB MALAD",
  "fax": "022-28827773",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential cum Commercial",
  "value": "Residential_cum_commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
```

```
"lastName": "Patil",
"mobileNo": "8830049996",
"designation": "Valuation Engineer",
"shortName": "SSP",
"workWithDocumentMaker": "60f91822f3dd69653a5922e3",
"profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.414107811660482",
  "longitude": "72.86027599963668"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
```

```
0
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/12/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gokhivire",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "TRIO Infra",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
}
```

```
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
```

```
"area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6756c4da821be57904f18701",
"ownerName": "Trio Infrastructure Pvt Ltd ",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9326579997",
"contactPersonName": "Aftab Alam",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Trio Infrastructure Pvt Ltd ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "848855"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact Person",
"fullAddress": "Residential cum Commercial Cost Vetting No. Ground Floor, TRIO
Infra, Village - Gokhivire, Vasai East, Vasai, State - Maharashtra, India",
"remark": "",
"documents": [],
"isUrgent": "false",
```

```
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"reralid": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "012952",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "491422",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Mon Dec 09 2024 10:22:18 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae13",
    "name": "externallmg_1733746035376_externallmg_1731145190377_1731145184039_image_0.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746035376_externallmg_1731145190377_1731145184039_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae14",
    "name": "externallmg_1733746035420_externallmg_1731145193259_1731145184039_image_1.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746035420_externallmg_1731145193259_1731145184039_image_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae15",
    "name": "externallmg_1733746035487_externallmg_1731145196237_1731145184040_image_2.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746035487_externallmg_1731145196237_1731145184040_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae16",
    "name": "externallmg_1733746035546_externallmg_1731145198678_1731145184040_image_3.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746035546_externallmg_1731145198678_1731145184040_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae17",
    "name": "externallmg_1733746035657_externallmg_1731145202440_1731145184040_image_4.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746035657_externallmg_1731145202440_1731145184040_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae18",
    "name": "externallmg_1733746035767_externallmg_1731145206638_1731145184040_image_5.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746035767_externallmg_1731145206638_1731145184040_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae19",
    "name": "externallmg_1733746035852_externallmg_1731145210538_1731145184040_image_6.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746035852_externallmg_1731145210538_1731145184040_image_6.jpeg",
    "orientation": "portrait"
  }
]
```

```
40_image_6.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746035852_externallmg_1731145210538_1731145184040_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae1a",
  "name": "externallmg_1733746035993_externallmg_1731145214703_1731145184040_image_7.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746035993_externallmg_1731145214703_1731145184040_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae1b",
  "name": "externallmg_1733746036139_externallmg_1731145218437_1731145184040_image_8.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746036139_externallmg_1731145218437_1731145184040_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae1c",
  "name": "externallmg_1733746036239_externallmg_1731146458665_1731146453271_image_0.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746036239_externallmg_1731146458665_1731146453271_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae1d",
  "name": "externallmg_1733746036431_externallmg_1731146467577_1731146453271_image_1.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746036431_externallmg_1731146467577_1731146453271_image_1.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae1e",
    "name": "externallmg_1733746036446_externallmg_1731146474119_17311464532
71_image_2.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746036446_externall
mg_1731146474119_1731146453271_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae1f",
    "name": "externallmg_1733746036660_externallmg_1731146481702_17311464532
71_image_3.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746036660_externall
mg_1731146481702_1731146453271_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae20",
    "name": "externallmg_1733746036671_externallmg_1731146484591_17311464532
71_image_4.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746036671_externall
mg_1731146484591_1731146453271_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae21",
    "name": "externallmg_1733746036936_externallmg_1731146488246_17311464532
71_image_5.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746036936_externall
mg_1731146488246_1731146453271_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd75821be57904f1ae22",
    "name": "externallmg_1733746037118_externallmg_1731146491631_17311464532
71_image_6.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746037118_externall
```

```
mg_1731146491631_1731146453271_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae23",
  "name": "externallmg_1733746037131_externallmg_1731146497466_1731146453271_image_7.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746037131_externallmg_1731146497466_1731146453271_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae24",
  "name": "externallmg_1733746037311_externallmg_1731146502002_1731146453271_image_8.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746037311_externallmg_1731146502002_1731146453271_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae25",
  "name": "externallmg_1733746037343_externallmg_1731146507901_1731146453271_image_9.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746037343_externallmg_1731146507901_1731146453271_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd75821be57904f1ae26",
  "name": "externallmg_1733746037494_externallmg_1731146510853_1731146453271_image_10.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746037494_externallmg_1731146510853_1731146453271_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6756dd87821be57904f1ae73",
    "name": "externalimg_1733746053025_externalimg_1731146514618_17311464532
71_image_11.jpeg",
    "path": "cases/6756c4da821be57904f18701/externalimg_1733746053025_external
mg_1731146514618_1731146453271_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae74",
    "name": "externalimg_1733746053078_externalimg_1731146516508_17311464532
71_image_12.jpeg",
    "path": "cases/6756c4da821be57904f18701/externalimg_1733746053078_external
mg_1731146516508_1731146453271_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae75",
    "name": "externalimg_1733746053154_externalimg_1731146519915_17311464532
71_image_13.jpeg",
    "path": "cases/6756c4da821be57904f18701/externalimg_1733746053154_external
mg_1731146519915_1731146453271_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae76",
    "name": "externalimg_1733746053179_externalimg_1731146522497_17311464532
71_image_14.jpeg",
    "path": "cases/6756c4da821be57904f18701/externalimg_1733746053179_external
mg_1731146522497_1731146453271_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae77",
    "name": "externalimg_1733746053269_externalimg_1731146525022_17311464532
71_image_15.jpeg",
    "path": "cases/6756c4da821be57904f18701/externalimg_1733746053269_external
mg_1731146525022_1731146453271_image_15.jpeg",
    "orientation": "landscape"
  }
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae78",
  "name": "externallmg_1733746053323_externallmg_1731146529368_1731146453271_image_16.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053323_externallmg_1731146529368_1731146453271_image_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae79",
  "name": "externallmg_1733746053412_externallmg_1731146535039_1731146453271_image_17.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053412_externallmg_1731146535039_1731146453271_image_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae7a",
  "name": "externallmg_1733746053532_externallmg_1731146536673_1731146453271_image_18.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053532_externallmg_1731146536673_1731146453271_image_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae7b",
  "name": "externallmg_1733746053570_externallmg_1731146539378_1731146453271_image_19.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053570_externallmg_1731146539378_1731146453271_image_19.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae7c",
  "name": "externallmg_1733746053711_externallmg_1731147831044_17311476820
```

```
02_image_0.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053711_externallmg_1731147831044_1731147682002_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae7d",
  "name": "externallmg_1733746053732_externallmg_1731147836852_1731147682002_image_1.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053732_externallmg_1731147836852_1731147682002_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae7e",
  "name": "externallmg_1733746053834_externallmg_1731147841133_1731147682002_image_2.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053834_externallmg_1731147841133_1731147682002_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae7f",
  "name": "externallmg_1733746053850_externallmg_1731147842324_1731147682002_image_3.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053850_externallmg_1731147842324_1731147682002_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae80",
  "name": "externallmg_1733746053971_externallmg_1731147843324_1731147682002_image_4.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746053971_externallmg_1731147843324_1731147682002_image_4.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae81",
    "name": "externallmg_1733746054002_externallmg_1731147845790_17311476820
02_image_5.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746054002_externall
mg_1731147845790_1731147682002_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae82",
    "name": "externallmg_1733746054216_externallmg_1731147848810_17311476820
02_image_6.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746054216_externall
mg_1731147848810_1731147682002_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae83",
    "name": "externallmg_1733746054368_externallmg_1731147851355_17311476820
02_image_7.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746054368_externall
mg_1731147851355_1731147682002_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae84",
    "name": "externallmg_1733746054621_externallmg_1731147852998_17311476820
02_image_8.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746054621_externall
mg_1731147852998_1731147682002_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd87821be57904f1ae85",
    "name": "externallmg_1733746054773_externallmg_1731147855559_17311476820
02_image_9.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746054773_externall
```

```
mg_173114785559_1731147682002_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd87821be57904f1ae86",
  "name": "externallmg_1733746055067_externallmg_1731147858524_1731147682002_image_10.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746055067_externallmg_1731147858524_1731147682002_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd93befd7f3db90858bd",
  "name": "externallmg_1733746065276_externallmg_1731147860033_1731147682002_image_11.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746065276_externallmg_1731147860033_1731147682002_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd93befd7f3db90858be",
  "name": "externallmg_1733746065457_externallmg_1731147861388_1731147682002_image_12.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746065457_externallmg_1731147861388_1731147682002_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6756dd93befd7f3db90858bf",
  "name": "externallmg_1733746065710_externallmg_1731147863214_1731147682002_image_13.jpeg",
  "path": "cases/6756c4da821be57904f18701/externallmg_1733746065710_externallmg_1731147863214_1731147682002_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6756dd93befd7f3db90858c0",
    "name": "externallmg_1733746066002_externallmg_1731147864730_17311476820
02_image_14.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746066002_externall
mg_1731147864730_1731147682002_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd93befd7f3db90858c1",
    "name": "externallmg_1733746066178_externallmg_1731147865261_17311476820
02_image_15.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746066178_externall
mg_1731147865261_1731147682002_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd93befd7f3db90858c2",
    "name": "externallmg_1733746066371_externallmg_1731147866537_17311476820
03_image_16.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746066371_externall
mg_1731147866537_1731147682003_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd93befd7f3db90858c3",
    "name": "externallmg_1733746066398_externallmg_1731147867479_17311476820
03_image_17.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746066398_externall
mg_1731147867479_1731147682003_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756dd93befd7f3db90858c4",
    "name": "externallmg_1733746066648_externallmg_1731147868860_17311476820
03_image_18.jpeg",
    "path": "cases/6756c4da821be57904f18701/externallmg_1733746066648_externall
mg_1731147868860_1731147682003_image_18.jpeg",
    "orientation": "landscape"
  }
}
```

```
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-09T10:22:18.875Z",
"updatedAt": "2024-12-09T12:07:47.214Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60f91822f3dd69653a5922e3"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			