

```
{
  "typeOfReport": {
    "label": "APF",
    "value": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Advance Processing Facility",
    "value": "A.P.F."
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "666d5dc4fad0e137dd90072"
    },
    "firstName": "Balaji",
    "type": "CREDITOFFICER",
    "_id": "66d16d900f117327db7934ba",
    "email": "balaji.jindam@sbi.co.in",
    "lastName": "Jindam",
    "mobileNo": "",
    "workMobileNo": "8655817235"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Balaji",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "666d5dc4fadc0e137dd90072",
  "name": "Administrative Office South Mumbai",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "nikhil.kharat@sbi.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential cum Commercial",
  "value": "Residential_cum_commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62550ed0aba01e0af98f2f75",
"role": "SITEENGINEER",
"firstName": "Chandan",
"email": "ck06806@gmail.com",
"lastName": "Singh",
"mobileNo": "8454863607",
"designation": "",
"shortName": "CH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.13007908849839",
  "longitude": "72.82517793683611"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82517793683611,
    19.13007908849839
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/12/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "West Wood ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "J P Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Versova",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```

```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```



```
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "400053",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
}
```

```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
```



```
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6756c50ecfae933db22c6637",
"ownerName": "West Wood ",
"ownerPhoneNo": "9004213102",
"appAddress": "Plot no 833,Ambivali Village, Andheri ",
"remark": "Contact Person Aakansha +91 90042 13102",
"documents": [
  {
    "documentType": {
      "label": "RERA Certificate",
      "value": "60ae129faa6d152c1801b47d"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6756c50ecfae933db22c6637/document_1733739686083_1733739614420_MAHARERA_Certificate_NO_P51800056187_DT_16052024.pdf",
  "fileName": "document_1733739686083_1733739614420_MAHARERA_Certificate_NO_P51800056187_DT_16052024.pdf",
  "id": "244351",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
```

```
    "createdAt": "Mon Dec 09 2024 10:23:09 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "012953",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "453738",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Dec 09 2024 10:23:10 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "West Wood ",
    "phone": "9004213102",
    "ownershipShare": "",
    "email": "",
    "id": "811446"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67590fa3bc26c2bda04d9d7b",
    "name": "externalImg_1733889918681_1733889911655_image_0.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/externalImg_1733889918681_1733889911655_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67590fa3bc26c2bda04d9d7c",
    "name": "externalImg_1733889919100_1733889911655_image_1.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/externalImg_1733889919100_1733889911655_image_1.jpeg",
  }
]
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d7d",
  "name": "externallmg_1733889919222_1733889911655_image_2.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889919222_1733889911655_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d7e",
  "name": "externallmg_1733889919493_1733889911655_image_3.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889919493_1733889911655_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d7f",
  "name": "externallmg_1733889919787_1733889911655_image_4.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889919787_1733889911655_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d80",
  "name": "externallmg_1733889923542_1733889911655_image_5.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889923542_1733889911655_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d81",
  "name": "externallmg_1733889926619_1733889911655_image_6.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889926619_1733889911655_image_6.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67590fa3bc26c2bda04d9d82",
      "name": "externalImg_1733889929148_1733889911655_image_7.jpeg",
      "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733889929148_1733889911655_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67590fa3bc26c2bda04d9d83",
      "name": "externalImg_1733889929937_1733889911655_image_8.jpeg",
      "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733889929937_1733889911655_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67590fa3bc26c2bda04d9d84",
      "name": "externalImg_1733889931661_1733889911655_image_9.jpeg",
      "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733889931661_1733889911655_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67590fa3bc26c2bda04d9d85",
      "name": "externalImg_1733889932958_1733889911655_image_10.jpeg",
      "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733889932958_1733889911655_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67590fa3bc26c2bda04d9d86",
      "name": "externalImg_1733889938433_1733889911655_image_11.jpeg",
      "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733889938433_1733889911655_image_11.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d87",
  "name": "externallmg_1733889939442_1733889911655_image_12.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889939442_1733889911655_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d88",
  "name": "externallmg_1733889943622_1733889911655_image_13.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889943622_1733889911655_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d89",
  "name": "externallmg_1733889944677_1733889911655_image_14.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889944677_1733889911655_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d8a",
  "name": "externallmg_1733889947437_1733889911655_image_15.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889947437_1733889911655_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67590fa3bc26c2bda04d9d8b",
  "name": "externallmg_1733889949313_1733889911656_image_16.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889949313_1733889911656_image_16.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67590fa3bc26c2bda04d9d8c",
    "name": "externallmg_1733889950327_1733889911656_image_17.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889950327_1733889911656_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67590fa3bc26c2bda04d9d8d",
    "name": "externallmg_1733889953523_1733889911656_image_18.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889953523_1733889911656_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67590fa3bc26c2bda04d9d8e",
    "name": "externallmg_1733889954477_1733889911656_image_19.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733889954477_1733889911656_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2e5",
    "name": "externallmg_1733890041448_1733890010630_image_0.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890041448_1733890010630_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2e6",
    "name": "externallmg_1733890046012_1733890010630_image_1.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890046012_1733890010630_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6759102174fe66bd67c2b2e7",
  "name": "externalimg_1733890053222_1733890010630_image_2.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externalimg_1733890053222_1733890010630_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6759102174fe66bd67c2b2e8",
  "name": "externalimg_1733890054364_1733890010630_image_3.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externalimg_1733890054364_1733890010630_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6759102174fe66bd67c2b2e9",
  "name": "externalimg_1733890059782_1733890010630_image_4.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externalimg_1733890059782_1733890010630_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6759102174fe66bd67c2b2ea",
  "name": "externalimg_1733890064762_1733890010630_image_5.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externalimg_1733890064762_1733890010630_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6759102174fe66bd67c2b2eb",
  "name": "externalimg_1733890066137_1733890010630_image_6.jpeg",
  "path": "cases/6756c50ecfae933db22c6637/
externalimg_1733890066137_1733890010630_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6759102174fe66bd67c2b2ec",
    "name": "externallmg_1733890067115_1733890010630_image_7.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890067115_1733890010630_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2ed",
    "name": "externallmg_1733890071877_1733890010630_image_8.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890071877_1733890010630_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2ee",
    "name": "externallmg_1733890075140_1733890010630_image_9.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890075140_1733890010630_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2ef",
    "name": "externallmg_1733890075925_1733890010630_image_10.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890075925_1733890010630_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f0",
    "name": "externallmg_1733890076543_1733890010630_image_11.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890076543_1733890010630_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f1",
```



```
    "name": "externallmg_1733890077205_1733890010630_image_12.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890077205_1733890010630_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f2",
    "name": "externallmg_1733890077883_1733890010630_image_13.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890077883_1733890010630_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f3",
    "name": "externallmg_1733890078292_1733890010630_image_14.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890078292_1733890010630_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f4",
    "name": "externallmg_1733890078704_1733890010630_image_15.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890078704_1733890010630_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f5",
    "name": "externallmg_1733890078963_1733890010630_image_16.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externallmg_1733890078963_1733890010630_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f6",
    "name": "externallmg_1733890079291_1733890010630_image_17.jpeg",
```

```
    "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733890079291_1733890010630_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f7",
    "name": "externalImg_1733890079651_1733890010630_image_18.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733890079651_1733890010630_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6759102174fe66bd67c2b2f8",
    "name": "externalImg_1733890080373_1733890010630_image_19.jpeg",
    "path": "cases/6756c50ecfae933db22c6637/
externalImg_1733890080373_1733890010630_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-09T10:23:10.190Z",
"updatedAt": "2024-12-11T04:08:01.186Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential APF No. Ground Floor, West Wood , J P Road, Versova,
Andheri West, Mumbai, 400053",
"updatedBy": "62550ed0aba01e0af98f2f75",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Aakansha",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"rerald": "",
"siteVisitContactNo": "9004213102"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			