

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
```

```
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.005371",
  "longitude": "73.802346"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "9/12/2024 12:00 am"
    },
    {
      "dateTime": "9/12/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-09",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-08",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "70",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Rajashree Sadan Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mumbai-Agra Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
```



```
"key": "landmark",
"value": "Behind Hotel Triton",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "295/A/1/1A/70",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "5",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/ _Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
```

```
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Adjoining Plot ",
    "west": "12.00 M Wide Road",
    "south": "Adjoining Plot ",
    "east": "Adjoining Plot "
  },
  "asPerDocumentAgreement": {
    "north": "Adjoining Plot ",
    "west": "12.00 M Wide Road",
    "south": "Adjoining Plot ",
    "east": "Adjoining Plot "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Passage & Staircase",
      "east": "Margin Space",
      "south": "Margin Space",
      "west": "Flat No.6"
    }
  },
}
```

```

"asPerDocument": {
  "north": "Passage & Staircase",
  "east": "Margin Space",
  "south": "Margin Space",
  "west": "Flat No.6"
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": " Copy of Building Plan Document No.BP/1137/3414
Dated 28.10.1997,Issued by Nashik Municipal Corporation, Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "39",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "4720",

```

```
"depreciatedBuildingRate": "1220"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "45740",
  "landRate": "28700",
  "igrImage": "cases/6756d5aebefd7f3db908450d/igr_1733744366261_Image.png",
  "squareMeterGuideLineRate": "41166.00",
  "squareFeetGuideLineRate": "3824.00"
},
"igrFinalRate": {
  "floorRatePercentage": "90",
  "depreciationPercentage": "74",
  "rate": "3523.00",
  "squareFeetGuideLineRate": "3523.00",
  "squareMeterGuideLineRate": "37925.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "NA",
  "taxPaidHolderName": "NA",
  "taxAmount": "NA",
  "electricityServiceConnectionNo": "NA",
  "meterCardHolderName": "NA",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "as per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
```

```
"anyFavouringForExtraPotentialValue": "NA",
"negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1998",
    "fullDate": "1/1/1998"
  },
  "planningArea": {
    "value": "Residential_cum_Commercial",
    "label": "Residential cum Commercial"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  }
}
```

```
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
```



```
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "26",
"totalLifeBuilding": "60",
"estimatedAge": "34",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/6756d5aebefd7f3db908450d/
routeMap_1733745176338_Image.png",
"routeLat": "20.005371",
"routeLng": "73.802346",
"stationName": "Nashik Road",
"routeDistance": "9.3",
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
```

```
0
],
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "xqpixh",
    "name": "xqpixh",
    "image": "cases/6756d5aebefd7f3db908450d/
routeMap_1733745106507_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
```

```
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2317520.00",
"finalValue": "2317520.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Dec 10 2024 04:42:28 GMT+0000 (Coordinated Universal Time)",
  "number": "2309507",
  "dayCount": "1",
  "monthCount": "205",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "1729793.00",
  "selectedBuildUpValue": "491.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6756da25cfae933db22c8cc3",
      "name":
"externalImg_1733745189138_WhatsApp_Image_20241209_at_120034_PM.jpeg",
      "path": "cases/6756d5aebefd7f3db908450d/
externalImg_1733745189138_WhatsApp_Image_20241209_at_120034_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "6756da48cfae933db22c8d8f",
      "name": "Living Room",
      "path": "cases/6756d5aebefd7f3db908450d/
externalImg_1733745189064_WhatsApp_Image_20241209_at_120032_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6756da25cfae933db22c8cc0",
      "name": "Living Room",
      "path": "cases/6756d5aebefd7f3db908450d/
externalImg_1733745189101_WhatsApp_Image_20241209_at_120033_PM.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6756da25cfae933db22c8cc1",
  "name": "Living Room",
  "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189113_WhatsApp_Image_20241209_at_120034_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6756da25cfae933db22c8cc4",
  "name": "Living Room",
  "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189143_WhatsApp_Image_20241209_at_120035_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6756da25cfae933db22c8cc2",
  "name": "Living Room",
  "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189119_WhatsApp_Image_20241209_at_120034_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6756da25cfae933db22c8cc7",
  "name": "Living Room",
  "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189192_WhatsApp_Image_20241209_at_120036_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6756da25cfae933db22c8cbf",
  "name": "Living Room",
  "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189072_WhatsApp_Image_20241209_at_120033_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6756da25cfae933db22c8cc8",
  "name": "Living Room",
  "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189197_WhatsApp_Image_20241209_at_120036_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6756da25cfae933db22c8cc5",
    "name": "Living Room",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189168_WhatsApp_Image_20241209_at_120035_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6756da25cfae933db22c8cc6",
    "name": "Living Room",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189173_WhatsApp_Image_20241209_at_120035_PM.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6000.00",
    "max": "6629.00"
  },
  "builtUpRateRange": {
    "min": "5000.00",
    "max": "5524.00"
  },
  "saleableRateRange": {
    "min": "4167.00",
    "max": "4604.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
```

```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "491.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6756d5aebefd7f3db908450d",
"ownerName": "Shri.Pravin Haribhai Patel",
"ownerPhoneNo": "9021337843",
"fullAddress": "Residential Flat No. 5, 2nd Floor, Rajashree Sadan Apartment, Behind
Hotel Triton, Plot No. 70, Mumbai-Agra Road, Village - Nashik, Taluka - Nashik, District
- Nashik, 422003, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "inputs": {
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Shri.Pravin Haribhai Patel",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Sau.Rakshaben Bechar Ravriya "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "322651",
    "path": "cases/6756d5aebefd7f3db908450d/
document_1733743817006_Notarized_Agreement_OC.pdf",
```

```
"fileName": "document_1733743817006_Notarized_Agreement_OC.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "22/05/1998",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "Javak No.NRV/0284"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1733743891229_Notarized_Agreement_OC.pdf",
"path": "cases/6756d5aebefd7f3db908450d/
document_1733743891229_Notarized_Agreement_OC.pdf",
"id": "659598",
"uploadedBy": "636a1ad14d42487767af3f91",
"createdAt": "Mon Dec 09 2024 11:34:05 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "documentDate": "28/10/1997",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "BP/1137/3414"
},
"isHardCopy": false,
```

```
    "displayStatus": false,
    "fileName": "document_1733744037082_Approved_Plan.pdf",
    "path": "cases/6756d5aebefd7f3db908450d/
document_1733744037082_Approved_Plan.pdf",
    "id": "727116",
    "uploadedBy": "636a1ad14d42487767af3f91",
    "createdAt": "Mon Dec 09 2024 11:34:05 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "012959",
"createdBy": "636a1ad14d42487767af3f91",
"caseHistory": [
  {
    "id": "547211",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Dec 09 2024 11:34:06 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri.Pravin Haribhai Patel",
    "phone": "9021337843",
    "ownershipShare": "",
    "email": "",
    "id": "613634"
  }
],
"proposePurchasers": [
  {
    "name": "Sau.Rakshaben Bechar Ravriya",
    "phone": "",
    "email": "",
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "154887",
  "name": "Living Room",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
```

```
"images": [],
"extraAreas": [],
"finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "25.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
```

```
"name": "Passage",
"length": "1.00",
"length1": "1",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "1.00",
"images": [],
"extraAreas": [],
"finalArea": "1.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Balcony",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "45.62",
    "totalAreaDocument": "491",
```



```
"docBuiltpPercentage": "",
"docFinalBuiltp": "0.00",
"docFinalBuiltpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "650891"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "875.00",
"squareMeterArea": "81.29",
"expectedRate": "6628.57",
"percentage": ""
},
"builtUpArea": {
"area": "1050.00",
"squareMeterArea": "97.55",
"expectedRate": "5523.81",
"percentage": "20"
},
"saleableArea": {
"area": "1260.00",
"squareMeterArea": "117.06",
"expectedRate": "4603.17",
"percentage": "20"
},
"printlnReport": true,
"_id": "6756d709821be57904f1a1ae",
"property": "Flat",
"area": "1050",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "5800000",
"expectedRate": "6628.57",
"builtUpExpectedRate": "5800000",
"image": "cases/6756d5aebefd7f3db908450d/
indicator_1733744229791_Image.png",
"squareMeter": "97.55",
```

```
"id": "439241"
},
{
  "carpetArea": {
    "area": "8333.33",
    "squareMeterArea": "774.19",
    "expectedRate": "6000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "10000.00",
    "squareMeterArea": "929.03",
    "expectedRate": "5000.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "12000.00",
    "squareMeterArea": "1114.84",
    "expectedRate": "4166.67",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6756d709821be57904f1a1af",
  "property": "Flat",
  "area": "10000",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "50000000",
  "expectedRate": "6000.00",
  "builtUpExpectedRate": "50000000",
  "image": "cases/6756d5aebefd7f3db908450d/
indicator_1733744269775_Image.png",
  "squareMeter": "929.03",
  "id": "500331"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cbe",
    "name":
"externallmg_1733745189064_WhatsApp_Image_20241209_at_120032_PM.jpeg",
```

```
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189064_WhatsApp_Image_20241209_at_120032_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cbf",
    "name":
"externallmg_1733745189072_WhatsApp_Image_20241209_at_120033_PM_1.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189072_WhatsApp_Image_20241209_at_120033_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc0",
    "name":
"externallmg_1733745189101_WhatsApp_Image_20241209_at_120033_PM.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189101_WhatsApp_Image_20241209_at_120033_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc1",
    "name":
"externallmg_1733745189113_WhatsApp_Image_20241209_at_120034_PM_1.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189113_WhatsApp_Image_20241209_at_120034_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc2",
    "name":
"externallmg_1733745189119_WhatsApp_Image_20241209_at_120034_PM_2.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189119_WhatsApp_Image_20241209_at_120034_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6756da25cfae933db22c8cc3",
    "name":
"externallmg_1733745189138_WhatsApp_Image_20241209_at_120034_PM.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189138_WhatsApp_Image_20241209_at_120034_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc4",
    "name":
"externallmg_1733745189143_WhatsApp_Image_20241209_at_120035_PM_1.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189143_WhatsApp_Image_20241209_at_120035_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc5",
    "name":
"externallmg_1733745189168_WhatsApp_Image_20241209_at_120035_PM_2.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189168_WhatsApp_Image_20241209_at_120035_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc6",
    "name":
"externallmg_1733745189173_WhatsApp_Image_20241209_at_120035_PM.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189173_WhatsApp_Image_20241209_at_120035_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc7",
    "name":
"externallmg_1733745189192_WhatsApp_Image_20241209_at_120036_PM_1.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189192_WhatsApp_Image_20241209_at_120036_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc8",
    "name":
"externallmg_1733745189197_WhatsApp_Image_20241209_at_120036_PM.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189197_WhatsApp_Image_20241209_at_120036_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cc9",
    "name":
"externallmg_1733745189217_WhatsApp_Image_20241209_at_120037_PM_1.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189217_WhatsApp_Image_20241209_at_120037_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8cca",
    "name":
"externallmg_1733745189220_WhatsApp_Image_20241209_at_120037_PM.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189220_WhatsApp_Image_20241209_at_120037_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6756da25cfae933db22c8ccb",
    "name":
"externallmg_1733745189239_WhatsApp_Image_20241209_at_120038_PM.jpeg",
    "path": "cases/6756d5aebefd7f3db908450d/
externallmg_1733745189239_WhatsApp_Image_20241209_at_120038_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-09T11:34:06.163Z",
"updatedAt": "2024-12-10T05:33:23.291Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Sau.Rakshaben Bechar Ravriya ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Sau.Rakshaben Bechar Ravriya",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9021337843",
"buildingServicesRate": "2000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Notarized Agreement for Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 491.00",
"flatRate": "5500",
"landOtherRate": "3500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom +
Passage + Balcony",
"carpetTotal": "328.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "393.60",
"finalCarpetArea": "328.00",
"finalSalableArea": "511.68",
"salablePercentage": "30",
"toBeAdded": "",
"extendOfSiteRemark": "",
```

```

"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Tue Dec 10 2024 11:40:04 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-08"
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'00"	10'00"	100.00
Kitchen	10'00"	10'00"	100.00
Bedroom	10'00"	10'00"	100.00
WC	5'00"	5'00"	25.00
Bathroom	1'00"	1'00"	1.00
Passage	1'00"	1'00"	1.00
Balcony	1'00"	1'00"	1.00

Other
Composition :
