

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65dd7807e333566c7d2fe330"
    },
    "firstName": "Rajani",
    "type": "CREDITOFFICER",
    "_id": "65dd7807e333566c7d2fe332",
    "lastName": "Shinde",
    "mobileNo": "",
    "workMobileNo": "9819190288",
    "email": "shinderk.1@svcbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65dd7807e333566c7d2fe330",
  "name": "Kalwa",
  "branchCode": "000073",
  "mobileNo": "02225362870",
  "alternateMobileNo": "",
  "email": "shinderk.1@svcbank.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground Floor, Kishor Plaza, Old Mumbai Pune Road, Kalwa, Thane - 400
605."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
```

```
"lastName": "Shilvanta",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
      },
    ]
  }
]
```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.205374071355227",
  "longitude": " 73.00840165648982"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Parsik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalwa (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kirpal Baug Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "Old Mumbai - Pune Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Parsik Nagar",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```



```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "303",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```

```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 605",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
```

```
"costOfConstruction": "",
"depreciationPercentage": "",
"depreciatedCostOfConstruction": "",
"totalFairMarketValue": ""
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
```

```
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isExternalReport": false,
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "675a8343bc26c2bda04e753a",
"ownerName": "Mr. Prathamesh Suhas Manjrekar",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. 303, 3rd Floor, Wing - B, Kirpal Baug Co-Op. Hsg.
Soc. Ltd., Parsik Nagar, Old Mumbai - Pune Road, Village - Parsik, Taluka - Thane,
District - Thane, Kalwa (West), PIN Code - 400 605, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1733985048032_Agreement.pdf",
    "path": "cases/675a8343bc26c2bda04e753a/
document_1733985048032_Agreement.pdf",
    "id": "341273",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Thu Dec 12 2024 06:31:31 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013020",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "538865",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 12 2024 06:31:31 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Prathamesh Suhas Manjrekar",
    "phone": "0000000000",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "311474"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "675b01e274fe66bd67c40af5",
    "name": "externalImg_1734017504252_1734017475232_image_0.png",
    "path": "cases/675a8343bc26c2bda04e753a/
externalImg_1734017504252_1734017475232_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "675b01e274fe66bd67c40af6",
    "name": "externalImg_r_1734017505421_1734017503176_image_0.jpg",
    "path": "cases/675a8343bc26c2bda04e753a/
externalImg_r_1734017505421_1734017503176_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "675b01e274fe66bd67c40af7",
    "name": "externalImg_r_1734017504725_1734017475232_image_1.jpg",
    "path": "cases/675a8343bc26c2bda04e753a/
externalImg_r_1734017504725_1734017475232_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675b020074fe66bd67c40b05",
    "name": "externalImg_r_1734017522353_1734017519876_image_0.jpg",
```

```
    "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017522353_1734017519876_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675b020074fe66bd67c40b06",
    "name": "externallmg_r_1734017523141_1734017519876_image_1.jpg",
    "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017523141_1734017519876_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675b020074fe66bd67c40b07",
    "name": "externallmg_r_1734017525010_1734017519876_image_3.jpg",
    "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017525010_1734017519876_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675b020074fe66bd67c40b08",
    "name": "externallmg_r_1734017524040_1734017519876_image_2.jpg",
    "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017524040_1734017519876_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675b020074fe66bd67c40b09",
    "name": "externallmg_r_1734017525970_1734017519876_image_4.jpg",
    "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017525970_1734017519876_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675b020074fe66bd67c40b0a",
    "name": "externallmg_r_1734017526813_1734017519876_image_5.jpg",
    "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017526813_1734017519876_image_5.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675b020074fe66bd67c40b0b",
  "name": "externallmg_r_1734017527813_1734017519876_image_6.jpg",
  "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017527813_1734017519876_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675b020074fe66bd67c40b0c",
  "name": "externallmg_r_1734017528350_1734017519876_image_7.jpg",
  "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017528350_1734017519876_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675b020074fe66bd67c40b0d",
  "name": "externallmg_r_1734017529086_1734017519876_image_8.jpg",
  "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017529086_1734017519876_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675b020074fe66bd67c40b0e",
  "name": "externallmg_r_1734017529630_1734017519876_image_9.jpg",
  "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017529630_1734017519876_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675b020074fe66bd67c40b0f",
  "name": "externallmg_r_1734017530516_1734017519876_image_10.jpg",
  "path": "cases/675a8343bc26c2bda04e753a/
externallmg_r_1734017530516_1734017519876_image_10.jpg",
  "orientation": "portrait"
}
```

```

    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "675b020074fe66bd67c40b10",
      "name": "externalImg_r_1734017531482_1734017519876_image_11.jpg",
      "path": "cases/675a8343bc26c2bda04e753a/
externalImg_r_1734017531482_1734017519876_image_11.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-12-12T06:31:31.533Z",
  "updatedAt": "2024-12-12T15:32:16.865Z",
  "__v": 0,
  "updatedBy": "62ea09ea4e679b264caf07d7",
  "addressForMap": "",
  "caseReferredBy": "64abdb2806d6ec174986d16b",
  "contactPersonName": "Siddhesh Pawar",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Representative ",
  "reald": "",
  "siteVisitContactNo": "9773508392"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			