

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6475ec63b05e530fb6c8c6d4"
    },
    "firstName": "Deepali ",
    "type": "CREDITOFFICER",
    "_id": "6475ec63b05e530fb6c8c6d6",
    "lastName": "Patil",
    "mobileNo": "",
    "workMobileNo": "9850124768",
    "email": "sbi@sbi.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6475ec63b05e530fb6c8c6d4",
  "name": "Jehan Circle Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "sbi@sbi.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mandalik Plaza, Near Hotel Curry Leaves, Jehan Circle, Gangapur road,
Nashik 422005\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushipingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "636a29b64d42487767af43ea",
  "role": "NASHIK (LEAD + VISIT + RATE)",
  "firstName": "Sachin",
  "email": "sachinraundal9021@gmail.com",
  "lastName": "Raundal",
  "mobileNo": "9021337843",
  "designation": "Site Engg",
  "shortName": "Sachin",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushipingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "designation": "",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushipingle2201@gmail.com",
  "lastName": "Pingle",
```

```
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.002271764383217",
  "longitude": "73.7679254441673"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "12/12/2024 12:00 am"
    },
    {
      "dateTime": "12/12/2024 12:00 am"
    },
    {
      "dateTime": "12/12/2024 12:00 am"
    },
    {
      "dateTime": "12/12/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-11",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-11",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "4BHK",
  "label": "4 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,

```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "59",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Amber Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off College Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```



```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp. Ramdas Garden, Near Boys Town School",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "71911 + 720/A/59",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```

```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "6",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422005",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
```

```
"value": "Wooden_frame_openable_widow_with_M._S._Grill",
"label": "Wooden frame openable widow with M. S. Grill"
},
"fittings": {
  "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
  "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Preeti Bungalow & Shri\nGanesh Apartment",
    "west": "Sai Prabha Bungalow",
    "south": "Road",
    "east": "Other Residential Building"
  },
  "asPerDocumentAgreement": {
    "north": "By Plot No. 51 & 52",
    "west": "By Plot No.58",
    "south": "By 50 Ft. Road",
    "east": "By Plot No. 60"
  },
  "unitBoundaries": {
```

```

"asPerActual": {
  "north": "Staircase",
  "east": "Marginal Space",
  "south": "Marginal Space",
  "west": "Marginal Space"
},
"asPerDocument": {
  "north": "-",
  "east": "-",
  "south": "-",
  "west": "-"
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": " Copy of Approved Building Plan Accupaining
Occupancy Certificate No.NSK/A1/10542/5530 Dated 10.12.2012 issued by Executive
Engineer Town Planning, Nashik Municipal Corporation, Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "NA",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
}

```

```
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "18",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "9640",
  "depreciatedBuildingRate": "1640"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "77100",
  "landRate": "69000",
  "igrImage": "cases/675a9799bc26c2bda04e8e86/igr_1733990714035_Image.png",
  "squareMeterGuideLineRate": "80955.00",
  "squareFeetGuideLineRate": "7521.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "88",
  "rate": "7388.00",
  "squareMeterGuideLineRate": "79520.00",
  "squareFeetGuideLineRate": "7388.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Posh",
    "label": "Posh"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "25700",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As per NMC Norms",
  "tenantName": ""
}
```

```
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2012",
    "fullDate": "1/1/2012"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
}
```

```
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
```



```
"label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "12",
"totalLifeBuilding": "60",
"estimatedAge": "48",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "6",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "1"
},
"finalPlinthArea": {
  "area": "1540.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/675a9799bc26c2bda04e8e86/
routeMap_1733995987854_Image.png",
    "routeLat": "20.002274",
    "routeLng": "73.767927",
```

```
"stationName": "Nashik Road",
"routeDistance": "11.4 KM",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "2bng8b",
    "name": "2bng8b",
    "image": "cases/675a9799bc26c2bda04e8e86/
routeMap_1733995912584_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "12377760.00",
"finalValue": "12377760.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "11383430.00",
"selectedBuildUpValue": "1540.80",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "675a97fab26c2bda04e8fd8",
"name":
"externallmg_1733990393929_WhatsApp_Image_20241211_at_135355_1.jpeg",
"path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990393929_WhatsApp_Image_20241211_at_135355_1.jpeg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "675a97f3bc26c2bda04e8f96",
"name":
"externallmg_1733990386251_WhatsApp_Image_20241211_at_135345.jpeg",
"path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386251_WhatsApp_Image_20241211_at_135345.jpeg",
"orientation": "landscape"
}
],
"externalPhotos": [
{
"status": false,
"_id": "675a97f3bc26c2bda04e8fa6",
"name":
"externallmg_1733990386982_WhatsApp_Image_20241211_at_135352_2.jpeg",
```

```
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386982_WhatsApp_Image_20241211_at_135352_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97fabcd26c2bda04e8fd3",
    "name":
"externallmg_1733990393765_WhatsApp_Image_20241211_at_135353_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990393765_WhatsApp_Image_20241211_at_135353_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97fabcd26c2bda04e8fd8",
    "name":
"externallmg_1733990393929_WhatsApp_Image_20241211_at_135355_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990393929_WhatsApp_Image_20241211_at_135355_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f98",
    "name": "Living Room",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386362_WhatsApp_Image_20241211_at_135346_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f99",
    "name": "Bedroom",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386430_WhatsApp_Image_20241211_at_135347_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9a",
    "name": "Passage",
```

```
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386443_WhatsApp_Image_20241211_at_135347.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9e",
    "name": "Dining",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386569_WhatsApp_Image_20241211_at_135349_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97f3bc26c2bda04e8fa0",
    "name": "Bedroom",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386726_WhatsApp_Image_20241211_at_135350_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97f3bc26c2bda04e8fa1",
    "name": "Bedroom",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386766_WhatsApp_Image_20241211_at_135350_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "675a97f3bc26c2bda04e8fa3",
    "name": "Balcony",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386849_WhatsApp_Image_20241211_at_135351_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "675a97fab26c2bda04e8fd4",
    "name": "Kitchen",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990393807_WhatsApp_Image_20241211_at_135353.jpeg",
    "orientation": "portrait"
  }
]
},
```



```
"indicatorRange": {
  "carpetRateRange": {
    "min": "6667.00",
    "max": "11364.00"
  },
  "builtUpRateRange": {
    "min": "5556.00",
    "max": "9470.00"
  },
  "saleableRateRange": {
    "min": "4630.00",
    "max": "7892.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1284.00",
"empanelmentNo": [
  "NZO /CR/22-23/39"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "675a9799bc26c2bda04e8e86",
"ownerName": "Mr. Sagar Shailesh Shah & Mrs. Vaishali Sagar Shah",
```

```
"ownerPhoneNo": "9422247125",
"fullAddress": "Residential Flat No. 6, 6th Floor, Amber Apartment, Opp. Ramdas
Garden, Near Boys Town School, Plot No. 59, Off College Road, Taluka - Nashik,
District - Nashik, Nashik, 422005, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "inputs": {
      "documentDate": "21/05/2013",
      "amount": "4900000",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Yashwant Pundlik Thakre",
      "to": {
        "value": "buyer",
        "label": "buyer"
      },
      "buyer": "Mr. Sagar Shailesh Shah & Mrs. Vaishali Sagar Shah"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1733990072459_deed_of_apartment.pdf",
    "path": "cases/675a9799bc26c2bda04e8e86/
document_1733990072459_deed_of_apartment.pdf",
    "id": "952496",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Thu Dec 12 2024 07:58:17 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "10/12/2012",
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      },
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "NSK/A1/10542/5530"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1733990172140_building_plan.pdf",
"path": "cases/675a9799bc26c2bda04e8e86/
document_1733990172140_building_plan.pdf",
"id": "962482",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Thu Dec 12 2024 07:58:17 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "28/03/2011",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "LND/BP/NSK/A1/222/6018"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1733990215331_commencement.pdf",
"path": "cases/675a9799bc26c2bda04e8e86/
document_1733990215331_commencement.pdf",
"id": "677681",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Thu Dec 12 2024 07:58:17 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
```

```
"documentDate": "10/02/2012",
"nameOfApprovingAuthority": {
  "value": "Nashik_Municipal_Corporation",
  "label": "Nashik Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "Javak No. NRV / Nashik West / 10542 / 5530"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1733990283743_Complition.pdf",
"path": "cases/675a9799bc26c2bda04e8e86/
document_1733990283743_Complition.pdf",
"id": "643372",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Thu Dec 12 2024 07:58:17 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013025",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "975391",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 12 2024 07:58:17 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sagar Shailesh Shah & Mrs. Vaishali Sagar Shah",
    "phone": "9422247125",
    "ownershipShare": "",
    "email": "",
    "id": "905617"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "935984",  
    "name": "Balcony",  
    "length": "7.17",  
    "length1": "7",  
    "length2": "2",  
    "width": "8.25",  
    "width1": "8",  
    "width2": "3",  
    "totalArea": "59.12",  
    "images": [],  
    "extraAreas": [],  
    "finalArea": "59.12"  
  },  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "1",  
    "name": "Bedroom",  
    "length": "11.50",  
    "length1": "11",  
    "length2": "6",  
    "width": "10.25",  
    "width1": "10",  
    "width2": "3",  
    "totalArea": "117.87",  
    "images": [],  
    "extraAreas": [],  
    "finalArea": "117.87"  
  },  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "2",  
    "name": "Bathroom",  
    "length": "6.25",  
    "length1": "6",
```

```
"length2": "3",
"width": "4.25",
"width1": "4",
"width2": "3",
"totalArea": "26.56",
"images": [],
"extraAreas": [],
"finalArea": "26.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "17.25",
  "length1": "17",
  "length2": "3",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "176.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "176.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Dining",
  "length": "13.17",
  "length1": "13",
  "length2": "2",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "125.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "125.08"
},
{
```



```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "5",
"name": "Bedroom",
"length": "14.25",
"length1": "14",
"length2": "3",
"width": "10.50",
"width1": "10",
"width2": "6",
"totalArea": "149.62",
"images": [],
"extraAreas": [],
"finalArea": "149.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "5.50",
  "length1": "5",
  "length2": "6",
  "width": "16.25",
  "width1": "16",
  "width2": "3",
  "totalArea": "89.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "89.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "17.50",
```

```
"width1": "17",
"width2": "6",
"totalArea": "61.25",
"images": [],
"extraAreas": [],
"finalArea": "61.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Living Room",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "18.25",
  "width1": "18",
  "width2": "3",
  "totalArea": "310.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "310.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Kitchen",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "14.25",
  "width1": "14",
  "width2": "3",
  "totalArea": "242.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "242.25"
}
],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "119.29",
    "totalAreaDocument": "1284",
    "docBuiltpupPercentage": "20",
    "docFinalBUILTUp": "1540.80",
    "docFinalBUILTUpSquareMeter": "143.15",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "164151"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "1100.00",
      "squareMeterArea": "102.19",
      "expectedRate": "11363.64",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1320.00",
      "squareMeterArea": "122.63",
      "expectedRate": "9469.70",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "1584.00",
      "squareMeterArea": "147.16",
      "expectedRate": "7891.41",
      "percentage": "20"
    },
    "printlnReport": true,
    "_id": "675a994d7e4dc2bd6efa4186",
    "property": "Flat",
```

```
"area": "1100",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "12500000",
"expectedRate": "11363.64",
"builtUpExpectedRate": "9469.70",
"image": "cases/675a9799bc26c2bda04e8e86/
indicator_1733990638511_Image.png",
"squareMeter": "102.19",
"id": "160829"
},
{
"carpetArea": {
"area": "1500.00",
"squareMeterArea": "139.35",
"expectedRate": "6666.67",
"percentage": ""
},
"builtUpArea": {
"area": "1800.00",
"squareMeterArea": "167.23",
"expectedRate": "5555.56",
"percentage": "20"
},
"saleableArea": {
"area": "2160.00",
"squareMeterArea": "200.67",
"expectedRate": "4629.63",
"percentage": "20"
},
"printlnReport": true,
"_id": "675a994d7e4dc2bd6efa4187",
"property": "Flat",
"area": "1500",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "10000000",
"expectedRate": "6666.67",
```

```
    "builtUpExpectedRate": "5555.56",
    "image": "cases/675a9799bc26c2bda04e8e86/
indicator_1733990663860_Image.png",
    "squareMeter": "139.35",
    "id": "883723"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f96",
    "name":
"externallmg_1733990386251_WhatsApp_Image_20241211_at_135345.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386251_WhatsApp_Image_20241211_at_135345.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f97",
    "name":
"externallmg_1733990386329_WhatsApp_Image_20241211_at_135346_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386329_WhatsApp_Image_20241211_at_135346_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f98",
    "name":
"externallmg_1733990386362_WhatsApp_Image_20241211_at_135346_2.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386362_WhatsApp_Image_20241211_at_135346_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f99",
    "name":
"externallmg_1733990386430_WhatsApp_Image_20241211_at_135347_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386430_WhatsApp_Image_20241211_at_135347_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9a",
    "name":
"externallmg_1733990386443_WhatsApp_Image_20241211_at_135347.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386443_WhatsApp_Image_20241211_at_135347.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9b",
    "name":
"externallmg_1733990386445_WhatsApp_Image_20241211_at_135348_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386445_WhatsApp_Image_20241211_at_135348_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9c",
    "name":
"externallmg_1733990386498_WhatsApp_Image_20241211_at_135348_3.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386498_WhatsApp_Image_20241211_at_135348_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9d",
    "name":
"externallmg_1733990386526_WhatsApp_Image_20241211_at_135348.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386526_WhatsApp_Image_20241211_at_135348.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9e",
```

```
    "name":
"externallmg_1733990386569_WhatsApp_Image_20241211_at_135349_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386569_WhatsApp_Image_20241211_at_135349_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8f9f",
    "name":
"externallmg_1733990386649_WhatsApp_Image_20241211_at_135349.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386649_WhatsApp_Image_20241211_at_135349.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8fa0",
    "name":
"externallmg_1733990386726_WhatsApp_Image_20241211_at_135350_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386726_WhatsApp_Image_20241211_at_135350_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8fa1",
    "name":
"externallmg_1733990386766_WhatsApp_Image_20241211_at_135350_2.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386766_WhatsApp_Image_20241211_at_135350_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8fa2",
    "name":
"externallmg_1733990386804_WhatsApp_Image_20241211_at_135350.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386804_WhatsApp_Image_20241211_at_135350.jpeg",
    "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675a97f3bc26c2bda04e8fa3",
  "name":
"externallmg_1733990386849_WhatsApp_Image_20241211_at_135351_1.jpeg",
  "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386849_WhatsApp_Image_20241211_at_135351_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675a97f3bc26c2bda04e8fa4",
  "name":
"externallmg_1733990386898_WhatsApp_Image_20241211_at_135351.jpeg",
  "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386898_WhatsApp_Image_20241211_at_135351.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675a97f3bc26c2bda04e8fa5",
  "name":
"externallmg_1733990386927_WhatsApp_Image_20241211_at_135352_1.jpeg",
  "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386927_WhatsApp_Image_20241211_at_135352_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675a97f3bc26c2bda04e8fa6",
  "name":
"externallmg_1733990386982_WhatsApp_Image_20241211_at_135352_2.jpeg",
  "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990386982_WhatsApp_Image_20241211_at_135352_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675a97f3bc26c2bda04e8fa7",
  "name":
"externallmg_1733990387008_WhatsApp_Image_20241211_at_135352.jpeg",
```



```
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990387008_WhatsApp_Image_20241211_at_135352.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97f3bc26c2bda04e8fa8",
    "name":
"externallmg_r_1733990386382_WhatsApp_Image_20241211_at_135346.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_r_1733990386382_WhatsApp_Image_20241211_at_135346.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97fab3bc26c2bda04e8fd3",
    "name":
"externallmg_1733990393765_WhatsApp_Image_20241211_at_135353_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990393765_WhatsApp_Image_20241211_at_135353_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97fab3bc26c2bda04e8fd4",
    "name":
"externallmg_1733990393807_WhatsApp_Image_20241211_at_135353.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990393807_WhatsApp_Image_20241211_at_135353.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675a97fab3bc26c2bda04e8fd5",
    "name":
"externallmg_1733990393831_WhatsApp_Image_20241211_at_135354_1.jpeg",
    "path": "cases/675a9799bc26c2bda04e8e86/
externallmg_1733990393831_WhatsApp_Image_20241211_at_135354_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "675a97fabc26c2bda04e8fd6",
  "name":
"externalImg_1733990393856_WhatsApp_Image_20241211_at_135354_2.jpeg",
  "path": "cases/675a9799bc26c2bda04e8e86/
externalImg_1733990393856_WhatsApp_Image_20241211_at_135354_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675a97fabc26c2bda04e8fd7",
  "name":
"externalImg_1733990393888_WhatsApp_Image_20241211_at_135354.jpeg",
  "path": "cases/675a9799bc26c2bda04e8e86/
externalImg_1733990393888_WhatsApp_Image_20241211_at_135354.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675a97fabc26c2bda04e8fd8",
  "name":
"externalImg_1733990393929_WhatsApp_Image_20241211_at_135355_1.jpeg",
  "path": "cases/675a9799bc26c2bda04e8e86/
externalImg_1733990393929_WhatsApp_Image_20241211_at_135355_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "SBI - Mr. Sagar Shailesh Shah & Mrs. Vaishali Sagar Shah.pdf",
    "filename":
"1733996311505_SBI__Mr_Sagar_Shailesh_Shah__Mrs_Vaishali_Sagar_Shah.pdf",
    "path": "cases/675a9799bc26c2bda04e8e86/processingDocuments/1733996311505
_SBI__Mr_Sagar_Shailesh_Shah__Mrs_Vaishali_Sagar_Shah.pdf",
    "size": "5409482",
    "createdAt": "Thu Dec 12 2024 09:38:34 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "Old Report.pdf",
    "filename": "1733996358924_Old_Report.pdf",
    "path": "cases/675a9799bc26c2bda04e8e86/
processingDocuments/1733996358924_Old_Report.pdf",
```

```
"size": "16971301",
"createdAt": "Thu Dec 12 2024 09:39:24 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
"originalname": "calc.xlsx",
"filename": "1733996393677_calc.xlsx",
"path": "cases/675a9799bc26c2bda04e8e86/
processingDocuments/1733996393677_calc.xlsx",
"size": "535386",
"createdAt": "Thu Dec 12 2024 09:39:54 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "63f9ed37ce84bf289ba991ac"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-12T07:58:17.260Z",
"updatedAt": "2024-12-12T10:56:08.945Z",
"__v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Mr. Sagar Shailesh Shah & Mrs. Vaishali Sagar Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9422247125",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Deed of Apartment",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1284.00",
"flatRate": "10000",
"landOtherRate": "8000",
"shopDetails": {
"typeOfShops": {
"label": "Independent Building",
"value": "Independent_Building"
```

```

    },
    "roadFacing": false,
    "mall": false
  },
  "briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Balcony + 2 Bathroom
+ Dining + Passage",
  "carpetTotal": "1358.18",
  "otherCarpetTotal": "0.00",
  "builtupPercentage": "20",
  "finalBuiltupArea": "1629.82",
  "finalCarpetArea": "1358.18",
  "finalSalableArea": "1792.80",
  "salablePercentage": "10",
  "toBeAdded": "",
  "extendOfSiteRemark": "",
  "siteMeasurementRemark": "",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    }
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Dec 12 2024 08:49:49 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-11",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			

Balcony	7'2"	8'3"	59.12
Bedroom	11'6"	10'3"	117.87
Bathroom	6'3"	4'3"	26.56
Bedroom	17'3"	10'3"	176.81
Dining	13'2"	9'6"	125.08
Bedroom	14'3"	10'6"	149.62
Bathroom	5'6"	16'3"	89.37
Passage	3'6"	17'6"	61.25
Living Room	17'00"	18'3"	310.25
Kitchen	17'00"	14'3"	242.25
Other Composition :			