

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Visa Application",
    "value": "Fair_Market_Value_Visa"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "4000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "67612f08d56f366c9e04b4ce",
```

```
"type": "PRIVATE_CLIENT",
"name": "Sushil B Uchil ",
"displayName": "Sushil B Uchil ",
"initial": "S"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "66891578194f4629de0af6da",
    "role": "SITEENGINEER",
    "firstName": "Govind",
    "email": "govindpande23@gmail.com",
    "lastName": "Pande",
    "mobileNo": "9096192041",
    "designation": "Site Engg",
    "shortName": "Deepak",
    "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shobha",
```

```
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
],
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
```

```
    }
  ]
},
"clientType": {
  "label": "Private Clients",
  "value": "PRIVATE_CLIENT"
},
"location": {
  "latitude": "19.22938944708056",
  "longitude": "72.8255136429459"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8255136429459,
    19.22938944708056
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "17/12/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-17",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Borivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Borivali (West), Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "AM-2",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gorai Aditi Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "RSC 31",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "RSC-31",
  "label": false
},
"street2": {
```

```
"status": true,
"name": "Street 2",
"key": "street2",
"value": "Gorai - II",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "187/(pt)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```



```
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "19",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 091",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_with_flush_shutters",
    "label": "Teak Wood Door with flush shutters"
  }
}
```

```

},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Plot No. 99 - Siddhesh CHSL",
    "west": "RSC Road No. 32",
    "south": "RSC Road No. 31",
    "east": "MHADA Complex"
  },
  "asPerDocumentAgreement": {
    "north": "Information not available",
    "west": "Information not available",
    "south": "Information not available",

```

```
"east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "+ Dry Balcony Area.",
"dateOfIssusApprovePlan": "The property is constructed by MHADA, hence MHADA
itself is an issuing authority.",
"approvePlanVerified": "No",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
```

```
"remark": "",
"depreciationPercentage": "0",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "22000",
"depreciatedBuildingRate": "2800"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "133860",
  "landRate": "65220",
  "igrImage": "cases/67612f08d56f366c9e04b4d3/igr_1734519948076_Image.png",
  "squareMeterGuideLineRate": "133860.00",
  "squareFeetGuideLineRate": "12436.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "86",
  "rate": "11543.00",
  "squareFeetGuideLineRate": "11543.00",
  "squareMeterGuideLineRate": "124250.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "23,000/- Expected rental income per month",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "CA No. 152998893",
  "meterCardHolderName": "Sushil B Uchil & Smita S Uchil",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MHADA / MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
```

```
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open / Covered Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2010",
    "fullDate": "1/1/2010"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
```

```
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
}
```

```
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Society_Letter",
  "label": "As Per Society Letter"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "46",
"ageOfBuilding": "14",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "502.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67612f08d56f366c9e04b4d3/
routeMap_1734524145526_Image.png",
    "routeLat": "19.229243",
    "routeLng": "72.825498",
    "stationName": "Borivali",
    "routeDistance": "2.6 Km.",
```



```
"routeStation": {
  "value": "Metro_Station",
  "label": "Metro Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "dh4fk7",
    "name": "dh4fk7",
    "image": "cases/67612f08d56f366c9e04b4d3/
routeMap_1734516751411_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
```

```
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9218000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "9218000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5803820.00",
  "selectedBuildUpValue": "502.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67629f2a31b0132fc58125af",
      "name": "externallmg_1734516521316_externallmg_1734496250830_IMG20241218WA0022.jpg",
      "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521316_external_lmg_1734496250830_IMG20241218WA0022.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "67629f2a31b0132fc58125b0",
      "name": "externallmg_1734516521329_externallmg_1734496250835_IMG20241218WA0023.jpg",
      "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521329_external_lmg_1734496250835_IMG20241218WA0023.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67629f2a31b0132fc58125ae",
      "name": "externallmg_1734516521302_externallmg_1734496250805_IMG20241218WA0021.jpg",
      "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521302_external_lmg_1734496250805_IMG20241218WA0021.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "67629f2a31b0132fc58125b4",
    "name": "externallmg_1734516521383_externallmg_1734496250977_IMG202412
18WA0018.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521383_external
lmg_1734496250977_IMG20241218WA0018.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "67629f191f06b62faf35b42f",
    "name": "Living Room",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504440_external
lmg_1734496235973_IMG20241218WA0001.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67629f191f06b62faf35b430",
    "name": "Living Room",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504445_external
lmg_1734496235978_IMG20241218WA0003.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67629f191f06b62faf35b431",
    "name": "Living Room",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504469_external
lmg_1734496235981_IMG20241218WA0004.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67629f191f06b62faf35b432",
    "name": "Living Room",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504471_external
lmg_1734496235983_IMG20241218WA0005.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "67629f191f06b62faf35b434",
      "name": "Living Room",
      "path": "cases/67612f08d56f366c9e04b4d3/externalImg_1734516504483_external
Img_1734496236009_IMG20241218WA0007.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67629f191f06b62faf35b439",
      "name": "Living Room",
      "path": "cases/67612f08d56f366c9e04b4d3/externalImg_1734516504525_external
Img_1734496250705_IMG20241218WA0012.jpg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20882.00",
    "max": "22028.00"
  },
  "builtUpRateRange": {
    "min": "17402.00",
    "max": "18357.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```

```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "419.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67612f08d56f366c9e04b4d3",
"ownerName": "Shree Sushil Beerappa Uchil",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 204,2Floor,Girai Aditi CHS,Plot no AM-2,RSC-31,Girai-II
Borivali West ",
"remark": "Contact Sujit +91 99200 11182",
"documents": [
  {
    "documentType": {
      "value": "60ae1270aa6d152c1801b3ab",
      "label": "Agreement for Allotment of Flats"
    },
    "inputs": {
      "documentDate": "31/12/2010",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Shri. Anil K. Aggarwal",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Shree Sushil Beerappa Uchil & Smt. Smita Sushil Uchil"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "924044",
    "path": "cases/67612f08d56f366c9e04b4d3/
document_1734422224499_1734422215728_Gorai_Aditi_Registration.pdf",
    "fileName":
"document_1734422224499_1734422215728_Gorai_Aditi_Registration.pdf"
```

```
  },
  {
    "documentType": {
      "label": "Electricity Bill",
      "value": "6077c791395bc80714864a30"
    },
    "inputs": {
      "documentDate": "02/12/2024",
      "number": {
        "value": "CA_No",
        "label": "CA No"
      },
      "CA_No": " 152998893"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "490362",
    "path": "cases/67612f08d56f366c9e04b4d3/
document_1734422252364_1734422250523_152998893_Nov24.pdf",
    "fileName": "document_1734422252364_1734422250523_152998893_Nov24.pdf"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f1",
      "label": "Society Maintenance Bill"
    },
    "inputs": {
      "documentDate": "01/10/2024",
      "remark": " in the name of Mr. Sushil B. Uchil & Smita S. Uchi issued by Gorai Aditi
Co-op. Hsg. Soc. Ltd.",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": " 100"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "397000",
    "path": "cases/67612f08d56f366c9e04b4d3/
document_1734422266150_1734422261152_bill_for_flat_no_204.pdf",
    "fileName": "document_1734422266150_1734422261152_bill_for_flat_no_204.pdf"
  },
  {
    "documentType": {
      "value": "60ae125baa6d152c1801b347",
```

```
    "label": "Society No Objection Letter"
  },
  "inputs": {
    "documentDate": "23/01/2024",
    "remark": " addressed to Collector of Stamps, issued by Gorai Aditi Co-op. Hsg.
Soc. Ltd."
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "639817",
  "path": "cases/67612f08d56f366c9e04b4d3/
document_1734521233180_Society_NOC_Letter.pdf",
  "fileName": "document_1734521233180_Society_NOC_Letter.pdf"
}
],
"caseNumber": "013119",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "717243",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 17 2024 07:58:00 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shree Sushil Beerappa Uchil",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "803766"
  },
  {
    "name": "Smt. Smita Sushil Uchil",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "354293"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "",
  "length1": "9",
  "length2": "0",
  "width": "",
  "width1": "15",
  "width2": "2",
  "totalArea": "136.50",
  "images": [],
  "finalArea": "136.50",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "14.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "11.17",
  "length1": "11",
  "length2": "2",
  "width": "7.50",
  "width1": "7",
```

```
"width2": "6",
"totalArea": "83.75",
"images": [],
"extraAreas": [],
"finalArea": "83.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "99.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "99.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "6.33",
  "width1": "6",
  "width2": "4",
  "totalArea": "25.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
    },
    "id": "5",
    "name": "Toilet",
    "length": "4.00",
    "length1": "4",
    "length2": "00",
    "width": "6.33",
    "width1": "6",
    "width2": "4",
    "totalArea": "25.33",
    "images": [],
    "extraAreas": [],
    "finalArea": "25.33"
  }
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony Area",
      "value": "Dry_Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "7.50",
    "length1": "7",
    "length2": "6",
    "width": "2.25",
    "width1": "2",
    "width2": "3",
    "totalArea": "16.87",
    "images": [],
    "extraAreas": [],
    "finalArea": "16.87",
    "percentageBeforeTotal": "16.87",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
```

```
{
  "typeOfDocument": {
    "value": "60ae1270aa6d152c1801b3ab",
    "label": "Agreement for Allotment of Flats"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "982167",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "419",
  "squareMeterArea": "38.93",
  "docFinalBuiltUp": "502.8",
  "docFinalBuiltUpSquareMeter": "46.716",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "319.00",
      "squareMeterArea": "29.64",
      "expectedRate": "21316.61",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "382.80",
      "squareMeterArea": "35.56",
      "expectedRate": "17763.85",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "6762acc4fe1fd12ff2131720",
  "property": "Gorai II, Borivali West",
  "area": "319",
```



```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "2",
"source": "https://www.99acres.com/",
"expectedPrice": "6800000",
"expectedRate": "21316.61",
"builtUpExpectedRate": "17763.85",
"image": "cases/67612f08d56f366c9e04b4d3/
indicator_1734519636348_Image.png",
"squareMeter": "29.64",
"id": "895759"
},
{
  "carpetArea": {
    "area": "304.17",
    "squareMeterArea": "28.26",
    "expectedRate": "22027.16",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "365.00",
    "squareMeterArea": "33.91",
    "expectedRate": "18356.16",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6762acc4fe1fd12ff2131721",
  "property": "Gorai II, Borivali West",
  "area": "365",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "6700000",
  "expectedRate": "22027.16",
  "builtUpExpectedRate": "6700000",
```

```
"image": "cases/67612f08d56f366c9e04b4d3/
indicator_1734519682225_Image.png",
"squareMeter": "33.91",
"id": "929155"
},
{
  "carpetArea": {
    "area": "359.17",
    "squareMeterArea": "33.37",
    "expectedRate": "20881.48",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "431.00",
    "squareMeterArea": "40.04",
    "expectedRate": "17401.39",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6762acc4fe1fd12ff2131722",
  "property": "Gorai II, Borivali West",
  "area": "431",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "Ground",
  "source": "Index_no.2",
  "expectedPrice": "7500000",
  "expectedRate": "20881.48",
  "builtUpExpectedRate": "7500000",
  "image": "cases/67612f08d56f366c9e04b4d3/
indicator_1734519756486_Image.png",
  "squareMeter": "40.04",
  "id": "659741"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67624ffb1bf19fae9789ae03",
    "name": "externalImg_1734496250907_IMG20241218WA0026.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/
externalImg_1734496250907_IMG20241218WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67624ffb1bf19fae9789ae04",
    "name": "externalImg_1734496250910_IMG20241218WA0027.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/
externalImg_1734496250910_IMG20241218WA0027.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67624ffb1bf19fae9789ae05",
    "name": "externalImg_1734496250934_IMG20241218WA0028.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/
externalImg_1734496250934_IMG20241218WA0028.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b42f",
    "name": "externalImg_1734516504440_externalImg_1734496235973_IMG2024121
8WA0001.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externalImg_1734516504440_externalI
mg_1734496235973_IMG20241218WA0001.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b430",
    "name": "externalImg_1734516504445_externalImg_1734496235978_IMG2024121
8WA0003.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externalImg_1734516504445_externalI
mg_1734496235978_IMG20241218WA0003.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b431",
    "name": "externallmg_1734516504469_externallmg_1734496235981_IMG20241218WA0004.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504469_externallmg_1734496235981_IMG20241218WA0004.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b432",
    "name": "externallmg_1734516504471_externallmg_1734496235983_IMG20241218WA0005.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504471_externallmg_1734496235983_IMG20241218WA0005.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b433",
    "name": "externallmg_1734516504475_externallmg_1734496235999_IMG20241218WA0006.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504475_externallmg_1734496235999_IMG20241218WA0006.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b434",
    "name": "externallmg_1734516504483_externallmg_1734496236009_IMG20241218WA0007.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504483_externallmg_1734496236009_IMG20241218WA0007.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b435",
    "name": "externallmg_1734516504508_externallmg_1734496236012_IMG20241218WA0008.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504508_externall
```

```
mg_1734496236012_IMG20241218WA0008.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f191f06b62faf35b436",
  "name": "externallmg_1734516504510_externallmg_1734496236030_IMG20241218WA0009.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504510_externallmg_1734496236030_IMG20241218WA0009.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f191f06b62faf35b437",
  "name": "externallmg_1734516504513_externallmg_1734496236056_IMG20241218WA0010.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504513_externallmg_1734496236056_IMG20241218WA0010.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f191f06b62faf35b438",
  "name": "externallmg_1734516504522_externallmg_1734496236059_IMG20241218WA0011.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504522_externallmg_1734496236059_IMG20241218WA0011.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f191f06b62faf35b439",
  "name": "externallmg_1734516504525_externallmg_1734496250705_IMG20241218WA0012.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516504525_externallmg_1734496250705_IMG20241218WA0012.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67629f191f06b62faf35b43a",
    "name": "externalimg_1734516504545_externalimg_1734496250710_IMG20241218WA0013.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externalimg_1734516504545_externalimg_1734496250710_IMG20241218WA0013.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b43b",
    "name": "externalimg_1734516504552_externalimg_1734496250713_IMG20241218WA0014.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externalimg_1734516504552_externalimg_1734496250713_IMG20241218WA0014.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f191f06b62faf35b43c",
    "name": "externalimg_1734516504557_externalimg_1734496250750_IMG20241218WA0015.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externalimg_1734516504557_externalimg_1734496250750_IMG20241218WA0015.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f2a31b0132fc58125aa",
    "name": "externalimg_1734516521261_externalimg_1734496250756_IMG20241218WA0016.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externalimg_1734516521261_externalimg_1734496250756_IMG20241218WA0016.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f2a31b0132fc58125ab",
    "name": "externalimg_1734516521267_externalimg_1734496250776_IMG20241218WA0017.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externalimg_1734516521267_externalimg_1734496250776_IMG20241218WA0017.jpg",
    "orientation": "portrait"
  }
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f2a31b0132fc58125ac",
    "name": "externallmg_1734516521278_externallmg_1734496250779_IMG20241218WA0019.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521278_externallmg_1734496250779_IMG20241218WA0019.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f2a31b0132fc58125ad",
    "name": "externallmg_1734516521297_externallmg_1734496250800_IMG20241218WA0020.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521297_externallmg_1734496250800_IMG20241218WA0020.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f2a31b0132fc58125ae",
    "name": "externallmg_1734516521302_externallmg_1734496250805_IMG20241218WA0021.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521302_externallmg_1734496250805_IMG20241218WA0021.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f2a31b0132fc58125af",
    "name": "externallmg_1734516521316_externallmg_1734496250830_IMG20241218WA0022.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521316_externallmg_1734496250830_IMG20241218WA0022.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67629f2a31b0132fc58125b0",
    "name": "externallmg_1734516521329_externallmg_1734496250835_IMG20241218WA0023.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521329_externallmg_1734496250835_IMG20241218WA0023.jpg",
    "orientation": "portrait"
  }
}
```

```
8WA0023.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521329_externallmg_1734496250835_IMG20241218WA0023.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f2a31b0132fc58125b1",
  "name": "externallmg_1734516521345_externallmg_1734496250869_IMG20241218WA0024.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521345_externallmg_1734496250869_IMG20241218WA0024.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f2a31b0132fc58125b2",
  "name": "externallmg_1734516521361_externallmg_1734496250885_IMG20241218WA0025.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521361_externallmg_1734496250885_IMG20241218WA0025.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f2a31b0132fc58125b3",
  "name": "externallmg_1734516521370_externallmg_1734496250939_IMG20241218WA0002.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521370_externallmg_1734496250939_IMG20241218WA0002.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67629f2a31b0132fc58125b4",
  "name": "externallmg_1734516521383_externallmg_1734496250977_IMG20241218WA0018.jpg",
  "path": "cases/67612f08d56f366c9e04b4d3/externallmg_1734516521383_externallmg_1734496250977_IMG20241218WA0018.jpg",
  "orientation": "portrait"
}
],
```



```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr_14247.pdf",
    "filename": "1734519987942_igr_14247.pdf",
    "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734519987942_igr_14247.pdf",
    "size": "152136",
    "createdAt": "Wed Dec 18 2024 11:06:28 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1721630584916-12.xlsx",
    "filename": "1734519987959_172163058491612.xlsx",
    "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734519987959_172163058491612.xlsx",
    "size": "1015768",
    "createdAt": "Wed Dec 18 2024 11:06:28 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_9191.pdf",
    "filename": "1734519988072_igr_9191.pdf",
    "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734519988072_igr_9191.pdf",
    "size": "153564",
    "createdAt": "Wed Dec 18 2024 11:06:28 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Electricity Bill.pdf",
    "filename": "1734522104643_Electricity_Bill.pdf",
    "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734522104643_Electricity_Bill.pdf",
    "size": "353904",
    "createdAt": "Wed Dec 18 2024 11:41:45 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Google Location.jpg",
    "filename": "1734522104673_Google_Location.jpg",
    "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734522104673_Google_Location.jpg",
    "size": "182333",
    "createdAt": "Wed Dec 18 2024 11:41:45 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
]
```

```
    },
    {
      "originalname": "Maintenance Bill.pdf",
      "filename": "1734522104704_Maintenance_Bill.pdf",
      "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734522104704_Maintenance_Bill.pdf",
      "size": "10928",
      "createdAt": "Wed Dec 18 2024 11:41:45 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Sale Deed - 2010.pdf",
      "filename": "1734522104706_Sale_Deed__2010.pdf",
      "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734522104706_Sale_Deed__2010.pdf",
      "size": "8814281",
      "createdAt": "Wed Dec 18 2024 11:41:45 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Site Details.jpg",
      "filename": "1734522105360_Site_Details.jpg",
      "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734522105360_Site_Details.jpg",
      "size": "260133",
      "createdAt": "Wed Dec 18 2024 11:41:45 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Sketch & Dimension.jpg",
      "filename": "1734522105613_Sketch__Dimension.jpg",
      "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734522105613_Sketch__Dimension.jpg",
      "size": "87457",
      "createdAt": "Wed Dec 18 2024 11:41:45 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Society NOC Letter.pdf",
      "filename": "1734522105618_Society_NOC_Letter.pdf",
      "path": "cases/67612f08d56f366c9e04b4d3/
processingDocuments/1734522105618_Society_NOC_Letter.pdf",
      "size": "493467",
      "createdAt": "Wed Dec 18 2024 11:41:45 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    }
  }
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-17T07:58:00.553Z",
"updatedAt": "2024-12-18T12:15:45.863Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 204, 2nd Floor, Gorai Aditi Co-op. Hsg. Soc. Ltd.,
Plot No. AM-2, Sector RSC 31, RSC-31, Gorai - II, Village - Borivali, Taluka - Borivali,
District - Mumbai Suburban, Borivali (West), Mumbai, PIN - 400 091, State -
Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Sushil Beerappa Uchil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"reald": "",
"siteVisitContactNo": "9920011182",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Dining + 2 Toilet",
"carpetTotal": "384.24",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "16.87",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "16.87",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 400.00\nExternal Service Area in
Sq. Ft. = 19.00\n",
"finalBuiltupArea": "481.33",
"finalCarpetArea": "401.11",
"finalSalableArea": "481.33",
"salablePercentage": "0",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 384.24\nDry Balcony Area in
Sq. Ft. = 16.87\n<br />\n",
"toBeAdded": "",
"buildingServicesRate": "2800",
```

```

"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for Allotment of Flats",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 419.00",
"flatRate": "22000",
"landOtherRate": "19200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Wed Dec 18 2024 11:08:08 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-17",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'0"	15'2"	136.50
Dining	3'7"	4'00"	14.33
Kitchen	11'2"	7'6"	83.75
Bedroom	9'00"	11'00"	99.00

Toilet	4'00"	6'4"	25.33
Toilet	4'00"	6'4"	25.33
Other Composition :			
Dry Balcony Area	7'6"	2'3"	16.87