

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "firstName": "Priti",
    "type": "CREDITOFFICER",
    "_id": "668915a4a403df7f574f391b",
    "email": "preeti.shinde@cosmosbank.in",
    "lastName": "Shinde",
    "mobileNo": "",
    "workMobileNo": "9773082894"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "000",
    "discussWithPerson": "Priti",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/64abdb2806d6ec174986d16b/
profilePhoto_1731563513029_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "663da98cfcea71232186f142",
  "role": "ACCOUNTANT",
  "firstName": "SONAL ",
```

```
"email": "sonal.ambekar19@gmail.com",
"lastName": " SHIVGAN",
"mobileNo": "9773395869",
"designation": "",
"shortName": "SONAL",
"workWithDocumentMaker": "",
"profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": {
  "_id": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg",
  "firstName": "Shyam",
  "lastName": "Kajvilkar",
  "shortName": "SK",
  "email": "shyam@vastukala.org",
  "designation": "",
  "mobileNo": "9765074720",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.36286411337631",
  "longitude": "72.80392493020162"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.80392493020162,
19.36286411337631
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-19",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "Single_Unit",
  "label": "Single Unit"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Sandor",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Dattani Prism - I (I.T. Park Building)",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "281, 282, 283A & 284A",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "252A, 255A & 256",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "2/1, 3, 4, 5, 10/1 & 11",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "218",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401202",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Window_",
    "label": "Aluminium Sliding Window "
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Vasai_Virar_City_Municipal_Corporation",
  "label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road & Dattani Linear Building",
  "west": "Open Plot",
  "south": "Open Plot",
  "east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Property of Promoters",
  "south": "The Land of E. S. Andrandes & Co. ",
  "east": "Main Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Unit No. 201",
    "east": "Marginal Space",
    "south": "Unit No. 217",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Unit No. 219",
    "east": "Unit No. 217",
    "south": "No Unit",
    "west": "No Unit"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
```

```
"buses": {
  "title": "Buses",
  "status": true
},
"taxies": {
  "title": "Taxies",
  "status": true
},
"auto": {
  "title": "Auto",
  "status": true
},
"privateCars": {
  "title": "Private Cars",
  "status": true
}
},
"extraDetailOfProperty": "The Composition of Commercial Property is Vacant Unit +
Toilet Block",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it is assumed that
the construction is as per Sanctioned Plan",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "ordinary",
  "label": "Ordinary"
},
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Commercial Office",
  "rate": "56600",
```

```
"landRate": "8880",
"igrImage": "cases/67628e77fe1fd12ff212f47a/igr_1735194265558_Image.png",
"squareMeterGuideLineRate": "56600.00",
"squareFeetGuideLineRate": "5258.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "95",
  "rate": "5037.00",
  "squareFeetGuideLineRate": "5037.00",
  "squareMeterGuideLineRate": "54214.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Industrial",
    "label": "Industrial"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "Information not available",
  "tenantName": "",
  "maintenanceOfFlat": "Information not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2020",
"fullDate": "1/1/2020"
},
"planningArea": {
"value": "Commercial",
"label": "Commercial"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
}
```

```
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
```



```
"label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "56",
"ageOfBuilding": "4",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "2",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "18"
},
"finalPlinthArea": {
  "area": "1089.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67628e77fe1fd12ff212f47a/
routeMap_1735201877305_Image.png",
    "routeLat": "19.359416",
    "routeLng": "72.811308",
    "stationName": "Vasai ",
    "routeDistance": "3.6",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "c1rnie",
    "name": "c1rnie",
    "image": "cases/67628e77fe1fd12ff212f47a/
routeMap_1735201791919_Image.jpeg"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "2722500.00",
    "depreciationPercentage": "0",
    "depreciatedCostOfConstruction": "0.00",
    "totalFairMarketValue": "9207000.00"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9207000.00",
"finalValue": "9207000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "5485293.00",
  "selectedBuildUpValue": "1089.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6764f7be31b0132fc58298b2",
      "name":
"externallmg_1734670270056_WhatsApp_Image_20241219_at_72013_PM.jpeg",
      "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270056_WhatsApp_Image_20241219_at_72013_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6764f7be31b0132fc58298b3",
      "name":
"externallmg_1734670270120_WhatsApp_Image_20241219_at_72014_PM_1.jpeg",
      "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270120_WhatsApp_Image_20241219_at_72014_PM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6764f7be31b0132fc58298b6",
      "name":
"externallmg_1734670270232_WhatsApp_Image_20241219_at_72015_PM.jpeg",
      "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270232_WhatsApp_Image_20241219_at_72015_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6764f7be31b0132fc58298b8",
      "name":
"externallmg_1734670270315_WhatsApp_Image_20241219_at_72016_PM.jpeg",
      "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270315_WhatsApp_Image_20241219_at_72016_PM.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "6764f7be31b0132fc58298bc",
      "name":
"externallmg_1734670270453_WhatsApp_Image_20241219_at_72018_PM.jpeg",
      "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270453_WhatsApp_Image_20241219_at_72018_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6764f7be31b0132fc58298be",
      "name":
"externallmg_1734670270515_WhatsApp_Image_20241219_at_72019_PM.jpeg",
      "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270515_WhatsApp_Image_20241219_at_72019_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6764f7be31b0132fc58298b2",
      "name":
"externallmg_1734670270056_WhatsApp_Image_20241219_at_72013_PM.jpeg",
      "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270056_WhatsApp_Image_20241219_at_72013_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8542.00",
    "max": "11105.00"
  },
  "builtUpRateRange": {
    "min": "7766.00",
    "max": "10096.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```

```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "990.00",
"empanelmentNo": [
  "HO/Credit/87/2022-23"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67628e77fe1fd12ff212f47a",
"ownerName": "Mr. Maqbool Ahmed Shaikh",
"ownerPhoneNo": "8424015476",
"appAddress": "unit no.218 2nd floor, Dattani plaza, at Sandor tal Vasai dist. Palghar ",
"remark": "urgent ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/08/2018",
      "amount": "6119700",
      "from": {
```

```
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Dattani Estate Developers ",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Maqbool Ahmed Shaikh",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "8141/2018"
},
"isHardCopy": false,
"displayStatus": true,
"fileName":
"document_1735197415764_Agreement_for_sale__Maqbool_Ahmed_Shaikh.pdf",
"path": "cases/67628e77fe1fd12ff212f47a/
document_1735197415764_Agreement_for_sale__Maqbool_Ahmed_Shaikh.pdf",
"id": "506499",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Thu Dec 26 2024 07:16:57 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "22/04/2010",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO/VVSR/CC/BP-736/W/170"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1735198088908_Commencement_Certificate_2010.pdf",
  "path": "cases/67628e77fe1fd12ff212f47a/
document_1735198088908_Commencement_Certificate_2010.pdf",
```

```
"id": "341320",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Thu Dec 26 2024 07:28:09 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "03/11/2020",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "VVCMC/TP/POC/VP-0762/30/2020-21"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "774616",
  "path": "cases/67628e77fe1fd12ff212f47a/
document_1735198194132_Occupancy_Certificate_2020.pdf",
  "fileName": "document_1735198194132_Occupancy_Certificate_2020.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "19/08/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P99000008471"
  },
  "isHardCopy": false,
```

```
    "displayStatus": true,
    "fileName": "document_1735206937590_RERA_Certificate.pdf",
    "path": "cases/67628e77fe1fd12ff212f47a/
document_1735206937590_RERA_Certificate.pdf",
    "id": "622468",
    "uploadedBy": "663da98cfcea71232186f142",
    "createdAt": "Thu Dec 26 2024 09:55:37 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013152",
"createdBy": "64abdb2806d6ec174986d16b",
"caseHistory": [
  {
    "id": "730966",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Dec 18 2024 08:57:27 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Maqbool Ahmed Shaikh",
    "phone": "8424015476",
    "ownershipShare": "",
    "email": "",
    "id": "126307"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "951730",
    "name": "Unit",
    "length": "33.00",
    "length1": "33",
    "length2": "0",
    "width": "30.00",
    "width1": "30",
    "width2": "00",
    "totalArea": "990.00",
    "images": [],
```

```
"extraAreas": [],
"finalArea": "990.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Toilet",
  "length": "5.25",
  "length1": "5",
  "length2": "3",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "27.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.12"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "720673",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "990",
    "squareMeterArea": "91.97",
    "docFinalBuiltUp": "1089",
    "docFinalBuiltUpSquareMeter": "101.167",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "1089",
    "docFinalSaleable": "12948.21",
    "docFinalSaleableSquareMeter": "1202.87563"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "1080.00",
      "squareMeterArea": "100.34",
      "expectedRate": "8541.67",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1188.00",
      "squareMeterArea": "110.37",
      "expectedRate": "7765.15",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "0.00",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "676cf69faa045e9e9382bf1b",
    "property": "Commercial Unit",
    "area": "1188",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "9225000",
    "expectedRate": "8541.67",
    "builtUpExpectedRate": "9225000",
    "image": "cases/67628e77fe1fd12ff212f47a/indicator_1735193922462_Image.png",
    "squareMeter": "110.37",
    "id": "698984"
  },
  {
    "carpetArea": {
      "area": "503.00",
      "squareMeterArea": "46.73",
      "expectedRate": "8946.32",
      "percentage": ""
    },
    "builtUpArea": {
```

```
"area": "553.30",
"squareMeterArea": "51.40",
"expectedRate": "8133.02",
"percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "676cf69faa045e9e9382bf1c",
"property": "Commercial Unit",
"area": "503",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4500000",
"expectedRate": "8946.32",
"builtUpExpectedRate": "8133.02",
"image": "cases/67628e77fe1fd12ff212f47a/indicator_1735194108977_Image.png",
"squareMeter": "46.73",
"id": "869240"
},
{
  "carpetArea": {
    "area": "400.00",
    "squareMeterArea": "37.16",
    "expectedRate": "10000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "440.00",
    "squareMeterArea": "40.88",
    "expectedRate": "9090.91",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```



```
},
"printlnReport": true,
"_id": "676cf69faa045e9e9382bf1d",
"property": "Commercial Unit",
"area": "400",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "4000000",
"expectedRate": "10000.00",
"builtUpExpectedRate": "9090.91",
"image": "cases/67628e77fe1fd12ff212f47a/indicator_1735194131845_Image.png",
"squareMeter": "37.16",
"id": "957842"
},
{
"carpetArea": {
"area": "477.27",
"squareMeterArea": "44.34",
"expectedRate": "11104.83",
"percentage": ""
},
"builtUpArea": {
"area": "525.00",
"squareMeterArea": "48.77",
"expectedRate": "10095.24",
"percentage": "10"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "676cf69faa045e9e9382bf1e",
"property": "Commercial Unit",
"area": "525",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
```

```
"source": "Nobroker.com",
"expectedPrice": "5300000",
"expectedRate": "11104.83",
"builtUpExpectedRate": "5300000",
"image": "cases/67628e77fe1fd12ff212f47a/indicator_1735194155673_Image.png",
"squareMeter": "48.77",
"id": "870957"
}
],
"externallImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6764f7be31b0132fc58298ac",
"name":
"externallmg_1734670269829_WhatsApp_Image_20241219_at_72004_PM.jpeg",
"path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670269829_WhatsApp_Image_20241219_at_72004_PM.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6764f7be31b0132fc58298ad",
"name":
"externallmg_1734670269835_WhatsApp_Image_20241219_at_72005_PM.jpeg",
"path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670269835_WhatsApp_Image_20241219_at_72005_PM.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6764f7be31b0132fc58298ae",
"name":
"externallmg_1734670269864_WhatsApp_Image_20241219_at_72006_PM.jpeg",
"path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670269864_WhatsApp_Image_20241219_at_72006_PM.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6764f7be31b0132fc58298af",
"name":
"externallmg_1734670269901_WhatsApp_Image_20241219_at_72007_PM.jpeg",
```

```
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670269901_WhatsApp_Image_20241219_at_72007_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b0",
    "name":
"externallmg_1734670269958_WhatsApp_Image_20241219_at_72012_PM.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670269958_WhatsApp_Image_20241219_at_72012_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b1",
    "name":
"externallmg_1734670270012_WhatsApp_Image_20241219_at_72013_PM_1.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270012_WhatsApp_Image_20241219_at_72013_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b2",
    "name":
"externallmg_1734670270056_WhatsApp_Image_20241219_at_72013_PM.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270056_WhatsApp_Image_20241219_at_72013_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b3",
    "name":
"externallmg_1734670270120_WhatsApp_Image_20241219_at_72014_PM_1.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270120_WhatsApp_Image_20241219_at_72014_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6764f7be31b0132fc58298b4",
    "name":
"externallmg_1734670270156_WhatsApp_Image_20241219_at_72014_PM.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270156_WhatsApp_Image_20241219_at_72014_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b5",
    "name":
"externallmg_1734670270193_WhatsApp_Image_20241219_at_72015_PM_1.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270193_WhatsApp_Image_20241219_at_72015_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b6",
    "name":
"externallmg_1734670270232_WhatsApp_Image_20241219_at_72015_PM.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270232_WhatsApp_Image_20241219_at_72015_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b7",
    "name":
"externallmg_1734670270265_WhatsApp_Image_20241219_at_72016_PM_1.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270265_WhatsApp_Image_20241219_at_72016_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b8",
    "name":
"externallmg_1734670270315_WhatsApp_Image_20241219_at_72016_PM.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270315_WhatsApp_Image_20241219_at_72016_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298b9",
    "name":
"externallmg_1734670270340_WhatsApp_Image_20241219_at_72017_PM_1.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270340_WhatsApp_Image_20241219_at_72017_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298ba",
    "name":
"externallmg_1734670270365_WhatsApp_Image_20241219_at_72017_PM.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270365_WhatsApp_Image_20241219_at_72017_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298bb",
    "name":
"externallmg_1734670270416_WhatsApp_Image_20241219_at_72018_PM_1.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270416_WhatsApp_Image_20241219_at_72018_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298bc",
    "name":
"externallmg_1734670270453_WhatsApp_Image_20241219_at_72018_PM.jpeg",
    "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270453_WhatsApp_Image_20241219_at_72018_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764f7be31b0132fc58298bd",
```

```
    "name":
"externallmg_1734670270486_WhatsApp_Image_20241219_at_72019_PM_1.jpeg",
  "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270486_WhatsApp_Image_20241219_at_72019_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6764f7be31b0132fc58298be",
  "name":
"externallmg_1734670270515_WhatsApp_Image_20241219_at_72019_PM.jpeg",
  "path": "cases/67628e77fe1fd12ff212f47a/
externallmg_1734670270515_WhatsApp_Image_20241219_at_72019_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "AGR-218.pdf",
  "filename": "1735194289021_AGR218.pdf",
  "path": "cases/67628e77fe1fd12ff212f47a/
processingDocuments/1735194289021_AGR218.pdf",
  "size": "19151332",
  "createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
"externallmg_1734670269829_WhatsApp_Image_20241219_at_72004_PM.jpeg",
  "filename": "1735194290925_externallmg_1734670269829_WhatsApp_Image_202
41219_at_72004_PM.jpeg",
  "path": "cases/67628e77fe1fd12ff212f47a/processingDocuments/1735194290925_e
xternallmg_1734670269829_WhatsApp_Image_20241219_at_72004_PM.jpeg",
  "size": "62943",
  "createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
"externallmg_1734670269835_WhatsApp_Image_20241219_at_72005_PM.jpeg",
  "filename": "1735194291002_externallmg_1734670269835_WhatsApp_Image_202
41219_at_72005_PM.jpeg",
  "path": "cases/67628e77fe1fd12ff212f47a/processingDocuments/1735194291002_e
xternallmg_1734670269835_WhatsApp_Image_20241219_at_72005_PM.jpeg",
```

```
"size": "101584",
"createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
"externallmg_1734670269864_WhatsApp_Image_20241219_at_72006_PM.jpeg",
  "filename": "1735194291007_externallmg_1734670269864_WhatsApp_Image_20241219_at_72006_PM.jpeg",
  "path": "cases/67628e77fe1fd12ff212f47a/processingDocuments/1735194291007_externallmg_1734670269864_WhatsApp_Image_20241219_at_72006_PM.jpeg",
  "size": "127466",
  "createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1735194291019_IGR01.pdf",
  "path": "cases/67628e77fe1fd12ff212f47a/processingDocuments/1735194291019_IGR01.pdf",
  "size": "130208",
  "createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1735194291032_IGR02.pdf",
  "path": "cases/67628e77fe1fd12ff212f47a/processingDocuments/1735194291032_IGR02.pdf",
  "size": "129245",
  "createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1735194291045_IGR03.pdf",
  "path": "cases/67628e77fe1fd12ff212f47a/processingDocuments/1735194291045_IGR03.pdf",
  "size": "136807",
  "createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1735194291067_IGR04.pdf",
  "path": "cases/67628e77fe1fd12ff212f47a/processingDocuments/1735194291067_IGR04.pdf",
```

```
"size": "131816",
"createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=UNIT NO. 218.xlsx",
"filename": "1735194291073_Summary_NewUNIT_NO_218.xlsx",
"path": "cases/67628e77fe1fd12ff212f47a/
processingDocuments/1735194291073_Summary_NewUNIT_NO_218.xlsx",
"size": "1829552",
"createdAt": "Thu Dec 26 2024 06:24:51 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"lastName": "Kajvilkar",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "67695606fe1fd12ff2161988",
"note": "Pending for value confirmation ",
"taskId": "6762b0231f06b62faf35cca4",
"createdAt": "2024-12-23T12:22:30.037Z"
}
],
"createdAt": "2024-12-18T08:57:27.917Z",
"updatedAt": "2024-12-26T10:19:37.625Z",
"__v": 0,
"assignmentType": {
"value": "Commercial",
"label": "Commercial"
},
"fullAddress": "Commercial Unit No. 218, 2nd Floor, Dattani Prism - I (I.T. Park
Building), Old Survey No. 281, 282, 283A & 284A, New/Current Survey No. 252A, 255A
& 256, Hissa No. 2/1, 3, 4, 5, 10/1 & 11, Village - Sandor, Taluka - Vasai, District -
Palghar, Vasai (West), 401202, State - Maharashtra, India",
```



```
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Ashok Pujara",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Relative",
"rerald": "",
"siteVisitContactNo": "9834356366",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 990.00",
"flatRate": "9300",
"landOtherRate": "6800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "Unit + Toilet",
"carpetTotal": "1017.12",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1118.83",
"finalCarpetArea": "1017.12",
"finalSalableArea": "1230.72",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "1089",
"reportGeneratedDate": "Thu Dec 26 2024 06:49:09 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-19",
"landDetails": {
```

```

"holdType": {
  "label": "Free Hold",
  "value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Unit	33'0"	30'00"	990.00
Toilet	5'3"	5'2"	27.12
Other Composition :			