

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Ashish",
    "type": "CREDITOFFICER",
    "_id": "66f3bd047d6d262b2ba806c1",
    "email": "ashish.bhabad@sbi.co.in",
    "lastName": "Bhabad",
    "mobileNo": "",
    "workMobileNo": "7709815152"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4500000",
    "discussWithPerson": "Ashish",
    "expectedFees": 2250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
```

```
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.471359208621948",
  "longitude": "72.81280473164125"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81280473164125,
    19.471359208621948
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "19/12/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
```

```
    "status": "COMPLETED",
    "dateTime": "2024-12-19",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-12-19",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-12-19",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Naringi",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Virar (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mrida Homes Hasha Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Naringi Bypass Road, Beside Foothill",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```



```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "17",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "231/2, 7, 8, 9 & 10",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "411",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 305",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tile_flooring",
    "label": "Vitrified tile flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Vasai_Virar_City_Municipal_Corporation",
"label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Shivkrupa Complex",
"west": "Naringi Bypass Road",
"south": "Dadu Smriti Building",
"east": "Kaashi Apartment"
},
"asPerDocumentAgreement": {
"north": "Shivcharan Building (As per RERA)",
"west": "D P Road (As per RERA)",
"south": "Survey No. 231/3 (As per RERA)",
"east": "Kaashi Apartment (As per RERA)"
},
"unitBoundaries": {
"asPerActual": {
"north": " Passage & Staircase ",
"east": "Flat No. 410",
"south": "Flat No. 412",
"west": "Marginal Space"
},
"asPerDocument": {
"north": " Passage & Staircase ",
"east": "Flat No. 410",
"south": "Marginal Space",
"west": "Flat No. 412"
},
"setDisplay": true,
"title": "Boundaries of The Flat"
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "+ Flowerbed + Dry Balcony Area.",
"dateOfIssusApprovePlan": "Approved Building Plan No. VVCMC/TP/RDP/AMEND/
VP-5692/519/2022-23 dated 21.02.2023 issued by Vasai Virar City Municipal
Corporation.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "11000.00",
  "depreciatedBuildingRate": "2500"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "44800",
  "landRate": "9310",
  "igrImage": "cases/6763e6ca31b0132fc582109e/igr_1734758837144_Image.png",
  "squareMeterGuideLineRate": "44800.00",
  "squareFeetGuideLineRate": "4162.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "44800.00",
  "squareMeterGuideLineRate": "44800.00",
  "squareFeetGuideLineRate": "4162.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Vacant flat in normal condition"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
```

```
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered Parking Pace",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
```

```
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "New_Building",
"label": "New Building"
},
"maintenancelssues": {
"value": "New_Building",
"label": "New Building"
},
"visibleDamageInBuilding": {
"value": "New_Building",
"label": "New Building"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
}
```



```
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "15",
"flatFloorNo": "4",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "14"
},
"finalPlinthArea": {
  "area": "350.90",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6763e6ca31b0132fc582109e/
routeMap_1734760596258_Image.png",
    "routeLat": "19.471465",
    "routeLng": "72.813150",
    "stationName": "Virar",
    "routeDistance": "3.5 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
}
```

```
},
"locationMapImg": [
  {
    "id": "js8zo",
    "name": "js8zo",
    "image": "cases/6763e6ca31b0132fc582109e/
routeMap_1734760518683_Image.png"
  }
],
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3509000.00",
  "distressValuePercentage": "80",
```

```
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "3509000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1460446.00",
  "selectedBuildUpValue": "350.90",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e903",
    "name": "externallmg_1734759622905_externallmg_1734666066866_WhatsApp_I
mage_20241220_at_003921.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622905_extern
lmg_1734666066866_WhatsApp_Image_20241220_at_003921.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6766552bfe1fd12ff214e9c7",
    "name": "externallmg_1734759722735_1.jpg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759722735_1.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e901",
    "name": "externallmg_1734759622880_externallmg_1734666054270_WhatsApp_I
mage_20241220_at_003919_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622880_extern
lmg_1734666054270_WhatsApp_Image_20241220_at_003919_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e902",
    "name": "externallmg_1734759622887_externallmg_1734666054295_WhatsApp_I
mage_20241220_at_003921_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622887_extern
lmg_1734666054295_WhatsApp_Image_20241220_at_003921_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6766557a1f06b62faf3796cf",
    "name": "externallmg_1734759801621_externallmg_1734666067066_WhatsApp_I
```

```
mage_20241220_at_003936_1.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/externalImg_1734759801621_external
Img_1734666067066_WhatsApp_Image_20241220_at_003936_1.jpeg",
  "orientation": "portrait"
}
],
"compositionImages": [
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e906",
    "name": "Living Room",
    "path": "cases/6763e6ca31b0132fc582109e/externalImg_1734759622947_external
Img_1734666066935_WhatsApp_Image_20241220_at_003925.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e908",
    "name": "Living Room",
    "path": "cases/6763e6ca31b0132fc582109e/externalImg_1734759622968_external
Img_1734666066949_WhatsApp_Image_20241220_at_003929_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e909",
    "name": "Living Room",
    "path": "cases/6763e6ca31b0132fc582109e/externalImg_1734759622984_external
Img_1734666066971_WhatsApp_Image_20241220_at_003929.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e90b",
    "name": "Living Room",
    "path": "cases/6763e6ca31b0132fc582109e/externalImg_1734759623002_external
Img_1734666066997_WhatsApp_Image_20241220_at_003930.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676654c7fe1fd12ff214e90e",
    "name": "Living Room",
    "path": "cases/6763e6ca31b0132fc582109e/externalImg_1734759623047_external
Img_1734666067038_WhatsApp_Image_20241220_at_003935_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9910.00",
    "max": "15334.00"
  },
  "builtUpRateRange": {
    "min": "9009.00",
    "max": "13940.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "319.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
```

```
"paymentIds": [],
"_id": "6763e6ca31b0132fc582109e",
"ownerName": "Mr. Tushar Baban Humane",
"ownerPhoneNo": "9158511322",
"appAddress": "FLAT NO 411 4TH FLOOR MIRDA HOMES HANSA HEIGHTS
NARANGI ROAD VIRAR EAST PALGHAR 401305",
"remark": "Sourcing person Ashish Bhabad 7709815152",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "11/12/2024",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Maheshwar Hasha Patil",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Tushar Baban Humane & Mrs. Tanvi Tushar Humane",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": " 26345/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "948156",
    "path": "cases/6763e6ca31b0132fc582109e/document_1734600320793_17346003
17541_TUSHAR_HUMANE__AGREEMENT.pdf",
    "fileName": "document_1734600320793_1734600317541_TUSHAR_HUMANE__A
GREEMENT.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "17/10/2024",
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": " P99000026476"
},
"isHardCopy": false,
"displayStatus": false,
"id": "372700",
"path": "cases/6763e6ca31b0132fc582109e/
document_1734764052232_P99000026476.pdf",
"fileName": "document_1734764052232_P99000026476.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/02/2023",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " VVCMC/TP/RDP/VP-5692/517/2022-23"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "254504",
  "path": "cases/6763e6ca31b0132fc582109e/document_1734764428878_6_Comme
ncement_Certificates___NA_Order_for_plotted_development.pdf",
  "fileName": "document_1734764428878_6_Commencement_Certificates___NA_Or
der_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "21/02/2023",
    "nameOfApprovingAuthority": {
```

```
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": " VVCMC/TP/RDP/AMEND/VP-5692/519/2022-23"
},
"isHardCopy": false,
"displayStatus": false,
"id": "200308",
"path": "cases/6763e6ca31b0132fc582109e/document_1734765566614_7_Building
_Plan_Approval___NA_Order_for_plotted_development.pdf",
"fileName": "document_1734765566614_7_Building_Plan_Approval___NA_Order_f
or_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "26/04/2024",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " VVCMC/PO/2024/APL/00016"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "107521",
  "path": "cases/6763e6ca31b0132fc582109e/document_1734765877312_1_Occupa
ncy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plot
ted_development.pdf",
  "fileName": "document_1734765877312_1_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development.pdf"
}
],
"caseNumber": "013197",
"createdBy": "659ccce98f39506e83489828",
```

```
"caseHistory": [
  {
    "id": "909787",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 19 2024 09:26:34 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Tushar Baban Humane",
    "phone": "9158511322",
    "ownershipShare": "",
    "email": "",
    "id": "849518"
  },
  {
    "name": "Mrs. Tanvi Tushar Humane",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "120408"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "825297",
    "name": "Passage",
    "length": "3.58",
    "length1": "3",
    "length2": "7",
    "width": "3.17",
    "width1": "3",
    "width2": "2",
    "totalArea": "11.35",
    "images": [],
    "extraAreas": [],
    "finalArea": "11.35"
  },
  {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"name": "Living Room",
"length": "8.67",
"length1": "8",
"length2": "8",
"width": "13.08",
"width1": "13",
"width2": "1",
"totalArea": "113.39",
"images": [],
"extraAreas": [],
"finalArea": "113.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "5.92",
  "length1": "5",
  "length2": "11",
  "width": "7.67",
  "width1": "7",
  "width2": "8",
  "totalArea": "45.36",
  "images": [],
  "extraAreas": [],
  "finalArea": "45.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "2.25",
```

```
"width1": "2",
"width2": "3",
"totalArea": "6.94",
"images": [],
"extraAreas": [],
"finalArea": "6.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "5.58",
  "width1": "5",
  "width2": "7",
  "totalArea": "21.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "7.92",
  "length1": "7",
  "length2": "11",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "74.55",
  "images": [],
  "extraAreas": [],
  "finalArea": "74.55"
},
{
  "measurementType": {
    "value": "Square_Feet",
```



```
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "4.75",
  "width1": "4",
  "width2": "9",
  "totalArea": "18.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.60"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony Area",
      "value": "Dry_Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "2.00",
    "length1": "2",
    "length2": "00",
    "width": "7.67",
    "width1": "7",
    "width2": "8",
    "totalArea": "15.33",
    "images": [],
    "extraAreas": [],
    "finalArea": "15.33",
    "percentageBeforeTotal": "15.33",
    "percentage": "100"
  },
  {
    "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "2.42",
  "length1": "2",
  "length2": "5",
  "width": "7.75",
  "width1": "7",
  "width2": "9",
  "totalArea": "18.73",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.73",
  "percentageBeforeTotal": "18.73",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "2.58",
  "length1": "2",
  "length2": "7",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "22.60",
```

```
"images": [],
"extraAreas": [],
"finalArea": "22.6",
"percentageBeforeTotal": "22.60",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
"typeofDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "500947",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "319",
"squareMeterArea": "29.64",
"docFinalBuiltUp": "350.9",
"docFinalBuiltUpSquareMeter": "32.604",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "292.00",
"squareMeterArea": "27.13",
"expectedRate": "10958.90",
"percentage": ""
},
"builtUpArea": {
"area": "321.20",
"squareMeterArea": "29.84",
"expectedRate": "9962.64",
"percentage": "10"
},
"saleableArea": {
```

```
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "676651f8fe1fd12ff214e3d2",
"property": "Residential Flat",
"area": "292",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "3200000",
"expectedRate": "10958.90",
"builtUpExpectedRate": "9962.64",
"image": "cases/6763e6ca31b0132fc582109e/
indicator_1734758480899_Image.png",
"squareMeter": "27.13",
"id": "138243"
},
{
"carpetArea": {
"area": "300.00",
"squareMeterArea": "27.87",
"expectedRate": "15333.33",
"percentage": ""
},
"builtUpArea": {
"area": "330.00",
"squareMeterArea": "30.66",
"expectedRate": "13939.39",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "676651f8fe1fd12ff214e3d3",
"property": "Residential Flat",
"area": "300",
```

```
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "4600000",
"expectedRate": "15333.33",
"builtUpExpectedRate": "13939.39",
"image": "cases/6763e6ca31b0132fc582109e/
indicator_1734758515050_Image.png",
"squareMeter": "27.87",
"id": "126349"
},
{
  "carpetArea": {
    "area": "319.00",
    "squareMeterArea": "29.64",
    "expectedRate": "9909.09",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "350.90",
    "squareMeterArea": "32.60",
    "expectedRate": "9008.26",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "676651f8fe1fd12ff214e3d4",
  "property": "Residential Flat",
  "area": "319",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3161000",
  "expectedRate": "9909.09",
  "builtUpExpectedRate": "9008.26",
```

```
"image": "cases/6763e6ca31b0132fc582109e/
indicator_1734758571134_Image.png",
"squareMeter": "29.64",
"id": "568092"
},
{
  "carpetArea": {
    "area": "240.00",
    "squareMeterArea": "22.30",
    "expectedRate": "10625.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "264.00",
    "squareMeterArea": "24.53",
    "expectedRate": "9659.09",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "676651f8fe1fd12ff214e3d5",
  "property": "Residential Flat",
  "area": "240",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "2550000",
  "expectedRate": "10625.00",
  "builtUpExpectedRate": "9659.09",
  "image": "cases/6763e6ca31b0132fc582109e/
indicator_1734758609079_Image.png",
  "squareMeter": "22.30",
  "id": "980264"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6764e7461f06b62faf36ceb8",
    "name":
"externallmg_1734666054255_WhatsApp_Image_20241220_at_003917.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666054255_WhatsApp_Image_20241220_at_003917.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764e7461f06b62faf36ceb9",
    "name":
"externallmg_1734666054266_WhatsApp_Image_20241220_at_003918.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666054266_WhatsApp_Image_20241220_at_003918.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764e7461f06b62faf36cebb",
    "name":
"externallmg_1734666054291_WhatsApp_Image_20241220_at_003919.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666054291_WhatsApp_Image_20241220_at_003919.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764e7531f06b62faf36cef3",
    "name":
"externallmg_1734666066872_WhatsApp_Image_20241220_at_003922_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666066872_WhatsApp_Image_20241220_at_003922_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764e7531f06b62faf36cef4",
    "name":
"externallmg_1734666066876_WhatsApp_Image_20241220_at_003922.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666066876_WhatsApp_Image_20241220_at_003922.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764e7531f06b62faf36cef5",
    "name":
"externallmg_1734666066877_WhatsApp_Image_20241220_at_003923.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666066877_WhatsApp_Image_20241220_at_003923.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764e7531f06b62faf36cef6",
    "name":
"externallmg_1734666066901_WhatsApp_Image_20241220_at_003924.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666066901_WhatsApp_Image_20241220_at_003924.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6764e7531f06b62faf36cf04",
    "name":
"externallmg_1734666067069_WhatsApp_Image_20241220_at_003936.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/
externallmg_1734666067069_WhatsApp_Image_20241220_at_003936.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e901",
    "name": "externallmg_1734759622880_externallmg_1734666054270_WhatsApp_I
mage_20241220_at_003919_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622880_externall
mg_1734666054270_WhatsApp_Image_20241220_at_003919_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e902",
```



```
    "name": "externalimg_1734759622887_externalimg_1734666054295_WhatsApp_I
mage_20241220_at_003921_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externalimg_1734759622887_external
mg_1734666054295_WhatsApp_Image_20241220_at_003921_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e903",
    "name": "externalimg_1734759622905_externalimg_1734666066866_WhatsApp_I
mage_20241220_at_003921.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externalimg_1734759622905_external
mg_1734666066866_WhatsApp_Image_20241220_at_003921.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e904",
    "name": "externalimg_1734759622924_externalimg_1734666066915_WhatsApp_I
mage_20241220_at_003925_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externalimg_1734759622924_external
mg_1734666066915_WhatsApp_Image_20241220_at_003925_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e905",
    "name": "externalimg_1734759622944_externalimg_1734666066917_WhatsApp_I
mage_20241220_at_003925_2.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externalimg_1734759622944_external
mg_1734666066917_WhatsApp_Image_20241220_at_003925_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e906",
    "name": "externalimg_1734759622947_externalimg_1734666066935_WhatsApp_I
mage_20241220_at_003925.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externalimg_1734759622947_external
mg_1734666066935_WhatsApp_Image_20241220_at_003925.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676654c7fe1fd12ff214e907",
  "name": "externallmg_1734759622966_externallmg_1734666066946_WhatsApp_I
mage_20241220_at_003926.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622966_externall
mg_1734666066946_WhatsApp_Image_20241220_at_003926.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676654c7fe1fd12ff214e908",
  "name": "externallmg_1734759622968_externallmg_1734666066949_WhatsApp_I
mage_20241220_at_003929_1.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622968_externall
mg_1734666066949_WhatsApp_Image_20241220_at_003929_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676654c7fe1fd12ff214e909",
  "name": "externallmg_1734759622984_externallmg_1734666066971_WhatsApp_I
mage_20241220_at_003929.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622984_externall
mg_1734666066971_WhatsApp_Image_20241220_at_003929.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676654c7fe1fd12ff214e90a",
  "name": "externallmg_1734759622989_externallmg_1734666066978_WhatsApp_I
mage_20241220_at_003930_1.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759622989_externall
mg_1734666066978_WhatsApp_Image_20241220_at_003930_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676654c7fe1fd12ff214e90b",
  "name": "externallmg_1734759623002_externallmg_1734666066997_WhatsApp_I
mage_20241220_at_003930.jpeg",
```

```
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759623002_externallmg_1734666066997_WhatsApp_Image_20241220_at_003930.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e90c",
    "name": "externallmg_1734759623019_externallmg_1734666067007_WhatsApp_Image_20241220_at_003934_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759623019_externallmg_1734666067007_WhatsApp_Image_20241220_at_003934_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e90d",
    "name": "externallmg_1734759623022_externallmg_1734666067022_WhatsApp_Image_20241220_at_003934.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759623022_externallmg_1734666067022_WhatsApp_Image_20241220_at_003934.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e90e",
    "name": "externallmg_1734759623047_externallmg_1734666067038_WhatsApp_Image_20241220_at_003935_1.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759623047_externallmg_1734666067038_WhatsApp_Image_20241220_at_003935_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676654c7fe1fd12ff214e90f",
    "name": "externallmg_1734759623059_externallmg_1734666067041_WhatsApp_Image_20241220_at_003935.jpeg",
    "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759623059_externallmg_1734666067041_WhatsApp_Image_20241220_at_003935.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6766552bfe1fd12ff214e9c7",
  "name": "externallmg_1734759722735_1.jpg",
  "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759722735_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6766557a1f06b62faf3796cf",
  "name": "externallmg_1734759801621_externallmg_1734666067066_WhatsApp_I
mage_20241220_at_003936_1.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/externallmg_1734759801621_externall
mg_1734666067066_WhatsApp_Image_20241220_at_003936_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Approved plans.pdf",
    "filename": "1734758872246_Aproved_plans.pdf",
    "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734758872246_Aproved_plans.pdf",
    "size": "976",
    "createdAt": "Sat Dec 21 2024 05:27:55 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1734758872247_Calculation_Sheet_NEW.xlsx",
    "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734758872247_Calculation_Sheet_NEW.xlsx",
    "size": "1148924",
    "createdAt": "Sat Dec 21 2024 05:27:55 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "CC 1.pdf",
    "filename": "1734758873310_CC_1.pdf",
    "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734758873310_CC_1.pdf",
    "size": "3680527",
    "createdAt": "Sat Dec 21 2024 05:27:55 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
```

```
{
  "originalname": "Rera Certificate.pdf",
  "filename": "1734758874692_Rera_Certificate.pdf",
  "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734758874692_Rera_Certificate.pdf",
  "size": "234117",
  "createdAt": "Sat Dec 21 2024 05:27:55 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "6 Commencement Certificates _ NA Order for plotted
development.pdf",
  "filename": "1734765683113_6_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
  "path": "cases/6763e6ca31b0132fc582109e/processingDocuments/1734765683113
_6_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
  "size": "2672065",
  "createdAt": "Sat Dec 21 2024 07:21:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "7 Building Plan Approval _ NA Order for plotted development.pdf",
  "filename": "1734765683153_7_Building_Plan_Approval__NA_Order_for_plotted_
development.pdf",
  "path": "cases/6763e6ca31b0132fc582109e/processingDocuments/1734765683153
_7_Building_Plan_Approval__NA_Order_for_plotted_development.pdf",
  "size": "1089119",
  "createdAt": "Sat Dec 21 2024 07:21:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Google Location.jpeg",
  "filename": "1734765683171_Google_Location.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734765683171_Google_Location.jpeg",
  "size": "141933",
  "createdAt": "Sat Dec 21 2024 07:21:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Deed - 2024.pdf",
  "filename": "1734765683478_Sale_Deed__2024.pdf",
  "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734765683478_Sale_Deed__2024.pdf",
  "size": "4095033",
  "createdAt": "Sat Dec 21 2024 07:21:23 GMT+0000 (Coordinated Universal Time)",
```

```
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Site Details.jpeg",
  "filename": "1734765693223_Site_Details.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734765693223_Site_Details.jpeg",
  "size": "101857",
  "createdAt": "Sat Dec 21 2024 07:21:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sketch & Dimention.jpeg",
  "filename": "1734765693227_Sketch__Dimention.jpeg",
  "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734765693227_Sketch__Dimention.jpeg",
  "size": "75174",
  "createdAt": "Sat Dec 21 2024 07:21:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "MRIDA HOMES.pdf",
  "filename": "1734765702499_MRIDA_HOMES.pdf",
  "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734765702499_MRIDA_HOMES.pdf",
  "size": "834451",
  "createdAt": "Sat Dec 21 2024 07:21:42 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "P99000026476.pdf",
  "filename": "1734765702528_P99000026476.pdf",
  "path": "cases/6763e6ca31b0132fc582109e/
processingDocuments/1734765702528_P99000026476.pdf",
  "size": "702366",
  "createdAt": "Sat Dec 21 2024 07:21:42 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "7 Building Plan Approval _ NA Order for plotted development.pdf",
  "filename": "1734766242540_7_Building_Plan_Approval__NA_Order_for_plotted_
development.pdf",
  "path": "cases/6763e6ca31b0132fc582109e/processingDocuments/1734766242540
_7_Building_Plan_Approval__NA_Order_for_plotted_development.pdf",
  "size": "1089119",
  "createdAt": "Sat Dec 21 2024 07:30:42 GMT+0000 (Coordinated Universal Time)",
```

```
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67650d401f06b62faf36f6a2",
  "note": "Value given for confirmation",
  "taskId": "6763f444fe1fd12ff213d02b",
  "createdAt": "2024-12-20T06:22:56.267Z"
}
],
"createdAt": "2024-12-19T09:26:34.515Z",
"updatedAt": "2024-12-21T07:33:29.930Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 411, 4th Floor, Mrida Homes Hasha Heights,
Naringi Bypass Road, Beside Foothill, Village - Naringi, Taluka - Vasai, District -
Palghar, Virar (East), PIN - 401 305, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Ms. Snehlata",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Builder Person",
"rerald": ""
```

```
"siteVisitContactNo": "9175112393",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 319.00",
"flatRate": "11000",
"landOtherRate": "8500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet",
"carpetTotal": "292.06",
"otherCarpetTotal": "56.66",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "56.66",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "383.59",
"finalCarpetArea": "348.72",
"finalSalableArea": "383.59",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 292.06\nDry Balcony Area in Sq.
Ft. = 15.33\nFlowered Area in Sq. Ft. = 41.33\n<br />\n",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Sat Dec 21 2024 05:34:21 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-19",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": ""
  }
}
```



```
"leaseRent": "",  
"leasePeriod": 0,  
"leaseFrom": "",  
"leaseTo": "",  
"remainingLeasePeriod": 0,  
"leaseDate": ""
```

```
}  
}  
}
```

Name	Length	Width	Total
Composition :			
Passage	3'7"	3'2"	11.35
Living Room	8'8"	13'1"	113.39
Kitchen	5'11"	7'8"	45.36
Passage	3'1"	2'3"	6.94
Toilet	3'11"	5'7"	21.87
Bedroom	7'11"	9'5"	74.55
Toilet	3'11"	4'9"	18.60
Other Composition :			
Dry Balcony Area	2'00"	7'8"	15.33
Flowered Area	2'5"	7'9"	18.73
Flowered Area	2'7"	8'9"	22.60