

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Atul",
    "type": "CREDITOFFICER",
    "_id": "67342e940b8f93c1cf1c3a20",
    "email": "atul.landge123@gmail.com",
    "lastName": "Landge",
    "mobileNo": "",
    "workMobileNo": "9768604755"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.175277069946908",
```

```
"longitude": "72.97210152647902"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.97210152647902,
    19.175277069946908
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "23/12/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-23T10:01:36.865Z",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "25000",
  "lumpsumValue": "1",
  "rateMax": "30000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "T",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Brighton Tower CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Hariom Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```



```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400081",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund East",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "Vitrified_Tile_Flooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
  "windows": {
    "label": "Powder Coated Aluminium Sliding",
```

```
"value": "PowderCoatedAluminiumSliding"
},
"fittings": {
  "label": "Concealed Plumbing with Conduit & Concealed Electrical wiring",
  "value": "Concealed_Plumbing_with_Conduit_&_Concealed_Electrical_wiring"
},
"finishing": {
  "label": "Normal",
  "value": "Normal"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "north": "millenium park society",
    "west": "hariom nagar road",
    "south": "internal road",
    "east": "ratnashri tower "
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
```

```
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Posh",
    "value": "Posh"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonry",
```

```
"value": "6\"_Thk._Brick_Masonry"
},
"waterTank": {
  "label": "Municipal Water Supply",
  "value": "MunicipalWaterSupply"
},
"pavementLaid": {
  "label": "Yes",
  "value": "Yes"
},
"carParking": {
  "label": "Podium Parking",
  "value": "Podium_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2010",
  "fullDate": "1/1/2010"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
```

```
"value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "46",
"ageOfBuilding": "14",
"noOfBasement": "0",
"noOfPodium": "01",
"noOfAmenityFloors": "0",
"noOfFloors": "017",
"flatFloorNo": "",
"noOfLifts": "02",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
```

```
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Approximate Rate Lead",
"value": "APPROXIMATE_LEAD"
},
siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
```

```
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6768e06bfe1fd12ff21569a8",
"ownerName": "Naveen Pradeep Bhartiya And Babita Pradipkumar Bhartiya ",
"ownerPhoneNo": "9769362361",
"appAddress": "Flat no. 1102, 11th Floor, Brighton Tower chs, Hari Om Nagar, Mulund
East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6768e06bfe1fd12ff21569a8/
document_1734926414852_1734926411098_Naveen_Bhartiya_Valuation_Docs.pdf",
    "fileName":
"document_1734926414852_1734926411098_Naveen_Bhartiya_Valuation_Docs.pdf",
    "id": "881537",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Mon Dec 23 2024 04:00:43 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013268",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "410982",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Dec 23 2024 04:00:43 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Naveen Pradeep Bhartiya And Babita Pradipkumar Bhartiya ",
    "phone": "9769362361",
    "ownershipShare": "",
    "email": "",
    "id": "250036"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "6769345631b0132fc584d539",
    "area": "895",
    "providedByName": "Naveen Pradeep Bhartiya And Babita Pradipkumar Bhartiya ",
    "providedByContactNo": "9769362361"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "296835",
    "name": "Living Room",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "67693d811f06b62faf38ac05",
    "name": "externalimg_1734950272703_IMG20241223WA0121.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalimg_1734950272703_IMG20241223WA0121.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac06",
    "name": "externalimg_1734950272707_IMG20241223WA0122.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalimg_1734950272707_IMG20241223WA0122.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac07",
    "name": "externalimg_1734950272734_IMG20241223WA0123.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalimg_1734950272734_IMG20241223WA0123.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac08",
    "name": "externalimg_1734950272762_IMG20241223WA0124.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalimg_1734950272762_IMG20241223WA0124.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac09",
    "name": "externalimg_1734950272772_IMG20241223WA0125.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalimg_1734950272772_IMG20241223WA0125.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac0a",
```

```
    "name": "externalImg_1734950272802_IMG20241223WA0126.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950272802_IMG20241223WA0126.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac0b",
    "name": "externalImg_1734950272824_IMG20241223WA0127.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950272824_IMG20241223WA0127.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac0c",
    "name": "externalImg_1734950272839_IMG20241223WA0128.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950272839_IMG20241223WA0128.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d811f06b62faf38ac0d",
    "name": "externalImg_1734950272848_IMG20241223WA0129.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950272848_IMG20241223WA0129.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac49",
    "name": "externalImg_1734950286456_IMG20241223WA0130.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950286456_IMG20241223WA0130.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac4a",
    "name": "externalImg_1734950286473_IMG20241223WA0131.jpg",
```



```
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286473_IMG20241223WA0131.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac4b",
    "name": "externallmg_1734950286498_IMG20241223WA0132.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286498_IMG20241223WA0132.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac4c",
    "name": "externallmg_1734950286502_IMG20241223WA0133.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286502_IMG20241223WA0133.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac4d",
    "name": "externallmg_1734950286524_IMG20241223WA0134.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286524_IMG20241223WA0134.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac4e",
    "name": "externallmg_1734950286542_IMG20241223WA0135.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286542_IMG20241223WA0135.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac4f",
    "name": "externallmg_1734950286543_IMG20241223WA0136.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286543_IMG20241223WA0136.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac50",
  "name": "externallmg_1734950286552_IMG20241223WA0137.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286552_IMG20241223WA0137.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac51",
  "name": "externallmg_1734950286569_IMG20241223WA0138.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286569_IMG20241223WA0138.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac52",
  "name": "externallmg_1734950286571_IMG20241223WA0139.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286571_IMG20241223WA0139.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac53",
  "name": "externallmg_1734950286572_IMG20241223WA0140.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286572_IMG20241223WA0140.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac54",
  "name": "externallmg_1734950286574_IMG20241223WA0141.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286574_IMG20241223WA0141.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac55",
    "name": "externallmg_1734950286576_IMG20241223WA0142.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286576_IMG20241223WA0142.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac56",
    "name": "externallmg_1734950286584_IMG20241223WA0143.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286584_IMG20241223WA0143.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac57",
    "name": "externallmg_1734950286600_IMG20241223WA0144.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286600_IMG20241223WA0144.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac58",
    "name": "externallmg_1734950286601_IMG20241223WA0145.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286601_IMG20241223WA0145.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67693d8e1f06b62faf38ac59",
    "name": "externallmg_1734950286603_IMG20241223WA0146.jpg",
    "path": "cases/6768e06bfe1fd12ff21569a8/
externallmg_1734950286603_IMG20241223WA0146.jpg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac5a",
  "name": "externalImg_1734950286604_IMG20241223WA0147.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950286604_IMG20241223WA0147.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac5b",
  "name": "externalImg_1734950286607_IMG20241223WA0148.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950286607_IMG20241223WA0148.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67693d8e1f06b62faf38ac5c",
  "name": "externalImg_1734950286628_IMG20241223WA0149.jpg",
  "path": "cases/6768e06bfe1fd12ff21569a8/
externalImg_1734950286628_IMG20241223WA0149.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "6006d4ce5080a310ac1fdfc2",
      "role": "ADMIN",
      "firstName": "Jagdish ",
      "lastName": "Bhatt",
      "profilePhoto": "users\\6006d4ce5080a310ac1fdfc2\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "67693d2031b0132fc584e5e3",
```

```

    "note": "For Photos (Task Reopen)",
    "taskId": "676905f231b0132fc5847a91",
    "createdAt": "2024-12-23T10:36:16.633Z"
  }
],
"createdAt": "2024-12-23T04:00:43.321Z",
"updatedAt": "2024-12-23T10:38:06.820Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1102, 11th Floor, Building No T, Brighton Tower
CHSL, Hariom Nagar, Mulund East, Mumbai, 400081",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Naveen Pradeep Bhartiya And Babita Pradipkumar Bhartiya ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9769362361",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2024-12-23"
}

```

Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			