

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6503f61fa8e9b70221e57e31"
    },
    "firstName": "Rahul waghmare",
    "type": "CREDITOFFICER",
    "_id": "6503f61fa8e9b70221e57e33",
    "lastName": "Sir",
    "mobileNo": "9850860792",
    "workMobileNo": "9850860792",
    "email": "ubin0559695@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3540"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6503f61fa8e9b70221e57e31",
  "name": "Panchavati Branch, Nashik",
  "branchCode": "559695",
  "mobileNo": "2532629306",
  "alternateMobileNo": "8104604059",
  "email": "ubin0559695@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SHOP NO 1,2 3 RUPASHRI APPARTMENT OPP TAXI STAND DINDORI
RD PANCHVATI,NASIK,422003"
},
"assetsClass": {
  "value": "Land_&_Building/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
```

```
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "_id": "64dc7184ccaf1e7b7f637f47",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg",
  "firstName": "Binumon",
  "lastName": "Moozhickal",
  "shortName": "BS",
  "email": "binu@vastukala.org",
  "designation": "Back Office Team Leader",
  "mobileNo": "9930252906",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
  "_id": "6084131a13f01f158c6ea1f4",
```

```
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.99383836008371",
  "longitude": "73.80901672382767"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "26/12/2024 12:00 am"
    },
    {
      "dateTime": "27/12/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-12-28",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-12-28",
    "remark": "MANUAL_IN_TASK"
  }
],
}
```

```
{
  "status": "COMPLETED",
  "dateTime": "2024-12-28",
  "remark": "MANUAL_IN_TASK"
},
{
  "status": "COMPLETED",
  "dateTime": "2024-12-27",
  "remark": "MANUAL_IN_TASK"
}
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "1+2+3+4+5+6+7+8/A",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreeji Jayshankar Towers",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Dr. Kadale Baba, Jayshankar Circle, Tapovan Link Road",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
```



```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "449/1/4/2/3/5/6/1to6/449/3/4/1/1/449/2P",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "706",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "PIN Code - 422003",
"label": false
},
"suburb": {
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_/_Glass_Door",
"label": "Teak Wood / Glass Door"
},
"windows": {
"value": "Wooden_frame_openable_widow_with_M._S._Grill",
"label": "Wooden frame openable widow with M. S. Grill"
},
"fittings": {
"value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
"label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
},
"finishing": {
"value": "Cement_Plastering_+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
```

```
"label": "Middle Class"
},
"populationGroupList": {
  "value": "Rural",
  "label": "Rural"
},
"townplanApprovedByList": {
  "value": "Nashik_Municipal_Corporation_",
  "label": "Nashik Municipal Corporation "
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "18 Meter Wide Road",
  "west": "15 Meter Wide Road",
  "south": "Akshar Bele Park Apartment",
  "east": "30 Meter Wide Road"
},
"asPerDocumentAgreement": {
  "north": "18 Meter Wide Road",
  "west": "15 Meter Wide Road",
  "south": "Akshar Bele Park Apartment",
  "east": "30 Meter Wide Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "MarginaL Space",
    "east": "30 Meter Wide Road",
    "south": "Flat No.705",
    "west": "Flat No.704"
  },
  "asPerDocument": {
    "north": "MarginaL Space",
    "east": "30 Meter Wide Road",
    "south": "Flat No.705",
    "west": "Flat No.704"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  }
},
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No.C1/ 103/ 06 Dated
14.02.2019,Issued by Nashik Municipal Corporation,Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "34850",
  "landRate": "12450",
  "igrImage": "cases/676d4da8755c10d6ee60a78d/igr_1735217118730_Image.png",
  "squareMeterGuideLineRate": "36593.00",
  "squareFeetGuideLineRate": "3400.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "34850.00",
  "squareMeterGuideLineRate": "36593.00",
  "squareFeetGuideLineRate": "3400.00"
},
```

```
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "NA",
  "taxPaidHolderName": "NA",
  "taxAmount": "NA",
  "electricityServiceConnectionNo": "NA",
  "meterCardHolderName": "NA",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Excellent",
    "label": "Excellent"
  },
  "anyFavouringForExtraPotentialValue": "NA",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
```

```
"value": "Yes",
"label": "Yes"
},
"carParking": "Yes",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2022",
  "fullDate": "1/1/2022"
},
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"protAgainstNatDis": {
  "value": "Yes",
  "label": "Yes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "2",
```



```
"totalLifeBuilding": "60",
"estimatedAge": "58",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "13",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "1203.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/676d4da8755c10d6ee60a78d/
routeMap_1735217338643_Image.png",
    "routeLat": "19.994031",
    "routeLng": "73.808980",
    "stationName": "Nashik Road",
    "routeDistance": "8.0",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "ye9och",
    "name": "ye9och",
    "image": "cases/676d4da8755c10d6ee60a78d/
routeMap_1735388216490_Image.png"
```

```
}
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "1000000",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8658000.00",
  "finalValue": "7658000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "95",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
```

```
"status": true,
"remark": "SYSTEMGENERATED",
"date": "Sat Dec 28 2024 12:31:13 GMT+0000 (Coordinated Universal Time)",
"number": "2309849",
"dayCount": "21",
"monthCount": "547",
"generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4091560.00",
  "selectedBuildUpValue": "1203.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "676d4e129d24bfd6f41e6570",
    "name":
"externallmg_1735216657641_WhatsApp_Image_20241226_at_45853_PM.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216657641_WhatsApp_Image_20241226_at_45853_PM.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a845",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216641551_WhatsApp_Image_20241226_at_45856_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a846",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216641803_WhatsApp_Image_20241226_at_45856_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a847",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642054_WhatsApp_Image_20241226_at_45857_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a848",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642225_WhatsApp_Image_20241226_at_45857_PM_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a849",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642437_WhatsApp_Image_20241226_at_45857_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a84a",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642713_WhatsApp_Image_20241226_at_45858_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a84b",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642925_WhatsApp_Image_20241226_at_45858_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a84d",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216643327_WhatsApp_Image_20241226_at_45859_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a84f",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216643916_WhatsApp_Image_20241226_at_45900_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a850",
    "name": "Living Room",
```

```
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216644085_WhatsApp_Image_20241226_at_45900_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e129d24bfd6f41e656c",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216656152_WhatsApp_Image_20241226_at_45852_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a841",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216640529_WhatsApp_Image_20241226_at_45854_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a843",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216641078_WhatsApp_Image_20241226_at_45855_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a840",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216640103_WhatsApp_Image_20241226_at_45854_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "676d4e05755c10d6ee60a842",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216640827_WhatsApp_Image_20241226_at_45855_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
```



```
    "_id": "676d4e129d24bfd6f41e6571",
    "name": "Living Room",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216658052_WhatsApp_Image_20241226_at_45854_PM_1.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6125.00",
    "max": "7068.00"
  },
  "builtUpRateRange": {
    "min": "5104.00",
    "max": "5890.00"
  },
  "saleableRateRange": {
    "min": "4253.00",
    "max": "4908.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
finalValuationArea": "1094.00",
empanelmentNo": [
"RO/CR/30129/ 2020-21"
],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "676d4da8755c10d6ee60a78d",
"ownerName": "Mr. Kunal Minnath Gosavi & Mrs. Khyati Kunal Gosavi",
"ownerPhoneNo": "9021336316",
"fullAddress": "Residential Flat No. 706, 7th Floor, Wing - A, Shreeji Jayshankar Towers, Near Dr. Kadale Baba, Jayshankar Circle, Tapovan Link Road, Plot No. 1+2+3+4+5+6+7+8/A, Village - Nashik, Taluka - Nashik, District - Nashik, Nashik, PIN Code - 422003, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "inputs": {
      "documentDate": "28/03/2024",
      "amount": "7012429",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Shreeji Life Space",
      "to": {
        "value": "buyer",
        "label": "buyer"
      },
      "buyer": "Mr. Kunal Minnath Gosavi & Mrs. Khyati Kunal Gosavi"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/676d4da8755c10d6ee60a78d/document_1735215989062_Adobe_Scan_26_Dec_2024_2.pdf",
    "fileName": "document_1735215989062_Adobe_Scan_26_Dec_2024_2.pdf",
    "id": "482165",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Thu Dec 26 2024 12:35:52 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
```

```
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "24/07/2019",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "LND/ BP/ A4/ RBP/162/ 2021"
},
"isHardCopy": false,
"displayStatus": false,
"id": "529891",
"path": "cases/676d4da8755c10d6ee60a78d/document_1735216205084_CC.pdf",
"fileName": "document_1735216205084_CC.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/02/2019",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "C1/ 103/ 06"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1735216232397_Adobe_Scan_26_Dec_2024_1.pdf",
"path": "cases/676d4da8755c10d6ee60a78d/
document_1735216232397_Adobe_Scan_26_Dec_2024_1.pdf",
"id": "817154",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Thu Dec 26 2024 12:35:52 GMT+0000 (Coordinated Universal Time)"
},
```

```
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "26/08/2022",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "Javak No. NRV/ 30851/ 2022"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1735216341414_Adobe_Scan_26_Dec_2024_2.pdf",
  "path": "cases/676d4da8755c10d6ee60a78d/
document_1735216341414_Adobe_Scan_26_Dec_2024_2.pdf",
  "id": "244816",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Dec 26 2024 12:35:52 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/08/2019",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51600021894"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1735216526760_Adobe_Scan_26_Dec_2024_2.pdf",
```

```
    "path": "cases/676d4da8755c10d6ee60a78d/
document_1735216526760_Adobe_Scan_26_Dec_2024_2.pdf",
    "id": "816474",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Thu Dec 26 2024 12:35:52 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013345",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "482442",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 26 2024 12:35:52 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Kunal Minnath Gosavi & Mrs. Khyati Kunal Gosavi",
    "phone": "9021336316",
    "ownershipShare": "",
    "email": "",
    "id": "215248"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "898098",
    "name": "Living Room",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
```

```
"totalArea": "120.00",
"images": [],
"extraAreas": [],
"finalArea": "120.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },

```



```
"id": "3",
"name": "Bedroom",
"length": "12.00",
"length1": "12",
"length2": "00",
"width": "12.00",
"width1": "12",
"width2": "00",
"totalArea": "144.00",
"images": [],
"extraAreas": [],
"finalArea": "144.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "15.00",
  "width1": "15",
  "width2": "00",
  "totalArea": "225.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "225.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "12.00",
  "width1": "12",
  "width2": "00",
  "totalArea": "120.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "120.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "120.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Balcony",
```

```
"length": "7.00",
"length1": "7",
"length2": "00",
"width": "5.00",
"width1": "5",
"width2": "00",
"totalArea": "35.00",
"images": [],
"extraAreas": [],
"finalArea": "35.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "101.64",
    "totalAreaDocument": "1094",
    "docBuiltpPercentage": "10",
```

```
"docFinalBuiltUp": "1203.40",
"docFinalBuiltUpSquareMeter": "111.80",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "147784"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "604.17",
"squareMeterArea": "56.13",
"expectedRate": "6124.10",
"percentage": ""
},
"builtUpArea": {
"area": "725.00",
"squareMeterArea": "67.35",
"expectedRate": "5103.45",
"percentage": "20"
},
"saleableArea": {
"area": "870.00",
"squareMeterArea": "80.83",
"expectedRate": "4252.87",
"percentage": "20"
},
"printlnReport": true,
"_id": "676d4fec553bfed7370f5215",
"property": "Flat",
"area": "870",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Saleable",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "3700000",
"expectedRate": "4252.873563218391",
"builtUpExpectedRate": "5103.45",
"image": "cases/676d4da8755c10d6ee60a78d/
indicator_1735216951912_Image.png",
"squareMeter": "80.83",
"id": "899803"
```

```
},
{
  "carpetArea": {
    "area": "1381.00",
    "squareMeterArea": "128.30",
    "expectedRate": "7067.34",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1657.20",
    "squareMeterArea": "153.96",
    "expectedRate": "5889.45",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1988.64",
    "squareMeterArea": "184.75",
    "expectedRate": "4907.88",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "676d4fec553bfed7370f5216",
  "property": "Flat",
  "area": "1381",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "9760000",
  "expectedRate": "7067.34",
  "builtUpExpectedRate": "5889.45",
  "image": "cases/676d4da8755c10d6ee60a78d/
indicator_1735217083282_Image.png",
  "squareMeter": "128.30",
  "id": "374289"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a840",
    "name":
"externalImg_1735216640103_WhatsApp_Image_20241226_at_45854_PM_2.jpeg",
```

```
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216640103_WhatsApp_Image_20241226_at_45854_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a841",
    "name":
"externallmg_1735216640529_WhatsApp_Image_20241226_at_45854_PM.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216640529_WhatsApp_Image_20241226_at_45854_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a842",
    "name":
"externallmg_1735216640827_WhatsApp_Image_20241226_at_45855_PM_1.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216640827_WhatsApp_Image_20241226_at_45855_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a843",
    "name":
"externallmg_1735216641078_WhatsApp_Image_20241226_at_45855_PM_2.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216641078_WhatsApp_Image_20241226_at_45855_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a844",
    "name":
"externallmg_1735216641317_WhatsApp_Image_20241226_at_45855_PM.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216641317_WhatsApp_Image_20241226_at_45855_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "676d4e05755c10d6ee60a845",
  "name":
"externallmg_1735216641551_WhatsApp_Image_20241226_at_45856_PM_1.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216641551_WhatsApp_Image_20241226_at_45856_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a846",
  "name":
"externallmg_1735216641803_WhatsApp_Image_20241226_at_45856_PM.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216641803_WhatsApp_Image_20241226_at_45856_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a847",
  "name":
"externallmg_1735216642054_WhatsApp_Image_20241226_at_45857_PM_1.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642054_WhatsApp_Image_20241226_at_45857_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a848",
  "name":
"externallmg_1735216642225_WhatsApp_Image_20241226_at_45857_PM_2.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642225_WhatsApp_Image_20241226_at_45857_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a849",
  "name":
"externallmg_1735216642437_WhatsApp_Image_20241226_at_45857_PM.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642437_WhatsApp_Image_20241226_at_45857_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a84a",
    "name":
"externallmg_1735216642713_WhatsApp_Image_20241226_at_45858_PM_1.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642713_WhatsApp_Image_20241226_at_45858_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a84b",
    "name":
"externallmg_1735216642925_WhatsApp_Image_20241226_at_45858_PM.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216642925_WhatsApp_Image_20241226_at_45858_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a84c",
    "name":
"externallmg_1735216643176_WhatsApp_Image_20241226_at_45859_PM_1.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216643176_WhatsApp_Image_20241226_at_45859_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a84d",
    "name":
"externallmg_1735216643327_WhatsApp_Image_20241226_at_45859_PM_2.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216643327_WhatsApp_Image_20241226_at_45859_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e05755c10d6ee60a84e",
```



```
"name":
"externallmg_1735216643600_WhatsApp_Image_20241226_at_45859_PM.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216643600_WhatsApp_Image_20241226_at_45859_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a84f",
  "name":
"externallmg_1735216643916_WhatsApp_Image_20241226_at_45900_PM_1.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216643916_WhatsApp_Image_20241226_at_45900_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a850",
  "name":
"externallmg_1735216644085_WhatsApp_Image_20241226_at_45900_PM_2.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216644085_WhatsApp_Image_20241226_at_45900_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a851",
  "name":
"externallmg_1735216644424_WhatsApp_Image_20241226_at_45900_PM.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216644424_WhatsApp_Image_20241226_at_45900_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e05755c10d6ee60a852",
  "name":
"externallmg_1735216644699_WhatsApp_Image_20241226_at_45901_PM.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216644699_WhatsApp_Image_20241226_at_45901_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e129d24bfd6f41e656c",
  "name":
"externallmg_1735216656152_WhatsApp_Image_20241226_at_45852_PM_1.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216656152_WhatsApp_Image_20241226_at_45852_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e129d24bfd6f41e656d",
  "name":
"externallmg_1735216656458_WhatsApp_Image_20241226_at_45852_PM.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216656458_WhatsApp_Image_20241226_at_45852_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e129d24bfd6f41e656e",
  "name":
"externallmg_1735216656795_WhatsApp_Image_20241226_at_45853_PM_1.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216656795_WhatsApp_Image_20241226_at_45853_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e129d24bfd6f41e656f",
  "name":
"externallmg_1735216657251_WhatsApp_Image_20241226_at_45853_PM_2.jpeg",
  "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216657251_WhatsApp_Image_20241226_at_45853_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "676d4e129d24bfd6f41e6570",
  "name":
"externallmg_1735216657641_WhatsApp_Image_20241226_at_45853_PM.jpeg",
```

```
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216657641_WhatsApp_Image_20241226_at_45853_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676d4e129d24bfd6f41e6571",
    "name":
"externallmg_1735216658052_WhatsApp_Image_20241226_at_45854_PM_1.jpeg",
    "path": "cases/676d4da8755c10d6ee60a78d/
externallmg_1735216658052_WhatsApp_Image_20241226_at_45854_PM_1.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Kunal Cal'.xlsx",
    "filename": "1735217187149_Kunal_Cal.xlsx",
    "path": "cases/676d4da8755c10d6ee60a78d/
processingDocuments/1735217187149_Kunal_Cal.xlsx",
    "size": "303286",
    "createdAt": "Thu Dec 26 2024 12:46:27 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "UBI - Mr. Kunal Minnath Gosavi & Mrs. Khyati Kunal Gosavi.pdf",
    "filename":
"1735388377564_UBI__Mr_Kunal_Minnath_Gosavi__Mrs_Khyati_Kunal_Gosavi.pdf",
    "path": "cases/676d4da8755c10d6ee60a78d/processingDocuments/173538837756
4_UBI__Mr_Kunal_Minnath_Gosavi__Mrs_Khyati_Kunal_Gosavi.pdf",
    "size": "7478309",
    "createdAt": "Sat Dec 28 2024 12:19:40 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-26T12:35:52.783Z",
"updatedAt": "2024-12-28T12:44:33.852Z",
"_v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "647ed1960ab64c23c9fcf71d",
```

```
"contactPersonName": "Mr. Kunal Minnath Gosavi & Mrs. Khyati Kunal Gosavi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9021336316",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Deed of Apartment",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1094.00",
"flatRate": "7000",
"landOtherRate": "5000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 3 Toilet + 3 Balcony",
"carpetTotal": "1099.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1208.90",
"finalCarpetArea": "1099.00",
"finalSalableArea": "1329.79",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
```

```

    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Dec 28 2024 11:40:32 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-27",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

| <b>Name</b>            | <b>Length</b> | <b>Width</b> | <b>Total</b> |
|------------------------|---------------|--------------|--------------|
| Composition :          |               |              |              |
| Living Room            | 12'00"        | 10'00"       | 120.00       |
| Kitchen                | 10'00"        | 10'00"       | 100.00       |
| Bedroom                | 10'00"        | 10'00"       | 100.00       |
| Bedroom                | 12'00"        | 12'00"       | 144.00       |
| Toilet                 | 15'00"        | 15'00"       | 225.00       |
| Toilet                 | 10'00"        | 12'00"       | 120.00       |
| Toilet                 | 12'00"        | 10'00"       | 120.00       |
| Balcony                | 10'00"        | 10'00"       | 100.00       |
| Balcony                | 7'00"         | 5'00"        | 35.00        |
| Balcony                | 7'00"         | 5'00"        | 35.00        |
| Other<br>Composition : |               |              |              |