

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
```

```
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.970751",
  "longitude": "73.743230"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "28/12/2024 12:00 am"
    },
    {
      "dateTime": "28/12/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-28",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-28",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "28",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kalpataru Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gulmohar Colony",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Ambad Kamathwde Link Road",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
```



```
"key": "landmark",
"value": "Behind Chirayu Panchakarma,Nr. Mauli Lawns",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "222/A/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "703",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422008",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Powder_Coated_Aluminum_Sliding_Windows",
    "label": "Proposed Powder Coated Aluminum Sliding Windows"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  }
},
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "80 Fts Colony Road",
    "west": "Plot No.27",
    "south": "Plot No.33 & 34 Paiki Area",
    "east": "Plot No.29"
  },
  "asPerDocumentAgreement": {
    "north": "80 Fts Colony Road",
    "west": "Plot No.27",
    "south": "Plot No.33 & 34 Paiki Area",
    "east": "Plot No.29"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Marginal Space",
      "south": "Lobby, Lift ",
      "west": "Flat No.702 and Marginal Space"
    },
    "asPerDocument": {
```

```
"north": "Marginal Space",
"east": "Marginal Space",
"south": "Lobby, Lift ",
"west": "Flat No.702 and Marginal Space"
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Building Plan Document No.B2/BP/543/2022
Dated 02.02.2022,Issued by Nashik Municipal Corporation, Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "36700",
```

```
"landRate": "12500",
"igrImage": "cases/676fd15895b033db3f4c773d/igr_1735382045579_Image.png",
"squareMeterGuideLineRate": "38535.00",
"squareFeetGuideLineRate": "3580.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "36700.00",
  "squareMeterGuideLineRate": "38535.00",
  "squareFeetGuideLineRate": "3580.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not provided",
  "taxPaidHolderName": "Details not provided",
  "taxAmount": "Details not provided",
  "electricityServiceConnectionNo": "Details not provided",
  "meterCardHolderName": "Details not provided",
  "undividedAreaOfLandAsPerSaleDeed": "Details not provided",
  "floorSpaceIndex": "as per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Details not provided"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "NA",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "Proposed_6" _Thk. _Brick_ Masonery",
"label": "Proposed 6" Thk. Brick Masonery"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"carParking": "Yes",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2025",
"fullDate": "1/1/2025"
},
"planningArea": {
"value": "Residential_cum_Commercial",
"label": "Residential cum Commercial"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
```

```
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Yes",
  "label": "Yes"
},
"sewerageSystem": {
  "value": "Proposed_Concealed_",
  "label": "Proposed Concealed "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
```



```
"label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "0",
"totalLifeBuilding": "60",
"estimatedAge": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "1032.90",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/676fd15895b033db3f4c773d/
routeMap_1735383231689_Image.png",
    "routeLat": "19.970751",
    "routeLng": "73.743230",
    "stationName": "Nashik Road",
    "routeDistance": "14",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "judr1",
    "name": "judr1",
    "image": "cases/676fd15895b033db3f4c773d/
routeMap_1735383142037_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7230300.00",
"finalValue": "7230300.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Dec 28 2024 11:06:35 GMT+0000 (Coordinated Universal Time)",
  "number": "2309844",
  "dayCount": "16",
  "monthCount": "542",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "9",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "9",
"percentage": "7.00",
"isHideFloor": false,
"status": true
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "9",
"percentage": "7.00",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "9",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "9",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "71.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "3697782.00",
"selectedBuildUpValue": "1032.90",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "676fd8cddabdc2db790eea55",
"name":
"externallmg_1735383244475_WhatsApp_Image_20241228_at_13548_PM.jpeg",
"path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244475_WhatsApp_Image_20241228_at_13548_PM.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
{
"status": false,
"_id": "676fd8cddabdc2db790eea45",
"name": "Living Room",
"path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244275_WhatsApp_Image_20241228_at_13536_PM_1.jpeg",
"orientation": "landscape"
},
{
"status": false,
"_id": "676fd8cddabdc2db790eea46",
"name": "Living Room",
"path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244290_WhatsApp_Image_20241228_at_13538_PM.jpeg",
"orientation": "landscape"
},
{
"status": false,
```

```
    "_id": "676fd8cddabdc2db790eea47",
    "name": "Living Room",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244304_WhatsApp_Image_20241228_at_13539_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676fd8cddabdc2db790eea49",
    "name": "Living Room",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244322_WhatsApp_Image_20241228_at_13540_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676fd8cddabdc2db790eea4a",
    "name": "Living Room",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244340_WhatsApp_Image_20241228_at_13540_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676fd8cddabdc2db790eea4b",
    "name": "Living Room",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244345_WhatsApp_Image_20241228_at_13541_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676fd8cddabdc2db790eea4d",
    "name": "Living Room",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244372_WhatsApp_Image_20241228_at_13542_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "676fd8cddabdc2db790eea4e",
    "name": "Living Room",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244383_WhatsApp_Image_20241228_at_13543_PM.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "status": false,
  "_id": "676fd8cddabdc2db790eea50",
  "name": "Living Room",
  "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244407_WhatsApp_Image_20241228_at_13544_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "676fd8cddabdc2db790eea51",
  "name": "Living Room",
  "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244410_WhatsApp_Image_20241228_at_13545_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "676fd8cddabdc2db790eea55",
  "name": "Living Room",
  "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244475_WhatsApp_Image_20241228_at_13548_PM.jpeg",
  "orientation": "landscape"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6462.00",
    "max": "7734.00"
  },
  "builtUpRateRange": {
    "min": "5385.00",
    "max": "6445.00"
  },
  "saleableRateRange": {
    "min": "4488.00",
    "max": "5371.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "939.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "676fd15895b033db3f4c773d",
"ownerName": "Mr.Dilip Shivmurti Bondar & Mrs.Surekha Dilip Bondar",
"ownerPhoneNo": "8237116625",
"fullAddress": "Residential Flat No. 703, 7th Floor, Kalpataru Heights, Behind Chirayu
Panchakarma,Nr. Mauli Lawns, Plot No. 28, Gulmohar Colony, Ambad Kamathwde
Link Road, Taluka - Nashik, District - Nashik, 422008, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "05/12/2024",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s.Dwarkesh Constructions",
      "to": {
        "value": "The_Apartment_Owner",
        "label": "The Apartment Owner"
      }
    }
  }
],
```

```
"The_Apartment_Owner": "Mr.Dilip Shivmurti Bondar & Mrs.Surekha Dilip Bondar",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "11943/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "274667",
"path": "cases/676fd15895b033db3f4c773d/
document_1735381064951_Agreement.pdf",
"fileName": "document_1735381064951_Agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "02/02/2022",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "LND/BP/B2/543/2022"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1735381129485_CC.pdf",
  "path": "cases/676fd15895b033db3f4c773d/document_1735381129485_CC.pdf",
  "id": "384423",
  "uploadedBy": "636a1ad14d42487767af3f91",
  "createdAt": "Sat Dec 28 2024 10:22:16 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "28/04/2022",
```

```
"nameOfApprovingAuthority": {
  "value": "Maharashtra_Real_Estate_Regulatory_Authority",
  "label": "Maharashtra Real Estate Regulatory Authority"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "P51600034757"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1735381184821_P51600034757.pdf",
"path": "cases/676fd15895b033db3f4c773d/
document_1735381184821_P51600034757.pdf",
"id": "394340",
"uploadedBy": "636a1ad14d42487767af3f91",
"createdAt": "Sat Dec 28 2024 10:22:16 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "documentDate": "02/02/2022",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "B2/BP/543/2022"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1735381324106_Plan.pdf",
  "path": "cases/676fd15895b033db3f4c773d/document_1735381324106_Plan.pdf",
  "id": "121606",
  "uploadedBy": "636a1ad14d42487767af3f91",
  "createdAt": "Sat Dec 28 2024 10:22:16 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
```

```
"value": "Commercial",
"label": "Commercial"
},
"caseNumber": "013388",
"createdBy": "636a1ad14d42487767af3f91",
"caseHistory": [
  {
    "id": "277283",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Dec 28 2024 10:22:16 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr.Dilip Shivmurti Bondar & Mrs.Surekha Dilip Bondar",
    "phone": "8237116625",
    "ownershipShare": "",
    "email": "",
    "id": "888491"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "175936",
    "name": "Living Room",
    "length": "20.00",
    "length1": "20",
    "length2": "00",
    "width": "20.00",
    "width1": "20",
    "width2": "00",
    "totalArea": "400.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "400.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "20.00",
  "length1": "20",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
```

```
"totalArea": "40.00",
"images": [],
"extraAreas": [],
"finalArea": "40.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
}
```



```
"id": "6",
"name": "Passage",
"length": "15.00",
"length1": "15",
"length2": "00",
"width": "15.00",
"width1": "15",
"width2": "00",
"totalArea": "225.00",
"images": [],
"extraAreas": [],
"finalArea": "225.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Balcony",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "1.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "87.24",
    "totalAreaDocument": "939",
    "docBultupPercentage": "10",
    "docFinalBultUp": "1032.90",
    "docFinalBultUpSquareMeter": "95.96",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "499160"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "941.67",
      "squareMeterArea": "87.48",
      "expectedRate": "50973.27",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1130.00",
      "squareMeterArea": "104.98",
      "expectedRate": "42477.88",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "1356.00",
      "squareMeterArea": "125.98",
      "expectedRate": "35398.23",
      "percentage": "20"
    },
    "printlnReport": false,
    "_id": "676fd42ddabdc2db790ede1e",
    "property": "Flat",
    "area": "1130",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Housing.Com",
    "expectedPrice": "48000000",
    "expectedRate": "50973.27",
    "builtUpExpectedRate": "48000000",
    "image": "cases/676fd15895b033db3f4c773d/
indicator_1735381654682_Image.png",
    "squareMeter": "104.98",
    "id": "896214"
  },
  {
    "carpetArea": {
      "area": "1083.33",
      "squareMeterArea": "100.64",
      "expectedRate": "6461.56",
      "percentage": ""
    },
  },

```

```
"builtUpArea": {
  "area": "1300.00",
  "squareMeterArea": "120.77",
  "expectedRate": "5384.62",
  "percentage": "20"
},
"saleableArea": {
  "area": "1560.00",
  "squareMeterArea": "144.93",
  "expectedRate": "4487.18",
  "percentage": "20"
},
"printInReport": true,
"_id": "676fd42ddabdc2db790ede1f",
"property": "Flat",
"area": "1300",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "7000000",
"expectedRate": "6461.56",
"builtUpExpectedRate": "7000000",
"image": "cases/676fd15895b033db3f4c773d/
indicator_1735381723503_Image.png",
"squareMeter": "120.77",
"id": "186030"
},
{
  "carpetArea": {
    "area": "750.00",
    "squareMeterArea": "69.68",
    "expectedRate": "7733.33",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "900.00",
    "squareMeterArea": "83.61",
    "expectedRate": "6444.44",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1080.00",
    "squareMeterArea": "100.34",
```

```
    "expectedRate": "5370.37",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "676fd42ddabdc2db790ede20",
  "property": "Flat",
  "area": "900",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "5800000",
  "expectedRate": "7733.33",
  "builtUpExpectedRate": "5800000",
  "image": "cases/676fd15895b033db3f4c773d/
indicator_1735381990521_Image.png",
  "squareMeter": "83.61",
  "id": "359483"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea45",
    "name":
"externalImg_1735383244275_WhatsApp_Image_20241228_at_13536_PM_1.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externalImg_1735383244275_WhatsApp_Image_20241228_at_13536_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea46",
    "name":
"externalImg_1735383244290_WhatsApp_Image_20241228_at_13538_PM.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externalImg_1735383244290_WhatsApp_Image_20241228_at_13538_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "676fd8cddabdc2db790eea47",
    "name":
"externallmg_1735383244304_WhatsApp_Image_20241228_at_13539_PM_1.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244304_WhatsApp_Image_20241228_at_13539_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea48",
    "name":
"externallmg_1735383244318_WhatsApp_Image_20241228_at_13539_PM.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244318_WhatsApp_Image_20241228_at_13539_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea49",
    "name":
"externallmg_1735383244322_WhatsApp_Image_20241228_at_13540_PM_1.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244322_WhatsApp_Image_20241228_at_13540_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea4a",
    "name":
"externallmg_1735383244340_WhatsApp_Image_20241228_at_13540_PM.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244340_WhatsApp_Image_20241228_at_13540_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea4b",
    "name":
"externallmg_1735383244345_WhatsApp_Image_20241228_at_13541_PM.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244345_WhatsApp_Image_20241228_at_13541_PM.jpeg",
    "orientation": "landscape"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "676fd8cddabdc2db790eea4c",
      "name":
"externallmg_1735383244367_WhatsApp_Image_20241228_at_13542_PM_1.jpeg",
      "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244367_WhatsApp_Image_20241228_at_13542_PM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "676fd8cddabdc2db790eea4d",
      "name":
"externallmg_1735383244372_WhatsApp_Image_20241228_at_13542_PM.jpeg",
      "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244372_WhatsApp_Image_20241228_at_13542_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "676fd8cddabdc2db790eea4e",
      "name":
"externallmg_1735383244383_WhatsApp_Image_20241228_at_13543_PM.jpeg",
      "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244383_WhatsApp_Image_20241228_at_13543_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "676fd8cddabdc2db790eea4f",
      "name":
"externallmg_1735383244393_WhatsApp_Image_20241228_at_13544_PM_1.jpeg",
      "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244393_WhatsApp_Image_20241228_at_13544_PM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "676fd8cddabdc2db790eea50",
      "name":
"externallmg_1735383244407_WhatsApp_Image_20241228_at_13544_PM.jpeg",
```

```
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244407_WhatsApp_Image_20241228_at_13544_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea51",
    "name":
"externallmg_1735383244410_WhatsApp_Image_20241228_at_13545_PM.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244410_WhatsApp_Image_20241228_at_13545_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea52",
    "name":
"externallmg_1735383244434_WhatsApp_Image_20241228_at_13546_PM.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244434_WhatsApp_Image_20241228_at_13546_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea53",
    "name":
"externallmg_1735383244440_WhatsApp_Image_20241228_at_13547_PM_1.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244440_WhatsApp_Image_20241228_at_13547_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "676fd8cddabdc2db790eea54",
    "name":
"externallmg_1735383244471_WhatsApp_Image_20241228_at_13547_PM.jpeg",
    "path": "cases/676fd15895b033db3f4c773d/
externallmg_1735383244471_WhatsApp_Image_20241228_at_13547_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "676fd8cddabdc2db790eea55",
  "name":
"externalImg_1735383244475_WhatsApp_Image_20241228_at_13548_PM.jpeg",
  "path": "cases/676fd15895b033db3f4c773d/
externalImg_1735383244475_WhatsApp_Image_20241228_at_13548_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalName": "Dilip Bondar.xlsx",
  "filename": "1735383349213_Dilip_Bondar.xlsx",
  "path": "cases/676fd15895b033db3f4c773d/
processingDocuments/1735383349213_Dilip_Bondar.xlsx",
  "size": "348204",
  "createdAt": "Sat Dec 28 2024 10:55:49 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "636a1ad14d42487767af3f91"
},
{
  "originalName": "BOB - Mr.Dilip Shivmurti Bondar & Mrs.Surekha Dilip Bondar.pdf",
  "filename":
"1735383356803_BOB__MrDilip_Shivmurti_Bondar__MrsSurekha_Dilip_Bondar.pdf",
  "path": "cases/676fd15895b033db3f4c773d/processingDocuments/1735383356803
_BOB__MrDilip_Shivmurti_Bondar__MrsSurekha_Dilip_Bondar.pdf",
  "size": "6192344",
  "createdAt": "Sat Dec 28 2024 10:55:58 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "636a1ad14d42487767af3f91"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-28T10:22:16.558Z",
"updatedAt": "2024-12-28T11:25:57.961Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Mr.Dilip Shivmurti Bondar & Mrs.Surekha Dilip Bondar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
```

```
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "8237116625",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 939.00",
"flatRate": "7700",
"landOtherRate": "5700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage + 3
Balcony",
"carpetTotal": "938.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1031.80",
"finalCarpetArea": "938.00",
"finalSalableArea": "1134.98",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Sat Dec 28 2024 10:34:31 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-28",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
```

```

    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	20'00"	20'00"	400.00
Kitchen	10'00"	10'00"	100.00
Bedroom	10'00"	10'00"	100.00
Bedroom	20'00"	2'00"	40.00
Toilet	7'00"	5'00"	35.00
Toilet	7'00"	5'00"	35.00
Passage	15'00"	15'00"	225.00
Balcony	1'00"	1'00"	1.00
Balcony	1'00"	1'00"	1.00
Balcony	1'00"	1'00"	1.00
Other Composition :			