

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "632ee4c4e2561b46f656d584"
    },
    "firstName": "testadgaon",
    "type": "CREDITOFFICER",
    "_id": "635f7a01e363ef22db2f2417",
    "lastName": "adgaon",
    "mobileNo": "",
    "email": "adgaon@vastukala.org",
    "workMobileNo": "0000000000"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "632ee4c4e2561b46f656d584",
  "name": "RACPC Adgaon,",
  "branchCode": "14",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "me@me.sbi",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RACPC Adgaon, Nashik Branch,Nshik, Maharashtra State –
Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "shortName": "cc",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
  "deliveryPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
    "email": "rushipingle2201@gmail.com",
    "lastName": "Pingle",
    "mobileNo": "8788210361",
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
    "role": "MAKER + RATE VERFIER",
    "firstName": "Chintamani",
    "email": "chintamanichaudhari099@gmail.com",
    "lastName": "Chaudhari",
    "mobileNo": "8007230780",
    "designation": "",
    "shortName": "cc",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
    "role": "MAKER + RATE VERFIER",
    "firstName": "Chintamani",
    "email": "chintamanichaudhari099@gmail.com",
    "lastName": "Chaudhari",
    "mobileNo": "8007230780",
```

```
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
```

```
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
```

```
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.961225",
  "longitude": "73.839518"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "30/12/2024 12:00 am"
    },
    {
      "dateTime": "30/12/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-30",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-30",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-29",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-28",
      "remark": "MANUAL_IN_TASK"
    }
  ]
}
```

```
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Deolali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "08",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sagar Heritage Apartment",
  "label": false
},
}
```



```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Jail Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp.Sent Philomena High School, Behind Indain Oil Petrol Pump",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```

```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "129/A+130/A/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "14",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```

```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
```

```

    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  }
}

```

```
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Plot No.7",
  "west": "30.00 Meter wide Road",
  "south": "Petrol Pump & Plot No.9",
  "east": "Survey No.130A/1"
},
"asPerDocumentAgreement": {
  "north": "Plot No.7",
  "west": "30.00 Meter wide Road",
  "south": "Petrol Pump & Plot No.9",
  "east": "Survey No.130A/1"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Passage & Staircase",
    "south": "Flat No.13",
    "west": "Other Wing Staircase"
  },
  "asPerDocument": {
    "north": "Marginal Space",
    "east": "Passage & Staircase",
    "south": "Flat No.13",
    "west": "Other Wing Staircase"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
```

```
    },
    "extraDetailOfProperty": "",
    "dateOfIssusApprovePlan": "Copy of Building Plan Document No.NMC/ II/ LND/ BP/
78/2006 Dated 30.09.2006,Issued by NMC",
    "approvePlanVerified": "Yes",
    "empanelledOfApprovePlan": "No",
    "unauthorizedConstruction": "",
    "extraDetailOfBuilding": "",
    "compoundWall": ""
  },
  "apfDetails": {
    "buildings": [],
    "compositions": []
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "24",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "depreciatedCostOfConstruction": "4020",
    "depreciatedBuildingRate": "1520"
  },
  "igrRate": {
    "propertyName": "Flat",
    "rate": "37500",
    "landRate": "13300",
    "igrImage": "cases/6772832b95b033db3f4d4873/igr_1735558214007_Image.png",
    "squareMeterGuideLineRate": "37500.00",
    "squareFeetGuideLineRate": "3484.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "0",
    "depreciationPercentage": "84",
    "rate": "3124.00",
    "squareFeetGuideLineRate": "3124.00",
    "squareMeterGuideLineRate": "33628.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Middle_Class",
      "label": "Middle Class"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    }
  },
}
```

```
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "NA",
"taxPaidHolderName": "NA",
"taxAmount": "NA",
"electricityServiceConnectionNo": "NA",
"meterCardHolderName": "NA",
"undividedAreaOfLandAsPerSaleDeed": "NA",
"floorSpaceIndex": "as per NMC Nomrs",
"tenantName": "",
"maintenanceOfFlat": "NA"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "NA",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
```

```
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2008",
  "fullDate": "1/1/2008"
},
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Yes",
  "label": "Yes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
```



```
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "16",
"totalLifeBuilding": "60",
"estimatedAge": "44",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
```

```
},
"finalPlinthArea": {
  "area": "1100.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Deed of Apartment"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6772832b95b033db3f4d4873/
routeMap_1735558938266_Image.png",
    "routeLat": "19.961112",
    "routeLng": "73.839505",
    "stationName": "Nashik Road",
    "routeDistance": "1.9",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "ba228",
      "name": "ba228",
      "image": "cases/6772832b95b033db3f4d4873/
routeMap_1735558870887_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
}
```

```
},
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "300000",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4722000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4422000.00",
"purchaseValueDocument": {
  "documentType": {
    "value": "60ae1269aa6d152c1801b389",
    "label": "Deed of Apartment"
  }
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1735557706486_Saled deed_OC.pdf",
"path": "cases/6772832b95b033db3f4d4873/
document_1735557706486_Saled deed_OC.pdf",
"id": "884868",
"uploadedBy": "636a1ad14d42487767af3f91",
"createdAt": "Mon Dec 30 2024 11:25:31 GMT+0000 (Coordinated Universal Time)",
```

```
"from": {
  "value": "Seller",
  "label": "Seller"
},
"seller": "Shri.Shailesh Vasant Vaidya",
"to": {
  "value": "The_Apartment_Owner",
  "label": "The Apartment Owner"
},
"The_Apartment_Owner": "Shri.Chetan Sakahhari Vaydande & Sau.Kirti Chetan
Vaydande "
}
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Dec 30 2024 11:51:15 GMT+0000 (Coordinated Universal Time)",
  "number": "2309860",
  "dayCount": "10",
  "monthCount": "558",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "3436400.00",
  "selectedBuildUpValue": "1100.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "677287a295b033db3f4d51e2",
      "name":
"externallmg_1735559072856_WhatsApp_Image_20241230_at_45226_PM.jpeg",
      "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072856_WhatsApp_Image_20241230_at_45226_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "6773968b95b033db3f4da632",
      "name":
"externallmg_1735628414048_WhatsApp_Image_20241231_at_122639_PM.jpeg",
      "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735628414048_WhatsApp_Image_20241231_at_122639_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "compositionImages": [
    {
      "status": false,
      "_id": "677287a295b033db3f4d51ef",
      "name": "Living Room",
      "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073178_WhatsApp_Image_20241230_at_45234_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51ee",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073151_WhatsApp_Image_20241230_at_45233_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51ed",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073127_WhatsApp_Image_20241230_at_45233_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51eb",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073089_WhatsApp_Image_20241230_at_45232_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51ec",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073112_WhatsApp_Image_20241230_at_45233_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51e8",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073031_WhatsApp_Image_20241230_at_45230_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51e7",
    "name": "Living Room",
```



```
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073005_WhatsApp_Image_20241230_at_45230_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51e5",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072963_WhatsApp_Image_20241230_at_45229_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51e6",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072983_WhatsApp_Image_20241230_at_45229_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51e4",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072918_WhatsApp_Image_20241230_at_45228_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51e2",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072856_WhatsApp_Image_20241230_at_45226_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677287a295b033db3f4d51e3",
    "name": "Living Room",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072915_WhatsApp_Image_20241230_at_45227_PM_2.jpeg",
    "orientation": "landscape"
  }
]
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "5159.00",
    "max": "5770.00"
  },
  "builtUpRateRange": {
    "min": "4299.00",
    "max": "4808.00"
  },
  "saleableRateRange": {
    "min": "3583.00",
    "max": "4007.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1100.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "DELIVERED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6772832b95b033db3f4d4873",
"ownerName": "Shri.Chetan Sakhahari Vaydande & Sau.Kirti Chetan Vaydande ",
```

```
"ownerPhoneNo": "9021337843",
"fullAddress": "Residential Flat No. 14, 2nd Floor, Sagar Heritage Apartment,
Opp.Sent Philomena High School, Behind Indain Oil Petrol Pump, Plot No. 08, Jail
Road, Village - Deolali, Taluka - Nashik, District - Nashik, 422101, State - Maharashtra,
India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "inputs": {
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Shri.Shailesh Vasant Vaidya",
      "to": {
        "value": "The_Apartment_Owner",
        "label": "The Apartment Owner"
      },
      "The_Apartment_Owner": "Shri.Chetan Sakhahari Vaydande & Sau.Kirti Chetan
Vaydande "
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1735557706486_Saledeed_OC.pdf",
    "path": "cases/6772832b95b033db3f4d4873/
document_1735557706486_Saledeed_OC.pdf",
    "id": "884868",
    "uploadedBy": "636a1ad14d42487767af3f91",
    "createdAt": "Mon Dec 30 2024 11:25:31 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "20/06/2008",
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      },
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "Javak No.NRV/NASHIK ROAD/0673"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1735557785777_Saledeed_OC.pdf",
"path": "cases/6772832b95b033db3f4d4873/
document_1735557785777_Saledeed_OC.pdf",
"id": "128602",
"uploadedBy": "636a1ad14d42487767af3f91",
"createdAt": "Mon Dec 30 2024 11:25:31 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "documentDate": "30/09/2006",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "NMC/ II/ LND/ BP/ 78/2006"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "617786",
  "path": "cases/6772832b95b033db3f4d4873/
document_1735557858970_Vaydande_Plan_1.pdf",
  "fileName": "document_1735557858970_Vaydande_Plan_1.pdf"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013403",
"createdBy": "636a1ad14d42487767af3f91",
"caseHistory": [
```

```
{
  "id": "928734",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Mon Dec 30 2024 11:25:31 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
  {
    "name": "Shri.Chetan Sakahari Vaydande & Sau.Kirti Chetan Vaydande ",
    "phone": "9021337843",
    "ownershipShare": "",
    "email": "",
    "id": "695830"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "344682",
    "name": "Living Room",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "20.00",
    "width1": "20",
    "width2": "00",
    "totalArea": "200.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "200.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "10.00",
    "length1": "10",
```

```
"length2": "00",
"width": "15.00",
"width1": "15",
"width2": "00",
"totalArea": "150.00",
"images": [],
"extraAreas": [],
"finalArea": "150.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "15.00",
  "width1": "15",
  "width2": "00",
  "totalArea": "225.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "225.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "15.00",
  "width1": "15",
  "width2": "00",
  "totalArea": "225.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "225.00"
},
{
```



```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "4",
"name": "Toilet",
"length": "5.00",
"length1": "5",
"length2": "00",
"width": "5.00",
"width1": "5",
"width2": "00",
"totalArea": "25.00",
"images": [],
"extraAreas": [],
"finalArea": "25.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
```

```
"width1": "1",
"width2": "00",
"totalArea": "1.00",
"images": [],
"extraAreas": [],
"finalArea": "1.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "1.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "102.19",
    "totalAreaDocument": "1100",
    "docBuiltpupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "178053"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "995.00",
      "squareMeterArea": "92.44",
      "expectedRate": "5158.79",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1194.00",
      "squareMeterArea": "110.93",
      "expectedRate": "4298.99",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "1432.80",
      "squareMeterArea": "133.11",
      "expectedRate": "3582.50",
      "percentage": "20"
    },
    "printlnReport": true,
    "_id": "67739eef95b033db3f4dae05",
    "property": "Flat",
```

```
"area": "1194",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "5133000",
"expectedRate": "5158.79",
"builtUpExpectedRate": "5133000",
"image": "cases/6772832b95b033db3f4d4873/
indicator_1735630575727_Image.png",
"squareMeter": "110.93",
"id": "682712"
},
{
"carpetArea": {
"area": "866.67",
"squareMeterArea": "80.52",
"expectedRate": "5769.21",
"percentage": ""
},
"builtUpArea": {
"area": "1040.00",
"squareMeterArea": "96.62",
"expectedRate": "4807.69",
"percentage": "20"
},
"saleableArea": {
"area": "1248.00",
"squareMeterArea": "115.94",
"expectedRate": "4006.41",
"percentage": "20"
},
"printlnReport": true,
"_id": "67739fa6dabdc2db791007be",
"property": "Flat",
"area": "1040",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "RealEstateIndia",
"expectedPrice": "5000000",
"expectedRate": "5769.21",
```

```
    "builtUpExpectedRate": "5000000",
    "image": "cases/6772832b95b033db3f4d4873/
indicator_1735630758776_Image.png",
    "squareMeter": "96.62",
    "id": "175760"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e1",
    "name":
"externallmg_1735559072799_WhatsApp_Image_20241230_at_45225_PM.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072799_WhatsApp_Image_20241230_at_45225_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e2",
    "name":
"externallmg_1735559072856_WhatsApp_Image_20241230_at_45226_PM.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072856_WhatsApp_Image_20241230_at_45226_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e3",
    "name":
"externallmg_1735559072915_WhatsApp_Image_20241230_at_45227_PM_2.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072915_WhatsApp_Image_20241230_at_45227_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e4",
    "name":
"externallmg_1735559072918_WhatsApp_Image_20241230_at_45228_PM.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072918_WhatsApp_Image_20241230_at_45228_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e5",
    "name":
"externallmg_1735559072963_WhatsApp_Image_20241230_at_45229_PM_1.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072963_WhatsApp_Image_20241230_at_45229_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e6",
    "name":
"externallmg_1735559072983_WhatsApp_Image_20241230_at_45229_PM.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559072983_WhatsApp_Image_20241230_at_45229_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e7",
    "name":
"externallmg_1735559073005_WhatsApp_Image_20241230_at_45230_PM_1.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073005_WhatsApp_Image_20241230_at_45230_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e8",
    "name":
"externallmg_1735559073031_WhatsApp_Image_20241230_at_45230_PM.jpeg",
    "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073031_WhatsApp_Image_20241230_at_45230_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677287a295b033db3f4d51e9",
```

```
    "name":
"externallmg_1735559073050_WhatsApp_Image_20241230_at_45231_PM_1.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073050_WhatsApp_Image_20241230_at_45231_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677287a295b033db3f4d51ea",
  "name":
"externallmg_1735559073071_WhatsApp_Image_20241230_at_45231_PM.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073071_WhatsApp_Image_20241230_at_45231_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677287a295b033db3f4d51eb",
  "name":
"externallmg_1735559073089_WhatsApp_Image_20241230_at_45232_PM.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073089_WhatsApp_Image_20241230_at_45232_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677287a295b033db3f4d51ec",
  "name":
"externallmg_1735559073112_WhatsApp_Image_20241230_at_45233_PM_1.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073112_WhatsApp_Image_20241230_at_45233_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677287a295b033db3f4d51ed",
  "name":
"externallmg_1735559073127_WhatsApp_Image_20241230_at_45233_PM_2.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073127_WhatsApp_Image_20241230_at_45233_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677287a295b033db3f4d51ee",
  "name":
"externallmg_1735559073151_WhatsApp_Image_20241230_at_45233_PM.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073151_WhatsApp_Image_20241230_at_45233_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677287a295b033db3f4d51ef",
  "name":
"externallmg_1735559073178_WhatsApp_Image_20241230_at_45234_PM.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735559073178_WhatsApp_Image_20241230_at_45234_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6773967f95b033db3f4da5f2",
  "name":
"externallmg_1735628414048_WhatsApp_Image_20241231_at_122639_PM.jpeg",
  "path": "cases/6772832b95b033db3f4d4873/
externallmg_1735628414048_WhatsApp_Image_20241231_at_122639_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
  {
    "originalname": "Chetan Sakhahari Vaydande Sau.Kirti Chetan Vaydande (2).pdf",
    "filename": "1735561918356_Chetan_Sakhahari_Vaydande____SauKirti_Chetan_Vaydande_2.pdf",
    "path": "cases/6772832b95b033db3f4d4873/externalDocuments/1735561918356_C
hetan_Sakhahari_Vaydande____SauKirti_Chetan_Vaydande_2.pdf",
    "size": "9128299",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Mon Dec 30 2024 12:32:07 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
]
```



```
{
  "originalname": "oc Chetan Sakhahari Vaydande.pdf",
  "filename": "1735563808639_oc_Chetan_Sakhahari_Vaydande.pdf",
  "path": "cases/6772832b95b033db3f4d4873/
externalDocuments/1735563808639_oc_Chetan_Sakhahari_Vaydande.pdf",
  "size": "361751",
  "documentType": {
    "value": "60ae124daa6d152c1801b307",
    "label": "Office Copy"
  },
  "createdAt": "Mon Dec 30 2024 13:03:29 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
],
"processingDocuments": [
  {
    "originalname": "Chetan Vaydande.xlsx",
    "filename": "1735559291492_Chetan_Vaydande.xlsx",
    "path": "cases/6772832b95b033db3f4d4873/
processingDocuments/1735559291492_Chetan_Vaydande.xlsx",
    "size": "408186",
    "createdAt": "Mon Dec 30 2024 11:48:28 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  },
  {
    "originalname": "SBI - Shri.Chetan Sakhahari Vaydande & Sau.Kirti Chetan
Vaydande.pdf",
    "filename": "1735559297441_SBI__ShriChetan_Sakhahari_Vaydande____SauKirti
_Chetan_Vaydande.pdf",
    "path": "cases/6772832b95b033db3f4d4873/processingDocuments/1735559297441
_SBI__ShriChetan_Sakhahari_Vaydande____SauKirti_Chetan_Vaydande.pdf",
    "size": "6153716",
    "createdAt": "Mon Dec 30 2024 11:48:28 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "63f9ed37ce84bf289ba991ac",
      "role": "FRONTDESK",
      "firstName": "Rushikesh",
      "lastName": "Pingle",
      "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
    }
  }
]
```

```
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "67738f5095b033db3f4d9b2f",
    "note": "change (Task Reopen)",
    "taskId": "6772846496317adb45165f49",
    "createdAt": "2024-12-31T06:29:36.147Z"
  }
],
"createdAt": "2024-12-30T11:25:31.462Z",
"updatedAt": "2024-12-31T07:43:07.342Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a1ad14d42487767af3f91",
"contactPersonName": "Shri.Chetan Sakhahari Vaydande & Sau.Kirti Chetan Vaydande ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9021337843",
"buildingServicesRate": "2000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Deed of Apartment",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1100.00",
"flatRate": "4500",
"landOtherRate": "2500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 3 Toilet + Balcony + Passage",
```

```

"carpetTotal": "827.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "911.90",
"finalCarpetArea": "829.00",
"finalSalableArea": "1185.47",
"salablePercentage": "30",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Mon Dec 30 2024 11:30:51 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-12-28",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'00"	20'00"	200.00
Kitchen	10'00"	15'00"	150.00
Bedroom	15'00"	15'00"	225.00
Bedroom	15'00"	15'00"	225.00

Toilet	5'00"	5'00"	25.00
Toilet	1'00"	1'00"	1.00
Toilet	1'00"	1'00"	1.00
Balcony	1'00"	1'00"	1.00
Passage	1'00"	1'00"	1.00
Other Composition :			