

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6752e66dbefd7f3db9064f99"
    },
    "firstName": "Sandesh",
    "type": "CREDITOFFICER",
    "_id": "6752e69bc5a60c3e016eba87",
    "email": "sandesh.sukhdare@janatabankpune.com",
    "lastName": "Sukhdare",
    "mobileNo": "",
    "workMobileNo": "7977641271"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Sandesh",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "645c92ba7f94762ec7884195",
  "type": "BANK",
  "name": "Janta Sahkari Bank LTD",
  "displayName": "Janta Sahkari Bank LTD\t",
  "initial": "JSB"
},
"branch": {
  "_id": "6752e66dbefd7f3db9064f99",
  "name": "Fort",
  "branchCode": "",
  "mobileNo": "7977641271",
  "alternateMobileNo": "",
  "email": "fort@janatabankpune.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Plot No. 11 & 12, CTS No. 1900 & 1901, Janmabhoomi Bhavan,
Janmabhoomi Marg, Fort, Mumbai - 400 001"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "645c93d47f94762ec788472a",
  "zoneName": "Mumbai Metro"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "665ac13f42f4717ae30de3d5",
    "role": "PICKUPPERSON",
    "firstName": "NIDHI",
```

```
"email": "nidhi.kajwe97@gmail.com",
"lastName": "KAJWE",
"mobileNo": "8850520881",
"shortName": "NIDHI",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
```

```
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.123575484635932",
  "longitude": "72.91312808646482"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.91312808646482,
    19.123575484635932
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2/01/2025 12:00 am"
    },
    {
      "dateTime": "2/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
}
```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Powai",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Powai Plaza",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Adi Shankracharya Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```



```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "48",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400076",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
```

```
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67766bec40248ae0addcbdb0",
"ownerName": "Vinod Govabhai Bangari & Dharti Vinod Bangari",
"ownerPhoneNo": "9604207720",
"appAddress": "Shop No 48 Powai Plaza Adi Shankaracharya Marg Powai Mumbai -
400076",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
```

```
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67766bec40248ae0addcbdb0/
document_1735814103873_1735814101478_DocScanner_Jan_1_2025_424_PM.pdf",
  "fileName":
"document_1735814103873_1735814101478_DocScanner_Jan_1_2025_424_PM.pdf",
  "id": "684934",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Thu Jan 02 2025 10:35:24 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "013448",
"createdBy": "665ac13f42f4717ae30de3d5",
"caseHistory": [
  {
    "id": "404022",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 02 2025 10:35:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Vinod Govabhai Bangari & Dharti Vinod Bangari",
    "phone": "9604207720",
    "ownershipShare": "",
    "email": "",
    "id": "891630"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef1e",
    "name": "externallmg_1735906258315_1735906254637_image_0.jpeg",
```

```
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906258315_1735906254637_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef1f",
    "name": "externallmg_1735906258952_1735906254637_image_1.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906258952_1735906254637_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef20",
    "name": "externallmg_1735906259427_1735906254637_image_2.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906259427_1735906254637_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef21",
    "name": "externallmg_1735906260121_1735906254637_image_3.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906260121_1735906254637_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef22",
    "name": "externallmg_1735906260455_1735906254637_image_4.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906260455_1735906254637_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef23",
    "name": "externallmg_1735906260970_1735906254637_image_5.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906260970_1735906254637_image_5.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6777d3d982ea0d50e100ef24",
  "name": "externallmg_1735906261263_1735906254637_image_6.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906261263_1735906254637_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6777d3d982ea0d50e100ef25",
  "name": "externallmg_1735906261757_1735906254637_image_7.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906261757_1735906254637_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6777d3d982ea0d50e100ef26",
  "name": "externallmg_1735906262015_1735906254637_image_8.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906262015_1735906254637_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6777d3d982ea0d50e100ef27",
  "name": "externallmg_1735906262451_1735906254637_image_9.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906262451_1735906254637_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6777d3d982ea0d50e100ef28",
  "name": "externallmg_1735906262553_1735906254637_image_10.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906262553_1735906254637_image_10.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef29",
    "name": "externallmg_1735906262842_1735906254637_image_11.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906262842_1735906254637_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef2a",
    "name": "externallmg_1735906263167_1735906254637_image_12.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906263167_1735906254637_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef2b",
    "name": "externallmg_1735906263476_1735906254637_image_13.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906263476_1735906254637_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef2c",
    "name": "externallmg_1735906263916_1735906254637_image_14.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906263916_1735906254637_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6777d3d982ea0d50e100ef2d",
    "name": "externallmg_1735906264215_1735906254637_image_15.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906264215_1735906254637_image_15.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6777d3d982ea0d50e100ef2e",
  "name": "externalImg_1735906264668_1735906254637_image_16.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906264668_1735906254637_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6777d3fc82ea0d50e100ef91",
  "name": "externalImg_1735906294465_1735906292081_image_0.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906294465_1735906292081_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6777d3fc82ea0d50e100ef92",
  "name": "externalImg_1735906294738_1735906292081_image_1.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906294738_1735906292081_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6777d3fc82ea0d50e100ef93",
  "name": "externalImg_1735906294945_1735906292081_image_2.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906294945_1735906292081_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6777d3fc82ea0d50e100ef94",
  "name": "externalImg_1735906295163_1735906292081_image_3.jpeg",
  "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906295163_1735906292081_image_3.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef95",
    "name": "externallmg_1735906295355_1735906292081_image_4.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906295355_1735906292081_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef96",
    "name": "externallmg_1735906295520_1735906292081_image_5.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906295520_1735906292081_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef97",
    "name": "externallmg_1735906296318_1735906292081_image_6.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906296318_1735906292081_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef98",
    "name": "externallmg_1735906296945_1735906292081_image_7.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906296945_1735906292081_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef99",
    "name": "externallmg_1735906297456_1735906292081_image_8.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externallmg_1735906297456_1735906292081_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef9a",
    "name": "externalImg_1735906297988_1735906292081_image_9.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906297988_1735906292081_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef9b",
    "name": "externalImg_1735906298934_1735906292081_image_10.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906298934_1735906292081_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6777d3fc82ea0d50e100ef9c",
    "name": "externalImg_1735906299338_1735906292081_image_11.jpeg",
    "path": "cases/67766bec40248ae0addcbdb0/
externalImg_1735906299338_1735906292081_image_11.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr1.pdf",
    "filename": "1735897251995_igr1.pdf",
    "path": "cases/67766bec40248ae0addcbdb0/
processingDocuments/1735897251995_igr1.pdf",
    "size": "131519",
    "createdAt": "Fri Jan 03 2025 09:40:52 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1735897252003_igr2.pdf",
    "path": "cases/67766bec40248ae0addcbdb0/
processingDocuments/1735897252003_igr2.pdf",
    "size": "131192",
    "createdAt": "Fri Jan 03 2025 09:40:52 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
],
```



```
{
  "originalname": "igr3.pdf",
  "filename": "1735897252007_igr3.pdf",
  "path": "cases/67766bec40248ae0addcbdb0/
processingDocuments/1735897252007_igr3.pdf",
  "size": "134517",
  "createdAt": "Fri Jan 03 2025 09:40:52 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr4.pdf",
  "filename": "1735897252032_igr4.pdf",
  "path": "cases/67766bec40248ae0addcbdb0/
processingDocuments/1735897252032_igr4.pdf",
  "size": "132660",
  "createdAt": "Fri Jan 03 2025 09:40:52 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - Vinod.xlsx",
  "filename": "1735897252038_Summary__Vinod.xlsx",
  "path": "cases/67766bec40248ae0addcbdb0/
processingDocuments/1735897252038_Summary__Vinod.xlsx",
  "size": "1740159",
  "createdAt": "Fri Jan 03 2025 09:40:52 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6777b09182ea0d50e100bb75",
    "note": "working done. visit pending",
    "taskId": "67768094b40b8ce125dc2d86",
  }
]
```

```

    "createdAt": "2025-01-03T09:40:33.530Z"
  }
],
"createdAt": "2025-01-02T10:35:24.386Z",
"updatedAt": "2025-01-03T12:11:40.585Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Shop No. 48, Ground Floor, Powai Plaza, Adi
Shankracharya Marg, Village - Powai, Mumbai, 400076, State - Maharashtra, India",
"updatedBy": "62550ed0aba01e0af98f2f75",
"addressForMap": "",
"caseReferredBy": "665ac13f42f4717ae30de3d5",
"contactPersonName": "Vinod Govabhai Bangari & Dharti Vinod Bangari",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9604207720"
}

```

| Name | Length | Width | Total |
|---------------|--------|-------|-------|
| Composition : | | | |
| Other | | | |
| Composition : | | | |