

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6401aa2a0e28255fb44e5222"
    },
    "firstName": "Minakshi\t",
    "type": "CREDITOFFICER",
    "_id": "6524deba703d7c40db979df7",
    "lastName": "Ajila\t",
    "mobileNo": "",
    "workMobileNo": "9930375648",
    "email": "1bmmsro0630@centrabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2549928",
    "discussWithPerson": "Minakshi\t",
    "expectedFees": 1274.964,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6401aa2a0e28255fb44e5222",
  "name": "Kandivali East Branch",
  "branchCode": "",
  "mobileNo": "02228546591",
  "alternateMobileNo": "",
  "email": "bmmsro0630@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground Floor, G-Bungalow, Crystal Lane, Thakur Complex, Kandivali
east, Mumbai - 400 101 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "FRONTDESK",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordination",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": ""
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.283817445651906",
  "longitude": "72.87636833424749"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87636833424749,
    19.283817445651906
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/01/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "RITU PARADISE C & D WING CO-OP. HOUSING SOCIETY LTD",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "NEAR HARIA'S DREAM PARK",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "OFF MIRA-BHAYANDER ROAD",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "302",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401107",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "OFF MIRA-BHAYANDER ROAD EAST",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67780e2d4dad6a51548f2ef2",
"ownerName": "Mrs.Priyanka Baburao More ",
"ownerPhoneNo": "9819084836",
"appAddress": "Flat no 302 C-wing 3 rd Floor Bldg Ritu Paradise C & D Wing Co-op
HSG Soc Ltd Mira Bhayander Road Mira road East 401107",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "label": "Draft Agreement",
  "value": "60ae124aaa6d152c1801b2f8"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/67780e2d4dad6a51548f2ef2/document_1735920332640_1735920329786_RITU_PARADISE_PHASE30211_draft.doc",
"fileName": "document_1735920332640_1735920329786_RITU_PARADISE_PHASE30211_draft.doc",
"id": "489293",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Fri Jan 03 2025 16:19:57 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67780e2d4dad6a51548f2ef2/document_1735920369672_1735920366921_OC.pdf",
  "fileName": "document_1735920369672_1735920366921_OC.pdf",
  "id": "118750",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Fri Jan 03 2025 16:19:57 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Share Certificate ",
    "value": "60ae1264aa6d152c1801b371"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67780e2d4dad6a51548f2ef2/document_1735920428570_1735920418061_Share_certificate_.pdf",
  "fileName": "document_1735920428570_1735920418061_Share_certificate_.pdf",
  "id": "220477",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Fri Jan 03 2025 16:19:57 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Gift Deed",
    "value": "60ae1251aa6d152c1801b317"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67780e2d4dad6a51548f2ef2/
document_1735920514213_1735920511516_GIFT_DEED_0001.pdf",
    "fileName": "document_1735920514213_1735920511516_GIFT_DEED_0001.pdf",
    "id": "172376",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Jan 03 2025 16:19:57 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67780e2d4dad6a51548f2ef2/
document_1735920889223_1735920854995_SELL_AGREEMENT_0001.pdf",
    "fileName":
"document_1735920889223_1735920854995_SELL_AGREEMENT_0001.pdf",
    "id": "517003",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Jan 03 2025 16:19:57 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013473",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "411359",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jan 03 2025 16:19:57 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mrs.Priyanka Baburao More ",
    "phone": "9819084836",
    "ownershipShare": "",
    "email": "",
    "id": "598633"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677eaa05fca4a7f46de3e148",
    "name": "externalImg_1736354268286_1736354238256_image_0.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externalImg_1736354268286_1736354238256_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677eaa05fca4a7f46de3e149",
    "name": "externalImg_1736354277060_1736354238256_image_1.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externalImg_1736354277060_1736354238256_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677eaa05fca4a7f46de3e14a",
    "name": "externalImg_1736354286770_1736354238256_image_2.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externalImg_1736354286770_1736354238256_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677eaa05fca4a7f46de3e14b",
    "name": "externalImg_1736354303071_1736354238256_image_3.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externalImg_1736354303071_1736354238256_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "677eaa21b80a2bf43605ea19",
    "name": "externallmg_1736354238109_1736354220773_image_0.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354238109_1736354220773_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea1a",
    "name": "externallmg_1736354240860_1736354220773_image_1.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354240860_1736354220773_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea1b",
    "name": "externallmg_1736354242185_1736354220773_image_2.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354242185_1736354220773_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea1c",
    "name": "externallmg_1736354247746_1736354220773_image_3.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354247746_1736354220773_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea1d",
    "name": "externallmg_1736354252890_1736354220773_image_4.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354252890_1736354220773_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "677eaa21b80a2bf43605ea1e",
    "name": "externallmg_1736354259026_1736354220773_image_5.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354259026_1736354220773_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea1f",
    "name": "externallmg_1736354266766_1736354220773_image_6.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354266766_1736354220773_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea20",
    "name": "externallmg_1736354272213_1736354220773_image_7.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354272213_1736354220773_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea21",
    "name": "externallmg_1736354276407_1736354220773_image_8.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354276407_1736354220773_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea22",
    "name": "externallmg_1736354281375_1736354220773_image_9.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354281375_1736354220773_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea23",
```

```
    "name": "externallmg_1736354281480_1736354220773_image_10.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354281480_1736354220773_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea24",
    "name": "externallmg_1736354321239_1736354220773_image_11.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354321239_1736354220773_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea25",
    "name": "externallmg_1736354323521_1736354220773_image_12.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354323521_1736354220773_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea26",
    "name": "externallmg_1736354324922_1736354220773_image_13.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354324922_1736354220773_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea27",
    "name": "externallmg_1736354327837_1736354220773_image_14.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354327837_1736354220773_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea28",
    "name": "externallmg_1736354329825_1736354220773_image_15.jpeg",
```

```
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354329825_1736354220773_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea29",
    "name": "externallmg_1736354331903_1736354220773_image_16.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354331903_1736354220773_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea2a",
    "name": "externallmg_1736354333358_1736354220773_image_17.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354333358_1736354220773_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea2b",
    "name": "externallmg_1736354334783_1736354220773_image_18.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354334783_1736354220773_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677eaa21b80a2bf43605ea2c",
    "name": "externallmg_1736354335924_1736354220773_image_19.jpeg",
    "path": "cases/67780e2d4dad6a51548f2ef2/
externallmg_1736354335924_1736354220773_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```



```

"createdAt": "2025-01-03T16:19:57.988Z",
"updatedAt": "2025-01-08T16:38:57.252Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62691c48afd7d55eddecfda3",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 302, 3rd Floor, Wing - C, RITU PARADISE C & D
WING CO-OP. HOUSING SOCIETY LTD, NEAR HARIA'S DREAM PARK, OFF MIRA-
BHAYANDER ROAD, OFF MIRA-BHAYANDER ROAD EAST, 401107, State -
Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mrs.Priyanka Baburao More ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9819084836"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			