

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Rajesh",
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmechby@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.308284375629874",
  "longitude": "72.85835228112506"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85835228112506,
    19.308284375629874
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "4/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-05",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Mira",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "6-7",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shalibhadra Gram",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mira Bhayandar Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
```



```
"name": "Wing",
"key": "wing",
"value": "B",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "New Shalibhadra Gram Co-op. Hsg. Soc. LTd.",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "19",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "74",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B-G-2",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```

    "key": "GUTNo",
    "value": "",
    "label": true
  },
  "postalCode": {
    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN - 401 107",
    "label": false
  },
  "suburb": {
    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Kashimira",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},

```

```
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building No. 6",
    "west": "Urdu School",
    "south": "Building No. 8",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Information not available",
    "west": "Information not available",
    "south": "Information not available",
    "east": "Information not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Marginal Space",
      "south": "Flat No. B-G-3",
      "west": "Flat No. B-G-1 / Staircase"
    },
    "asPerDocument": {
      "north": "Information not available",
      "east": "Information not available",
      "south": "Information not available",
      "west": "Information not available"
    }
  },
}
```

```
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "37.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "10000",
  "depreciatedBuildingRate": "1500"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "97700",
  "landRate": "28700",
  "igrImage": "cases/6778cebca5477d50e7dca14c/igr_1736145658887_Image.png",
  "squareMeterGuideLineRate": "97700.00",
  "squareFeetGuideLineRate": "9077.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "75",
  "rate": "7474.00",
  "squareMeterGuideLineRate": "80450.00",
  "squareFeetGuideLineRate": "7474.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "Rs. 9,000/- Present rental income per month.",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "Mr. Kailash from 6 months",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
```

```
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
```

```
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
}
```



```
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "35",
"ageOfBuilding": "25",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "Ground",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "310.00",
  "areaType": "Saleable",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6778cebca5477d50e7dca14c/
routeMap_1736147429788_Image.png",
    "routeLat": "19.274831",
    "routeLng": "72.881052",
    "stationName": "Mira Road",
    "routeDistance": "4.1 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
}
```

```
},
"locationMapImg": [
  {
    "id": "u1zb3qr",
    "name": "u1zb3qr",
    "image": "cases/6778cebca5477d50e7dca14c/
routeMap_1736147314417_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3100000.00",
  "distressValuePercentage": "80",
```

```
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "3100000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2316940.00",
  "selectedBuildUpValue": "310.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "677b7f64f37fa6d52b97949d",
    "name":
"externallmg_1736146788093_WhatsApp_Image_20250106_at_121755_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146788093_WhatsApp_Image_20250106_at_121755_PM.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "677b8076f37fa6d52b97990e",
    "name":
"externallmg_1736147061971_WhatsApp_Image_20250106_at_121807_PM_1.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147061971_WhatsApp_Image_20250106_at_121807_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "677b7f508ebdf2d52561c1e2",
    "name":
"externallmg_1736146768178_WhatsApp_Image_20250106_at_121754_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146768178_WhatsApp_Image_20250106_at_121754_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677b804bf37fa6d52b97983f",
    "name":
"externallmg_1736147018642_WhatsApp_Image_20250106_at_121805_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147018642_WhatsApp_Image_20250106_at_121805_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
```

```
    "status": false,
    "_id": "677b7f828ebdf2d52561c250",
    "name": "Living Room",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146818132_WhatsApp_Image_20250106_at_121757_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677b7fe3f37fa6d52b97972c",
    "name": "Living Room",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146915363_WhatsApp_Image_20250106_at_121801_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677b8005e92a37d576e2fbb1",
    "name": "Living Room",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146949026_WhatsApp_Image_20250106_at_121802_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677b8019e92a37d576e2fc1a",
    "name": "Living Room",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146968878_WhatsApp_Image_20250106_at_121803_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677b7eeae92a37d576e2f902",
    "name": "Living Room",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146665466_WhatsApp_Image_20250106_at_121748_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "677b7fdaf37fa6d52b9796e0",
    "name": "Living Room",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146905361_WhatsApp_Image_20250106_at_121800_PM.jpeg",
    "orientation": "portrait"
  }
```

```
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "13624.00",
    "max": "15790.00"
  },
  "builtUpRateRange": {
    "min": "11353.00",
    "max": "13158.00"
  },
  "saleableRateRange": {
    "min": "9461.00",
    "max": "10965.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "310.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
```

```
"paymentIds": [],
"_id": "6778cebca5477d50e7dca14c",
"ownerName": "Mr. Subramanya Krishna Nayak",
"ownerPhoneNo": "9820071136",
"appAddress": "FLAT NO B-G-2 GROUND FLOOR SHALIBHADRA GRAM BLDG NO
6 & 7 CHS LTD KASHIMIRA MIRA ROAD EAST THANE ",
"remark": "sourcing Rishi singh 9967166330",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "08/11/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Hiral Hardip Bhaimani",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Subramanya Krishna Nayak & MR. Vinayak Narayan Nayak",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "19938/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "551678",
    "path": "cases/6778cebca5477d50e7dca14c/
document_1735970296299_1735970293739_VINAYAK_AGREEMENT_01.pdf",
    "fileName":
"document_1735970296299_1735970293739_VINAYAK_AGREEMENT_01.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "07/11/2000",
```

```
"nameOfApprovingAuthority": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": " NP/NR/755//2000-2001"
},
"isHardCopy": false,
"displayStatus": false,
"id": "217804",
"path": "cases/6778cebca5477d50e7dca14c/
document_1736148940532_part_OC.pdf",
"fileName": "document_1736148940532_part_OC.pdf"
},
{
  "documentType": {
    "value": "60ae125eaa6d152c1801b353",
    "label": "Maintenance Bill"
  },
  "inputs": {
    "documentDate": "15/09/2024",
    "remark": " in the name of Hiral Hardip Bhimani, issued by New Shalibhadra Grma
Co-op. Hsg. Soc. Ltd.",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "287"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "755545",
  "path": "cases/6778cebca5477d50e7dca14c/
document_1736149036046_Maintenance_Bill.pdf",
  "fileName": "document_1736149036046_Maintenance_Bill.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "19/09/2000",
```

```
"nameOfApprovingAuthority": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": " NP/NR/269/3688/2000-2001"
},
"isHardCopy": false,
"displayStatus": false,
"id": "475637",
"path": "cases/6778cebca5477d50e7dca14c/document_1736150474763_CC.pdf",
"fileName": "document_1736150474763_CC.pdf"
}
],
"caseNumber": "013476",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "122994",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jan 04 2025 06:01:32 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Subramanya Krishna Nayak",
    "phone": "9820071136",
    "ownershipShare": "",
    "email": "",
    "id": "150214"
  },
  {
    "name": "Mr. Vinayak Narayan Nayak",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "664475"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Living Room",
  "length": "10.58",
  "length1": "10",
  "length2": "7",
  "width": "12.00",
  "width1": "12",
  "width2": "00",
  "totalArea": "127.00",
  "images": [],
  "finalArea": "127.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "58.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "58.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
```

```
"width": "3.50",
"width1": "3",
"width2": "6",
"totalArea": "16.33",
"images": [],
"finalArea": "16.33",
"extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "262724",
  "selectAreaTypeDocument": "Saleable",
  "totalAreaDocument": "310",
  "squareMeterArea": "28.80",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "335.00",
    "squareMeterArea": "31.12",
    "expectedRate": "13731.34",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "402.00",
    "squareMeterArea": "37.35",
    "expectedRate": "11442.79",
```

```
"percentage": "20"
},
"saleableArea": {
  "area": "482.40",
  "squareMeterArea": "44.82",
  "expectedRate": "9535.66",
  "percentage": "20"
},
"printlnReport": true,
"_id": "677b7bc98ebdf2d52561bc1c",
"property": "Flat",
"area": "335",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "4600000",
"expectedRate": "13731.34",
"builtUpExpectedRate": "11442.79",
"image": "cases/6778cebca5477d50e7dca14c/
indicator_1736142683762_Image.png",
"squareMeter": "31.12",
"id": "980460"
},
{
  "carpetArea": {
    "area": "327.00",
    "squareMeterArea": "30.38",
    "expectedRate": "14678.90",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "392.40",
    "squareMeterArea": "36.46",
    "expectedRate": "12232.42",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "470.88",
    "squareMeterArea": "43.75",
    "expectedRate": "10193.68",
    "percentage": "20"
  },
  "printlnReport": true,
```



```
"_id": "677b7bc98ebdf2d52561bc1d",
"property": "Flat",
"area": "327",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "4800000",
"expectedRate": "14678.90",
"builtUpExpectedRate": "12232.42",
"image": "cases/6778cebca5477d50e7dca14c/
indicator_1736142761367_Image.png",
"squareMeter": "30.38",
"id": "782403"
},
{
  "carpetArea": {
    "area": "434.17",
    "squareMeterArea": "40.34",
    "expectedRate": "7713.57",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "521.00",
    "squareMeterArea": "48.40",
    "expectedRate": "6428.02",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "625.20",
    "squareMeterArea": "58.08",
    "expectedRate": "5356.69",
    "percentage": "20"
  },
  "printlnReport": false,
  "_id": "677b7bc98ebdf2d52561bc1e",
  "property": "Flat",
  "area": "521",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
```

```
"expectedPrice": "3349000",
"expectedRate": "7713.57",
"builtUpExpectedRate": "3349000",
"image": "cases/6778cebca5477d50e7dca14c/
indicator_1736143143288_Image.png",
"squareMeter": "48.40",
"id": "468713"
},
{
  "carpetArea": {
    "area": "530.00",
    "squareMeterArea": "49.24",
    "expectedRate": "14188.68",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "636.00",
    "squareMeterArea": "59.09",
    "expectedRate": "11823.90",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "763.20",
    "squareMeterArea": "70.90",
    "expectedRate": "9853.25",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "677b7bc98ebdf2d52561bc1f",
  "property": "Flat",
  "area": "530",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "7520000",
  "expectedRate": "14188.68",
  "builtUpExpectedRate": "11823.90",
  "image": "cases/6778cebca5477d50e7dca14c/
indicator_1736144632480_Image.png",
  "squareMeter": "49.24",
  "id": "210127"
},
{
```

```
"carpetArea": {
  "area": "356.00",
  "squareMeterArea": "33.07",
  "expectedRate": "13623.60",
  "percentage": ""
},
"builtUpArea": {
  "area": "427.20",
  "squareMeterArea": "39.69",
  "expectedRate": "11353.00",
  "percentage": "20"
},
"saleableArea": {
  "area": "512.64",
  "squareMeterArea": "47.63",
  "expectedRate": "9460.83",
  "percentage": "20"
},
"printInReport": true,
"_id": "677b7bc98ebdf2d52561bc20",
"property": "Flat",
"area": "356",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4850000",
"expectedRate": "13623.60",
"builtUpExpectedRate": "11353.00",
"image": "cases/6778cebca5477d50e7dca14c/
indicator_1736145026707_Image.png",
"squareMeter": "33.07",
"id": "297974"
},
{
  "carpetArea": {
    "area": "190.00",
    "squareMeterArea": "17.65",
    "expectedRate": "15789.47",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "228.00",
    "squareMeterArea": "21.18",
```

```
    "expectedRate": "13157.89",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "273.60",
    "squareMeterArea": "25.42",
    "expectedRate": "10964.91",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "677b7bc98ebdf2d52561bc21",
  "property": "Flat",
  "area": "190",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "3000000",
  "expectedRate": "15789.47",
  "builtUpExpectedRate": "13157.89",
  "image": "cases/6778cebca5477d50e7dca14c/
indicator_1736145340074_Image.png",
  "squareMeter": "17.65",
  "id": "577437"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7edd8ebdf2d52561c14d",
    "name":
"externalImg_1736146653100_WhatsApp_Image_20250106_at_121748_PM_1.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externalImg_1736146653100_WhatsApp_Image_20250106_at_121748_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7eeae92a37d576e2f902",
    "name":
"externalImg_1736146665466_WhatsApp_Image_20250106_at_121748_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externalImg_1736146665466_WhatsApp_Image_20250106_at_121748_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7efae92a37d576e2f91b",
    "name":
"externallmg_1736146681810_WhatsApp_Image_20250106_at_121749_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146681810_WhatsApp_Image_20250106_at_121749_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7f02e92a37d576e2f937",
    "name":
"externallmg_1736146690115_WhatsApp_Image_20250106_at_121750_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146690115_WhatsApp_Image_20250106_at_121750_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7f0de92a37d576e2f958",
    "name":
"externallmg_1736146701363_WhatsApp_Image_20250106_at_121751_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146701363_WhatsApp_Image_20250106_at_121751_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7f1a8ebdf2d52561c1a1",
    "name":
"externallmg_1736146714227_WhatsApp_Image_20250106_at_121752_PM_1.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146714227_WhatsApp_Image_20250106_at_121752_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7f25f37fa6d52b979377",
```

```
"name":
"externallmg_1736146725108_WhatsApp_Image_20250106_at_121752_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146725108_WhatsApp_Image_20250106_at_121752_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f2ef37fa6d52b97939d",
  "name":
"externallmg_1736146733545_WhatsApp_Image_20250106_at_121753_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146733545_WhatsApp_Image_20250106_at_121753_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f37f37fa6d52b9793db",
  "name":
"externallmg_1736146743060_WhatsApp_Image_20250106_at_121753_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146743060_WhatsApp_Image_20250106_at_121753_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f40f37fa6d52b97940c",
  "name":
"externallmg_1736146752142_WhatsApp_Image_20250106_at_121754_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146752142_WhatsApp_Image_20250106_at_121754_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f508ebdf2d52561c1e2",
  "name":
"externallmg_1736146768178_WhatsApp_Image_20250106_at_121754_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146768178_WhatsApp_Image_20250106_at_121754_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f5cf37fa6d52b979466",
  "name":
"externallmg_1736146779749_WhatsApp_Image_20250106_at_121755_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146779749_WhatsApp_Image_20250106_at_121755_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f64f37fa6d52b97949d",
  "name":
"externallmg_1736146788093_WhatsApp_Image_20250106_at_121755_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146788093_WhatsApp_Image_20250106_at_121755_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f6df37fa6d52b979503",
  "name":
"externallmg_1736146796886_WhatsApp_Image_20250106_at_121756_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146796886_WhatsApp_Image_20250106_at_121756_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f798ebdf2d52561c22a",
  "name":
"externallmg_1736146809142_WhatsApp_Image_20250106_at_121756_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146809142_WhatsApp_Image_20250106_at_121756_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7f828ebdf2d52561c250",
  "name":
"externallmg_1736146818132_WhatsApp_Image_20250106_at_121757_PM_1.jpeg",
```

```
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146818132_WhatsApp_Image_20250106_at_121757_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7f8b8ebdf2d52561c2b7",
    "name":
"externallmg_1736146826907_WhatsApp_Image_20250106_at_121757_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146826907_WhatsApp_Image_20250106_at_121757_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7f958ebdf2d52561c308",
    "name":
"externallmg_1736146836492_WhatsApp_Image_20250106_at_121758_PM_1.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146836492_WhatsApp_Image_20250106_at_121758_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7f9d8ebdf2d52561c34a",
    "name":
"externallmg_1736146845230_WhatsApp_Image_20250106_at_121758_PM_1.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146845230_WhatsApp_Image_20250106_at_121758_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b7fa8f37fa6d52b9795ea",
    "name":
"externallmg_1736146856131_WhatsApp_Image_20250106_at_121758_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146856131_WhatsApp_Image_20250106_at_121758_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "677b7fcff37fa6d52b97969e",
  "name":
"externallmg_1736146894354_WhatsApp_Image_20250106_at_121800_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146894354_WhatsApp_Image_20250106_at_121800_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7fdaf37fa6d52b9796e0",
  "name":
"externallmg_1736146905361_WhatsApp_Image_20250106_at_121800_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146905361_WhatsApp_Image_20250106_at_121800_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7fe3f37fa6d52b97972c",
  "name":
"externallmg_1736146915363_WhatsApp_Image_20250106_at_121801_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146915363_WhatsApp_Image_20250106_at_121801_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7fedf37fa6d52b97975d",
  "name":
"externallmg_1736146924785_WhatsApp_Image_20250106_at_121801_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146924785_WhatsApp_Image_20250106_at_121801_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b7ff6f37fa6d52b979795",
  "name":
"externallmg_1736146933819_WhatsApp_Image_20250106_at_121802_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146933819_WhatsApp_Image_20250106_at_121802_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b8005e92a37d576e2fbb1",
    "name":
"externallmg_1736146949026_WhatsApp_Image_20250106_at_121802_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146949026_WhatsApp_Image_20250106_at_121802_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b8019e92a37d576e2fc1a",
    "name":
"externallmg_1736146968878_WhatsApp_Image_20250106_at_121803_PM_1.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146968878_WhatsApp_Image_20250106_at_121803_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b8022e92a37d576e2fc4c",
    "name":
"externallmg_1736146977468_WhatsApp_Image_20250106_at_121803_PM.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146977468_WhatsApp_Image_20250106_at_121803_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b80308ebdf2d52561c4c1",
    "name":
"externallmg_1736146991747_WhatsApp_Image_20250106_at_121804_PM_1.jpeg",
    "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736146991747_WhatsApp_Image_20250106_at_121804_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677b80398ebdf2d52561c506",
```

```
    "name":
"externallmg_1736147000702_WhatsApp_Image_20250106_at_121804_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147000702_WhatsApp_Image_20250106_at_121804_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b80418ebdf2d52561c53b",
  "name":
"externallmg_1736147008876_WhatsApp_Image_20250106_at_121805_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147008876_WhatsApp_Image_20250106_at_121805_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b804bf37fa6d52b97983f",
  "name":
"externallmg_1736147018642_WhatsApp_Image_20250106_at_121805_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147018642_WhatsApp_Image_20250106_at_121805_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b8057f37fa6d52b979886",
  "name":
"externallmg_1736147030910_WhatsApp_Image_20250106_at_121805_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147030910_WhatsApp_Image_20250106_at_121805_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b8061e92a37d576e2fcdd",
  "name":
"externallmg_1736147040717_WhatsApp_Image_20250106_at_121806_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147040717_WhatsApp_Image_20250106_at_121806_PM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b806bf37fa6d52b9798d0",
  "name":
"externallmg_1736147050834_WhatsApp_Image_20250106_at_121806_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147050834_WhatsApp_Image_20250106_at_121806_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b8076f37fa6d52b97990e",
  "name":
"externallmg_1736147061971_WhatsApp_Image_20250106_at_121807_PM_1.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147061971_WhatsApp_Image_20250106_at_121807_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677b807ff37fa6d52b979953",
  "name":
"externallmg_1736147071162_WhatsApp_Image_20250106_at_121807_PM.jpeg",
  "path": "cases/6778cebca5477d50e7dca14c/
externallmg_1736147071162_WhatsApp_Image_20250106_at_121807_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "SUBRAMANYA NAYAK(Cal).xlsx",
    "filename": "1736145796939_SUBRAMANYA_NAYAKCal.xlsx",
    "path": "cases/6778cebca5477d50e7dca14c/
processingDocuments/1736145796939_SUBRAMANYA_NAYAKCal.xlsx",
    "size": "4246752",
    "createdAt": "Mon Jan 06 2025 06:43:17 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  },
  {
    "originalname": "A704.pdf",
    "filename": "1736145813729_A704.pdf",
    "path": "cases/6778cebca5477d50e7dca14c/
processingDocuments/1736145813729_A704.pdf",
```

```
"size": "130485",
"createdAt": "Mon Jan 06 2025 06:43:33 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
  "originalname": "204.pdf",
  "filename": "1736145829031_204.pdf",
  "path": "cases/6778cebca5477d50e7dca14c/
processingDocuments/1736145829031_204.pdf",
  "size": "139193",
  "createdAt": "Mon Jan 06 2025 06:43:49 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9147bf3dd69653a591e8c"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f9147bf3dd69653a591e8c",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Vinita",
      "lastName": "Surve",
      "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67790ef6af1c9077302cb18b",
    "note": "Pending for value confirmation",
    "taskId": "6778de684dad6a51548f657e",
    "createdAt": "2025-01-04T10:35:34.143Z"
  },
  {
    "createdBy": {
      "_id": "60f9147bf3dd69653a591e8c",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Vinita",
      "lastName": "Surve",
      "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
  }
]
```

```
    "_id": "677929a0af1c9077302ccabc",
    "note": "Visit pending",
    "taskId": "6778de684dad6a51548f657e",
    "createdAt": "2025-01-04T12:29:20.869Z"
  }
],
"createdAt": "2025-01-04T06:01:32.676Z",
"updatedAt": "2025-01-06T10:29:19.796Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f9147bf3dd69653a591e8c",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B-G-2, Ground Floor, Building No 6-7, Wing - B,
Shalibhadra Gram, New Shalibhadra Gram Co-op. Hsg. Soc. LTd., Mira Bhayandar
Road, Village - Mira, Kashimira, Taluka - Thane, District - Thane, Mira Road (East), PIN
- 401 107, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Vinayak Nayak",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Representative of owner",
"rerald": "",
"siteVisitContactNo": "9820071136",
"buildingServicesRate": "2400",
"finalAreaType": "Saleable Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Saleable Area in Sq. Ft. = 310.00",
"flatRate": "10900",
"landOtherRate": "8500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
```

```

    "mall": false
  },
  "reportGeneratedDate": "Mon Jan 06 2025 06:50:49 GMT+0000 (Coordinated
Universal Time)",
  "siteVisitDate": "2025-01-05",
  "briefDescOfProperty": "Living Room + Kitchen + Toilet",
  "carpetTotal": "201.96",
  "otherCarpetTotal": "0.00",
  "builtupPercentage": "20",
  "finalBuiltupArea": "242.70",
  "finalCarpetArea": "202.25",
  "finalSalableArea": "242.70",
  "salablePercentage": "0",
  "toBeAdded": "",
  "extendOfSiteRemark": "",
  "siteMeasurementRemark": "",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    }
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'7"	12'00"	127.00
Kitchen	8'5"	7'00"	58.92
Toilet	4'8"	3'6"	16.33

Other  
Composition :

---