

# Vastukala Consultants (I) Pvt. Ltd.

#### www.vastukala.co.in

# Valuation Report of the Immovable Property



#### **Details of the property under consideration:**

Name of Owner: Mr. Vishwanath P. Nagnath Dake

Land and Building Known as "Fitbeat Fitness Forever", House No. 776/3, Plot No. 01/P, Survey No. 110/1/K & 110/1/D, Near Kisan Tractors, Village - Basmath, Taluka - Basmath, District – Hingoli, PIN – 431 512, Maharashtra, India.

Longitude Latitude: 19°19'14.1"N 77°10'35.8"E

#### **Valuation Done for: Axis Bank Basmat Hingoli Branch**

Plot No A-498, Ground Floor, Mama Chowk Basmath, Tal. - Basmath, Dist. - Hingoli, Basmath, PIN – 431512, State – Maharashtra, Country – India



Nanded: 28, S.G.G.S Stadium Complex, Nanded - 431 602, (M.S), INDIA Email: nanded@vastukala.co.in| Tel: +91 2462 244288 +91 94221 71100

Our Pan India Presence at:

Nanded Mumbai

Thane Nashik Aurangabad Pune

Ahmedabad Opelhi NCR Raikot

Raipur Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India

**3** +91 2247495919

👔 mumbai@vastukala.co.in www.vastukala.co.in



### Vastukala Consultants (I) Pvt. Ltd.

Valuation Report Prepared For: Axis Bank / Mr. Vishwanath P. Nagnath Dake (13548/2310006) Page 2 of 13

> Vastu/Axis Bank/Nanded/01/2025/13548/2310006 10/08-125-SOVSM

Date: 10.01.2025

#### VALUER'S OPINION REPORT

This is to certify that the property bearing Land and Building Known as "Fitbeat Fitness Forever", House No. 776/3, Plot No. 01/P. Survey No. 110/1/K & 110/1/D, Near Kisan Tractors, Village - Basmath, Taluka - Basmath, District - Hingoli, PIN – 431 512, Maharashtra, India belongs to Mr. Vishwanath P. Nagnath Dake.

Boundaries of the property.

North Parbhani Nanded Road

South Open Plot East Open Plot

West Sarda Traders Shop & Open Plot

Considering various parameters recorded, existing economic scenario, and the information that is available with reference to the development of neighborhood and method selected for valuation, we are of the opinion that, the property premises can be assessed are as under:

**Guideline Value of the Property** Rs. 67.79.023.00 Fair Market Value of the Property Rs. 1,97,18,940.00 Realizable Value of the Property 1,77,47,046.00 Rs. Forced/ Distress Sale value of the Property. 1,57,75,152.00 Rs.

The valuation of the property is based on the documents produced by the concern. Legal aspects have not been taken into considerations while preparing this valuation report.

Hence certified

For, Vastukala Consultants (I) Pvt. Ltd.

#### Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

IBBI Reg.No. IBBI/RV/07/2019/11744

Nanded: 28, S.G.G.S Stadium Complex, Nanded - 431 602, (M.S), INDIA Email: nanded@vastukala.co.in| Tel: +91 2462 244288 +91 94221 71100

Our Pan India Presence at:

Nanded Mumbai

Nashik Aurangabad Pune

Ahmedabad Opelhi NCR Raikot

Raipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India

**3** +91 2247495919

🕯 mumbai@vastukala.co.in www.vastukala.co.in



Jaipur

# **VALUATION REPORT (IN RESPECT OF LAND AND BUILDING)**

1.	CBB/C	CCMC/CCSU			-				
	N.			-	-				
2.	Name	of Owner & Addr	ess:	Mr. Vishwanath P. Nagnath Dake					
	Name	of Borrower & Ad	ldress		Gunj, Taluka Basmat, District Hingoli  Mr. Vishwanath P. Nagnath Dake				
	Ivallic	or borrower & Ac	Jul 633	Gunj, Taluka Basmat, District Hingoli					
3.	Name	of the Bank Offic	ial Present	No.					
			ative & Mobile No.		d Vishwanath Dake (Owner's Son)				
	- Name	or the represent	ativo a mobilo mo.	Mob. No. # 8007					
4.			Details of the P	roperty Being Val	ued				
4.1	Descri	iption of the Prop	erty		und Floor + Ground Floor RCC framed				
				structure with R0					
4.2	Locati	on of Property			ilding Known as "Fitbeat Fitness				
					e No. 776/3, Plot No. 01/P, Survey No.				
					/1/D, Near Kisan Tractors, Village -				
				431 512, Mahara	a – Basmath, District – Hingoli, PIN –				
	(Rura	I / Semi Urban / l	Irhan)	Urban.	definita, maia.				
4.3		nents Provided:	or barry	OTDUTT.					
			nent for sale dated 17.01.20	19 between Mr. D	attatray P. Gangadharsa Nampalli, Mr.				
	1	Sanjay P. Hari	kishor Kabra, Mr. Arun P. I	Nagoba Shahari &	Mr. Kamal Bh. Suresh Bobade (The				
		Transferor) & M	r. Vishwanath P. Nagnath Da	ake (The Purchase	r)				
	2	Copy of 7/12 Ex							
	Copy of N.A Order No. Ja. No. 2017/ Plot / 1 / Pra. No. 32 Dated. 15.06.2018 issued by District Collect Hingoli								
	Copy of Commencement Certificate No. vide Grampanchyat Tharay No. 09 / dated 23 08 2021 issued								
	by Grampanchayat Malvata, Taluka Basmat, District Hingoli								
	Copy of Plan issued by Group Grampanch								
	ayat Malvata, Taluka Basmat, District Hingoli.								
	Copy of Property Tax Receipt No. 05 dated 18.04.2023 for the year 2023 – 2024 for House No. 776/3 issued by Gramp Panchayat Malvata.								
4.4		o / Survey No. /	House No. 776/3, Plot No.	Road	12 Mtr. Service Road				
	Gut N	o./ Khasra No:	01/P, Survey No. 110/1/K		All Mark Kings Tonday				
		\ <u>\</u>	& 110/1/D						
4.5	Colon		Basmat	Locality / Landmark Near Kisan Tractors					
4.6	Village	e/Town/City	Village - Basmat	District: Hingoli					
4.7	State Maharashtra		Pin code:	431 512					
4.8		ice from Area Offi							
<b>5.</b>	Distance from Area Office (Nanded Branch)  @ 2.3 Km Basmat Main Branch  Type of Property								
	(A) Plot: (Residential / Commercial / Industrial)  Commercial								
			raphical conditions		Leveled				
			nicipal / Corporation Limit		Grampanchayat Basmat				
		onstruction obser			Yes, Semi Under Ground Floor +				
					Ground Floor				
		esidential Prope e / Flat)	erty: (Independent house /	Bungalow / Row	Commercial Property				
	Civic A	Amenities like sch	ool, hospital, market, etc. (Av	vailable, within the	All available in village Basmat.				
		of Km./ Not Avai	lable) <b>strial Property:</b> (Office / Sh	on / Unit in a Mall	Commercial Property used for Gym				
			sulai Flupelly . (Ollice / Si	iop / Officili a ividii	Commercial Property used for Gym and storage purpose.				
	/ Gowdown) and storage purpose.								



Valuers & Appraisers
Architects &
Architects

6.0	Accessibility / Boundaries / Others									
6.1	Availability of	local tran	sport (M		Local Transport, Bus Stand, Railway					
	Personal Transport)				Station, Personal Transport.					
6.2	Distance from Nanded Railway station @ 29.3 Km					2.2 km. from Basmat Bus Depo				
6.3	Does the appro	es the approach road to the Property / Yes.				Will it be able to accommo	odate Yes			
	Building is inde					a fire extinguisher				
6.4	Does the prope	erty fall ur	nder land	locked	No.	Does the property fall				
0.5	area		- 4			community dominated are	ea			
6.5 <b>6.6</b>	Cornered / Inter	rmittent Pi	Ot		Boundaries	Intermittent Plot.				
0.0	Boundaries		ΛοΙ	Per Sale		As Per Site				
		12 Mtr. Se			Deeu	Parbhani Nanded Road	ile			
		Plot No. 2		au		Open Plot				
		12 Mtr. In		nad		Open Plot				
					Santosh	Sarda Traders Shop & Op	en Plot			
		Toshniwa		Joiongo k	Cantoon	caraa maadic onop a op	7011 1 100			
6.7				liddle Cla	ass / Middle Class /	Middle Class				
	Lower Middle C	lass / Poo	or)							
6.8	Quality of Infra Average / Poor		in the	vicinity (	Excellent / Good /	Good				
6.9			Property	v (Free H	Hold / Reg. Lease /	Freehold				
	Govt. Authority)					Treenoid				
6.10	Approved usa				rcial as per Plan	Actual usage of property	Commercial			
	(Industrial /		cial /		by Gram Sevak,	(Industrial / Commercial				
	Residential / Mix) Group Grampanchayat					/ Residential / Mix)	. \			
	Malvata, Taluka Basmat, District Hingoli.									
6.11	Restrictive cove	enants in r	egards to	Commercial	1					
6.12	Type of Structu	re (Load E	Bearing /	RCC / Al	RCC Framed Structure	/				
6.13	Number of floor	rs A	As per Ac	ctual		Semi Under Ground Flo				
						Semi Under Ground Floor – Godown + Storage area Ground floor – Gymkhana + Waiting area +				
						Staircase	a + Waiting area +			
	16.	As per Sanctioned Plan				Semi Under Ground Flo	or + Ground			
	No por current riam					Floor+ First floor				
						Semi Under Ground Floor	– Shop			
						Ground Floor – Shop				
0.44	Occupancy Details (Self-Occupied / Rented / Vacant)					First Floor – Shop				
6.14				ı / Rented	ı / vacant)	Owner Occupied.				
<b>7.</b> 7.1	If the property Name of tenant			No.						
7.1	Was there any			No.	in teriality	If yes, from the current	N.A.			
1 .2	valuation	. 5010(41100	, 101	. 10.		occupants	14.7%			
7.3		property have basic Yes.				Development of	Under			
	amenities				surrounding area	developed				
					Underdeveloped /					
	Developing / Developed									
8.		is Leasehold								
8.1	Name of Lesse		V.A.	Nature of Lease: N.A.						
8.2	Total Period of		V.A.	If yes, from the current occupants  N.A.						
8.3	Does property hasic amenities		No.	Development of surrounding area Underdeveloped / Under Developing / Developed						
9.	Approval Deta									
J.	Approval Dela	113								



Since 1989



Valuers & Appraisers (1)
Architects & Service (1)
Architects & Service

9.1	RERA Registration Nu	mber	Not Applicable					
9.2	Layout Approval Numb	per:	Not Available.					
	Date of Approval		Not Available.					
	Expiry Date		Not Available.					
9.3	Building Plan Approval	Number:	Copy of Plan issued by Group Grampanchayat Malvata,					
			Taluka Basmat,	District Hingoli.	•			
	Date of Approval		Not mentioned in	n the plan				
	Expiry Date		Not mentioned in	n the plan				
9.4	Occupancy Certificate		Not available.					
10.00	Plot Area Details.							
10.01	Plot Area			Ar	ea in Sq. M.			
10.02	Plot Area As per Sale				311.58			
10.03	Plot Area as per sancti		N 0 D)		311.58			
10.04 10.05	Plot Area Considered	I for Valuation (Minimum of A	on Area Details		311.58			
10.03	Floor	Built up area as per	Floor	Constructe	d area as ner Δctual			
	11001	Sanctioned Plan in Sq. M.	1 1001		Constructed area as per Actual in Sq. M.			
		ounotioned i lan in eq. in:			64			
	Semi Under Ground	303.51	Under Ground		135.00			
	Floor		Floor = Godown	+				
	Ground Floor	303.51	Store Ground Floor =		166.00			
	Ground Floor	303.51	Gym + Waiting +		100.00			
	/ <sup>3</sup>		Staircase					
	First Floor	303.51	First Floor		Not constructed at site			
	Total	910.53	Total		301.00			
40.00	Floorwice	made um an fallacca			0			
10.06	Floor	reak up as follows  Built up area as per	Floor	Actual	Current Usage (Storage /			
	11001	Sanctioned Plan in Sq.M.	11001	Constructed area in Sq.M.	Commercial)			
	Semi Under Ground Floor	303.51	Under Ground Floor	135.00	Godown + Store			
	Ground Floor	303.51	Ground	166.00	Gym + Waiting + Staircase			
	First Floor	303.51	First Floor -		Not constructed at site			
	Total 910.53		Total	301.00				
10.07	Amenities Details (if ar	ny):	RCC footing, Kota stone tiles, Vitrified tiles, granite trades and riser, SS railings, false ceiling, emulsion paint internally, cement paint external					
10.08	Floor Space Index peri	missible	As per local norms					
10.09	FSI Utilized		Details not available					
10.10	Whether the constructi building plan and / or k		<ul><li>No</li><li>We have considered actual area at site for valuation.</li></ul>					
10.11	Details of Extra Constr	uction	No					
10.12	Percentage of Extra Co	onstruction	-					
10.13	Whether the extra co OR Non-Compoundab	nstruction is Compoundable le?	Not applicable					



Since 1989



Valuers & Appraisers (I)
Architects & archit

40.44	0					01					
10.14	Quality of const			Good.							
10.15	Maintenance of the Property					Good					
10.16	Condition of Bui				Good.						
10.17	Current Life of the 3 Years structure				Projected Future Life of the		57 Years.				
10.10					Structure						
10.18	Land Revenu		etails n	ot availat	ole	Municipal				ax Receipt No.	
	Taxes Paid upt	to (lor				Paid up Building)	to (for			3 for the year use No. 776/3	
	Lanu)			Dullullig		Dulluling)	37			Gram Panchayat	
								Malwata			
11.	Details of Value	ation:									
	Floor	Constructed Area	Year Of Const.	Age of the building	Total Life of	Estimated Replacement	Balance Life of Structures	Depreciated Rate to be	Depreciated Value to be	Replacement Cost	
			Collst.		Structure	Rate	in Years	considered	considered	( <del>=</del> )	
		(Sq. M)		(Years)		(₹)		(₹)	(₹)	(₹)	
	Under Ground Floor = Godown + Store	135.00	2022	3	60.00	21,000.00	57.00	N.A.	N.A.	28,35,000.00	
	Ground = Gym + Waiting + Staircase	166.00	2022	3	60.00	21,000.00	57.00	N.A.	N.A.	34,86,000.00	
									TOTAL	63,21,000.00	
12.	Government G	uideline v	alue								
	Particu	lars		Area i	n Sq. M.	T	Rate in F	 ₹s.	Va	alue in Rs.	
1	Land					1,470.0	_		4,58,023.00		
	Land		1,470.0		1		, ,				
2	Construction			As per valuation table					63,21,000.00		
	TOTAL			\	AY				14/	67,79,023.00	
13.	Market Value of Land										
	Particulars			Area in Sq. M. Rate in Rs.				e in Rs.			
4.4	Land			311.58 43,000.00			1,33,97,940.00				
14.	Value of the Property										
	Market Value	<b>Land</b> 1,33,97,940.00		Building		Amenitie		Total			
	Market Value	7,940.00	63,21,000.00 - 1,97,18,940.00								
	Interior and other Development								-		
	Land Development Value							-			
								1,97,18,940.00			
	Realizable Value						1,77,47,046.00				
	Distressed/Forced Sale Value Insurable Value								1,57,75,152.00		
	27, 722.2							JJ, I Z, OJU.UU			
	Remark:  1. We have considered the plot area as per Plan issued by Gram Sevak, Gram Panchayat Malvata.								t Malvata		
	2. As per Approved Plan structure is Semi Underground Floor + Ground floor + First Floor. As per site										
	structure is Semi Underground Floor + Ground floor used for commercial purpose.							1			
	3. As per Approved Plan total Built up area of Semi Underground Floor + Ground floor + First Floor is										
	910.53 Sq. M. As per our actual site measurement area of Semi Underground Floor + Ground floor						Ground floor is				
										0.00.10	
	301.00	Sq. M. W	e have	considere	ed least a	rea for the p	urpose of	valuation.			
	301.00 4. Recent	Sq. M. W t sale / pu	e have rchase	considere listings a	ed least a re not ava	rea for the p ailable on int	urpose of ternet site.	valuation. Our rate is	based on	local enquiry,	



Since 1989



Government IGR site are very much below than the market rate.



#### **Undertaking:**

- 1. I have / our / representative Md. Shareq has inspected the subject property on 10.01.2025 along with Mr. Vishwanath P. Nagnath Dake identified the same based on the documents provided.
- 2. I/We have no direct or Indirect interest in the property being valued.
- 3. The information furnished above is true and correct to my/our knowledge
- 4. I/ we have not been dismissed or removed from govt. Service or convicted of an offence connected with any proceedings of income tax act, wealth tax act or gift tax act or have been blacklisted by any bank/ financial institution/ govt. Department/ public sector enterprise/ body corporate etc.
- 5. This valuation is prepared without any prejudice or bias to any person or institution.
- 6. The value of land is taken into account by making due enquires in the locality and ascertaining the sales value of the properties in the locality.
- 7. Any additions/alterations made to the property after the date of valuations shall not fall under the scope of this report.

For, Vastukala Consultants (I) Pvt. Ltd.

#### Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09 IBBI Reg.No. IBBI/RV/07/2019/11744

Date: 10.01.2025

Attachments							
Photographs of the Property from inside & outside	:	Attached					
Location sketch for the property:	:	Attached					
Geo Tagging	:	Attached					
Topography	:	Leveled Land					
Government Value Document	:	Attached					





An ISO 9001: 2015 Certified Company


# **Actual Site Photographs**



















# **Actual Site Photographs**



















# **Construction Plan issued by Group Gram Panchayat**




## Construction as per site





**VASTUKALA** 




An ISO 9001 : 2015 Certified Company



# Route Map of the property Site u/r






#### Latitude Longitude: 19°19'14.1"N 77°10'35.8"E

Note: The Blue line shows the route to site from nearest railway station (Basmat – 4.1 KM.)



# **Ready Reckoner Rate**







#### ASSUMPTIONS, CAVEATS, LIMITATION AND DISCLAIMERS

- 1. We assume no responsibility for matters of legal nature affecting the property appraised or the title thereto, nor do we render our opinion as to the title, which is assumed to be good and marketable.
- 2. The property is valued as though under responsible ownership.
- 3. It is assumed that the property is free of liens and encumbrances.
- 4. It is assumed that there are no hidden or unapparent conditions of the subsoil or structure that would render it more or less valuable. No responsibility is assumed for such conditions or for engineering that might be required to discover such factors.
- 5. The rates for valuation of the property are in accordance with the Govt. approved rates and prevailing market rates

Date: 10.01.2025 Place: Nanded.

For, Vastukala Consultants (I) Pvt. Ltd.

#### Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 IBBI Reg.No. IBBI/RV/07/2019/11744





An ISO 9001: 2015 Certified Company