

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba7d"
    },
    "firstName": "Anshuman",
    "type": "CREDITOFFICER",
    "_id": "658279f465d49d78457e3b08",
    "lastName": "Giri",
    "mobileNo": "",
    "workMobileNo": "9943935253",
    "email": "anshuman.giri@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Anshuman",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba7d",
  "branchCode": "000024",
  "type": "BRANCH",
  "name": "Veer Nariman Road Branch ",
  "email": "ubin0531952@unionbankofindia.bank",
  "mobileNo": "02222045200",
  "alternateMobileNo": "02222048268",
  "address": "84,Raj Mahal Building, Veer Nariman Road, Churchgate, Mumbai,
Maharashtra 400020 ,cbsvnroad@unionbankofindia.com",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "67776d60a5477d50e7dbc213",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "AJAY",
  "email": "ajayrewale503@gmail.com",
  "lastName": "REWALE",
  "mobileNo": "9766640171",
  "designation": "",
  "shortName": "AJAY",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
```

```
{
  "title": {
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.053953251142335",
  "longitude": "72.8324005445362"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8324005445362,
    19.053953251142335
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "8/01/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "29",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "Chapel Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400050",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bandra West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
}
```

```
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
```



```
"paymentIds": [],
"_id": "677df5011180e21f2a86fd8b",
"ownerName": "Shri Max F D'souza",
"ownerPhoneNo": "9821018523",
"appAddress": "flat No 102\nMaster vinayak Road \nBandra West \nMumbai ",
"remark": "All documents visit time ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/677df5011180e21f2a86fd8b/
document_1736307937105_1003980.pdf",
    "fileName": "document_1736307937105_1003980.pdf",
    "id": "443385",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Wed Jan 08 2025 03:46:08 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013552",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "551004",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jan 08 2025 03:46:09 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri Max F D'souza",
    "phone": "9821018523",
    "ownershipShare": "",
    "email": "",
    "id": "173907"
  }
],
"proposePurchasers": [
  {
    "name": "Rushi Hashmi & karishma Hashmi"
  }
],
```

```
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677e5dd91d3324cd96b46261",
    "name": "externalImg_1736334802129_1736334799252_image_0.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externalImg_1736334802129_1736334799252_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "677e5dd91d3324cd96b46262",
    "name": "externalImg_1736334805931_1736334799252_image_1.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externalImg_1736334805931_1736334799252_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a3025b",
    "name": "externalImg_1736334912589_1736334894365_image_0.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externalImg_1736334912589_1736334894365_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a3025c",
    "name": "externalImg_1736334917764_1736334894365_image_1.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externalImg_1736334917764_1736334894365_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "677e5e67fb7886cd95a3025d",
  "name": "externalimg_1736334920336_1736334894365_image_2.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externalimg_1736334920336_1736334894365_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5e67fb7886cd95a3025e",
  "name": "externalimg_1736334923896_1736334894365_image_3.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externalimg_1736334923896_1736334894365_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5e67fb7886cd95a3025f",
  "name": "externalimg_1736334930669_1736334894365_image_4.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externalimg_1736334930669_1736334894365_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5e67fb7886cd95a30260",
  "name": "externalimg_1736334937193_1736334894365_image_5.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externalimg_1736334937193_1736334894365_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5e67fb7886cd95a30261",
  "name": "externalimg_1736334942496_1736334894365_image_6.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externalimg_1736334942496_1736334894365_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "677e5e67fb7886cd95a30262",
    "name": "externallmg_1736334943304_1736334894365_image_7.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334943304_1736334894365_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a30263",
    "name": "externallmg_1736334943531_1736334894365_image_8.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334943531_1736334894365_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a30264",
    "name": "externallmg_1736334944082_1736334894365_image_9.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334944082_1736334894365_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a30265",
    "name": "externallmg_1736334944641_1736334894365_image_10.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334944641_1736334894365_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a30266",
    "name": "externallmg_1736334945815_1736334894365_image_11.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334945815_1736334894365_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a30267",
```

```
    "name": "externallmg_1736334947199_1736334894365_image_12.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334947199_1736334894365_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a30268",
    "name": "externallmg_1736334948013_1736334894365_image_13.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334948013_1736334894365_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a30269",
    "name": "externallmg_1736334948531_1736334894365_image_14.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334948531_1736334894365_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a3026a",
    "name": "externallmg_1736334948986_1736334894365_image_15.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334948986_1736334894365_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a3026b",
    "name": "externallmg_1736334949448_1736334894365_image_16.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334949448_1736334894365_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a3026c",
    "name": "externallmg_1736334949938_1736334894365_image_17.jpeg",
```

```
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334949938_1736334894365_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5e67fb7886cd95a3026d",
    "name": "externallmg_1736334950343_1736334894365_image_18.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736334950343_1736334894365_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5f8f1d3324cd96b463c1",
    "name": "externallmg_1736335209255_1736335202485_image_0.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335209255_1736335202485_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5f8f1d3324cd96b463c2",
    "name": "externallmg_1736335211057_1736335202485_image_1.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335211057_1736335202485_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5f8f1d3324cd96b463c3",
    "name": "externallmg_1736335211997_1736335202485_image_2.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335211997_1736335202485_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5f8f1d3324cd96b463c4",
    "name": "externallmg_1736335214296_1736335202485_image_3.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335214296_1736335202485_image_3.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463c5",
  "name": "externallmg_1736335216337_1736335202485_image_4.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335216337_1736335202485_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463c6",
  "name": "externallmg_1736335219261_1736335202485_image_5.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335219261_1736335202485_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463c7",
  "name": "externallmg_1736335221912_1736335202485_image_6.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335221912_1736335202485_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463c8",
  "name": "externallmg_1736335225037_1736335202485_image_7.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335225037_1736335202485_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463c9",
  "name": "externallmg_1736335230441_1736335202485_image_8.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335230441_1736335202485_image_8.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463ca",
  "name": "externallmg_1736335231582_1736335202485_image_9.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335231582_1736335202485_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463cb",
  "name": "externallmg_1736335233686_1736335202485_image_10.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335233686_1736335202485_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463cc",
  "name": "externallmg_1736335235117_1736335202485_image_11.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335235117_1736335202485_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463cd",
  "name": "externallmg_1736335236711_1736335202485_image_12.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335236711_1736335202485_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463ce",
  "name": "externallmg_1736335237617_1736335202485_image_13.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335237617_1736335202485_image_13.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463cf",
  "name": "externallmg_1736335239497_1736335202485_image_14.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335239497_1736335202485_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463d0",
  "name": "externallmg_1736335241936_1736335202485_image_15.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335241936_1736335202485_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463d1",
  "name": "externallmg_1736335242982_1736335202485_image_16.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335242982_1736335202485_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463d2",
  "name": "externallmg_1736335243968_1736335202485_image_17.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335243968_1736335202485_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677e5f8f1d3324cd96b463d3",
  "name": "externallmg_1736335244916_1736335202485_image_18.jpeg",
  "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335244916_1736335202485_image_18.jpeg",
  "orientation": "portrait"
},
{
```

```

    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677e5f8f1d3324cd96b463d4",
    "name": "externallmg_1736335245951_1736335202485_image_19.jpeg",
    "path": "cases/677df5011180e21f2a86fd8b/
externallmg_1736335245951_1736335202485_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-08T03:46:09.190Z",
"updatedAt": "2025-01-08T11:20:47.881Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "67776d60a5477d50e7dbc213",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. Ground Floor, Plot No. 29, Chapel Road, Bandra
West, Mumbai, 400050",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Javed Hashmi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Rushi Hashmi & karishma Hashmi",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9821018523"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
