

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "firstName": "Priti",
    "type": "CREDITOFFICER",
    "_id": "64c8b0a2a5c3051014f5f888",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9773028294",
    "email": "preeti.shinde@comsosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) ",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhudurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
(East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/64abdb2806d6ec174986d16b/
profilePhoto_1731563513029_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "19.18653495348364",
"longitude": "73.21063974319934"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},

```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Chikhholi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Darshan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "18",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```

```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "603",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```



```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
```

```
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "basement parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2026",
    "fullDate": "1/1/2026"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
}
```

```
"typeOfStructure": {
  "value": "Kuccha_Structure",
  "label": "Kuccha Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
```

```
"label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "10",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "9"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  }
},
"finalLatLng": {
```

```
"coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "13",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "8",
    "percentage": "4.31",
    "isHideFloor": false,
```

```
"status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "8",
  "percentage": "4.31",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "58.62",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "677fbfb427fcec82c8384426",
"ownerName": "Mr. Hemant Gautam Dudhale & Mrs. Vaishnavi Hemant Dudhale",
"ownerPhoneNo": "9834772879",
"fullAddress": "Residential Flat No. 603, 6th Floor, Sai Darshan, Village - Chikhlioli,
Taluka - Ambernath, District - Thane, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "30/12/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Sai Krupa Builders",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Hemant Gautam Dudhale & Mrs. Vaishnavi Hemant Dudhale",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "16946/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "709685",
    "path": "cases/677fbfb427fcec82c8384426/
document_1736425390049_Canara_bank.pdf",
```

```
"fileName": "document_1736425390049_Canara_bank.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "06/03/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700049948"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1736487374544_RERA_Certificate.pdf",
"path": "cases/677fbfb427fcec82c8384426/
document_1736487374544_RERA_Certificate.pdf",
"id": "671557",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Jan 10 2025 05:39:57 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "28/07/2022",
    "nameOfApprovingAuthority": {
      "value": "Ambarnath_Municipal_Council",
      "label": "Ambarnath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "ANP / NRV / BP / 2022 - 2023 / 630 / 9344 / 36"
},
"isHardCopy": false,
```

```
"displayStatus": true,
"fileName": "document_1736487414939_CC.pdf",
"path": "cases/677fbfb427fcec82c8384426/document_1736487414939_CC.pdf",
"id": "430128",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Jan 10 2025 05:39:57 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "28/07/2022",
    "nameOfApprovingAuthority": {
      "value": "Ambernath_Municipal_Council",
      "label": "Ambernath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "ANP / NRV / BP / 2022 - 2023 / 630 / 9344 / 36"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1736487503363_Approved_Plan.pdf",
  "path": "cases/677fbfb427fcec82c8384426/
document_1736487503363_Approved_Plan.pdf",
  "id": "457038",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Jan 10 2025 05:39:57 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013584",
"createdBy": "64abdb2806d6ec174986d16b",
"caseHistory": [
  {
    "id": "707954",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 09 2025 12:23:16 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Mr. Hemant Gautam Dudhale & Mrs. Vaishnavi Hemant Dudhale",
    "phone": "9834772879",
    "ownershipShare": "",
    "email": "",
    "id": "556143"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0dd601c90e6961f5ab0",
    "name":
"externalImg_1736749276905_WhatsApp_Image_20250113_at_114551_AM.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externalImg_1736749276905_WhatsApp_Image_20250113_at_114551_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0dd601c90e6961f5ab1",
    "name":
"externalImg_1736749276963_WhatsApp_Image_20250113_at_114553_AM_1.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externalImg_1736749276963_WhatsApp_Image_20250113_at_114553_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0dd601c90e6961f5ab2",
    "name":
"externalImg_1736749277060_WhatsApp_Image_20250113_at_114553_AM.jpeg",
```

```
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749277060_WhatsApp_Image_20250113_at_114553_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0eb290edae64f15dbcf",
    "name":
"externallmg_1736749289622_WhatsApp_Image_20250113_at_114554_AM.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749289622_WhatsApp_Image_20250113_at_114554_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0eb290edae64f15dbd0",
    "name":
"externallmg_1736749289697_WhatsApp_Image_20250113_at_114555_AM_1.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749289697_WhatsApp_Image_20250113_at_114555_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0eb290edae64f15dbd1",
    "name":
"externallmg_1736749289774_WhatsApp_Image_20250113_at_114555_AM.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749289774_WhatsApp_Image_20250113_at_114555_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0eb290edae64f15dbd2",
    "name":
"externallmg_1736749289813_WhatsApp_Image_20250113_at_114556_AM.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749289813_WhatsApp_Image_20250113_at_114556_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6784b0eb290edae64f15dbd3",
  "name":
"externallmg_1736749289862_WhatsApp_Image_20250113_at_114557_AM_1.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749289862_WhatsApp_Image_20250113_at_114557_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b0fd290edae64f15dc06",
  "name":
"externallmg_1736749308966_WhatsApp_Image_20250113_at_114557_AM.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749308966_WhatsApp_Image_20250113_at_114557_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b0fd290edae64f15dc07",
  "name":
"externallmg_1736749309009_WhatsApp_Image_20250113_at_114558_AM_1.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749309009_WhatsApp_Image_20250113_at_114558_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b0fd290edae64f15dc08",
  "name":
"externallmg_1736749309349_WhatsApp_Image_20250113_at_114558_AM_2.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749309349_WhatsApp_Image_20250113_at_114558_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b0fd290edae64f15dc09",
  "name":
"externallmg_1736749309369_WhatsApp_Image_20250113_at_114558_AM.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749309369_WhatsApp_Image_20250113_at_114558_AM.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0fd290edae64f15dc0a",
    "name":
"externallmg_1736749309393_WhatsApp_Image_20250113_at_114559_AM_1.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749309393_WhatsApp_Image_20250113_at_114559_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0fd290edae64f15dc0b",
    "name":
"externallmg_1736749309424_WhatsApp_Image_20250113_at_114559_AM_2.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749309424_WhatsApp_Image_20250113_at_114559_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0fd290edae64f15dc0c",
    "name":
"externallmg_1736749309454_WhatsApp_Image_20250113_at_114559_AM_3.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749309454_WhatsApp_Image_20250113_at_114559_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b0fd290edae64f15dc0d",
    "name":
"externallmg_1736749309779_WhatsApp_Image_20250113_at_114559_AM.jpeg",
    "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749309779_WhatsApp_Image_20250113_at_114559_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6784b10a601c90e6961f5ae8",
```

```
"name":
"externallmg_1736749322030_WhatsApp_Image_20250113_at_114600_AM_1.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749322030_WhatsApp_Image_20250113_at_114600_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b10a601c90e6961f5ae9",
  "name":
"externallmg_1736749322128_WhatsApp_Image_20250113_at_114600_AM.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749322128_WhatsApp_Image_20250113_at_114600_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b10a601c90e6961f5aea",
  "name":
"externallmg_1736749322222_WhatsApp_Image_20250113_at_114601_AM_1.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749322222_WhatsApp_Image_20250113_at_114601_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b10a601c90e6961f5aeb",
  "name":
"externallmg_1736749322369_WhatsApp_Image_20250113_at_114601_AM.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749322369_WhatsApp_Image_20250113_at_114601_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b10a601c90e6961f5aec",
  "name":
"externallmg_1736749322526_WhatsApp_Image_20250113_at_114602_AM_1.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749322526_WhatsApp_Image_20250113_at_114602_AM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b10a601c90e6961f5aed",
  "name":
"externallmg_1736749322554_WhatsApp_Image_20250113_at_114602_AM_2.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749322554_WhatsApp_Image_20250113_at_114602_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6784b10a601c90e6961f5aee",
  "name":
"externallmg_1736749322642_WhatsApp_Image_20250113_at_114602_AM.jpeg",
  "path": "cases/677fbfb427fcec82c8384426/
externallmg_1736749322642_WhatsApp_Image_20250113_at_114602_AM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-09T12:23:16.146Z",
"updatedAt": "2025-01-13T10:27:52.567Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Hemant Gautam Dudhale & Mrs. Vaishnavi Hemant
Dudhale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reId": "",
"siteVisitContactNo": "9834772879"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			